

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>924K #1405</u> MAKE <u>Cat</u> MODEL <u>924K</u> SERIAL # _____ HOUR METER <u>1500 HRS</u> MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____						
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>9-20-19</u> DATE COMPLETED <u>9-24-19</u> MECHANIC <u>JAMES & BRYAN</u> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:70%;">JOB NAME/LOCATION <u>Shop</u></td> <td style="width:30%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER				
JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER							
PROBLEM: <u>service check over</u>								
REPAIRED: <u>serviced Took oil samples</u>								
<table style="width:100%;"> <tr> <td style="width:40%;">PARTS: <u>All Air Filters</u></td> <td style="width:20%; text-align: right;"><u>282.³⁴</u></td> <td style="width:40%; text-align: right;"><u>Thompson</u></td> </tr> <tr> <td><u>Other Filters</u></td> <td style="text-align: right;"><u>126.³⁶</u></td> <td style="text-align: right;"><u>Thompson</u></td> </tr> </table>			PARTS: <u>All Air Filters</u>	<u>282.³⁴</u>	<u>Thompson</u>	<u>Other Filters</u>	<u>126.³⁶</u>	<u>Thompson</u>
PARTS: <u>All Air Filters</u>	<u>282.³⁴</u>	<u>Thompson</u>						
<u>Other Filters</u>	<u>126.³⁶</u>	<u>Thompson</u>						

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1405</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924K</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: <u>11-13-19</u> DATE COMPLETED <u>11-18-19</u> MECHANIC <u>Bryan</u>	
			JOB NAME/LOCATION <u>Camdenland behavior</u>	JOB NUMBER
PROBLEM: <u>hoses leaking going to quick connect cylinder</u>				
REPAIRED: _____				
PARTS: <u>2-hoses</u> <u>119.30</u> <u>Thompson Machinery</u> <u>hose</u> <u>48.98</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1405</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924K</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>2K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>4-14-2020</u> DATE COMPLETED <u>4-16-2020</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Cumberland Belvoir</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS <u>All Filters</u> <u>356.86</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1405</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924K</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>2500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>4-7-21</u> DATE COMPLETED <u>4-13-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>service</u>				
REPAIRED: <u>served</u>				
PARTS: <u>All Filters</u> <u>413.42</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1405</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924K</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>6-24-21</u>	
PROBLEM: <u>CAP MISSING</u>			MECHANIC <u>Caleb</u>	
			JOB NAME/LOCATION <u>GARGI</u>	JOB NUMBER
REPAIRED: <u>replaced cap</u>				
PARTS: <u>Radiator Cap</u> <u>32.02</u> <u>Thompson</u>				
<u>369-6549</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1405</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924K</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>3K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>10-5-21</u> DATE COMPLETED _____	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC _____	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviceed</u>				
PARTS: <u>All Filters</u> <u>345.33</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>1405</u>		HOURS _____	DAYS _____	BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>		REASON _____		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>924K</u>		PARTS _____	LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>3,500 HRS</u>				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE <u>5-13-22</u>	DATE COMPLETED <u>6-13-22</u>
PROBLEM: <u>Service</u>				MECHANIC <u>Ben</u>	
				JOB NAME/LOCATION <u>West Trinity</u>	JOB NUMBER _____
REPAIRED: <u>Serviced</u>					
PARTS: <u>Filters</u> <u>673.62</u> <u>Thompson</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1405

MAKE CAT

MODEL 924K

SERIAL # _____

HOUR METER 4K HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____

LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 9-24-22 DATE COMPLETED 10-1-22

MECHANIC Anthony

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: Service

REPAIRED: Serviced

PARTS:

All Filters

398.86

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1405</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924K</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>4,500 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>6-2-23</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Anthony</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Thorne Trace</u>	JOB NUMBER _____	
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>Filters</u> <u>796.88</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>1405</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>924K</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER <u>5K NRS</u>		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>10-16-23</u> DATE COMPLETED <u>10-19-23</u> MECHANIC <u>Anthony & Justin</u>
		JOB NAME/LOCATION <u>Stone Trace</u> JOB NUMBER _____
PROBLEM: <u>Service</u>		
REPAIRED: <u>Service</u>		
PARTS: <u>Filters</u> <u>794.43</u> <u>Thompson</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1405</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924K</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>5,500 Hrs</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>5-29-24</u> DATE COMPLETED <u>5-28-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>LIV Anthen</u>	JOB NUMBER _____
PROBLEM: <u>service</u>				
REPAIRED: <u>serviced</u>				
PARTS: <u>filters</u> <u>524.18</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1405</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>924K</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>9-3-24</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION	JOB NUMBER	
PROBLEM: <u>won't start</u>		<u>Quail Run</u>		
REPAIRED: <u>replaced batteries</u>				
PARTS: <u>Z-GRP31</u> <u>326.59</u> <u>Advance</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1405</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>924K</u>		COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER		
SERIAL # _____		OTHER _____		
HOUR METER _____				
MILES <u>10000 11000</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>7-3-24</u> DATE COMPLETED <u>7-3-24</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Anthony</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Anthony</u>	JOB NUMBER	
PROBLEM: <u>sensor bad batteries</u>				
REPAIRED: <u>replaced batteries</u>				
PARTS: <u>Filters</u> <u>513.74</u> <u>Thompson</u>				
<u>2 batteries 31P30 326.59</u> <u>Advance 9-3-24</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES			
EQUIP. # <u>1405</u>	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____				
MAKE <u>Cat</u>						
MODEL <u>924K</u>						
SERIAL # _____						
HOUR METER _____						
MILES _____						
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>10-31-24</u> DATE COMPLETED <u>11-2-24</u> MECHANIC <u>Al</u> <table border="1"> <tr> <td>JOB NAME/LOCATION <u>To Shop</u></td> <td>JOB NUMBER</td> </tr> </table>			JOB NAME/LOCATION <u>To Shop</u>	JOB NUMBER
JOB NAME/LOCATION <u>To Shop</u>	JOB NUMBER					
PROBLEM: <u>needs tires</u>						
REPAIRED: <u>replaced tires</u>						
PARTS: <u>20.5 X 25 Maxam M5301 5899.50 Gateway Tire</u>						

SINCE 1963

PARTS: Filters 580.94 Thompson