

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1402</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924G</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>12-2-19</u> DATE COMPLETED <u>12-3-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Bev</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Ashland Farms</u>	JOB NUMBER _____
PROBLEM: <u>Wont start</u>				
REPAIRED: <u>replaced battery on Right side</u>				
PARTS: <u>Battery</u> <u>164.90</u> <u>Interstate Battery</u>				
<u>29H-UHD</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1401</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924G</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>13K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>1-31-2020</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>ALL</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>needs serviced</u>				
REPAIRED: <u>serviced</u>				
PARTS: <u>most filters</u> <u>193.7L</u> <u>NAPA</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>1401</u> MAKE <u>Cat</u> MODEL <u>924G</u> SERIAL # _____ HOUR METER <u>13,388</u> MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>1-15-21</u> DATE COMPLETED <u>2-3-21</u> MECHANIC <u>All</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____
PROBLEM: <u>serviced, pack tilt cylinder</u>		
REPAIRED: <u>serviced, replaced front windshield wiper</u> <u>Packed tilt cylinder</u>		
PARTS: <u>All Filters</u> <u>380.⁰⁰</u> <u>Pan Filter</u> <u>seal kit</u> <u>162.⁵⁰</u> <u>Thompson</u> <u>wiper</u> <u>11.⁵¹</u> <u>Advance Auto Parts</u> <u>Fittings</u> <u>6.⁴⁷</u> <u>Thompson</u> <u>cylinder packed</u> <u>349.⁶⁰</u> <u>Mid South Hydraulics</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>1401</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924G</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>13,500 HRS</u>				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE <u>6-18-21</u> DATE COMPLETED <u>7-27-21</u>	
				MECHANIC <u>All</u>	
				JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>Service + weld bucket</u>					
REPAIRED: <u>serviced, Tapped A/c, welded cracks on bucket</u>					
PARTS: <u>All Filters</u> <u>372.77</u> <u>Tenno Filter</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1401</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>3246</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>2-9-22</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Vintage Edge</u>		
PROBLEM: <u>boom hose leaking</u>		JOB NUMBER _____		
REPAIRED: <u>replaced hose</u>				
PARTS: <u>hose</u> <u>312.28</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1401
MAKE CAT
MODEL 924G
SERIAL # _____
HOUR METER 14K HRS
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE 3-30-20 DATE COMPLETED 4-18-20

MECHANIC James

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: Service

REPAIRED: Serviced & washed

PARTS: Filters

667.03

Turn. Filter

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1401</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924G</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>13,760 mi</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>6-15-22</u> DATE COMPLETED <u>11-5-22</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>All</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shops</u>		
PROBLEM: <u>won't move needs cutting edge</u>		JOB NUMBER _____		
REPAIRED: <u>replaced Transmission controls & relay</u>				
<u>new cutting edges</u>				
<u>replaced missing hardware</u>				
<u>washed & greased</u>				
PARTS: <u>Edges & bolts</u> <u>Edge</u> <u>801.18</u>				
<u>hardware</u> <u>183.04</u> <u>Thompson</u>				
<u>End bits</u> <u>288.45</u>				
<u>control & relay</u> <u>526.26</u> <u>Thompson</u>				
<u>Armrest & hardware</u> <u>Thompson</u>				
<u>hardware</u> <u>87.61</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1401</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>924G</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
OUR METER <u>0 new @ 14,300 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>11-28-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Anthony & Justin</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>41st Ave</u>	JOB NUMBER _____
PROBLEM: <u>Service & new HR meter</u>				
REPAIRED: <u>serviced, replaced hr meter</u>				
PARTS <u>Filter & HR meter 634.29</u> <u>Thompson</u>				

WHEEL LOADER
OIL SAMPLING SCHEDULE

CAT EXTENDED WARRANTY MACHINES MUST BE MONITORED UNDER SCHEDULED OIL SAMPLING (S.O.S.) IN ORDER FOR EXTENDED WARRANTIES TO BE HONORED. THE USER IS RESPONSIBLE FOR TAKING OIL SAMPLES, PER THE SCHEDULE BELOW, AND MAILING OR DELIVERING THESE SAMPLES TO THOMPSON MACHINERY. THE FIRST SAMPLING KIT IS FURNISHED. ADDITIONAL BOTTLES MAY BE PURCHASED FROM THOMPSON MACHINERY PARTS DEPARTMENT.

ENGINE

EVERY 250 HOURS OR 3 MONTHS,
WHICHEVER COMES FIRST.

TRANSMISSION-
POWERSHIFT

EVERY 500 HOURS OR EVERY 3 MONTHS,
WHICHEVER COMES FIRST.

DIFFERENTIALS
FINAL DRIVES

EVERY 500 HOURS OR EVERY 3 MONTHS,
WHICHEVER COMES FIRST.

HYDRAULIC SYSTEMS ARE NOT COVERED UNDER EXTENDED WARRANTY, BUT WE SUGGEST SAMPLES EVERY 500 HOURS OR EVERY 3 MONTHS, WHICHEVER COMES FIRST.

I ACKNOWLEDGE RECEIPT OF AN INITIAL SUPPLY OF OIL SAMPLE KITS AND A COPY OF THIS SAMPLING SCHEDULE.

COMPANY NAME:

Thorne Brothers, LLC

MACHINE MODEL
SERIAL NUMBER

924G 95W02241

PRINTED NAME

SIGNATURE

John O. Pauer

9-23-02

DATE

FAILURE TO ADHERE TO THE ABOVE GUIDELINES COULD RESULT IN LOSS OF WARRANTY COVERAGE, BECAUSE SOME FAILURES CAN BE PREVENTED BY S.O.S.

EQUIPMENT
REPAIRS

DATE 9-24-02

MILEAGE/HOURS 5 hrs.

EQUIPMENT REPAIRED 9246 # 2101

REPAIRS MADE Weld hook Plate in Bucket
Raise front Fenders

HOURS WORKED _____

PARTS USED

Hook & cleves \$ 81.90
Set of Larks \$4,400.00

EQUIPMENT
REPAIRS

DATE 11/27/08

MILEAGE/HOURS 250

EQUIPMENT REPAIRED 9546

REPAIRS MADE Service Engine

HOURS WORKED _____

PARTS USED

Fuel Filter \$46.78
Oil

EQUIPMENT
REPAIRS

DATE 2-11-03

MILEAGE/HOURS 500

EQUIPMENT REPAIRED 9246

REPAIRS MADE Complete Service change oil,
hydro, Trans, fuel filters, Blw A.r filters

HOURS WORKED _____

PARTS USED

Filters - \$ 175.46
Fuel Filter \$ 12.96