

5800 Crossings Blvd
 Antioch, TN 37013
 (615) 696-4000

SERVICE DEPARTMENT HOURS
 7:00 a.m. to 6:00 p.m.
 Monday - Friday
 7:00 a.m. to 3:00 p.m. Saturday

R/O Open Date	R/O Number
11/28/22	6088810/2
R/O Close Date	Status
11/30/22	Pre-Invoice
Mileage In	Mileage Out
35749	35753
Service Advisor / Tag #	
KRISTEN MCCULLO/9748	
Vehicle Identification Number	
3C7WRNAL0JG128437	
Delivery Date	In-Service Date
03/12/20	03/12/20
Color	License Number
BRIGHT WHI	

THORNE EXCAVATING COMPANY- LLC
 624 OLD HORN SPRINGS RD
 LEBANON, TN 37087-1811

Work Phone

Home Phone

615-337-8170

Body

SLT 4X4 REG CAB 6

Year

Make

Model

2018

RAM

5500

CHASSIS

FC1156

DESCRIPTION OF SERVICE AND PARTS

Sub Total: .00

AMOUNT

 * WITHOUT YOUR BUSINESS...WE HAVE NO BUSINESS. THANK *
 * YOU!!!! CUSTOMER SATISFACTION IS OUR #1 PRIORITY! *
 * SERVICE DEPT. GUESTS MAY RECEIVE A SURVEY IN YOUR *
 * E-MAIL. OUR GOAL IS 10'S & YES! *

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

LABOR	.00
PARTS	.00
DEDUCTIBLE	.00
SUBLET	.00
SHOP SUPPLIES	.00
HAZARDOUS MATERIALS	.00
SALES TAX OR TAX I.D.	.00
SPECIAL ORDER DEPOSIT	.00
DISCOUNTS	.00
TOTAL DUE	.00

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

PROBLEM:	Service	Shop
REPAIRED:	serviced	
PARTS:	Filters	312. ³⁰
		Term Filter

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109

MAKE Ford

MODEL 15' F750

SERIAL # Mech. Truck

HOURLY METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 8-21-24

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: A/C comp clutch bad

REPAIRED: replaced compressor

PARTS: A/C compressor

3/8" 28

Advance

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109

MAKE Ford

MODEL 15' F750

SERIAL # _____

HOURLY METER _____

MILES 100k mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____

LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 7-12-24

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: Service

REPAIRED: Serviced

PARTS:

Filter

285.25

Team Filter

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109

MAKE Ford

MODEL 15' F750

SERIAL # _____

HOURLY METER _____

MILES 95K mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 4-1-24 DATE COMPLETED 4-2-24

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: Service

REPAIRED: Service

PARTS: Filters

285.95

Ken Fitter

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109

MAKE Ford

MODEL 15' F750

SERIAL # _____

HOUR METER _____

MILES 86,607 mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 9-26-21

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: needs tires

REPAIRED: Replaced all 51K tires

PARTS 6-Hankook AL21 3420.66 Gateway Tire
11K.22.5

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109

MAKE Ford

MODEL 15' F750

SERIAL # _____

HOURLY METER _____

MILES 90K mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE 11-16-23 DATE COMPLETED 11-29-23

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: Service

REPAIRED: serviced

PARTS: Filters

283.1L

Tenn Filter

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0109</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Ford</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>15' F750</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES <u>92k mi</u>		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE <u>1-8-24</u> DATE COMPLETED <u>1-16-24</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Ben</u>
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____

PROBLEM: clean out exhaust system

REPAIRED: had DPF & catalyst cleaned. cleaned EGR cooler installed & reset.

PARTS: <u>Gaskets</u>	<u>46.¹⁶</u>	<u>Cummins</u>
<u>Gaskets & bracket</u>	<u>94.¹⁷</u>	<u>Mid Tenn Ford</u>
<u>Ex gaskets</u>	<u>20.¹⁸</u>	<u>Advance</u>
<u>acetylene</u>	<u>70.⁷⁷</u>	<u>Holston Gas</u>
<u>clean up</u>	<u>1147.¹³</u>	<u>Taylor Diesel</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109
MAKE Ford
MODEL 15' F750
SERIAL # _____
HOUR METER _____
MILES 85K mi.

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
COMPONENT LOCATION
FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: 9-6-23 DATE COMPLETED 9-6-23
MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

5490

PROBLEM: Service

REPAIRED: Serviced

PARTS: filters 285.12

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109
MAKE Ford
MODEL 15' F750
SERIAL # _____

HOUR METER _____
MILES 82,585 mi.

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

PROBLEM: Turbo

DATE: 7-21-23 DATE COMPLETED 7-22-23

MECHANIC Ben

JOB NAME/LOCATION

Shop

JOB NUMBER

REPAIRED: replaced turbo

PARTS Turbo
seals

3594.33
45.12

Taylor Diesel
Cummins

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109

MAKE Ford

MODEL 15' F750

SERIAL # _____

HOURLY METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____

LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 6-17-23

MECHANIC Ben

JOB NAME/LOCATION _____

JOB NUMBER _____

PROBLEM: hole in air bag

REPAIRED: replaced one air bag. other in stock

PARTS: 2 air bags

389.78

Truck Pro

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
SUP. # <u>0109</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ford</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>15' F750</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES <u>80K mi</u>					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: <u>6-15-23</u> DATE COMPLETED <u>6-17-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>Service</u>					

REPAIRED: serviced

PARTS: filters 282.26 Two Filter sales

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109
MAKE Ford
MODEL 15' F750
SERIAL # _____
HOUR METER _____
MILES 77K mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: 5-3-23 DATE COMPLETED 5-3-23

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: no brakes, worn out.

REPAIRED: new shoes and drums front & rear

PARTS: Brake shoes & Drums 1253 78

Fleetpride

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109
 MAKE Ford
 MODEL 15' F750
 SERIAL # _____
 HOUR METER _____
 MILES 56K mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: 4-13-22 DATE COMPLETED 4-22-22

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: needs batteries, Turbo

Shop

REPAIRED: Replaced batteries, removed turbo bad actuator
replaced actuator, removed DPF had cleaned

PARTS: 2-Grip 31

286.36

Advance Auto Parts

DPF Gaskets

179.45

Mid Run Ford

actuator

DPF clean

464.21

Emissions solutions

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109
 MAKE Ford
 MODEL 15' F750
 SERIAL # _____
 HOUR METER _____
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 4-28-22

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: sensor failure

REPAIRED: replaced DPF pressure sensors

PARTS: sensor T4D 476.13 Mid Tenn Ford

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109
 MAKE Ford
 MODEL 15' F750
 SERIAL # _____
 HOUR METER _____
 MILES 60k mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: 6-24-22 DATE COMPLETED 6-24-22

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: Service

REPAIRED: serviced

PARTS: Filters 282.18 Tran Filt
Fuel Filter 39.00 Napa
Napa Gold 3965
Fuel/water sep.

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109
 MAKE Miller
 MODEL 250D welder
 SERIAL # _____
 HOUR METER _____
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 7-10-22

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

shop

PROBLEM: won't run

REPAIRED: replaced start switch & fuel shut off solenoid

PARTS: Switch Ign. 207110 84.13
Fuel shut off solenoid 82.00

Quality Machine
Ebay

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0109</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ford</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>15' F750</u>		PARTS _____ LAIBOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES <u>65k mi</u>					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____ DATE COMPLETED <u>9-15-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Shop</u>	
PROBLEM: <u>Service</u>				JOB NUMBER _____	
REPAIRED: <u>serviced</u>					
PARTS: <u>All Filters</u> <u>298.⁷⁶</u> <u>Tenn Filter sales</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109
 MAKE Ford
 MODEL F750
 SERIAL # _____
 HOUR METER _____
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 11-15-22

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: Def fluid sensor bad in Tank

REPAIRED: replaced sender in tank

PARTS: Sender assembly 1,076.⁹³ Mid Term Ford

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109

MAKE Ford

MODEL F750

SERIAL # Mech. Truck

OUR METER _____

MILES 70k mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 12-17-22

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: Service

REPAIRED: serviced

PARTS: Fitters

351.67

Ken Fitter sales

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109
MAKE Ford
MODEL 15' F750
SERIAL # _____
HOUR METER _____
MILES 25k mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE 3-23-23 DATE COMPLETED 3-27-23

MECHANIC Ben

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: Service

REPAIRED: Serviced

PARTS: Filters

289.26

Ten Filter Sales

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109

MAKE Ford

MODEL 15' F750

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 3-24-21

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: bad belt

REPAIRED: replaced belt

PARTS: 25-080830 61.50 NAPA

belt

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109
MAKE Ford
MODEL 15 F750
SERIAL # _____
HOUR METER _____
MILES 45K mi.

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 8-31-21

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: Service

REPAIRED: serviced

PARTS: All Filters but outside air 154. ^{FL} Tenn. Filter sales

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109
 MAKE Ford
 MODEL F750
 SERIAL # _____
 HOUR METER _____
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: 9-13-21 DATE COMPLETED 9-13-21

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: need new fan belt.

REPAIRED: new fan belt

PARTS 5' X 1" Napa 22.2 NAPA
belt 6'7.39 NAPA

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109
 MAKE Ford
 MODEL 15' F750
 SERIAL # _____
 HOUR METER _____
 MILES 50k mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKE SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 1-13-22

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: Service

REPAIRED: Serviced

PARTS: Filters

227.⁰⁰

Ten Filter sales

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109
 MAKE Ford
 MODEL F750
 SERIAL # _____
 HOUR METER _____
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 2-17-22

MECHANIC Bent & Caleb

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: needs rear tires

REPAIRED: 4- rear tires

PARTS: 2- Sumitomo 992.05 Gateway
2- Toyo in stock

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109

MAKE Ford

MODEL 15' F750

SERIAL # Ben

HOURLY METER _____

MILES 40K mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 3-10-21

MECHANIC James

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: _____

REPAIRED: serviced

PARTS: Filters

205.11

Ten Filter

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109

MAKE Ford

MODEL F750 15'

SERIAL # _____

HOUR METER _____

MILES 35K mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 9-24-20 DATE COMPLETED 9-24-20

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: Service

REPAIRED: Serviced

PARTS: All but air filter 134.05 Tenn Filter

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109

MAKE Ford

MODEL 15' F750

SERIAL # _____

HOUR METER _____

MILES 30k mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 12-19-19 DATE COMPLETED 1-30-2020

MECHANIC Charles

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: Service

REPAIRED: Serviced & serviced Trans.

PARTS: Oil & Fuel Filter 93.⁰⁰

Trans oil 209.⁶³

Hyd Filter 61.⁵⁴

Trans Filter sales

Advance

Trans Filter

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109

MAKE Ford

MODEL 15' F750

SERIAL # _____

HOUR METER _____

MILES 25K mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 9-18-19

MECHANIC Charles

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: rear tires

REPAIRED: replaced rear tires

PARTS: 4-295/75R22.5 2,174.82 Gateway Tire

Toyo M177

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109

MAKE Ford

MODEL 15' F750

SERIAL # _____

HOURLY METER _____

MILES 25k mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 9-14-19

MECHANIC Horneee

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: Service

REPAIRED: Serviced

PARTS: All Filters, no Air 93.00 Teens Filter

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109

MAKE Ford

MODEL 15' F750

SERIAL # _____

HOURLY METER _____

MILES 20K mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE 6-12-19 DATE COMPLETED 6-14-19

MECHANIC Charles

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: Service

over head safety light

REPAIRED: Serviced

PARTS: <u>All Filters</u>	<u>176.47</u>	<u>Tenn Filter sales</u>
<u>light</u>	<u>277.09</u>	<u>Truckers lighthouse</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109

MAKE Ford

MODEL 15' F750

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 5-7-19

MECHANIC Charles

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: A/C Gauges

REPAIRED: _____

PARTS: A/C Gauges

\$108.00

NAPA

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109

MAKE Ford

MODEL F750

SERIAL # Chucky

HOURLY METER _____

MILES 15K mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE 3-21-19 DATE COMPLETED 3-23-19

MECHANIC Chucky

JOB NAME/LOCATION


JOB NUMBER

Shop

PROBLEM: Service

REPAIRED: serviced

PARTS: All Filters 205.00 Ken Filter sales



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0109</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS			
MAKE <u>Ford</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED			
MODEL <u>16' FT750</u>		COMPONENT LOCATION			
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER			
HOUR METER _____		OTHER _____			
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>7-12-18</u>		MECHANIC _____	
PROBLEM: <u>block off plugs</u>		JOB NAME/LOCATION		JOB NUMBER	
REPAIRED: _____					
PARTS <u>2 plug kits</u> \$ <u>228.33</u> <u>IR+G</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0109</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS			
MAKE <u>Ford</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED			
MODEL <u>15' F450</u>		COMPONENT LOCATION			
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER			
HOUR METER _____		OTHER _____			
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>4-12-18</u>		DATE COMPLETED _____	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Charles</u>			
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u>		JOB NUMBER _____	
PROBLEM: <u>3500 mi Truck</u>					
<u>set up.</u>					
REPAIRED: <u>set up truck + service</u>					
<u>lights</u>					
<u>Ox+Acc Tanks</u>					
<u>Truck's lighthouse</u>					
<u>Airco</u>					
PARTS: <u>Triangles</u>	<u>38.13</u>	<u>Napa</u>			
<u>G Fittings + Ties</u>	<u>220.⁰⁰</u>	<u>IR+G</u>			
<u>Shelves 6+6</u>	<u>360.⁰⁰</u>	<u>Nashville sheet metal</u>			
<u>PT 23092 -mpg Paltinger underbed</u>					
<u>Hyd Fitters</u>					
<u>LB 950/20</u>	<u>100.⁴²</u>	<u>TPS</u>			
<u>WD 920</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0109

MAKE Ford

MODEL 15' F750

SERIAL # Mech. Truck

HOUR METER _____

MILES 3500 mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED _____

MECHANIC _____

JOB NAME/LOCATION _____

JOB NUMBER _____

PROBLEM: Serviced

REPAIRED: _____

PARTS: Oil P550428

Fuel F#63009

Fuel P551103

Outer Air DBA5291

Inner Air P633483

TRANS

P550606

Tenn Filter

210.00