

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>1205</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>A406</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES _____			

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE <u>1-7-26</u>	DATE COMPLETED <u>1-14-26</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>High Park</u>	JOB NUMBER _____

PROBLEM: 3-pilot hoses leaking

REPAIRED: replaced 3-pilot hoses

PARTS: 3 Hoses 557.96 Scott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>1205</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>A40G Trak</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE <u>10-23-25</u>	DATE COMPLETED <u>10-31-25</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Scott Equipment</u>	
SMOKE SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____

PROBLEM: Scott Equipment took over brake pressure issue.

REPAIRED: replaced 12 brake accumulators & pilot valve.

PARTS: 12-Accumulators & 1 valve plus labor 18,914.²³ Scott Equipment

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION IP. # <u>1205</u> MAKE <u>Volvo</u> MODEL <u>A40G</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
---	--	--

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SWITCHES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 10-22-25
MECHANIC Ben

JOB NAME/LOCATION <u>To Stop</u>	JOB NUMBER
-------------------------------------	------------

PROBLEM: hyd. problem, A/C condenser busted, trailer break sys failure

REPAIRED:

<u>Valve</u>	<u>471.⁸⁶</u>	<u>Scott Equipment</u>
<u>Coils & press sensor</u>		
<u>Sensor & Seal</u>	<u>348.⁵⁹</u>	<u>Scott Equipment</u>
<u>Valve</u>	<u>1196.⁹⁰</u>	<u>Scott Equipment</u>
<u>Coil</u>	<u>638.⁴⁸</u>	<u>Scott Equipment</u>
<u>check valve - solenoid valve</u>	<u>723.²⁷</u>	<u>Scott Equipment</u>

PARTS: <u>Oil</u>	<u>\$1465</u>	<u>Advance</u>
<u>Condens. Drier, seals</u>	<u>2041.⁷²</u>	<u>Scott Equipment</u>
<u>Accumulator</u>	<u>378.⁵⁸</u>	<u>Scott Equipment</u>
<u>Coil</u>	<u>180.³⁴</u>	<u>Scott Equipment</u>
<u>brake oil seals & cylinder</u>	<u>1038.⁶¹</u>	<u>Scott Equipment</u>
<u>Foot valve</u>	<u>5,717.⁷⁹</u>	<u>Scott Equipment</u>
<u>Coil</u>	<u>180.³⁴</u>	<u>Scott Equipment</u>
<u>Pressure sensor</u>	<u>359.⁹⁸</u>	<u>Scott Equipment</u>
<u>FD Battery</u>	<u>271.⁰³</u>	<u>Interstate battery</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1205

MAKE Volvo

MODEL A40G

SERIAL # _____

HOURLY METER 10K HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 1-23-23

MECHANIC Anthony

JOB NAME/LOCATION
Steve Trace

JOB NUMBER

PROBLEM: Service

REPAIRED: Service

PARTS: Scott R Filters 394.01 Scott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1205</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>A40G</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____	OTHER _____	OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>12-5-22</u>	DATE COMPLETED <u>1-17-23</u>
PROBLEM: <u>Electrical problems</u>		MECHANIC <u>Ben</u>	
JOB NAME/LOCATION		JOB NUMBER	
<u>Stone Trace</u>			
REPAIRED: <u>replaced control + heat valve.</u>			
PARTS: <u>Panel & 2 relays</u> <u>443.⁰⁷</u> <u>Scott Equipment</u>			
<u>Heater valve</u> <u>180.²⁸</u> <u>Scott Equipment</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1205

MAKE Volvo

MODEL A40G

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 1-11-23

MECHANIC McGriff Tire

JOB NAME/LOCATION

Stone Trace

JOB NUMBER

PROBLEM: left rear tire blown

REPAIRED: replaced left rear tire

PARTS: 29.5X R25

5177.98

McGriff Tire

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>1205</u> MAKE <u>Volvo</u> MODEL <u>A40G</u> SERIAL # _____ HOUR METER <u>9,600 HRS</u> MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
--	---	--

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 9-14-22
MECHANIC Scott Equipment
JOB NAME/LOCATION Stone Trace JOB NUMBER _____

PROBLEM: secondary water pump bad.

REPAIRED: replaced pump

PARTS: Pump + labor 6369.⁵² Scott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

<p>EQUIPMENT INFORMATION</p> <p>EQUIP. # <u>1205</u></p> <p>MAKE <u>Volvo</u></p> <p>MODEL <u>A40G</u></p> <p>SERIAL # _____</p> <p>HOUR METER <u>9500 HRS</u></p> <p>MILES _____</p>	<p>EQUIPMENT DOWNTIME</p> <p>HOURS _____ DAYS _____</p> <p>REASON _____</p> <p>PARTS _____ LABOR _____</p> <p>OTHER _____</p>	<p>COMPONENT CODES</p> <p>BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS</p> <p>POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED</p> <p>COMPONENT LOCATION</p> <p>FRONT REAR LEFT RIGHT UPPER LOWER</p> <p>OTHER _____</p>
<p>REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED</p> <p>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH</p> <p>SMOKES SHORTED VIBRATE OTHER _____</p>	<p>DATE: <u>6-23-22</u> DATE COMPLETED <u>8-8-22</u></p> <p>MECHANIC: <u>All</u></p> <p>JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____</p>	
<p>PROBLEM: <u>service check over bought used</u></p>		
<p>REPAIRED: <u>Full service, all oils & filters, New u-joints on rear driveshaft.</u></p> <p><u>New front wiper blade</u></p>		
<p>PARTS: <u>All Filters & w/13101 Finas oil 3749.⁷⁹ Scott Equipment</u></p> <p><u>u-joints 625.⁴⁶</u></p> <p><u>fuel filter 86.⁸² Scott Equipment</u></p> <p><u>2-quick connect hoses 78.¹³ Scott Equipment</u></p> <p><u>wiper blade 44.¹³ Scott Equipment</u></p>		

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1205

MAKE Volvo

MODEL A40G

SERIAL # _____

HOUR METER 10,500 HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 3-15-23 DATE COMPLETED 3-21-23

MECHANIC _____

JOB NAME/LOCATION
Steve Trace

JOB NUMBER

PROBLEM: Service scollar

REPAIRED: serviced

PARTS: filters 394.00 Scott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1205
MAKE Volvo
MODEL A40G
SERIAL # _____
HOUR METER 11K HRS
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 7-12-23

MECHANIC Anthony

JOB NAME/LOCATION
Steve Trace

JOB NUMBER

PROBLEM: Service

REPAIRED: serviced

PARTS: Filters \$ 1067.62 Scott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>1205</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>A40G</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
_____	_____	OTHER _____
_____	_____	_____
_____	_____	_____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: _____	DATE COMPLETED <u>9-18-23</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Anthony</u>	_____
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION _____	JOB NUMBER _____

PROBLEM: loosing power at key switch

REPAIRED: replaced whole switch

PARTS: Starter switch 285.¹⁶ Scott Equipment
lock 43.⁴⁴ Scott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1205
MAKE Volvo
MODEL A40G
SERIAL # _____
HOUR METER _____
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
COMPONENT LOCATION
FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE 10-16-23 DATE COMPLETED _____
MECHANIC _____

JOB NAME/LOCATION Stone Trace JOB NUMBER _____

PROBLEM: drive bar bearing on rear axle dropped

REPAIRED: Scott Equipment pressed ball & installed new bushing.

PARTS: bearing kit 1413.⁶⁸ Scott Equipment
Scott labor Scott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>1205</u> MAKE <u>Volvo</u> MODEL <u>A40G</u> SERIAL # _____ HOUR METER <u>11,500 HRS</u> MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
---	---	--

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: <u>11-28-23</u> DATE COMPLETED <u>12-5-23</u> MECHANIC <u>Anthony</u> JOB NAME/LOCATION <u>Stone Trace</u> JOB NUMBER _____
---	---

PROBLEM: Service

REPAIRED: serviced

PARTS: Filters 266.96

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>1205</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>A40G</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: _____ DATE COMPLETED <u>1-23-24</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Anthony</u>
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Steve Trace</u>
	JOB NUMBER _____

PROBLEM: won't start

REPAIRED: replaced bad batteries

PARTS: 2 .8D-MHD 520.10 Interstate battery

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>1205</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Volvo</u>		REASON		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>A40G</u>		PARTS LABOR		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>11,500 HRS</u>				OTHER _____	
MILES _____					

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>3-20-24</u>	DATE COMPLETED: <u>4-8-24</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
			<u>To Shop</u>	

PROBLEM: codes Active

REPAIRED: removed DPF Taylor Diesel cleaned.
replaced DP sensor, cleaned tube
replace a DPF line.
Scott Equipment reset system.

PARTS: <u>Press. sensor</u>	<u>205.⁹²</u>	<u>Scott Equipment</u>
<u>DPF clean</u>	<u>382.³⁸</u>	<u>Taylor Diesel</u>
<u>Gaskets clamp & insulation</u>	<u>521.⁸⁴</u>	<u>Scott Equipment</u>
<u>cover & tube</u>	<u>700.³⁸</u>	<u>Scott Equipment</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>1205</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Volvo</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>A40G</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES _____		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 6-11-24
MECHANIC Ben

JOB NAME/LOCATION
Quail Run

JOB NUMBER

PROBLEM: cracked coolant Reservoir

REPAIRED: replaced reservoir

PARTS Exp Tank 341.49 Scott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>1205</u> MAKE <u>Volvo</u> MODEL <u>A40G</u> SERIAL # <u>340171</u> HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
---	---	--

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: <u>7-10-24</u> DATE COMPLETED <u>7-17-24</u> MECHANIC <u>Ben</u> JOB NAME/LOCATION <u>To Shop</u> JOB NUMBER _____
---	--

PROBLEM: NO/ A/C

REPAIRED: A/C comp. clutch bad. Replaced comp. drier + ex. valve. Adjusted parking brake

PARTS: comp. Drier + Expan. Valve 1711.38 Scott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>1205</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MAKE <u>Volvo</u>	REASON	COMPONENT LOCATION	
MODEL <u>A406</u>	PARTS _____ LABOR _____	FRONT REAR LEFT RIGHT UPPER LOWER	
SERIAL # _____	OTHER _____	OTHER _____	
HOUR METER _____			
MILES _____			

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE <u>2-25-25</u>	DATE COMPLETED <u>2-25-25</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Ben</u>	
SMOKE SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>Wilson Judicial</u>	JOB NUMBER _____

PROBLEM: leaking hoses

REPAIRED: replaced two dump cylinder hoses

PARTS: 2 hoses 1007.36 Nashville Rubber Gasket

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>1205</u> MAKE <u>Volvo</u> MODEL <u>A40G</u> SERIAL # _____ HOUR METER <u>12K HRS</u> MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
--	---	--

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>3-14-25</u> MECHANIC <u>Bert Bryan</u>
	JOB NAME/LOCATION <u>Wilson Judicial</u> JOB NUMBER _____

PROBLEM: Service

REPAIRED: serviced

PARTS: filters 960.56 Scott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1205
MAKE Valco
MODEL A406
SERIAL # _____
HOUR METER 12k hrs
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE 1-13-25 DATE COMPLETED 3-14-25

MECHANIC _____

JOB NAME/LOCATION

Wilson Judicial

JOB NUMBER

PROBLEM: service

REPAIRED: serviced

PARTS:

filters

857.3L

Scott Equipment

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

<p>EQUIPMENT INFORMATION</p> <p>EQUIP. # <u>1205</u></p> <p>MAKE <u>Volvo</u></p> <p>MODEL <u>A40G</u></p> <p>SERIAL # _____</p> <p>HOUR METER _____</p> <p>MILES _____</p>	<p>EQUIPMENT DOWNTIME</p> <p>HOURS _____ DAYS _____</p> <p>REASON _____</p> <p>PARTS _____ LABOR _____</p> <p>OTHER _____</p>	<p>COMPONENT CODES</p> <p>BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS</p> <p>POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED</p> <p>COMPONENT LOCATION</p> <p>FRONT REAR LEFT RIGHT UPPER LOWER</p> <p>OTHER _____</p>
<p>REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED</p> <p>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH</p> <p>SMOKES SHORTED VIBRATE OTHER _____</p> <p>PROBLEM: <u>won't start</u></p>	<p>DATE: _____ DATE COMPLETED <u>6-4-25</u></p> <p>MECHANIC <u>Bryan</u></p> <p>JOB NAME/LOCATION <u>Trail Run</u></p> <p>JOB NUMBER _____</p>	

REPAIRED: replaced batteries

PARTS: 2-4D-XHD 471, FL Interstate