

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0111</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>12' TD713</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>10-18-22</u> DATE COMPLETED <u>10-19-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>All</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>LF front Tractor wheel seal leaking</u>				
REPAIRED: <u>replaced bearings, races + seals</u> <u>replaced broken exhaust pipe</u>				
PARTS: <u>Bearings + seals</u> 229.50 <u>Truck Pro</u>				
<u>nut + cap</u> 125.81 <u>McMahon Truck</u>				
10' x 12' ps 400.00 McMahon Trucks				
<u>Exhaust pipe</u> \$ 744.49 900.94 <u>McMahon Trucks</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0111</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>12' Mack</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>Titan TD713</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>11-10-22</u> DATE COMPLETED <u>11-17-22</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>		
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>To Shop</u> JOB NUMBER _____		
PROBLEM: <u>carrier input shaft broken</u>					
REPAIRED: <u>had driveshaft repaired, new input shaft</u>					
<u>Completed on 11-17-2022</u>					
<u>replaced input cage on front diff.</u>					
PARTS <u>bearings, seal & retainers 531.⁶⁶</u> <u>McMahon Trucks</u>					
<u>set,oring & gaskets 251.¹²</u> <u>McMahon Trucks</u>					
<u>Driveshaft repair 1142.⁰²</u> <u>Daves Driveshaft shop</u>					
<u>Cage 1337.⁰⁰</u> <u>McMahon Trucks</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0111
MAKE Mack
MODEL Titan 12'
SERIAL # _____
HOUR METER _____
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 12-9-22
MECHANIC Caleb

JOB NAME/LOCATION

shop

JOB NUMBER

PROBLEM: coolant tank cracked

REPAIRED: replaced tank

PARTS:

Tank

307.20

McMahan Trucks

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>8111</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>MACK</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>12' Titan</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>270k mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>1-9-22</u> MECHANIC <u>T&K Truck repair</u>	
			JOB NAME/LOCATION <u>T&K</u>	JOB NUMBER
PROBLEM: <u>needs clutch</u>				
REPAIRED: <u>replaced clutch, bearings & input shaft, carrier yoke</u>				
PARTS: <u>clutch & all parts needed 6355.⁶⁴ T&K Truck repair</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0111</u> MAKE <u>Mack</u> MODEL <u>12' Titan</u> SERIAL # _____ HOUR METER _____ MILES <u>272k mi</u>	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____																					
REASON FOR FAILURE: ☐ BROKEN ☐ WORN ☐ ABUSE ☐ LOOSE ☐ SEIZED ☐ OVERHEAT ☐ PLANNED ☐ CONTAM ☐ LEAKING ☐ NOISY ☐ SCRATCH ☐ SMOKES ☐ SHORTED ☐ VIBRATE ☐ OTHER _____		DATE: <u>1-19-23</u> DATE COMPLETED <u>2-7-23</u> MECHANIC <u>All</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____																					
PROBLEM: <u>Service</u>																							
REPAIRED: <u>serviced</u> <u>replaced Fuel & P/steering pump old hoses. Broken dipstick tube. Replaced batteries. Replaced fuel valve</u>																							
<table style="width:100%; border-collapse: collapse;"> <tr> <td style="width:40%;">Fuel valve</td> <td style="width:20%;">76.⁰⁰</td> <td style="width:40%;">McMahon Trucks</td> </tr> </table>			Fuel valve	76. ⁰⁰	McMahon Trucks																		
Fuel valve	76. ⁰⁰	McMahon Trucks																					
<table style="width:100%; border-collapse: collapse;"> <tr> <td style="width:40%;">PARTS: Filters no air</td> <td style="width:20%;">138.⁷⁶</td> <td style="width:40%;">Tenn Filter sales</td> </tr> <tr> <td>P/steer + Fuel pump</td> <td>1,943.⁷³</td> <td>McMahon Truck</td> </tr> <tr> <td>hoses</td> <td>76.⁰⁵</td> <td>McMahon Truck</td> </tr> <tr> <td>w/ritter base</td> <td>641.⁰⁰</td> <td>McMahon Truck</td> </tr> <tr> <td>Air Fitters</td> <td>218.⁵⁰</td> <td>Tenn Filter</td> </tr> <tr> <td>Dip stick + Tube</td> <td>215.⁰⁰</td> <td>McMahon</td> </tr> <tr> <td>3 Gp 31 batteries</td> <td>437.⁷⁴</td> <td>Interstate Battery</td> </tr> </table>			PARTS: Filters no air	138. ⁷⁶	Tenn Filter sales	P/steer + Fuel pump	1,943. ⁷³	McMahon Truck	hoses	76. ⁰⁵	McMahon Truck	w/ritter base	641. ⁰⁰	McMahon Truck	Air Fitters	218. ⁵⁰	Tenn Filter	Dip stick + Tube	215. ⁰⁰	McMahon	3 Gp 31 batteries	437. ⁷⁴	Interstate Battery
PARTS: Filters no air	138. ⁷⁶	Tenn Filter sales																					
P/steer + Fuel pump	1,943. ⁷³	McMahon Truck																					
hoses	76. ⁰⁵	McMahon Truck																					
w/ritter base	641. ⁰⁰	McMahon Truck																					
Air Fitters	218. ⁵⁰	Tenn Filter																					
Dip stick + Tube	215. ⁰⁰	McMahon																					
3 Gp 31 batteries	437. ⁷⁴	Interstate Battery																					

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0111</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>MAK</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>Titan</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE <u>2-23-23</u> DATE COMPLETED <u>3-1-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>Engine oil leak</u>					
REPAIRED: <u>replaced gasket to block & O-ring to valve cover</u>					
PARTS <u>Gasket & O-ring</u> <u>59.99</u> <u>MS Mahan Trucks</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0111</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>12' Titan</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE <u>3-24-23</u> DATE COMPLETED <u>3-27-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Shop</u>	
JOB NUMBER _____					
PROBLEM: <u>hole in radiator</u>					

REPAIRED: replaced bad radiator and a/c Trans. cooler hose

PARTS: radiator \$1443.²⁴ Truck P20
hose 190.⁵⁶ Crook's

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0111

MAKE Mack

MODEL 12' Titan

SERIAL # _____

HOUR METER _____

MILES 277K mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 4-3-23 DATE COMPLETED 4-27-23

MECHANIC AL

JOB NAME/LOCATION

5490

JOB NUMBER

PROBLEM: Service, anti-freeze leak

REPAIRED: serviced, replaced coolant line at Air comp.

PARTS: Filters

229.27

Tenn Filter