

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0017
MAKE Ram
MODEL 17 1500
SERIAL # Philip
HOUR METER _____
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 6-27-23

MECHANIC Anthony

JOB NAME/LOCATION Steve Trace

JOB NUMBER _____

PROBLEM: blower motor bad

REPAIRED: replaced blower motor + fuse

PARTS: motor + fuse 179.86

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0017</u>	HOURS _____ DAYS _____	REASON PARTS _____ LABOR _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>RAM</u>			POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>1500</u>	OTHER _____	OTHER _____	COMPONENT LOCATION	
SERIAL # _____			FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____	OTHER _____	OTHER _____	OTHER _____	
MILES <u>125K mi.</u>			OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>11-9-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>ALL</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop & Tire Shop</u> JOB NUMBER _____	
PROBLEM: <u>Needs tires serviced</u>				
REPAIRED: <u>new tires all around & serviced</u>				
PARTS: <u>4-Tires</u> <u>Charlie's Tire</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0017</u>	MAKE <u>Ram</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MODEL <u>17' 1500 4x4</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
SERIAL # _____		PARTS _____ LABOR _____	COMPONENT LOCATION	
HOUR METER _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
MILES <u>133400 mi</u>			OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>7-29-24</u> DATE COMPLETED <u>7-30-24</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Anthony + Bryan</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>5490</u>		JOB NUMBER _____
PROBLEM: <u>needs rear shocks</u>				
REPAIRED: _____				
PARTS: <u>2-shocks</u> <u>162.63</u> <u>Advance</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0017</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17' 1500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Philip</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>135K mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>8-13-24</u> DATE COMPLETED <u>8-14-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>All</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>brakes, belt, service</u>				
<u>check struts</u>				
REPAIRED: <u>served, replaced brake pads ALL 4. Replaced belt.</u>				
<u>sent to Charlie's Tire</u>				
PARTS: <u>brakes & belt</u> <u>162.93</u> <u>Advance</u>				
<u>Tie rod alignment</u> <u>337.65</u> <u>Charlie's Tire</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0017</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Ram</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>18' NEO</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # <u>Philip</u>	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>7-16-24</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Bryan</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____	
PROBLEM: <u>Freeze out plug leaking on LT head.</u> <u>bad battery</u>				
REPAIRED: <u>replaced plug & battery</u> <u>replaced RT Exhaust manifold & Gasket.</u>				
PARTS: <u>Plug</u> <u>5.47</u> <u>MT. Juliet Ram</u> <u>gaskets & bolts</u> <u>in stock</u> <u>battery</u> <u>108.99</u> <u>Advance</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0017</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>18' 1500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Philip</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>9-19-24</u> DATE COMPLETED <u>9-20-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Aubrey's</u>	JOB NUMBER _____
PROBLEM: <u>seat bottom bad</u>				
REPAIRED: <u>replaced seat bottom</u>				
PARTS: <u>foam & cover</u> <u>P37.0E</u> <u>MT Juliet Ram</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0017</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>18' 1500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>140K mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>11-1-24</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Bryan</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____	
PROBLEM: <u>locked in 4wd</u>				
REPAIRED: <u>replaced 4wd actuator on front diff.</u>				
PARTS: <u>Actuator</u> <u>158.25</u> <u>Advance Auto Parts</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0017</u>	MAKE <u>Ram</u>	HOURS _____ DAYS _____	BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MODEL <u>1500 4x4</u>	SERIAL # <u>Philip</u>	REASON _____	POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
HOUR METER _____	MILES <u>141K mi</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
			OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____	DATE COMPLETED <u>11-5-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Bryan</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Sports Pk</u>	JOB NUMBER _____	
PROBLEM: _____				
REPAIRED: <u>replaced front struts swaybar kits</u>				
<u>rear coil springs + sway bar kits.</u>				
PARTS: <u>2 strut spring assemblies 291.⁰⁴</u>				
<u>coil springs</u>		<u>393.⁰⁴</u>	<u>Advance</u>	
<u>stabilizer bars</u>		<u>67.³⁰</u>	<u>Advance</u>	

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0017</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17' 1500</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # <u>Philip</u>		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: _____ DATE COMPLETED <u>3-31-25</u> MECHANIC <u>Bryan</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____		
PROBLEM: <u>Axle boot broken</u>					
REPAIRED: <u>replaced RT front cv axle and synchro links</u>					
PARTS: <u>RT CV Axle</u> <u>176.⁶³</u> <u>Advance Auto</u> <u>links</u> <u>90.⁰²</u> <u>Advance Auto</u>					