

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0308
 MAKE Cat
 MODEL 420F IT
 SERIAL # _____
 HOUR METER 3000 HRS
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: 3-27-23 DATE COMPLETED 4-11-23

MECHANIC ALL

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: Service, bought used check over

REPAIRED: serviced, bucket teeth.

PARTS: <u>Filters</u>	<u>457.29</u>	<u>Thompson</u>
<u>Tooth pins & retainers</u>	<u>265.72</u>	<u>Thompson</u>
<u>cover</u>	<u>139.42</u>	<u>Thompson</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0308

MAKE CAT

MODEL 420F IT

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 7-7-23 DATE COMPLETED 7-7-23

MECHANIC Ben

JOB NAME/LOCATION East gate JOB NUMBER _____

PROBLEM: NO A/C fan

REPAIRED: replaced fan motor

PARTS: motor

241.11

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0308

MAKE CAT

MODEL 420F IT

SERIAL # _____

HOURLY METER 3,520 HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE 11-28-23 DATE COMPLETED 12-15-23

MECHANIC Anthony

JOB NAME/LOCATION

Flare Trace

JOB NUMBER

PROBLEM: Service

REPAIRED: _____

PARTS: Filters

2 Filters

319.71

138.00

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0308</u> MAKE <u>Cat</u> MODEL <u>420F IT</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>8-13-24</u> DATE COMPLETED <u>8-20-24</u> MECHANIC <u>All</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____
PROBLEM: <u>seat belt & door</u>		
REPAIRED: <u>replaced seat belt hardware</u> <u>repaired door handle, latch & hinge.</u>		
PARTS: <u>left door parts & hardware 191.58</u> <u>latch 109.05 Thompson</u> <u>hinge 26.48 Thompson</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0308
 MAKE CAT
 MODEL 420F IT
 SERIAL # _____
 HOUR METER _____
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: 4-23-25 DATE COMPLETED 4-29-25

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: bad cylinder on rear controls

REPAIRED: replaced cylinder

PARTS: cylinder 429.70 Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0308</u>		HOURS _____ DAYS _____		BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Cat</u>		REASON _____		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>420F IT</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>4K HRS</u>				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>10-13-25</u> DATE COMPLETED <u>11-1-25</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James</u>		
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>MACON Co.</u> JOB NUMBER <u>To shop</u>		
PROBLEM: <u>Service, fuel pump bad</u>					
REPAIRED: <u>serviced, replaced fuel pump</u>					
PARTS: <u>filter</u> <u>494.96</u> <u>Thompson</u>					
<u>fuel pump</u> <u>424.00</u> <u>Thompson</u>					
<u>fuel line</u> <u>33.83</u> <u>Thompson</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0308
 MAKE CAT
 MODEL 420F IT
 SERIAL # _____
 HOUR METER _____
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: 2-3-26 DATE COMPLETED 2-17-26

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: heater fan motor quit bought motor, found
burned wiring.

REPAIRED: replaced fan motor & repaired wiring.

PARTS: fan motor 259.35 Thompson