

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>9</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Dodge</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17 2500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>TJ</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>5K mi.</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>2-6-17</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Steven B.</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>First service</u>				
REPAIRED: <u>serviced</u>				
PARTS: <u>All Filters in stock</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963


EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>9</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Dodge</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17 2500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>TJ</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>15k mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>5-23-17</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>AI</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>Hit deer</u>				
REPAIRED: <u>repaired front end.</u>				
PARTS: <u>Bumper, Air Dam, & Condenser</u> <u>877.45</u> <u>Premier Dodge</u>				
<u>RT Headlamp</u> <u>Premier Dodge</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>9</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Dodge</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17' 2500HD</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Mike</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>11-27-17</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Steven B.</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>PFG</u>	JOB NUMBER
PROBLEM: <u>batteries weak</u>				
REPAIRED: <u>replaced both batteries</u>				
PARTS: <u>2-batteries</u>				
<u>MTP.94</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0009</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>17' Ram 2500</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL _____		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>2009 Amigo</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>41K mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>8-22-18</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>All</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>utility bed and set up.</u>				
REPAIRED: <u>made vise stand</u>				
<u>made light stand</u>				
<u>need to install rear sensors</u>				
Tools <u>161.59</u>		<u>lowe's</u>		
Tools <u>601.50</u>		<u>lowe's</u>		
PARTS: <u>Utility Bed</u> <u>7032.⁰⁰</u>		<u>String fellow</u>		
<u>3/4" leds</u> <u>31.79</u>		<u>Trailer Depot</u>		
<u>Vise</u> <u>76.⁰⁰</u>		<u>lowe's</u>		
<u>Flare Equipment</u> <u>170.⁰⁵</u>		<u>Napa</u>		
<u>senser holders</u> <u>31.50</u>		<u>Premier Dodge</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>9</u> MAKE <u>Ram</u> MODEL <u>17' 2500</u> SERIAL # <u>Amigo</u> HOUR METER _____ MILES <u>47K mi</u>	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>12-19-18</u> MECHANIC <u>James</u> JOB NAME/LOCATION <u>Ship</u> JOB NUMBER _____
PROBLEM: <u>water in fuel</u>		
REPAIRED: <u>replaced both fuel filters</u>		
PARTS: <u>filters</u> <u>in stock</u> <u>Term Filter</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0009</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17'2500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>59,287 mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>10-3-19</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charlie's Tire</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Charlie's Tire</u>	JOB NUMBER _____
PROBLEM: <u>New Tires</u>				
REPAIRED: <u>New Tires</u>				
PARTS <u>265/70-17</u> <u>947.43</u> <u>Charlie's Tires</u>				
<u>Toyo HTII 10PL</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0009</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17' 2500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Aureliano</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>66K mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>1-30-2020</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Charles & Bryan</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>Service, needs brake pads</u>				
REPAIRED: <u>serviced & replaced brake pads</u>				
PARTS: <u>All Filters in stock</u>				
<u>front & rear brake pads 75.⁷³ Advance Auto Parts</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0009</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17' 2800</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Arcliano</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>4-2-2020</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>WAL</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Timberland behavior</u>	JOB NUMBER _____
PROBLEM: <u>busted left front tire</u>				
REPAIRED: <u>replaced left front tire</u>				
PARTS: <u>LT265-70-17</u> <u>238.49</u> <u>charlies tire</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0009</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17' 2500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>95K mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>7-15-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ali</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>service, needs tires</u>				
REPAIRED: <u>4-Tires</u>				
<u>serviced</u>				
PARTS: <u>4-265-70-17</u> <u>1047.23</u> <u>Charles Tire</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0009</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>2500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Amigo</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>12-1-21</u> DATE COMPLETED <u>12-6-21</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shgs</u>	JOB NUMBER _____
PROBLEM: <u>safety light needs replaced</u>				
REPAIRED: <u>replaced light</u>				
PARTS: <u>light</u> <u>300.⁰⁰</u> <u>Truckers lighthouse</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0009</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17' 2500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>1-18-22</u> DATE COMPLETED <u>1-18-22</u> MECHANIC <u>Anthony</u>		
PROBLEM: <u>won't start</u>		JOB NAME/LOCATION <u>Oliveri</u> JOB NUMBER _____		
REPAIRED: <u>replaced both batteries</u> <u>one bad & one weak</u>				
PARTS <u>Z-MTX-94R/H7</u> <u>384.01</u> <u>Interstate Battery</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0009</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17' 2500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>Arliano</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>5-13-22</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Brian</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____		
PROBLEM: <u>brake noise</u>				
REPAIRED: <u>replaced front + rear pads + rotors</u>				
PARTS: <u>Front + Rear pads + rotors 574.29</u> <u>Advance Auto Parts</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0009</u> MAKE <u>Ram</u> MODEL <u>17' Ram 2500</u> SERIAL # <u>Amigo to David</u> HOUR METER _____ MILES <u>115K mi</u>		EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____		COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: <u>4-20-22</u> DATE COMPLETED <u>8-19-22</u> MECHANIC <u>AIL</u>	
PROBLEM: <u>coolant tank stained, service</u>				JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
REPAIRED: <u>replaced coolant tank, serviced</u>					
PARTS: <u>Tank</u> <u>188.33</u> <u>Premier Ram</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0009</u> MAKE <u>Ram</u> MODEL <u>2500</u> SERIAL # <u>David</u> HOUR METER _____ MILES <u>115K mi</u>		EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____		COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKE SHORTED VIBRATE OTHER _____				DATE <u>8-19-22</u> DATE COMPLETED <u>8-24-22</u> MECHANIC <u>All</u>	
PROBLEM: <u>set up for new pipe foreman</u>				JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
REPAIRED: <u>serviced replaced left front hub bearing, cleaned welded job box hinges made up new claw rods</u>					
PARTS: <u>hub</u> <u>266.17</u> <u>Advance</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

<p>EQUIPMENT INFORMATION</p> <p>EQUIP. # <u>0009</u></p> <p>MAKE <u>Ram</u></p> <p>MODEL <u>17' 2500 HD</u></p> <p>SERIAL # <u>David</u></p> <p>HOUR METER _____</p> <p>MILES <u>127,673 mi.</u></p>	<p>EQUIPMENT DOWNTIME</p> <p>HOURS _____ DAYS _____</p> <p>REASON _____</p> <p>PARTS _____ LABOR _____</p> <p>OTHER _____</p>	<p>COMPONENT CODES</p> <p>BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS</p> <p>POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED</p> <p>COMPONENT LOCATION</p> <p>FRONT REAR LEFT RIGHT UPPER LOWER</p> <p>OTHER _____</p>															
<p>REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED</p> <p>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH</p> <p>SMOKES SHORTED VIBRATE OTHER _____</p>		<p>DATE: <u>1-16-23</u> DATE COMPLETED <u>1-17-23</u></p> <p>MECHANIC <u>All</u></p> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:70%;">JOB NAME/LOCATION <u>Shop</u></td> <td style="width:30%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER													
JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER																
<p>PROBLEM: <u>Trans. stuck in fourth gear</u> <u>needs new tires</u></p>																	
<p>REPAIRED: <u>replaced shift solenoid</u> <u>Trans oil & filters</u> <u>4- new tires</u></p>																	
<table style="width:100%;"> <tr> <td style="width:33%;">PARTS: <u>Oil & filters</u></td> <td style="width:33%; text-align: right;"><u>166.⁰³</u></td> <td style="width:33%;"></td> </tr> <tr> <td><u>Shift solenoid</u></td> <td style="text-align: right;"><u>432.²⁰</u></td> <td><u>Advance</u></td> </tr> <tr> <td><u>4- Togo 265-70-17</u></td> <td style="text-align: right;"><u>1,116.³⁸</u></td> <td><u>M^r Juliet Ram</u></td> </tr> <tr> <td><u>2- seat bottom covers</u></td> <td style="text-align: right;"><u>626.³⁴</u></td> <td><u>charlie's Tire</u></td> </tr> <tr> <td></td> <td></td> <td><u>M^r Juliet Ram</u></td> </tr> </table>			PARTS: <u>Oil & filters</u>	<u>166.⁰³</u>		<u>Shift solenoid</u>	<u>432.²⁰</u>	<u>Advance</u>	<u>4- Togo 265-70-17</u>	<u>1,116.³⁸</u>	<u>M^r Juliet Ram</u>	<u>2- seat bottom covers</u>	<u>626.³⁴</u>	<u>charlie's Tire</u>			<u>M^r Juliet Ram</u>
PARTS: <u>Oil & filters</u>	<u>166.⁰³</u>																
<u>Shift solenoid</u>	<u>432.²⁰</u>	<u>Advance</u>															
<u>4- Togo 265-70-17</u>	<u>1,116.³⁸</u>	<u>M^r Juliet Ram</u>															
<u>2- seat bottom covers</u>	<u>626.³⁴</u>	<u>charlie's Tire</u>															
		<u>M^r Juliet Ram</u>															

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0009</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Ram</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17' 2500</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>DAVID</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>1-25-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>large hole in RT rear tire.</u>				
REPAIRED: <u>replaced tire</u>				
PARTS: <u>265/70-17</u> <u>279.09</u> <u>Charles Tire</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0009
MAKE Ram
MODEL 17' 2500
SERIAL # David
HOUR METER _____
MILES 150k mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
COMPONENT LOCATION
FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 7-18-23

MECHANIC _____

JOB NAME/LOCATION

JOB NUMBER

shop

PROBLEM: service, check over

REPAIRED: replaced bad air comp.
replaced Tire That couldn't be fixed.
replaced front & rear brake pads
replaced crankcase vent filter.
serviced

PARTS: Kobalt Air comp. \$141.50 Lowe's
Front & rear pads \$127.00 Advance
1. LT265/70-17 279.09 Charlie's Tire

CUSTOMER #: R211295

100400



INVOICE

600 PLEASANT GROVE ROAD
MT. JULIET, TN 37122
TELEPHONE: (615) 288-8535
FAX: (615) 307-1949

THORNES EXCAVATING CO LLC
624 OLD HORN SPRINGS ROAD
LEBANON, TN 37087
HOME: 615-444-5142 CONT: 615-444-5142
BUS: 615-444-5142 CELL:

PAGE 1

SERVICE ADVISOR: 9139 LUIS VIANA

BUS: 615-444-5142 CELL:			SERVICE ADVISOR: 9155 BOB VIKARI				
COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG	
FLAME RED	17	RAM TRUCK 2500	3C6UR4HL7HG580374		162670/162670	T2511	
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
18NOV16 DD			WAIT 09JAN24		0.00	CASH	09JAN24

R.O. OPENED READY OPTIONS: STK:RD5933 DLR:45868 ENG:ETK

11:48 09JAN24 13:14 09JAN24

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A Recall / Customer Satisfaction Notification 1 [Recall Customer
Satisfaction Notification 1 ** 67A - 2013-2018 D Truck Engine
Calibration (VB6 Expansio]

CAUSE: RECALL

RECALL Recall / Customer Satisfaction

Notification 1

9025 WC

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: (N/C) 0.00

FLASHED PCM 32370731AH to targeted part number 32370731AL.

B Recall / Customer Satisfaction Notification 4 [Recall Customer
Satisfaction Notification 4 ** U53 - OCCUPANT RESTRAINT CONTROL
MODULE]

CAUSE: RECALL

RECALL Recall / Customer Satisfaction

Notification 4

9025 WC

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: (N/C) 0.00

FLASHED ORC 68303224AA to targeted part number 68346749AB.

C Recall / Customer Satisfaction Notification 7 [Recall Customer
Satisfaction Notification 7 ** V44 - 2013-2018 D TRUCK TAILGATE
LATCH]

MISC NO TAIL GATE ON TRUCK

9025 IPS

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: (N/C) 0.00

NO TAILGATE ON THIS TRUCK IT IS A BOX TRUCK DID NOT PERFORM RECALL

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.
I HEREBY AUTHORIZE THE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES PERMISSION TO OPERATE THE CAR OR TRUCK HEREIN DESCRIBED ON STREETS, HIGHWAYS, OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LIEN IS HEREBY ACKNOWLEDGED ON THE CAR OR TRUCK TO SECURE THE AMOUNT OF REPAIRS THERETO. ALL WORK GUARANTEED FOR 90 DAYS OR 4,000 MILES, WHICHEVER OCCURS FIRST.

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.

DESCRIPTION	TOTALS
LABOR AMOUNT	0.00
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	0.00
LESS INSURANCE	0.00
SALES TAX	0.00
PLEASE PAY THIS AMOUNT	0.00

(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON DATE

X

This notice applies to your vehicle,

2017 RAM 2500

VIN: 3C6UR4HL7HG580374

67A



RAM

YOUR SCHEDULING OPTIONS

1. **RECOMMENDED OPTION**

Call your authorized Chrysler / Dodge / Jeep® / RAM / Dealership.

2. Call the FCA Recall Assistance Center at **1-800-853-1403**. An agent can confirm part availability and help schedule an appointment.

3. Visit recalls.mopar.com, scan the QR code below, or download the Mopar Owner's Companion App.



Get access to recall notifications, locate your nearest dealer, and more through this website or Mopar Owner's Companion App. You will be asked to provide your Vehicle Identification Number (VIN) to protect and verify your identity. The last eight characters of your VIN are provided above.

DEALERSHIP INSTRUCTIONS

Please reference Emissions Recall

67A

IMPORTANT EMISSIONS RECALL

D Truck Engine Calibration

Dear THORNES EXCAVATING CO,

FCA US LLC, has determined that certain 2017 RAM 2500 trucks equipped with a 6.7L Cummins Turbo Diesel engine requires upgraded emission control software according to Federal and California regulations/standards.

WHY DOES MY VEHICLE NEED REPAIRS?

The engine control software in your vehicle ^[1] must be updated with an upgraded calibration as required by the US Environmental Protection Agency and California Air Resources Board for better emission performance.

HOW DO I RESOLVE THIS IMPORTANT EMISSIONS ISSUE?

FCA will repair your truck free of charge (parts and labor). To do this, your dealer will reprogram the Powertrain Control Module (PCM). The estimated repair time is one hour. In addition, your dealer will require your vehicle for proper check-in, preparation, and check-out during your visit, which require more time. Your time is important to us, so we recommend that you schedule a service appointment to minimize your inconvenience. Please bring this letter with you to your dealership.

**TO SCHEDULE YOUR FREE REPAIR,
CALL YOUR CHRYSLER, DODGE, JEEP OR RAM DEALER TODAY**

CALIFORNIA RESIDENTS

The State of California requires the completion of this emission recall repair prior to vehicle registration renewal. Your dealer will provide you with a Vehicle Emission Recall Proof of Correction Form after the Emission Recall service is performed. Be sure to save this form since the California Department of Motor Vehicles may require that you supply it as proof that the Emission Recall has been performed.

In order to ensure your full protection under the emissions warranty provisions, it is recommended that you have your vehicle serviced as soon as possible. Failure to do so could be determined as lack of proper maintenance of your vehicle.

WHAT IF I ALREADY PAID TO HAVE THIS REPAIR COMPLETED?


If you have already experienced this specific condition and have paid to have it repaired, you may visit www.fcarecallreimbursement.com to submit your reimbursement request online. ^[2] Once we receive and verify the required documents, reimbursement will be sent to you within 60 days. If you have had previous repairs performed and/or already received reimbursement, you may still need to have the recall repair performed.

We apologize for any inconvenience, but are sincerely concerned about your satisfaction. Thank you for your attention to this important matter.

Customer Assistance/Field Operations
FCA US LLC

PREMIER DODGE CHRYSLER JEEP OF LEBANON, LLC

600 Pleasant Grove Rd.
Mount Juliet, TN 37122
(615) 288-8525



SERVICE DEPARTMENT HOURS
7:30 a.m. to 6:00 p.m.
Monday - Friday
8:00 a.m. - 4:00 p.m. Saturday

R/O Open Date	R/O Number
1/31/18	6094657/1
R/O Close Date	Status
2/02/18	Pre-Invoice
Mileage In	Mileage Out
30164	30165
Service Advisor / Tag #	
ALICIA SMITH/642*W*	
Vehicle Identification Number	
3C6UR4HL7HG580374	
Delivery Date	In-Service Date
11/18/16	11/18/16
Color	License Number
FLAME RED	

THORNES EXCAVATING CO LLC 624 OLD HORN SPRINGS RD LEBANON, TN 37087-1811			Work Phone		
			Home Phone	615-444-5142	
Year	Make	Model	Body		
2017	RAM	2500	TRADESMAN 4X2 CRE		
D5933					

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
----------------------------------	--------

Email: erict@tec63.com

#1 - ELECT: ELECTRICAL
INDICATOR/WARNING LIGHTS CONCERN CUSTOMER STATES
BRKS AND TRACTION LIGHT CAME ON AND WENT OFF THEN
CEL CAME ON WENT OFF THEN THE OTHER LIGHT CAME ON
CK AND ADVISE
Tech: MARK FAUST (351)
Installed 68144665AB :MTR CYL: BRAKE MASTER CYLIND
Installed 4318080AD :FLUID: BRAKE
FLASH PCM AND DCU
ORDERED MASTER CYLINDER LEVEL SWITCH
REPLACE BRAKE MASTER CYLINDER RESOVORE

Qty: 1 Warranty
Qty: 4 Warranty

Mike
#9

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	.00
PARTS	.00
DEDUCTIBLE	.00
SUBLET	.00
SHOP SUPPLIES	.00
HAZARDOUS MATERIALS	.00
SALES TAX OR TAX I.D.	.00
SPECIAL ORDER DEPOSIT	.00
DISCOUNTS	.00
TOTAL DUE	.00

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

PREMIER DODGE CHRYSLER JEEP OF LEBANON, LLC

600 Pleasant Grove Rd.
Mount Juliet, TN 37122
(615) 288-8525



SERVICE DEPARTMENT HOURS
7:30 a.m. to 6:00 p.m.
Monday - Friday
8:00 a.m. - 4:00 p.m. Saturday

R/O Open Date	R/O Number
2/28/18	6095944/1
R/O Close Date	Status
2/28/18	Pre-Invoice
Mileage In	Mileage Out
31414	31414
Service Advisor / Tag #	
ALICIA SMITH/*W*	
Vehicle Identification Number	
3C6UR4HL7HG580374	
Delivery Date	In-Service Date
11/18/16	11/18/16
Color	License Number
FLAME RED	

THORNES EXCAVATING CO LLC
624 OLD HORN SPRINGS RD
LEBANON, TN 37087-1811

Year	Make	Model	Work Phone	Home Phone	Body	TRADESMAN 4X2 CRE
2017	RAM	2500		615-444-5142		
D5933						

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
Email: erict@tec63.com	
#1 - RECALL: RECALL RECALL / CSN 1 T51: SAFETY RECALL T51 - DIESEL WATER PUMP** Tech: MARK FAUST (351) Installed 68163848AB :ANTIFREEZ: COOLANT Installed CS2HT512AA :CAMPAIGN: WATER PUMP INSPECT AND REPLACE WATER PUMP	Warranty Warranty Warranty
#2 - RECALL: RECALL RECALL / CSN 2 T79: SAFETY RECALL T79 - BRAKE TRANSMISSION SHIFT INTERLOCK** Tech: MARK FAUST (351) INSPECTED AND FLASH BCM	Warranty
#3 - INSP: VEHICLE INSPECTION 23 POINTS CHECK LIST MULTI-POINT INSPECTION (ACCORDING TO MAINTENANCE INTERVAL) Sub Total: .00	

#9
Mike

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.


LABOR	.00
PARTS	.00
DEDUCTIBLE	.00
SUBLET	.00
SHOP SUPPLIES	.00
HAZARDOUS MATERIALS	.00
SALES TAX OR TAX I.D.	.00
SPECIAL ORDER DEPOSIT	.00
DISCOUNTS	.00
TOTAL DUE	.00

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

One Time Free replacement warranty

#9



LOWE'S HOME CENTERS, LLC
300 PLEASANT GROVE RD, STE
MT JULIET, TN 37122 (615) 773-6370

- 10.00% OFF MILITARY- PERSONAL USE DISCOUNT SALE -

- SALE -

SALES#: S2654PB1 1245916 TRANS#: 14199239 08-25-18

997948 CRFTSMN 27-IN BLK 5 DRVR	80.10
89.00 DISCOUNT EACH	-8.90
815565 HITACHI 7-IN 15A GRINDER	48.19
53.55 DISCOUNT EACH	-5.36
795313 DW 4.5-IN 11A GRINDER (-6	71.10
79.00 DISCOUNT EACH	-7.90
28180 KOBALT IMPACT WRENCH	89.10
99.00 DISCOUNT EACH	-9.90
309812 DEWALT 1/2-IN 2-SPEED HAM	125.10
139.00 DISCOUNT EACH	-13.90
77591 DW 3-IN KNOTTED WIRE CUP	15.28
16.98 DISCOUNT EACH	-1.70
293402 DW 16-PC WOOD/MTL RECIP B	20.68
22.98 DISCOUNT EACH	-2.30
813978 KOB 13-AMP RECIPROCATING	89.10
99.00 DISCOUNT EACH	-9.90
731835 2YR RP TOOLS \$50-99.99	11.97

SUBTOTAL: 550.62

TAX: 50.93

INVOICE 14842 TOTAL: 601.55

M/C: 601.55

TOTAL DISCOUNT: 59.86

THANK YOU FOR YOUR
MILITARY SERVICE

MYLOWE'S CARD NUMBER: 489001065006643


M/C:XXXXXXXXXX8503 AMOUNT:601.55 AUTHCD:002631

CHIP REFID:265414381492 08/25/18 07:09:39

APL: MasterCard TVR: 8000008000

AID: A0000000041010 TSI: 6800

#9



LOWE'S HOME CENTERS, LLC
300 PLEASANT GROVE RD, STE
MT JULIET, TN 37122 (615) 773-6370

- 10.00% OFF MILITARY- PERSONAL USE DISCOUNT SALE -

- SALE -

SALES#: S2654RS1 2501124 TRANS#: 14205654 08-25-18

277876 TRU PRO 69-IN POST HOLE D	28.78
31.98 DISCOUNT EACH	-3.20
1073887 IO KOBALT 50-PC DRILL/DRI	11.68
12.98 DISCOUNT EACH	-1.30
856846 KBLT 2-PC IMPCT SWIVEL AD	22.03
24.48 DISCOUNT EACH	-2.45
464614 KOBALT 5-PC PLIERS SET	22.48
24.98 DISCOUNT EACH	-2.50
525827 KOBALT 12-PC SCREWDRIVER	26.98
29.98 DISCOUNT EACH	-3.00
752190 KBLT 4-PC PRY BAR SET	17.98
19.98 DISCOUNT EACH	-2.00
464613 KOBALT 3-PC LOCKING PLIER	17.98
19.98 DISCOUNT EACH	-2.00

SUBTOTAL: 147.91

TAX: 13.68

INVOICE 14863 TOTAL: 161.59

M/C: 161.59

TOTAL DISCOUNT: 16.45

THANK YOU FOR YOUR
MILITARY SERVICE