

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0512

MAKE CAT

MODEL 313F

SERIAL # GJD10048

HOOR METER 1250 HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 4-4-19 DATE COMPLETED 4-10-19

MECHANIC JAMES & BRIAN

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: bought used check over
service

REPAIRED: serviced, removed Accessory fuel pump
Decaled

PARTS: All Filters 269.44 Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0512

MAKE CAT

MODEL 313F

SERIAL # _____

HOURLY METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 5-29-19

MECHANIC Charles

JOB NAME/LOCATION

JOB NUMBER

Journey

PROBLEM: broken hose & fitting AT Quick connect

REPAIRED: replaced hose & fitting

PARTS: hose & fitting

74.32

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0512

MAKE CAT

MODEL 313F

SERIAL # _____

HOURLY METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 6-18-19

MECHANIC ALL

JOB NAME/LOCATION

Preserve

JOB NUMBER

PROBLEM: need hammer pins

REPAIRED: _____

PARTS: 2 pins 203.04 Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0512

MAKE CAT

MODEL 313F

SERIAL # _____

HOURLY METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 8-2-19 DATE COMPLETED 8-10-19

MECHANIC Charles

JOB NAME/LOCATION

Ashland Farms

JOB NUMBER

PROBLEM: Service

REPAIRED: Serviced

PARTS: All Filters

268.16

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0512

MAKE Cat

MODEL 313F

SERIAL # _____

HOURLY METER 2K HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE 10-28-19 DATE COMPLETED 10-28-19

MECHANIC _____

JOB NAME/LOCATION

Ashland Farms

JOB NUMBER

PROBLEM: Service

REPAIRED: Serviced

PARTS: All Filters

269.12

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0512

MAKE CAT

MODEL 313F

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 12-19-19

MECHANIC Bryan

JOB NAME/LOCATION

Ashland Arms

JOB NUMBER

PROBLEM: low front glass broken

REPAIRED: replaced glass

PARTS: GLASS

172.24

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0512

MAKE CAT

MODEL 313F

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 1-23-2020 DATE COMPLETED 1-24-2020

MECHANIC Charles

JOB NAME/LOCATION

Towne Place

JOB NUMBER

PROBLEM: quick connects for hammer

REPAIRED: Installed quick connects.

PARTS: couplings & Adapters 40' 1/2" Industrial Rubber & Gasket

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0512

MAKE CAT

MODEL 313F

SERIAL # _____

HOUR METER 3K HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE 3-30-21 DATE COMPLETED 4-1-21

MECHANIC ALL

JOB NAME/LOCATION

EASTgate

JOB NUMBER

PROBLEM: Service

REPAIRED: Serviced

PARTS: Oil Filter

26.74

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0512</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>313F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>5-6-21</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Eastgate</u>		
PROBLEM: <u>blown quick coupler hose</u>		JOB NUMBER _____		
REPAIRED: <u>replaced hose</u>				
PARTS: <u>Hose Assembly 127.04 Cracks</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0512

MAKE CAT

MODEL 313F

SERIAL # _____

HOURLY METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE 8-17-21 DATE COMPLETED 8-18-21

MECHANIC Bew

JOB NAME/LOCATION Carver Station JOB NUMBER _____

PROBLEM: Service

REPAIRED: Serviced

PARTS: All Filters

305-22

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0513

MAKE Cat

MODEL 315F

SERIAL # _____

HOUR METER 2500 HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 9-15-21

DATE COMPLETED 10-2-21

MECHANIC Ben

JOB NAME/LOCATION

Carver Station

JOB NUMBER

PROBLEM: Service

REPAIRED: serviceed

PARTS: All Filters

315: 36

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0512
 MAKE CAT
 MODEL 313F
 SERIAL # _____
 HOUR METER 4K HRS
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE 3-2-22 DATE COMPLETED 3-5-22

MECHANIC _____

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: Service

REPAIRED: Serviced And washed

PARTS: All Filters 320.70

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0512

MAKE CAT

MODEL 313F

SERIAL # _____

HOOR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 3-24-22

MECHANIC Bew

JOB NAME/LOCATION

West Trinity

JOB NUMBER

PROBLEM: smashed hose + fittings

REPAIRED: replaced hose and female fitting

PARTS: hose - 4 meter + female 1062. 4P

IR+G

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0512

MAKE CAT

MODEL 313F

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 3-10-22 DATE COMPLETED 3-22-22

MECHANIC _____

JOB NAME/LOCATION Shop + West Trinity JOB NUMBER _____

PROBLEM: HR meter + parts book

REPAIRED: HR meter 40,50 HRS

PARTS: meter + book \$275.94 Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0512</u>		HOURS _____	DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>313F</u>		PARTS _____	LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____ DATE COMPLETED <u>7-29-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Bew</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>loose stick pin & bushings at bucket</u>					
REPAIRED: <u>replaced stick bushings & pin</u>					
PARTS: <u>2 seals & 2 bearings 293.43 Thompson</u>					
<u>6-1/8 NF nuts 31.79 Action bolt</u>					
<u>2 pins 444.40 Thompson</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0512

MAKE Cat

MODEL 313F

SERIAL # Quick connect

HOURLY METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____

LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 10-13-22

MECHANIC James

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: broken cylinder

REPAIRED: replaced cylinder

PARTS: cylinder

1,235.³⁴ + TAX

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0512

MAKE Cat

MODEL 313F

SERIAL # _____

OUR METER 4,500 HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 1-23-23 DATE COMPLETED 1-27-23

MECHANIC Anthony

JOB NAME/LOCATION

Carver Town Home

JOB NUMBER

PROBLEM: Service

REPAIRED: serviced

PARTS: Filters

381.82

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0512
MAKE Cat
MODEL 313F
SERIAL # _____
HOUR METER _____
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 3-30-23

MECHANIC Ben

JOB NAME/LOCATION
STONE TRACE

JOB NUMBER

PROBLEM: low battery voltage

REPAIRED: replaced old batteries

PARTS 2-Gmp 3T 5760 508.74
Alternator 299.21

Thompson
A+B Electric

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0572

MAKE CAT

MODEL 313F

SERIAL # _____

HOUR METER 5K HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE 3-10-23 DATE COMPLETED 4-13-23

MECHANIC Anthony

JOB NAME/LOCATION Star Trace

JOB NUMBER _____

PROBLEM: Service

REPAIRED: Service

PARTS: Fitters

3877 35

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0512

MAKE Cat

MODEL 313F

SERIAL # _____

HOOR METER 5100 HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 4-25-23 DATE COMPLETED 4-29-23

MECHANIC James

JOB NAME/LOCATION

To Shop

JOB NUMBER

PROBLEM: EGR controlled DPF clean replace

REPAIRED: DPF bad, EGR controller bad, replaced both
no active codes. Replaced missing track and
bolts.

PARTS: Controller EGR 2582.00

Gaskets, clamps & seals

DPF

Thompson

Thompson

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0512

MAKE Cat

MODEL 313F

SERIAL # _____

HOURLY METER 6K HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 5-2-24 DATE COMPLETED 5-3-24

MECHANIC Anthony

JOB NAME/LOCATION

ST Anthony

JOB NUMBER

PROBLEM: Service

REPAIRED: Serviced

PARTS: Pitters

395.65

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0572</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>313F</u>		PARTS LABOR		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____ DATE COMPLETED <u>2-14-25</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Bryan</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION	
				<u>Authe</u>	
				JOB NUMBER	
PROBLEM: <u>won't start</u>					
REPAIRED: <u>replaced batteries</u>					
PARTS: <u>2-29H-VHD</u> <u>364.26</u> <u>Interstate battery</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0512</u>	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____		
MAKE <u>CAT</u>				
MODEL <u>313F</u>				
SERIAL # _____				
HOUR METER _____				
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>10-28-15</u> MECHANIC <u>Bryan</u>		
		JOB NAME/LOCATION _____		JOB NUMBER _____
PROBLEM: <u>hammer hoses and valve bolts</u>				
REPAIRED: <u>replaced both main hammer hoses, replaced missing bolts on stick shut off valve.</u>				
PARTS: <u>bolts</u> <u>20.41</u> <u>Thompson</u> <u>bolts + hoses</u> <u>834.52</u> <u>Thompson</u>				