

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0808
MAKE Cat
MODEL 259D
SERIAL # _____
HOUR METER 1,268 HRS
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 3-27-23 DATE COMPLETED 4-4-23

MECHANIC James

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: service, check over bought used

REPAIRED: revised

PARTS: Filters 221, EL Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0808</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>2590</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>1268 HRS</u>				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____ DATE COMPLETED <u>8-2-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>James & Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Shop</u>	
PROBLEM: <u>needs Tracks & sprockets</u>				JOB NUMBER _____	

REPAIRED: replaced Tracks & sprockets

PARTS: <u>Tracks</u>	<u>2600.⁰⁰</u>	<u>Thompson</u>
<u>Sprockets</u>	<u>847.49</u>	

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0808

MAKE CAT

MODEL 259D

SERIAL # _____

HOURLY METER 1750 HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 2-1-24 DATE COMPLETED 3-20-24

MECHANIC Anthony

JOB NAME/LOCATION

Sub station

JOB NUMBER

PROBLEM: Service

REPAIRED: Service

PARTS Filters

225.96

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0808

MAKE CAT

MODEL 259D

SERIAL # _____

HOURLY METER 2,200 HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE 1-13-25 DATE COMPLETED 1-15-25

MECHANIC Al

JOB NAME/LOCATION

JOB NUMBER

New Shop

PROBLEM: service

REPAIRED: serviced

PARTS: Filters

226.32

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0808</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Cat</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>259D</u>		COMPONENT LOCATION		
SERIAL # _____	REASON	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____	PARTS	OTHER _____		
MILES _____	LABOR	OTHER _____		
OTHER _____		OTHER _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>5-13-25</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION	JOB NUMBER	
PROBLEM: <u>blown hose</u>		<u>Macon Justice</u>		
REPAIRED: <u>replaced hose</u>				
PARTS: <u>hose</u> <u>228.07</u> <u>RGA</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0808
MAKE Cat
MODEL 259D
SERIAL # _____
HOUR METER _____
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 8-22-25

MECHANIC Bryan

JOB NAME/LOCATION

Antenn

JOB NUMBER

PROBLEM: Key switch locked up.

REPAIRED: replaced key switch

PARTS: switch

174.00

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0808</u> MAKE <u>Cat</u> MODEL <u>259D</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>9-10-25</u> MECHANIC <u>Bryan</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>water pump noise</u>			
REPAIRED: <u>replaced water pump, belt and Thermostat</u>			
PARTS: <u>pump</u> <u>474.⁷¹</u> <u>Thompson</u> <u>Therm. belt & gaskets</u> <u>96.²⁶</u> <u>Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIPMENT DOWNTIME

COMPONENT CODES

EQUIP. # 0808

HOURS _____ DAYS _____

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

MAKE Cat

REASON

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

MODEL 259D

PARTS

LABOR

COMPONENT LOCATION

SERIAL # _____

FRONT REAR LEFT RIGHT UPPER LOWER

HOUR METER 2500 HRS

OTHER _____

MILES _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

DATE 1-7-26 DATE COMPLETED 1-15-26

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

MECHANIC Ben

SMOKES SHORTED VIBRATE OTHER _____

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: Service

Shop

REPAIRED: Serviced

PARTS: filters
Hyd filter

158.00
55.94

Thompson
Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0808</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>2550 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>1-9-26</u> DATE COMPLETED <u>1-15-26</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
PROBLEM: <u>Fuel pump Quit Service</u>			<u>To Shop</u>	
REPAIRED: <u>Serviced</u>				
PARTS: <u>Fuel pump</u> <u>290.25</u> <u>Thompson</u>				
<u>filters</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0808</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>2-20-26</u> DATE COMPLETED <u>2-23-26</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u>	
		JOB NUMBER _____	

PROBLEM: blown Aux connection hose

REPAIRED: replaced both Aux hoses going down
lift arm to quick connect.

PARTS: 2 Hoses 443.16 Thompson