

EQUIPMENT  
REPAIRS

DATE 4-23-03  
1750 Last Service

MILEAGE/HOURS 1850 7XM04139

EQUIPMENT REPAIRED D-8R

REPAIRS MADE Check all oils Pt Black on  
Spray all Rust spots

HOURS WORKED \_\_\_\_\_

PARTS USED

Rust Spray \$ 55.00

EQUIPMENT  
REPAIRS

DATE 4-28-03

MILEAGE/HOURS 1865

EQUIPMENT REPAIRED D-8-R 4139

REPAIRS MADE Replace Starter. Cable block  
and Cable end.

HOURS WORKED \_\_\_\_\_

PARTS USED

Starter \$ 221.78  
Gasket \$ 3.00  
Block \$ 73.25

EQUIPMENT  
REPAIRS

DATE 5/1/83

MILEAGE/HOURS 1907

EQUIPMENT REPAIRED 8R-7XM 4139

REPAIRS MADE Repair Manifold to Head, Intake  
manifold

HOURS WORKED \_\_\_\_\_

PARTS USED

Drill Bits \$70.00

Studs }  
Yrkt } \$510.00  
Clamps }  
Spacers }  
Nuts }

Plain Manifold - \$253.00

Aftercool Adapter \$115.41

EQUIPMENT  
REPAIRS

DATE 6-12-03

MILEAGE/HOURS 2000

EQUIPMENT REPAIRED D8R 7XMD4139

REPAIRS MADE Complete Service changed oil  
& filter, fuel, trans, hydra & blow air

HOURS WORKED \_\_\_\_\_

PARTS USED

oil filter  
fuel filter  
Trans filter  
hydra filter  
water filter - \$15.97  
} - \$74.41

EQUIPMENT  
REPAIRS

DATE 10-22-03

MILEAGE/HOURS 2500

EQUIPMENT REPAIRED D8R #905

REPAIRS MADE Complete service oil & filter  
fuel, trans, hydro filters. Main air filter.  
Drain and clean fuel tank.  
Put 3 <sup>fuel</sup> filters in stock

HOURS WORKED \_\_\_\_\_

PARTS USED

valve cover seals \$ 18.54	oil
pipe plug \$ 5.60	fuel filters \$ 97.48
coupling	hydro
Radiator cap - \$ 11.62	trans
	fuel filter \$ 49.50

EQUIPMENT  
REPAIRS

DATE 11-5-03

MILEAGE/HOURS 2556

EQUIPMENT REPAIRED #905 D8R

REPAIRS MADE install new front Motor Mount.

Replace all bottom water hoses. 2 new  
bottom cover bolts. Replace valve & Rocker  
box gaskets. Replace rocker boxes with used parts.  
install new bolts & regulator (water).

HOURS WORKED \_\_\_\_\_

PARTS USED

(Thompson new)  
Motor Mount \$ 241.98  
water hoses &  
Gaskets, clamps } \$ 125.06

bottom cover bolts \$ 12.23  
pin & bear \$ 19.64

Regulator, gaskets } \$ 97.26

Bolts & nuts  
valve cover gaskets \$ 37.09  
finger tool \$ 4.91

Art's used parts

2-Rocker boxes \$ 105.00



EQUIPMENT  
REPAIRS

DATE 1-5-04

MILEAGE/HOURS \_\_\_\_\_

EQUIPMENT REPAIRED #905 D-8R

REPAIRS MADE install new cab incloser

HOURS WORKED \_\_\_\_\_

PARTS USED

cab incloser - \$651.51

EQUIPMENT  
REPAIRS

DATE 1-15-04

MILEAGE/HOURS 2648

EQUIPMENT REPAIRED #905 D8R

REPAIRS MADE install Muffler + shield

HOURS WORKED \_\_\_\_\_

PARTS USED

Muffler  
shield  
Bolts

\$909.05



EQUIPMENT  
REPAIRS

DATE \_\_\_\_\_

MILEAGE/HOURS \_\_\_\_\_

EQUIPMENT REPAIRED # 905

REPAIRS MADE new seals and belt, bypass  
tubes on radiator.

HOURS WORKED \_\_\_\_\_

PARTS USED

Thompson C639803 A,B,C

2- seals \$58.03  
2- belts

1- seal \$28.72

1- seals \$172.33

C639803  
washers

hoses  
bolts  
seals  
\$156.04

EQUIPMENT  
REPAIRS

DATE 4-26-04

MILEAGE/HOURS 3000

EQUIPMENT REPAIRED #905 D-8R

REPAIRS MADE Complete service oil &  
filter, fuel, trans, hydra filters  
blow air filter.

HOURS WORKED \_\_\_\_\_

PARTS USED

oil 8 gals.

all filters \$153.46

EQUIPMENT  
REPAIRS

DATE 7-6-04

MILEAGE/HOURS \_\_\_\_\_

EQUIPMENT REPAIRED 905 D8R

REPAIRS MADE replace hydro hose to oil  
cooler. 7-2-04 install new plate  
bolts and one base to tilt cylinder

HOURS WORKED \_\_\_\_\_

PARTS USED

cooler hose \$ 83.98

plate \$ 146.02

bolts

flange

~~washers~~

orings

\$ 49.38

hose \$ 91.52

bolts \$ 15.44

EQUIPMENT  
REPAIRS

DATE 8-20-04

MILEAGE/HOURS 3430

EQUIPMENT REPAIRED DBR #905

REPAIRS MADE install bolt & nut  
in track pad

HOURS WORKED \_\_\_\_\_

PARTS USED

12 bolts } \$62.03  
12 nuts }

EQUIPMENT  
REPAIRS

DATE 9-2-04

MILEAGE/HOURS 3431

EQUIPMENT REPAIRED DDR #905

REPAIRS MADE hydra hose

HOURS WORKED \_\_\_\_\_

PARTS USED

hose \$105.04

EQUIPMENT  
REPAIRS

DATE 8-16-04

MILEAGE/HOURS 3500

EQUIPMENT REPAIRED DBR #905

REPAIRS MADE Complete Service

HOURS WORKED \_\_\_\_\_

PARTS USED

*all filter \$146.15*



EQUIPMENT  
REPAIRS

DATE 5-20-05

MILEAGE/HOURS 4000

EQUIPMENT REPAIRED 905

REPAIRS MADE Complete Service

HOURS WORKED \_\_\_\_\_

PARTS USED

*all parts \$131.63*

EQUIPMENT  
REPAIRS

DATE 6-3-08

MILEAGE/HOURS \_\_\_\_\_

EQUIPMENT REPAIRED #905 D8R

REPAIRS MADE Repair 2 center radiator cores  
and replace 1 core.

HOURS WORKED \_\_\_\_\_

PARTS USED

2 <sup>copass</sup> core repair \$ 188.77

1 <sup>CAT</sup> core replace \$ 463.67

Retainer \$ 43.06

EQUIPMENT  
REPAIRS

DATE 8-17-05

MILEAGE/HOURS \_\_\_\_\_

EQUIPMENT REPAIRED #905 DBR

REPAIRS MADE replace push tubes on #1  
cylinder, rocker box cover seals.

HOURS WORKED \_\_\_\_\_

PARTS USED

seals  
Rods ) \$1 54.63

~~Welded 10/10/05~~  
~~10/10/05~~

EQUIPMENT  
REPAIRS

DATE 9-21-05

MILEAGE/HOURS 4432

EQUIPMENT REPAIRED #905

REPAIRS MADE Replace hydro hose on tilt  
cylinder. replace all 6-fuel lines &  
~~clamps~~ clamps

HOURS WORKED \_\_\_\_\_

PARTS USED

hose \$ 114.30

fuel lines  
screws \$ 904.11

clamps \$ 145.06

4-labors \$ 1.31

EQUIPMENT  
REPAIRS

DATE 10-1-05

MILEAGE/HOURS 4500

EQUIPMENT REPAIRED D8R 905

REPAIRS MADE Complete Service all  
filters no Air. Replace seals in  
boom valve and bolts.

HOURS WORKED \_\_\_\_\_

PARTS USED

*filters \$ 106.97*

*3 bolts \$ 57.09*

*O-ring seals \$ 127.00*

EQUIPMENT  
REPAIRS

DATE 4-18-06

MILEAGE/HOURS \_\_\_\_\_

EQUIPMENT REPAIRED 905 D8R

REPAIRS MADE hydra hose

HOURS WORKED \_\_\_\_\_

PARTS USED

hose #65.94



EQUIPMENT  
REPAIRS

DATE 9-25-06

MILEAGE/HOURS 1645

EQUIPMENT REPAIRED #905 7XMO4139

REPAIRS MADE replace extra gaskets, bolts,  
seals.

HOURS WORKED \_\_\_\_\_

PARTS USED

gaskets  
Bolts  
seals } 323.24

gaskets  
clap } \$50.58

EQUIPMENT  
REPAIRS

DATE 9-18-06

MILEAGE/HOURS 4946

EQUIPMENT REPAIRED DBR 905

REPAIRS MADE 2 Tuna back exhaust gaskets

HOURS WORKED \_\_\_\_\_

PARTS USED

Gaskets @ 7.03

EQUIPMENT  
REPAIRS

DATE 10-13-06

MILEAGE/HOURS 5000

EQUIPMENT REPAIRED DDR #905

REPAIRS MADE Complete Service

HOURS WORKED \_\_\_\_\_

PARTS USED

All f.1 hrs @ 97.09

EQUIPMENT  
REPAIRS

DATE 12-01-06

MILEAGE/HOURS 5043

EQUIPMENT REPAIRED 905

REPAIRS MADE heat tube

HOURS WORKED \_\_\_\_\_

PARTS USED

tube \$ 184.69

EQUIPMENT  
REPAIRS

DATE 3-8-07

MILEAGE/HOURS 5157

EQUIPMENT REPAIRED 905 D80C

REPAIRS MADE replace fuel cap

HOURS WORKED \_\_\_\_\_

PARTS USED

cap @ 61.00 Thompson

EQUIPMENT  
REPAIRS

DATE 7-24-07

MILEAGE/HOURS 5528

EQUIPMENT REPAIRED 905 D8R

REPAIRS MADE Complete service

replace Rear 2 Manifold gaskets

HOURS WORKED \_\_\_\_\_

PARTS USED

All Filters \$ 290.04

gaskets  
sealer \$ 119.36



EQUIPMENT  
REPAIRS

DATE 10-07

MILEAGE/HOURS \_\_\_\_\_

EQUIPMENT REPAIRED 905

REPAIRS MADE Replace horns

HOURS WORKED \_\_\_\_\_

PARTS USED

horns  
Plug kits ) 104.02

EQUIPMENT  
REPAIRS

DATE 12-13-07

MILEAGE/HOURS 6000

EQUIPMENT REPAIRED #905 D8R

REPAIRS MADE Complete Service

HOURS WORKED \_\_\_\_\_

PARTS USED

All filters \$191.00

EQUIPMENT  
REPAIRS

DATE 3-31-08

MILEAGE/HOURS 6100

EQUIPMENT REPAIRED #905 D8R

REPAIRS MADE replaced one blade hoist hose  
going to control valve. Drilled out broken  
manifold and mount bolts.

HOURS WORKED \_\_\_\_\_

PARTS USED

Hydraulic hose \$297.<sup>23</sup> Thompson  
Bolts - o-rings - flanges \$58.<sup>44</sup> Thompson

EQUIPMENT  
REPAIRS

DATE 6-19-08

MILEAGE/HOURS #905 6270


EQUIPMENT REPAIRED #905 D8R

REPAIRS MADE replaced end bits rotate cutting  
edges

HOURS WORKED \_\_\_\_\_

PARTS USED


2- End bits JE4193  
JE4194 \$621.09 White Horse Equipment  
33 bolts, nuts & washers



THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>905</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D8R</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>6,299 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>8-5-09</u> DATE COMPLETED _____	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES &amp; DANIEL</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>won't start, needs cleaned up.</u>				
REPAIRED: <u>replaced all four batteries, made up two crossover cables Replaced one posi. terminal on main cable, Removed belly pans to clean. removed starter solenoid cleaned contacts, starter o.k. removed blade cylinders &amp; packed</u>				
PARTS:				
<u>4-GRP31 Batteries</u>		<u>450.<sup>00</sup></u>	<u>Interstate, battery</u>	
<u>blade / 1st cyl. Packings</u>			<u>White House Equip</u>	
<u>4-bolts 3/4" x 8"</u>		<u>26.<sup>03</sup></u>	<u>Fastenal</u>	





THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>905</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON PARTS _____ LABOR _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D8R</u>			COMPONENT LOCATION	
SERIAL # <u>4139</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>6,300 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____			DATE: <u>9-15-09</u> DATE COMPLETED _____ MECHANIC: <u>JAMES &amp; DANIEL</u>	
			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>work on cosmetics</u>				
REPAIRED: <u>Fabricated A new fender lamp box</u>				
<u>replaced lamp and made lamp bracket</u>				
<u>replaced seat cushion</u>				
PARTS: <u>24V lamp 33.00 NAPA</u>				
<u>seat bottom cushion 125.31 Thompson</u>				





THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>905</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS			
MAKE <u>CAT</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED			
MODEL <u>D8R</u>	PARTS _____ LABOR _____	COMPONENT LOCATION			
SERIAL # <u>7XMM4139</u>	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER			
HOUR METER <u>6,301 HRS</u>		OTHER _____			
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____		DATE COMPLETED <u>8-5-10</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>JAMES, Jeff + Eddie</u>			
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u>		JOB NUMBER _____	
PROBLEM: <u>rails + sprocket segments</u>					
REPAIRED: <u>replaced rails + sprocket segments</u>					
PARTS: <u>rails + segments</u> <u>Thompson</u>					



THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>905</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D8R</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED _____	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES + JEFF</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>pilot steering hoses need replaced</u> <u>controls sticking</u>				
REPAIRED: <u>removed four pilot hoses, removed trans.</u> <u>lock linkage, bellcrank frozen up.</u> <u>replaced rusted out seat frame with used</u> <u>frame.</u>				
PARTS: <u>4-pilot hoses &amp; O-rings \$145.12 Thompson</u> <u>used seat frame 54.58 Thompson</u> <u>bearing &amp; bolt 13.54 Thompson</u>				

EQUIPMENT  
REPAIRS

DATE 11-8-11

MILEAGE/HOURS 6,500 HRS

EQUIPMENT REPAIRED #905 cat DFR

REPAIRS MADE serviced + washed

HOURS WORKED \_\_\_\_\_

PARTS USED

Fitters oil + Air + Trans.	\$183. <sup>34</sup>	Tenn. Filter
Coolant Filter	\$13. <sup>21</sup>	NAPA
Hyd Filters	\$74. <sup>11</sup>	Thompson





THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>905</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>D8R</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>3-28-13</u> DATE COMPLETED _____		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>JAMES</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Goodville W/V</u>	JOB NUMBER	
PROBLEM: <u>won't start</u>				
REPAIRED: <u>cleaned and repaired battery ends, still won't start. Removed starter and sent to crooks for repair. Installed starter, Engine</u>				
PARTS: <u>battery terminals 50.<sup>00</sup> Napa</u> <u>starter rebuild 245.<sup>00</sup> Crooks</u>				



# THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>905</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D8R</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>7-11-13</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
			<u>Shop</u>	
PROBLEM: <u>TRANS. oil leak, check over</u>				
REPAIRED: <u>replaced hose from trans filter housing to trans. casing</u>				
PARTS: <u>Hose Assembly + O-rings \$105.52 Thompson Machinery</u>				
<u>4-light mounts</u>				