

Brian Prince Transmissions Inc.
 13253 Wire Road
 Cottondale, AL 35453
 205-556-6197



NAME: Southland Res.
 ADDRESS: Jeb
 CITY: King Ranch
 STATE: SD
 ZIP: 57044
 PHONE: 607-281-1670
 FAX: 607-281-1670
 LICENSE NO. 120404
 MECHANIC/TECHNICIAN

VEHICLE MAKE AND MODEL: 60.7
 COLOR: white
 Hitting hard

APPROVED
 RS 10/23/23

PO# 30492
 # 847
 INSTALL JASPER
 TRANSMISSION
 SW [Signature]

Jasper
 3 Year
 100000 mile Warranty
 Shop supplies

TRANSMISSION
 Replaced
 # 8,185.33

ENTERED
 10-30-23
 RS

| | |
|--------------|---------|
| TOTAL PARTS | 6014.00 |
| TOTAL LABOR | 176.00 |
| Trans. Fluid | 180.00 |
| Program | 250.00 |
| Tax | 571.33 |
| Total | 8185.33 |

Not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any other cause beyond our control. If applicable, in shop warranty only. No warranty on vehicles with programmers or customer furnished parts. Any misuse or abuse voids warranty. Warranty does not cover loss of time, inconvenience, loss of use of vehicle, commercial loss, or rental vehicles. Services are warranted only for cost of repair. I hereby authorize the above repair work to be done along with the necessary materials. The employees may operate vehicle for purposes of testing, inspection, or delivery at owner's risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. Not responsible for court costs and/or attorney fees.

SIGNATURE: _____
 DATE: _____
 TIME: _____



1224

Brookwood Truck & Trailer
11903 Aspenwood Drive
Moundville, AL
205-765-6644



NAME: Buddy Jones

| QTY. | PART NO. AND DESCRIPTION (All parts new unless otherwise specified) | AMOUNT |
|------|--|-----------|
| 1 | Used Engine | |
| 4 | 15w-40 Engine oil | |
| 6 | 50/50 Antifreeze Freon | |
| 1 | Powersteering Fluid | |
| 1 | Oil Filter | |
| 2 | Fuel Filters | |
| 1 | Hose | |
| 1 | Water in Fuel sensor and pigtail | |
| 1 | Alternator and pigtail | |
| 1 | tube | |
| 1 | Hose | |
| 1 | ABS sensor | |
| | Engine | |
| | 4/6/26 | |
| | \$14,159. | |
| | TOTAL PARTS | \$8854.00 |

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate vehicle for purposes of testing, inspection, or delivery at my risk. An excess mechanics lien is acknowledged on above vehicle to secure the amount of repair billings. It is understood that you will not be held responsible for loss or damage to vehicle or contents of vehicle in case of fire, theft or any other cause beyond your control.

HOW TO PAY: CASH VISA MC

DATE: 4-6-26
CUSTOMER'S SIGNATURE: [Signature]

P.S. POINT: [Blank]
DIVE ENGINE: [Blank]

VEHICLE NO.: [Blank]
VIN AND FEED: YES NO

REPAIR ORDER NO.: 193079

VEHICLE MAKE AND MODEL: 2017 Ford F250
VIN: 1FT7W2BTAHEE16742

SERVICE REQUESTED/DESCRIPTION OF WORK:

Remove cab and replace Engine with used Engine.
install cab and All components
change oil and Filter
replace Fuel Filters
replace oil cooler hose + quick connect
replace water in Fuel sensor and pigtail
Fill with Antifreeze and Freon
Replace driver side Alternator and pigtail
Replace right Front ABS sensor and repair wiring.

TOTAL LABOR: 4,420.00
TOTAL PARTS: 8,854.00
TOTAL SUBLET: [Blank]
GAS, OIL AND GREASE: [Blank]
EPA / WASTE DISPOSAL: [Blank]

TOTAL: \$14,159.40

REPAIR ORDER

DATE

JOB NUMBER

JOB NAME

**PRODUCTION STICKER
INSTRUCTIONS FOR CORRECT
INSTALLATION AND SERVICE**



5503765V

R #: 281924

BIRMINGHAM

OD #: 550376 STOCK #: 5606950

0 3



Scan this QR Code or visit
www.jasperengines.com and mark
your core ready for pickup.



**PRODUCTION STICKER &
INSTRUCTIONS FOR CORRECT
INSTALLATION AND SERVICE**

This transmission has a Solenoid ID and Strategy that is unique to every valve body installed into this type of transmission. This information must be programmed into the TCM prior to test driving or severe transmission damage will occur.

Mercon LV ATF must be used or warranty will be void. If transmission develops a 3-4 shift squawk add additive XL- 16 to the fluid.

FORD made a running change and eliminated the drain plug on some oil pans. The supplied pan may or may not have a drain plug.

Clearing shift adapts and TCM KAM:

1. Connect the scan tool to the vehicle.
2. NOTE: Do not clear the PCM Keep Alive Memory (KAM). Using the scan tool, clear the Transmission Control Module (TCM) KAM and the