

Highland Truck Repair llc

ga 30223
4045120957 |
zach8749@gmail.com

Lot#: 332



scan to view online

Invoice 822

Bill to
AJC HEAVY HAULING
ajc031503@yahoo.com

19-Apr-2025

Vehicle (Truck)
2020 PETERBILT 389
1XPXP4EX3LD639900
ODO in. : 448274 miles
ODO out: 448274 miles

Item	QTY	Materials/Parts used
	1	Oil pressure sensor
	1	Coolant reservoir
	4.9	Brake cleaner
	1	Hoses
	12	Oil 15w40
	14	Coolant

Hrs.	Services Performed	Rate	Amount
50	Pushing coolant Head gasket blown removed radiator, fan, fan clutch, accessory bracket, turbo, exhaust manifold, thermostat, intake manifold, fuel lines, fuel rail, valve cover, rockers inspect cam and rockers good removed injectors removed cam and removed cylinder head, checked liner protrusion all are below specs removed oil pan. And removed all pistons removed oil pump and disassembled and checked for reuse good removed all liners cleaned block and got counterbores machined installed new liners with shims and now have .014" across the board replaced all main bearings and torqued Mains to specs removed pistons from rods and checked for reuse good installed new pistons in rods installed pistons into block and torqued to specs cleaned all gears cleaned new cylinder head installed head and torqued to specs with new head bolts installed cam and set engine base timing and backlash to specs torqued all gears cleaned bolts to specs installed rockers and torqued to specs adjusted all valves and Jake's to specs replaced injector seals and reinstalled injectors and torqued to specs reinstalled all removed parts turbo speed sensor broken replaced turbo speed sensor replaced shunt hose replaced bypass hose replaced reservoir filled with oil and coolant replaced oil and fuel filter primed oil system and started truck ran and checked for leaks none found ran at high idle to 200 degrees repair complete	\$125.00	* \$ 6,250.00

Parts	\$622.54
Services	\$6,250.00
Subtotal	\$6,872.54
GST(7%)	\$43.58
Total	\$ 6,916.12
Paid	\$ 0.00

Balance Due	\$6,916.12
--------------------	-------------------

Technician_signature

Customer Signature

Highland Truck Repair LLC

ga 30223
4045120957 |
zach8749@gmail.com



scan to view online

Invoice 1071

Bill to

AJC HEAVY HAULING
ajc031503@yahoo.com

27-Mar-2026

Vehicle (Truck)

2020 PETERBILT 389 ISX
1XPXP4EX3LD639900
ODO in: 448274 miles
ODO out: 448274 miles

QTY	Materials/Parts used		
hrs.	Services_Performed	Rate	Amount
Breakdown			
3.5 hrs.	Starter picked up starter and drove to suwanee replaced starter and truck now starts repair complet	\$125.00	* \$437.50
		Parts	\$0.00
		Services_Performed	\$437.50
		Subtotal	\$437.50
		GST(7%)	\$0.00
		Total	\$437.50
		Paid	\$0.00
		Balance Due	\$437.50

Technician_signature

Customer Signature

Highland Truck Repair llc

ga 30223
4045120957 |
zach8749@gmail.com



scan to view online

Invoice 734

Bill to

AJC HEAVY HAULING
ajc031503@yahoo.com

26-Nov-2024

Vehicle (Truck)

2020 PETERBILT 389
1XPXP4EX3LD639900
ODO 448274 miles

Item	QTY	Materials/Parts used		
	1	Grease fittings		
	1	Grease		
	Hrs.	Services_Performed	Rate	Amount
	14	Clutch inop Found release bearing failed grease line to release bearing broken removed exhaust, drive line, clutch linkage, blocked off coolant to trans cooler and removed coolant lines from trans cooler, removed floor plate removed shifter, removed transmission found input shaft damaged removed clutch and found pilot bearing damaged replaced flywheel installed new pilot bearing installed new clutch installed new input shaft and bearing and bearing cover replaced clutch forks reinstalled transmission and reinstalled shifter with new gasket reinstalled all removed parts removed remote grease lines and installed standard grease fittings grease clutch and cross shafts checked transmission level good adjust clutch free play and test operation repair complete 12hr for clutch 2 hr for input shaft and install kit	\$125.00	* \$ 1,750.00
			Parts	\$20.00
			Services	\$1,750.00
			Subtotal	\$1,770.00
			GST(7%)	\$1.40
			Total	\$ 1,771.40
			Paid	\$ 0.00
			Balance Due	\$1,771.40

Technician_signature

Customer Signature