

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

|                                                                                                                                                               |                                                                                                               |                                                                                                                                                                                                                                                                |                                 |            |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------|------------|
| <b>EQUIPMENT INFORMATION</b><br>EQUIP. # <u>0507</u><br>MAKE <u>CAT</u><br>MODEL <u>303.5EZ</u><br>SERIAL # _____<br>HOUR METER <u>500 HRS</u><br>MILES _____ | <b>EQUIPMENT DOWNTIME</b><br>HOURS _____ DAYS _____<br>REASON _____<br>PARTS _____ LABOR _____<br>OTHER _____ | <b>COMPONENT CODES</b><br>BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS<br>POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED<br><b>COMPONENT LOCATION</b><br>FRONT REAR LEFT RIGHT UPPER LOWER<br>OTHER _____                                                           |                                 |            |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED<br>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH<br>SMOKES SHORTED VIBRATE OTHER _____                     |                                                                                                               | DATE: _____ DATE COMPLETED <u>5-8-18</u><br>MECHANIC <u>James</u><br><table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:50%;">JOB NAME/LOCATION<br/><u>Shp</u></td> <td style="width:50%;">JOB NUMBER</td> </tr> </table> | JOB NAME/LOCATION<br><u>Shp</u> | JOB NUMBER |
| JOB NAME/LOCATION<br><u>Shp</u>                                                                                                                               | JOB NUMBER                                                                                                    |                                                                                                                                                                                                                                                                |                                 |            |
| PROBLEM: <u>Service</u>                                                                                                                                       |                                                                                                               |                                                                                                                                                                                                                                                                |                                 |            |
|                                                                                                                                                               |                                                                                                               |                                                                                                                                                                                                                                                                |                                 |            |
| REPAIRED: <u>Serviced</u>                                                                                                                                     |                                                                                                               |                                                                                                                                                                                                                                                                |                                 |            |
|                                                                                                                                                               |                                                                                                               |                                                                                                                                                                                                                                                                |                                 |            |
| PARTS: <u>All Filters</u> <u>149.82</u> <u>Thompson</u><br><u>50.5</u> <u>142.68</u> <u>Thompson</u>                                                          |                                                                                                               |                                                                                                                                                                                                                                                                |                                 |            |

TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0507

MAKE CAT

MODEL 303.5E2

SERIAL # \_\_\_\_\_

HOUR METER 1K HRS

MILES \_\_\_\_\_

EQUIPMENT DOWNTIME

HOURS \_\_\_\_\_ DAYS \_\_\_\_\_

REASON

PARTS

LABOR

OTHER \_\_\_\_\_

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER \_\_\_\_\_

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER \_\_\_\_\_

DATE: 11-9-18 DATE COMPLETED 11-19-18

MECHANIC ALL

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: Service

REPAIRED: serviced, Took oil samples, changed final drives

PARTS: All Filters

282.44

Thompson

10 Sample bottles

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

### EQUIPMENT INFORMATION

EQUIP. # 0507  
 MAKE Cat  
 MODEL 303.5  
 SERIAL # \_\_\_\_\_  
 HOUR METER 1K HRS  
 MILES \_\_\_\_\_

### EQUIPMENT DOWNTIME

HOURS \_\_\_\_\_ DAYS \_\_\_\_\_  
 REASON  
 PARTS \_\_\_\_\_ LABOR \_\_\_\_\_  
 OTHER \_\_\_\_\_

### COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS  
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

### COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER  
 OTHER \_\_\_\_\_

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED  
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH  
 SMOKES SHORTED VIBRATE OTHER \_\_\_\_\_

DATE: 11-19-18 DATE COMPLETED 11-19-18

MECHANIC \_\_\_\_\_

JOB NAME/LOCATION \_\_\_\_\_

JOB NUMBER \_\_\_\_\_

PROBLEM: needs serviced

REPAIRED: serviced & sampled

PARTS: Filters + 292.50 Thompson  
sample bottles

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

### EQUIPMENT INFORMATION

EQUIP. # 0507  
 MAKE CAT  
 MODEL 303.5  
 SERIAL # \_\_\_\_\_  
 HOUR METER \_\_\_\_\_  
 MILES \_\_\_\_\_

### EQUIPMENT DOWNTIME

HOURS \_\_\_\_\_ DAYS \_\_\_\_\_  
 REASON \_\_\_\_\_  
 PARTS \_\_\_\_\_ LABOR \_\_\_\_\_  
 OTHER \_\_\_\_\_

### COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS  
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

### COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER \_\_\_\_\_  
 \_\_\_\_\_

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED  
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH  
 SMOKES SHORTED VIBRATE OTHER \_\_\_\_\_

DATE: \_\_\_\_\_ DATE COMPLETED 11-28-10

MECHANIC Ali

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: new 36" bucket

REPAIRED: smooth bucket & bolts

PARTS: Bucket 36"  
bolts & nuts

1393.83  
41.52

Thompson  
Fastenal

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

### EQUIPMENT INFORMATION

EQUIP. # 0507

MAKE CAT

MODEL 303.5

SERIAL # \_\_\_\_\_

HOUR METER \_\_\_\_\_

MILES \_\_\_\_\_

### EQUIPMENT DOWNTIME

HOURS \_\_\_\_\_ DAYS \_\_\_\_\_

REASON

PARTS

LABOR

OTHER \_\_\_\_\_

### COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

### COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER \_\_\_\_\_

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER \_\_\_\_\_

DATE: \_\_\_\_\_ DATE COMPLETED 2-18-19

MECHANIC Charles

JOB NAME/LOCATION

JOB NUMBER

Legends Dr

PROBLEM: Tracks

REPAIRED: replaced Tracks

PARTS: Tracks

White House Equipment

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

### EQUIPMENT INFORMATION

EQUIP. # 05017

MAKE Cat

MODEL 303.5

SERIAL # \_\_\_\_\_

HOURLY METER \_\_\_\_\_

MILES \_\_\_\_\_

### EQUIPMENT DOWNTIME

HOURS \_\_\_\_\_ DAYS \_\_\_\_\_

#### REASON

PARTS \_\_\_\_\_ LABOR \_\_\_\_\_

OTHER \_\_\_\_\_

### COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

### COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER \_\_\_\_\_

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER \_\_\_\_\_

DATE: \_\_\_\_\_ DATE COMPLETED 10-4-19

MECHANIC James

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: \_\_\_\_\_

REPAIRED: Added two shanks

Tracks looking old

PARTS: Tips, pins & retainers 185.49 Thompson  
2-shanks

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

### EQUIPMENT INFORMATION

EQUIP. # 0507

MAKE CAT

MODEL 303.5

SERIAL # \_\_\_\_\_

HOURLY METER 2K HRS

MILES \_\_\_\_\_

### EQUIPMENT DOWNTIME

HOURS \_\_\_\_\_ DAYS \_\_\_\_\_

#### REASON

PARTS \_\_\_\_\_ LABOR \_\_\_\_\_

OTHER \_\_\_\_\_

### COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

### COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER \_\_\_\_\_

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER \_\_\_\_\_

DATE: \_\_\_\_\_ DATE COMPLETED 3-2-2020

MECHANIC Ben

JOB NAME/LOCATION

Faith Family

JOB NUMBER

PROBLEM: Service

REPAIRED: Serviced

PARTS: All Filters 152.14 Thompson

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

### EQUIPMENT INFORMATION

EQUIP. # 0507

MAKE CAT

MODEL 303.5

SERIAL # \_\_\_\_\_

HOUR METER 2,500 HRS

MILES \_\_\_\_\_

### EQUIPMENT DOWNTIME

HOURS \_\_\_\_\_ DAYS \_\_\_\_\_

REASON

PARTS

LABOR

OTHER \_\_\_\_\_

### COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

### COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER \_\_\_\_\_

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER \_\_\_\_\_

DATE: \_\_\_\_\_ DATE COMPLETED 10-29-20

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

Ashland Farms

PROBLEM: cracked fuel hose

Service

REPAIRED: Eric patched still need to fix

Service

PARTS: hoses & clamps

58.01

Thompson

hose

19.75

Thompson

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

### EQUIPMENT INFORMATION

EQUIP. # 0507

MAKE CAT

MODEL 303.5

SERIAL # \_\_\_\_\_

HOURLY METER 2,750 HRS

MILES \_\_\_\_\_

### EQUIPMENT DOWNTIME

HOURS \_\_\_\_\_ DAYS \_\_\_\_\_

REASON \_\_\_\_\_

PARTS \_\_\_\_\_

LABOR \_\_\_\_\_

OTHER \_\_\_\_\_

### COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

### COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER \_\_\_\_\_

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER \_\_\_\_\_

DATE: \_\_\_\_\_ DATE COMPLETED 8-3-21

MECHANIC JAMES

JOB NAME/LOCATION

JOB NUMBER

shop

PROBLEM: worn out tracks

REPAIRED: replaced both tracks change final drive oils

PARTS: Tracks in stock

seat bottom

295.35

Thompson

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

### EQUIPMENT INFORMATION

EQUIP. # 0507  
MAKE Cat  
MODEL 303.5  
SERIAL # \_\_\_\_\_  
HOUR METER 3k N/25  
MILES \_\_\_\_\_

### EQUIPMENT DOWNTIME

HOURS \_\_\_\_\_ DAYS \_\_\_\_\_  
REASON \_\_\_\_\_  
PARTS \_\_\_\_\_ LABOR \_\_\_\_\_  
OTHER \_\_\_\_\_

### COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS  
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

### COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER \_\_\_\_\_  
\_\_\_\_\_

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED  
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH  
SMOKES SHORTED VIBRATE OTHER \_\_\_\_\_

DATE: 11-9-21 DATE COMPLETED 11-18-21

MECHANIC BLN

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: service

REPAIRED: serviced

PARTS: All Filters

162.46

Thompson

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

### EQUIPMENT INFORMATION

EQUIP. # 0507

MAKE CAT

MODEL 303.5

SERIAL # \_\_\_\_\_

HOURLY METER \_\_\_\_\_

MILES \_\_\_\_\_

### EQUIPMENT DOWNTIME

HOURS \_\_\_\_\_ DAYS \_\_\_\_\_

REASON \_\_\_\_\_

PARTS \_\_\_\_\_

LABOR \_\_\_\_\_

OTHER \_\_\_\_\_

### COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS  
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

### COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER \_\_\_\_\_

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER \_\_\_\_\_

DATE: \_\_\_\_\_ DATE COMPLETED 3-15-22

MECHANIC James

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: start switch bad

REPAIRED: replaced start switch

PARTS: switch

140.38

Thompson

467-8535

TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0507

MAKE CAT

MODEL 303.5

SERIAL # \_\_\_\_\_

HOUR METER 500 HRS

MILES \_\_\_\_\_

EQUIPMENT DOWNTIME

HOURS \_\_\_\_\_ DAYS \_\_\_\_\_

REASON \_\_\_\_\_

PARTS \_\_\_\_\_

LABOR \_\_\_\_\_

OTHER \_\_\_\_\_

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER \_\_\_\_\_

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER \_\_\_\_\_

DATE: 6-20-23

DATE COMPLETED 6-21-23

MECHANIC \_\_\_\_\_

JOB NAME/LOCATION

West Trinity

JOB NUMBER

PROBLEM: Service

REPAIRED: Serviced

PARTS: Filters

191.44

Thompson

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

|                                                                    |  |                         |  |                                                   |  |
|--------------------------------------------------------------------|--|-------------------------|--|---------------------------------------------------|--|
| EQUIPMENT INFORMATION                                              |  | EQUIPMENT DOWNTIME      |  | COMPONENT CODES                                   |  |
| EQUIP. # <u>0507</u>                                               |  | HOURS _____ DAYS _____  |  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS         |  |
| MAKE <u>Cat</u>                                                    |  | REASON _____            |  | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED      |  |
| MODEL _____                                                        |  | PARTS _____ LABOR _____ |  | COMPONENT LOCATION                                |  |
| SERIAL # _____                                                     |  | OTHER _____             |  | FRONT REAR LEFT RIGHT UPPER LOWER                 |  |
| HOUR METER <u>new meter</u>                                        |  |                         |  | OTHER _____                                       |  |
| MILES _____                                                        |  |                         |  |                                                   |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED                 |  |                         |  | DATE <u>10-4-22</u> DATE COMPLETED <u>10-5-22</u> |  |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH                      |  |                         |  | MECHANIC <u>James &amp; Anthony</u>               |  |
| SMOKES SHORTED VIBRATE OTHER _____                                 |  |                         |  | JOB NAME/LOCATION _____                           |  |
|                                                                    |  |                         |  | JOB NUMBER _____                                  |  |
| PROBLEM: <u>service &amp; hour meter</u>                           |  |                         |  |                                                   |  |
|                                                                    |  |                         |  |                                                   |  |
|                                                                    |  |                         |  |                                                   |  |
| REPAIRED: <u>serviced, replaced hour meter</u>                     |  |                         |  |                                                   |  |
|                                                                    |  |                         |  |                                                   |  |
|                                                                    |  |                         |  |                                                   |  |
|                                                                    |  |                         |  |                                                   |  |
|                                                                    |  |                         |  |                                                   |  |
|                                                                    |  |                         |  |                                                   |  |
|                                                                    |  |                         |  |                                                   |  |
| PARTS <u>Filter &amp; hour meter</u> <u>329.52</u> <u>Thompson</u> |  |                         |  |                                                   |  |
|                                                                    |  |                         |  |                                                   |  |
|                                                                    |  |                         |  |                                                   |  |
|                                                                    |  |                         |  |                                                   |  |
|                                                                    |  |                         |  |                                                   |  |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

### EQUIPMENT INFORMATION

EQUIP. # 0507

MAKE CAT

MODEL 303.5

SERIAL # \_\_\_\_\_

HOOR METER 1,000 HRS

MILES \_\_\_\_\_

### EQUIPMENT DOWNTIME

HOURS \_\_\_\_\_ DAYS \_\_\_\_\_

REASON

PARTS

LABOR

OTHER \_\_\_\_\_

### COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

### COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER \_\_\_\_\_

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER \_\_\_\_\_

DATE 12-15-23 DATE COMPLETED 12-15-23

MECHANIC \_\_\_\_\_

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: Service + ~~Starter~~

REPAIRED: serviced

PARTS: Filters

248.23

Thompson

Starter

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

### EQUIPMENT INFORMATION

EQUIP. # 0507

MAKE CAT

MODEL 303.5

SERIAL # \_\_\_\_\_

OUR METER 0 HRS

MILES new meter

### EQUIPMENT DOWNTIME

HOURS \_\_\_\_\_ DAYS \_\_\_\_\_

REASON

PARTS \_\_\_\_\_ LABOR \_\_\_\_\_

OTHER \_\_\_\_\_

### COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

### COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER \_\_\_\_\_

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER \_\_\_\_\_

DATE: 8-6-24 DATE COMPLETED 8-7-24

MECHANIC Anthony

JOB NAME/LOCATION

To shop

JOB NUMBER

PROBLEM: Service

REPAIRED: serviced  
new hour meter

PARTS: Filters

Mounts

125. LE

362 74

Thompson

Thompson

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

### EQUIPMENT INFORMATION

EQUIP. # 0507  
MAKE CAT  
MODEL 303.5  
SERIAL # \_\_\_\_\_  
HOUR METER 67.1  
MILES \_\_\_\_\_

### EQUIPMENT DOWNTIME

HOURS \_\_\_\_\_ DAYS \_\_\_\_\_  
REASON \_\_\_\_\_  
PARTS \_\_\_\_\_ LABOR \_\_\_\_\_  
OTHER \_\_\_\_\_

### COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS  
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

### COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER  
OTHER \_\_\_\_\_

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED  
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH  
SMOKES SHORTED VIBRATE OTHER \_\_\_\_\_

DATE: \_\_\_\_\_ DATE COMPLETED 10-1-24  
MECHANIC ALL

JOB NAME/LOCATION

To Shop

JOB NUMBER

PROBLEM: blade cylinder leak

REPAIRED: Mid South repaired cylinder

PARTS: cylinder repair 699.<sup>20</sup> Mid South hydraulics

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

|                                                                 |  |                         |  |                                              |  |
|-----------------------------------------------------------------|--|-------------------------|--|----------------------------------------------|--|
| EQUIPMENT INFORMATION                                           |  | EQUIPMENT DOWNTIME      |  | COMPONENT CODES                              |  |
| EQUIP. # <u>0507</u>                                            |  | HOURS _____ DAYS _____  |  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |  |
| MAKE <u>Cat</u>                                                 |  | REASON _____            |  | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |  |
| MODEL <u>303.5</u>                                              |  | PARTS _____ LABOR _____ |  | COMPONENT LOCATION                           |  |
| SERIAL # _____                                                  |  | OTHER _____             |  | FRONT REAR LEFT RIGHT UPPER LOWER            |  |
| HOUR METER _____                                                |  |                         |  | OTHER _____                                  |  |
| MILES _____                                                     |  |                         |  |                                              |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED              |  |                         |  | DATE: _____ DATE COMPLETED <u>3-25-25</u>    |  |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH                   |  |                         |  | MECHANIC <u>Roger</u>                        |  |
| SMOKES SHORTED VIBRATE OTHER _____                              |  |                         |  | JOB NAME/LOCATION <u>Shop</u>                |  |
|                                                                 |  |                         |  | JOB NUMBER _____                             |  |
| PROBLEM: <u>stick bushings bad</u>                              |  |                         |  |                                              |  |
|                                                                 |  |                         |  |                                              |  |
|                                                                 |  |                         |  |                                              |  |
| REPAIRED: <u>replaced stick bushings &amp; pin.</u>             |  |                         |  |                                              |  |
|                                                                 |  |                         |  |                                              |  |
|                                                                 |  |                         |  |                                              |  |
|                                                                 |  |                         |  |                                              |  |
|                                                                 |  |                         |  |                                              |  |
|                                                                 |  |                         |  |                                              |  |
| PARTS: <u>pins &amp; bearings</u> <u>523.33</u> <u>Thompson</u> |  |                         |  |                                              |  |
|                                                                 |  |                         |  |                                              |  |
|                                                                 |  |                         |  |                                              |  |
|                                                                 |  |                         |  |                                              |  |
|                                                                 |  |                         |  |                                              |  |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

|                                                    |  |                         |  |                                                  |  |
|----------------------------------------------------|--|-------------------------|--|--------------------------------------------------|--|
| EQUIPMENT INFORMATION                              |  | EQUIPMENT DOWNTIME      |  | COMPONENT CODES                                  |  |
| EQUIP. # <u>0507</u>                               |  | HOURS _____ DAYS _____  |  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS        |  |
| MAKE <u>Cat</u>                                    |  | REASON                  |  | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED     |  |
| MODEL <u>303.5</u>                                 |  | PARTS _____ LABOR _____ |  | COMPONENT LOCATION                               |  |
| SERIAL # _____                                     |  | OTHER _____             |  | FRONT REAR LEFT RIGHT UPPER LOWER                |  |
| HOUR METER _____                                   |  |                         |  | OTHER _____                                      |  |
| MILES _____                                        |  |                         |  |                                                  |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED |  |                         |  | DATE: <u>5-5-25</u> DATE COMPLETED <u>5-7-25</u> |  |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH      |  |                         |  | MECHANIC <u>Ben</u>                              |  |
| SMOKES SHORTED VIBRATE OTHER _____                 |  |                         |  | JOB NAME/LOCATION                                |  |
| PROBLEM: <u>leaks</u>                              |  |                         |  | <u>Shop.</u>                                     |  |
|                                                    |  |                         |  | JOB NUMBER                                       |  |

REPAIRED: separated boom and blade cylinder and packed

|        |                       |               |                                    |
|--------|-----------------------|---------------|------------------------------------|
| PARTS: | <u>boom seal kit</u>  | <u>403.44</u> | <u>Thompson</u><br><u>Thompson</u> |
|        | <u>blade seal kit</u> | <u>320.94</u> |                                    |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

### EQUIPMENT INFORMATION

EQUIP. # 0507  
 MAKE CAT  
 MODEL 303.5  
 SERIAL # \_\_\_\_\_  
 HOUR METER \_\_\_\_\_  
 MILES \_\_\_\_\_

### EQUIPMENT DOWNTIME

HOURS \_\_\_\_\_ DAYS \_\_\_\_\_  
 REASON \_\_\_\_\_  
 PARTS \_\_\_\_\_ LABOR \_\_\_\_\_  
 OTHER \_\_\_\_\_

### COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS  
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

### COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER  
 OTHER \_\_\_\_\_

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED  
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH  
 SMOKES SHORTED VIBRATE OTHER \_\_\_\_\_

DATE: \_\_\_\_\_ DATE COMPLETED 11-7-25

MECHANIC Bryan

JOB NAME/LOCATION Andis Howe

JOB NUMBER \_\_\_\_\_

PROBLEM: Hr. meter bad

REPAIRED: replaced HR meter.

PARTS: meter

153.03

Thompson