

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0006</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Chevy</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>23' 3500</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER _____		OTHER _____
MILES <u>New</u>		

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: <u>1-10-24</u> DATE COMPLETED <u>1-26-24</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>All</u>
SMOKES SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>shop</u> JOB NUMBER _____

PROBLEM: set up new Truck installed power inverter.
Made ladder rack. Made vice stand. Installed
upper box. Installed safety light & running boards.

REPAIRED: _____

<u>running boards</u>	<u>145.²³</u>	<u>Amazon</u>
PARTS: <u>inverter</u>	<u>395.⁰⁰</u>	<u>Harbor Freight</u>
<u>cables & breakers</u>	<u>111.⁰⁰</u>	<u>Amazon</u>
<u>light</u>	<u>367.⁵⁰</u>	<u>Trucker's Light House</u>
<u>upper box</u>	<u>836.⁶¹</u>	<u>Amazon</u>
<u>vice</u>	<u>137.³⁰</u>	<u>Houes</u>
<u>mats</u>	<u>114.⁰⁰</u>	<u>TSC</u>

Air comp.