

EQUIPMENT
REPAIRS

DATE 10-16-03

MILEAGE/HOURS 2000

EQUIPMENT REPAIRED # 904 D-8-R

REPAIRS MADE Complete Service oil & filter
hydra, trans, fuel filter, blow air
filter, check everything.

HOURS WORKED _____

PARTS USED

oil
fuel filters # 97.48
hydra
trans

[Handwritten signature]

EQUIPMENT
REPAIRS

DATE 10-29-03

MILEAGE/HOURS 2105

EQUIPMENT REPAIRED 904 D-8R

REPAIRS MADE install new fan belts
stock fuel filters

HOURS WORKED _____

PARTS USED

belts - \$ 82.93
3 filters \$ 49.50

EQUIPMENT
REPAIRS

DATE 11-12-03

MILEAGE/HOURS 2109

EQUIPMENT REPAIRED # 904 D8R

REPAIRS MADE install 4 new batteries

HOURS WORKED _____

PARTS USED

Batteries \$261.98

EQUIPMENT
REPAIRS

DATE 1-6-04

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #904 D-8R

REPAIRS MADE install new cab inclasser

HOURS WORKED _____

PARTS USED

cab inclasser - \$651.51

EQUIPMENT
REPAIRS

DATE 6-8-04

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #904 D8R

REPAIRS MADE replace elec. block to
starter.

HOURS WORKED _____

PARTS USED

~~scribble~~

block \$ 74.67

EQUIPMENT
REPAIRS

DATE 7-29-04

MILEAGE/HOURS 2500

EQUIPMENT REPAIRED #904 D8R

REPAIRS MADE Complete Service oil & filter
fuel, hydro and trans filter.
blow air filters bring on hydro
line.

HOURS WORKED _____

PARTS USED

filters \$177.53

~~seals~~
~~hose~~
~~elbow~~
~~valve~~

seals	\$	74.20
hose		72.88
elbow		11.48
valve		18.70

EQUIPMENT
REPAIRS

DATE 9-13-04

MILEAGE/HOURS 71

EQUIPMENT REPAIRED 904 D8R

REPAIRS MADE install new muffler, stack
and rings on adaptor.

HOURS WORKED _____

PARTS USED

muffler \$1228.07
rings
stack \$8.00

EQUIPMENT
REPAIRS

DATE 7-26-04

MILEAGE/HOURS 58

EQUIPMENT REPAIRED D-8-R 904

REPAIRS MADE replace fuel adapter on
#3.

HOURS WORKED _____

PARTS USED

Adapter
seals
basket
nut

) \$45.00

Cleaning fluid \$ 39.07

EQUIPMENT
REPAIRS

DATE 8-19-04

MILEAGE/HOURS 2560

EQUIPMENT REPAIRED D8R #904

REPAIRS MADE Replace hour meter &
raincap install new master
switch and lug on cable.

HOURS WORKED _____

PARTS USED

raincap \$ 17.00

hour meter \$ _____

switch \$ 54.90

lug \$ 3.38

EQUIPMENT
REPAIRS

DATE 1/14/05

MILEAGE/HOURS _____

EQUIPMENT REPAIRED D8R-4123 #904

REPAIRS MADE _____

HOURS WORKED _____

PARTS USED

Pain Cap - \$44.37

EQUIPMENT
REPAIRS

DATE 2-14-05

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #904 D8R

REPAIRS MADE heat tube

HOURS WORKED _____

PARTS USED

tube # 164.63

EQUIPMENT
REPAIRS

DATE 3-16-05

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #904 D8R

REPAIRS MADE headlight clamp

HOURS WORKED _____

PARTS USED

clamp # 3.56

EQUIPMENT
REPAIRS

DATE 4-11-05

MILEAGE/HOURS _____

EQUIPMENT REPAIRED 904 D8R

REPAIRS MADE Replace two hoses 2 clamp
8 bolts & washers,

HOURS WORKED _____

PARTS USED

2 hoses
bolt
washer
flange) \$ 247.44

EQUIPMENT
REPAIRS

DATE 5-3-05

MILEAGE/HOURS 500

EQUIPMENT REPAIRED 904 D8R

REPAIRS MADE complete service all
filter and outer air filter

HOURS WORKED _____

PARTS USED

filters - \$ 163.02
~~163.02~~

EQUIPMENT
REPAIRS

DATE 11-18-05

MILEAGE/HOURS 624

EQUIPMENT REPAIRED 904

REPAIRS MADE Parking brake rod and joint

fit Trunion ball bush

HOURS WORKED _____

PARTS USED

rod
joint) \$24.97
2 - rings \$6.54

EQUIPMENT
REPAIRS

DATE 2-28-06

MILEAGE/HOURS _____

EQUIPMENT REPAIRED 904

REPAIRS MADE muffler stack

HOURS WORKED _____

PARTS USED

*Stack
exhaust* \$239.95

EQUIPMENT
REPAIRS

DATE 3-16-06

MILEAGE/HOURS _____

EQUIPMENT REPAIRED D8R 4123 904

REPAIRS MADE Replace bearings on
fuel rod.

HOURS WORKED _____

PARTS USED

Bearings @ 43.33

EQUIPMENT
REPAIRS

DATE 5-31-06

MILEAGE/HOURS 4800

EQUIPMENT REPAIRED 904

REPAIRS MADE _____

HOURS WORKED _____

PARTS USED

Price \$ 667.45

Bolts
washers) \$57.86
Nuts

EQUIPMENT
REPAIRS

DATE 8-1-06

MILEAGE/HOURS 1500

EQUIPMENT REPAIRED 904

REPAIRS MADE Complete Service

HOURS WORKED _____

PARTS USED

Filters \$ 208.60

EQUIPMENT
REPAIRS

DATE 9-25-06

MILEAGE/HOURS 4971

EQUIPMENT REPAIRED #904 7XMO4123

REPAIRS MADE Replace ether gaskets, Bolts

HOURS WORKED _____

PARTS USED

Bolts
gaskets) \$ 323.24
seals

Brush
tips) 26.85
wire

Tax 5.23

EQUIPMENT
REPAIRS

DATE 9-25-06

MILEAGE/HOURS 1713

EQUIPMENT REPAIRED #904 D8R

REPAIRS MADE Track guide

HOURS WORKED _____

PARTS USED

Guide
Bolts
washers) \$ 6.04
71.35

EQUIPMENT REPAIRS

DATE 2-10-07

MILEAGE HOURS 2000

EQUIPMENT REPAIRED 904 DBR

REPAIRS MADE Complete service

HOURS WORKED _____

PARTS USED

all filters \$190.74

EQUIPMENT REPAIRS

DATE 2-20-07

MILEAGE HOURS 2042

EQUIPMENT REPAIRED 904 #4123

REPAIRS MADE replace prescreener &
Body, Bolts & washer

HOURS WORKED _____

PARTS USED

Body
Prescr.
Bolts
washer
A609.41

EQUIPMENT
REPAIRS

DATE _____

MILEAGE/HOURS _____

EQUIPMENT REPAIRED 904

REPAIRS MADE Replace Horns

HOURS WORKED _____

PARTS USED

2 horns
plus kits) \$ 104.02

EQUIPMENT
REPAIRS

DATE 10-10-07

MILEAGE/HOURS 2558

EQUIPMENT REPAIRED 904 D8R

REPAIRS MADE replace oil jug & hose
replace water flow switch

HOURS WORKED _____

PARTS USED

Oring
Breather
Elbow
Bottle # 182.79
Jug
hose # 92.95
flow switch
Gasket # 127.86

EQUIPMENT
REPAIRS

DATE 11-5-07
~~11-5-07~~
2625

MILEAGE/HOURS 2500

EQUIPMENT REPAIRED #904 D8R

REPAIRS MADE Complete service

HOURS WORKED _____

PARTS USED

All Filters \$290.04

EQUIPMENT
REPAIRS

DATE 9-3-08

MILEAGE/HOURS _____

EQUIPMENT REPAIRED # 904

REPAIRS MADE bottom seat cushion

HOURS WORKED _____

PARTS USED

cushion \$117.17 Thompson

EQUIPMENT
REPAIRS

DATE 12-8-08

MILEAGE/HOURS _____


EQUIPMENT REPAIRED #904

REPAIRS MADE replaced bad torque converter
temp guage

HOURS WORKED _____


PARTS USED

guage 52.81 Thompson
4W-0485




THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>904</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>DPR</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>7xm4123</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>3,000</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>2-9-09</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES & DANIEL</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
			<u>Owl Hollow</u>	
PROBLEM: <u>need service</u>				
REPAIRED: <u>Serviced</u>				
PARTS:				
<u>Filters</u> <u>198.98</u> <u>Thompson</u>				
<u>w/Filter</u> <u>Hsd Filter</u> } <u>in stock</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>#904</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D8R</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>3000</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>2-23-09</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Out Hollow</u>	JOB NUMBER
PROBLEM: <u>Trunion bolts</u>				
REPAIRED: <u>replaced bolts on left blade Arm</u>				
PARTS: <u>bolts nuts & washers 90.00 Thompson</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>904</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D8R</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>4139</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>7-9-09</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>Rain Cap broken</u>				
REPAIRED: <u>replaced rain cap</u>				
PARTS: <u>Cap A</u> <u>\$59.73</u> <u>Thompson</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>904</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS			
MAKE <u>CAT</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED			
MODEL <u>DPR</u>	PARTS _____ LABOR _____	COMPONENT LOCATION			
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER			
HOOR METER _____		OTHER _____			
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____		DATE COMPLETED <u>4-10</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>JAMES</u>			
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION		JOB NUMBER	
PROBLEM: <u>won't start</u>					
REPAIRED: <u>replaced one battery</u>					
PARTS: <u>Grp 31P-MHD</u> <u>#112.47</u> <u>Interstate Battery</u>					



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>904</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Cat</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>D8R</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____	DATE COMPLETED <u>5/12-10</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>JAMES</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Kingston Springs</u>	JOB NUMBER _____	
PROBLEM: <u>Hyd leak</u>				
REPAIRED: <u>replaced blown hyd. hose</u>				
PARTS: <u>Hose</u> <u>\$226.35</u> <u>Thompson</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>904</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D8R</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>7XM4128</u>			FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>5,919 HRS</u> <u>total</u>	OTHER _____		OTHER _____	
MILES <u>3,300 one meter</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED _____	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES, Jeff + Eddie</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>rails and sprocket segments</u>				
REPAIRED: <u>replaced rails and sprocket segments</u>				
PARTS: <u>rails & segments</u> <u>Thompson</u>				

TEC


THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>904</u>		HOURS _____	DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D8R</u>		PARTS _____	LABOR _____	COMPONENT LOCATION	
SERIAL # <u>7X14123</u>		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
OUR METER <u>5,919 total</u>				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: _____ DATE COMPLETED <u>8-30-10</u>	
				MECHANIC <u>JAMES</u>	
				JOB NAME/LOCATION <u>Shop</u>	
				JOB NUMBER _____	
PROBLEM: <u>Clean up, repair lights, fix leaks</u> <u>no back up alarm. check over</u>					
REPAIRED: <u>replaced back up alarm + cleaned switch</u> <u>rebuilt light boxes on fenders, replaced lights</u> <u>replaced left rear light washed machine</u>					
PARTS: <u>back up alarm</u> <u>57.00</u> <u>NAPA</u> <u>3 Flood lights</u> <u>95.97</u> <u>NAPA</u> <u>2 cans paint</u> <u>12.00</u> <u>Tractor supply</u>					




THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>904</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON PARTS LABOR	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D8R</u>			COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED _____	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC _____	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
PROBLEM: <u>blown hydraulic hose at trans. lock valve</u>				
REPAIRED: _____				
PARTS: <u>4-Hoses & seals</u> <u>150.³⁶</u> <u>Thompson</u>				
<u>Ice union, nut & fittings</u> <u>50.⁰⁰</u> <u>Thompson</u>				
<u>1-Hose</u> <u>45.²³</u> <u>Thompson</u>				
<u>Hyd Filter, o-ring</u> <u>37.⁰⁵</u> <u>Thompson</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>904</u>	MAKE <u>CAT</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MODEL <u>DFR</u>	SERIAL # _____	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
HOOR METER _____	MILES _____	PARTS _____ LABOR _____	COMPONENT LOCATION	
		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
			OTHER _____	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>10-5-11</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>starter solenoid broken</u>				
<u>weak batteries</u>				
REPAIRED: <u>replaced solenoid starter O.K.</u>				
<u>needs batteries (parked behind shop)</u>				
PARTS: <u>solenoid</u> <u>54.63</u> <u>Crooks</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>904</u>	MAKE <u>CAT</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MODEL <u>DPR</u>	SERIAL # _____	REASON PARTS _____ LABOR _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
HOURLY METER _____	MILES _____	OTHER _____	COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER	
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>9-12-12</u> DATE COMPLETED <u>9-13-12</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Bel-Air</u>	JOB NUMBER _____
PROBLEM: <u>muffler needs replaced</u> <u>Air Filter Housing cover bolts need replaced</u>				
REPAIRED: <u>replaced muffler</u> <u>replaced left air filter cover bolt & nut</u>				
PARTS: <u>muffler 360.53 White Horse Equipment</u> <u>Air Filter Housing bolts 23.80 Thompson</u>				