

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
QUIP. # <u>0115</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17' G713</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>275k ml.</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>6-27-23</u> DATE COMPLETED <u>6-30-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>All</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>Service</u> <u>4-rear tires</u>				

REPAIRED: serviced, replaced 4 rear tires

PARTS: Filters 238.51 Ten Filter sales

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0115
MAKE Mack
MODEL 17'64713
SERIAL # _____
HOUR METER _____
MILES 280K

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: 8-3-23 DATE COMPLETED 8-5-23
MECHANIC All

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: Filter Service

REPAIRED: Serviced

PARTS:

Filters

269.36

Term Filter

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0115

MAKE Mack

MODEL M' GU713

SERIAL # _____

HOURLY METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 8-17-23 DATE COMPLETED _____

MECHANIC ALL

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: New Tires

REPAIRED: _____

PARTS:

4-Hankook 11R-24.5 2495.01 Gateway

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0115
 MAKE Mack
 MODEL GM713
 SERIAL # _____
 HOUR METER _____
 MILES 284K mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 10-17-23

MECHANIC ALL

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: center diff bad

REPAIRED: full center axle clean up. replaced diff wheel bearings & seals.

PARTS: Center Diff \$8200.00 Welder Truck Parts
Bearings & Nuts & seals \$625.99 McMahon Trucks

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0115</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Mack</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>17' GU713</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>11-27-23</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shops</u>	JOB NUMBER	
PROBLEM: <u>Radiator leak</u>				
<u>broken Transmission sensor</u>				
REPAIRED: <u>replaced radiator Condensor + vent hose</u>				
<u>replaced sensor</u>				
<u>resealed pto gaskets.</u>				
Filters 303. ²² Ten filter				
PARTS: radiator hose + radiator 1029. ⁵² McMahon Truck				
Condensor 321. ⁶² Truck Pro				
sensor 68. ¹⁶ Weller Truck parts				
hose & fittings 214. ²⁷ McMahon Trucks				
wrecker 825. ⁴⁰ Ten Pro				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0115

MAKE Mack

MODEL 17' 64713

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETE 12-7-23

MECHANIC James

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: leaks

REPAIRED: replaced pto solenoid & hose.

PARTS:

solenoid

299.67

Weller

hose

44.65

Creek's

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0115</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17' G4713</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>11-5-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Gateway</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>hole at edge of sidewalk RT steer</u>				
REPAIRED: <u>replaced tire</u>				
PARTS: <u>385/65R 22.5 Toyo M-149 833.23 Gateway</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0115</u> MAKE <u>Mack</u> MODEL <u>17' G6713</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____ _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>11-14-24</u> MECHANIC <u>Anthony</u> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:50%;">JOB NAME/LOCATION <u>Shop</u></td> <td style="width:50%;">JOB NUMBER</td> </tr> </table>	JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER			
PROBLEM: <u>bad batteries</u> _____ _____				
REPAIRED: <u>replaced two batteries</u> _____ _____ _____ _____ _____ _____				
PARTS: <u>2- Gyp 31-MHD 307.19 Interstate battery</u> _____ _____ _____				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0115</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17' Dump Truck</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>325K mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>2-6-25</u> DATE COMPLETED <u>2-11-25</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>All</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER

PROBLEM: Service

REPAIRED: serviced

PARTS: Oil & Fuel filters 146.30 Ten Filter sales

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0115</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17' GU713</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: <u>5-18-23</u> DATE COMPLETED <u>5-24-23</u>	
PROBLEM: <u>Service</u>				MECHANIC <u>Al</u>	
				JOB NAME/LOCATION <u>Shops</u>	
				JOB NUMBER _____	

REPAIRED: serviced

PARTS: filters 301.35 Term Filler

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0115</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Make</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17' GU713</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>3-17-23</u> DATE COMPLETED <u>3-17-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>latch cylinder solenoid bad</u>				
REPAIRED: <u>replaced latch solenoid</u>				
PARTS: <u>solenoid</u> <u>189.94</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0115</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17' GU713</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>265K mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>4-3-23</u> DATE COMPLETED <u>4-6-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>All</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>Service</u>				

REPAIRED: serviced

PARTS: Filters 168.27 Ken Filter sales
Air Filter 81.07 Napa

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0115</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17 G4713</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>247K mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>10-4-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>All</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>bought used</u>				

REPAIRED: serviced, new windshields, new steer tires & Alignment
sealed high lift cylinders
new tailgate, straightened all leaf pins

Cylinder seals 124.²⁵ Signal

PARTS: Filters 497.⁶⁴ Terex Filter

bearing 137.⁰⁰ McMahon Trucks

return bracket 169.²⁵ McMahon Trucks

new windshields 1734.⁰⁰ Lawrence Glass

Tires & Alignment 2572.⁵¹ Swider Fleet

Pins & bushings 600.⁰⁰ OK body
Solenoid (latch) 129.¹⁹ Truck Pro
Tailgate 2600.⁰⁰ OK BEDS

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0115

MAKE Mack

MODEL 17' G4713

SERIAL # _____

HOUR METER _____

MILES 307K mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 7-29-24 DATE COMPLETED 8-7-24

MECHANIC All

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: Service

REPAIRED: serviced

PARTS: filters

347.25

Tran Filter

Tail lamp

48.06

Truck Pro

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0115</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Mack</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>17 GU713</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES <u>310k mi</u>				
REASON FOR FAILURE: ☐ BROKEN ☐ WORN ☐ ABUSE ☐ LOOSE ☐ SEIZED		DATE: _____ DATE COMPLETED <u>9-30-24</u>		
☐ OVERHEAT ☐ PLANNED ☐ CONTAM ☐ LEAKING ☐ NOISY ☐ SCRATCH		MECHANIC <u>Anthony</u>		
☐ SMOKES ☐ SHORTED ☐ VIBRATE ☐ OTHER _____		JOB NAME/LOCATION <u>Shop</u>		JOB NUMBER _____
PROBLEM: <u>broken left rear studs & rear brakes</u>				
REPAIRED: <u>replaced studs on left rear axle.</u>				
<u>replaced brakes & drums on both rear axles.</u>				
PARTS: <u>brakes, Drums & studs 1,399.⁷⁰</u> <u>Truck pro</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>0115</u> MAKE <u>Mock</u> MODEL <u>17' 64713</u> SERIAL # _____ HOUR METER _____ MILES <u>307K mi</u>	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: <u>8.14.24</u> DATE COMPLETED <u>8.14.24</u> MECHANIC <u>Ben</u> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:50%;">JOB NAME/LOCATION</td> <td style="width:50%;">JOB NUMBER</td> </tr> </table>		JOB NAME/LOCATION	JOB NUMBER
JOB NAME/LOCATION	JOB NUMBER				
PROBLEM: <u>Tires, stuck in 1st gear</u>					
REPAIRED: <u>Changed trans oil & filters.</u>					
PARTS: <u>2 - Ralsa RunR157</u> <u>1707.56</u> <u>Swider Tive</u> <u>Trans oil</u> <u>987.25</u> <u>NAPA</u>					

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0115</u>		HOURS _____ DAYS _____		BASIC MACHINE	HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>Mark</u>		REASON _____		POWER TRAIN	ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>17' G4713</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES <u>316k mi</u>					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>10-10-24</u> DATE COMPLETED <u>10-15-24</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>All</u>		
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>		JOB NUMBER _____
PROBLEM: <u>Service</u>					
REPAIRED: <u>Serviced</u>					
PARTS: <u>Filters</u> <u>\$406.20</u> <u>Tenn Filter Sales</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0115
 MAKE Mack
 MODEL 17' 64713
 SERIAL # _____
 HOUR METER _____
 MILES 287,500 mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
 COMPONENT LOCATION
 FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 12-11-23

MECHANIC A11

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: service loose wheel

REPAIRED: serviced, replaced broken stud

PARTS: studs & nuts 4/169 Fleetpride

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0115
MAKE Mack
MODEL 17' G713
SERIAL # _____
HOUR METER _____
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
COMPONENT LOCATION
FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE 12-15-23 DATE COMPLETED 12-16-23

MECHANIC James

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: leaking brake chamber

REPAIRED: replaced brake chamber

PARTS: 2 chambers 156.⁴²
clevis 15.⁰⁰

Fleet pride
O'Reilly Auto Parts

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0115
 MAKE Mack
 MODEL 64713
 SERIAL # _____
 HOUR METER _____
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
 COMPONENT LOCATION
 FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 2-16-24

MECHANIC Mark

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: needs Tarp motor

REPAIRED: replaced tarp motor & bracket & breaker

PARTS: Motor

294.⁹⁶

Fleet price

Breaker & extra

15.⁸⁵

Shop

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0115

MAKE Mack

MODEL 17.6U713

SERIAL # _____

HOURLY METER _____

MILES 290K mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 2-19-24

MECHANIC Tride Fleet

JOB NAME/LOCATION

JOB NUMBER

PROBLEM:

no steer tires

REPAIRED:

PARTS:

385 65 22.5

1744.5

Tride Fleet

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0115

MAKE Mack

MODEL 17 GU713

SERIAL # _____

HOUR METER _____

MILES 295K mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 3-15-24

MECHANIC ALL

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: service & broken tail light

REPAIRED: serviced

PARTS: Fitters

340.70

Tenn Fitter sales

light

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0115</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS			
MAKE <u>Mack</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED			
MODEL <u>17' GU713</u>	PARTS _____ LABOR _____	COMPONENT LOCATION			
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER			
OUR METER _____		OTHER _____			
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>3-18-24</u>		DATE COMPLETED <u>3-20-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>			
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION		JOB NUMBER	
		<u>900 Dickerson & Shop</u>			
PROBLEM: <u>needs Tap Quit charging</u>					
REPAIRED: <u>replaced Tap & Alternator</u>					
PARTS: <u>Tap</u>		<u>115.53</u>		<u>Truck Pro</u>	
<u>Alternator</u>		<u>388.62</u>		<u>A+B Electric</u>	

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0115

MAKE Mack

MODEL 64713

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 4-2-24 DATE COMPLETED 4-2-24

MECHANIC Ali

JOB NAME/LOCATION

JOB NUMBER

To Shop

PROBLEM: bad DPS & Det Tank cap.

REPAIRED: replaced d.t.a. press. sensor. Forced regen.
replaced particle sensor
Mack dealer reset system

PARTS: <u>sensor & cap</u>	<u>119.77</u>	<u>McMahon Trucks</u>
<u>particle sensor</u>	<u>387.25</u>	<u>McMahon Trucks</u>
<u>Sensors, dump & initiator</u>	<u>524.</u>	

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0115
 MAKE MAK
 MODEL 175U713
 SERIAL # _____
 HOUR METER _____
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
 COMPONENT LOCATION
 FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE 5-3-24 DATE COMPLETED 5-16-24
 MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

To Shop

PROBLEM: bad injector, restricted EGR system
check engine light on

REPAIRED: cleaned out EGR system, replaced
injector & seals.

PARTS: Injector NO. 7 186.97 Mc Mahon Trucks
seals, rings & clamps 543.27 Mc Mahon Trucks
Elbow 372.91 Mc Mahon Trucks

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0115

MAKE Mack

MODEL 17' G4713

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE 10-1-22 DATE COMPLETED 10-3-22

MECHANIC All

JOB NAME/LOCATION

JOB NUMBER

shop

PROBLEM: needs rear brakes

REPAIRED: replaced brakes on rear axles

PARTS: 4 drums & 4 shoe kits 1,481.⁰⁰ Truck Pro

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0115

MAKE Mack

MODEL GU 713 17

SERIAL # _____

HOURLY METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED _____

MECHANIC _____

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: Tarp quit rolling one way.

REPAIRED: replaced rocker switch & module.

PARTS: switch 61.17 Fleet pride

module 134.37 Fleet pride

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0115</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17' GU713</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>10-20-22</u> DATE COMPLETED <u>11-8-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>check engine light & exhaust test</u>				
REPAIRED: <u>removed DPF had cleaned and re-sealed</u>				
<u>Mack mechanic reset the codes. replaced fan belt.</u>				
<u>new coolant hoses at DPF</u>				
PARTS: <u>hose & fittings \$447.⁹³ McMahon Trucks</u>				
<u>belts - Fan 23961828 \$170.⁰² WE Crossville TN</u>				
<u>belt-AIT 60.⁸⁰ McMahon Trucks</u>				
<u>Analys & re program \$745.⁹³ McMahon Trucks</u>				
<u>DPF & Clean, new clamps 481.⁵⁰ EMS</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0115

MAKE Mack

MODEL 17' GU713

SERIAL # _____

HOUR METER _____

MILES 255K mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE 1-19-23 DATE COMPLETED 1-21-23

MECHANIC Ali

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: Service

REPAIRED: serviced

PARTS: Filters

437.83

Tenn Filter sales

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0115

MAKE Mack

MODEL 17' GU713

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 2-7-23

MECHANIC Al

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: Tarp Torn, check engine light. blown steer
Tire

REPAIRED: replaced Tarp & Det dose valve.
Mack mechanic cleaned up system with laptop.

PARTS: Tarp 116.³⁵ Truck Pro
Michelin X 385/65R22.5 1183.⁶⁵ Surge Tire
Det Dose valve 528.²³ McMahon Trucks

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0115
 MAKE Mack
 MODEL 17' G4713
 SERIAL # _____
 HOUR METER _____
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 2-23-23

MECHANIC All

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: flat tire

Shop

REPAIRED: Tire repair Gateway

PARTS: repair


4-11R-24.5

59.89

1869.26

Gate way

Gate way



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0115

MAKE MAK

MODEL 64713 17

SERIAL # _____

HOUR METER _____

MILES 260K mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____

LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 2-24-23 DATE COMPLETED 3-2-23

MECHANIC Ben & Anthony

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: Service

REPAIRED: serviced & replaced PTO solenoid

PARTS: Filters

439.43

Terre Filter Sales

solenoid & press. switch

493.20

Weller Truck Parts

Key Switch

97.95

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # #0115

MAKE Mack

MODEL 17' 622713

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 7-2-24 DATE COMPLETED 7-8-24

MECHANIC Bryan

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: coolant tank cracked

REPAIRED: replaced tank

PARTS: Tank 247, SE McMahan Trucks

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0115
 MAKE Mack
 MODEL 17 G4713
 SERIAL # _____
 HOUR METER _____
 MILES 330K mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: 4-15-25 DATE COMPLETED 4-17-25

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: wiring, leaks & service.

REPAIRED: serviced, repaired light wiring.

PARTS: Filters 467.88 Terex filter
Tube & clamps 98.48 Mc Mahon Trucks

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0115</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17' GU713</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>345k mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: <u>9-18-25</u> DATE COMPLETED <u>9-24-25</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Bryan & Justin</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>Service</u>				
REPAIRED: <u>serviced</u>				
PARTS: <u>Filters</u> <u>473.96</u> <u>Tenn Filter sales</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0115</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Mack</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17' 64713</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>350K mi</u>				

REASON FOR FAILURE: ☐ BROKEN ☐ WORN ☐ ABUSE ☐ LOOSE ☐ SEIZED	DATE <u>12-18-25</u>	DATE COMPLETED <u>12-18-25</u>
OVERHEAT ☐ PLANNED ☐ CONTAM ☐ LEAKING ☐ NOISY ☐ SCRATCH	MECHANIC <u>Ben</u>	
SMOKES ☐ SHORTED ☐ VIBRATE ☐ OTHER _____	JOB NAME/LOCATION <u>To Shop</u>	JOB NUMBER

PROBLEM: Service, cab protector broken.

REPAIRED: Serviced, welded cab protector.

PARTS: Filters 473.92 Tenn Filter saks

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0115
 MAKE Mack
 MODEL 17' GU713
 SERIAL # _____
 HOUR METER _____
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE 2-16-26 DATE COMPLETED _____

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

To Shop

PROBLEM: bad high lift cylinder had no. 1 nox sensor
one bad ash sensor
now fan motor speed code.

REPAIRED: replaced no. 1 nox sensor,
removed high lift cylinder on RT side,
replaced one ash sensor.

PARTS: cylinder

Nox sensor

894.06

Mc Mahon

Ash sensor

426.36

Mc Mahon

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0115</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>MAK</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>17 GU713</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES <u>355K mi</u>				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>3-6-26</u> DATE COMPLETED <u>3-11-26</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>All</u> <u>Service 3-26-26</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	
			JOB NUMBER _____	
PROBLEM: <u>Service</u>				

REPAIRED: replaced both belts and tensioners
replaced both steer axle brakes and drums.
serviced

PARTS: Filter 490.25 Tenn Filter
3-10-26
belts & tensioners \$758.57 McMahon Truck parts
steer brakes & Drums - 625.56 Fleet Pride