

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

| EQUIPMENT INFORMATION                                                   |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                              |                  |
|-------------------------------------------------------------------------|--|-------------------------|----------------------------------------------|------------------|
| EQUIP. # <u>1005</u>                                                    |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |                  |
| MAKE <u>Cat</u>                                                         |  | REASON _____            | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |                  |
| MODEL <u>D6R</u>                                                        |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                           |                  |
| SERIAL # _____                                                          |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER            |                  |
| HOUR METER _____                                                        |  |                         | OTHER _____                                  |                  |
| MILES _____                                                             |  |                         |                                              |                  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED                      |  |                         | DATE: _____ DATE COMPLETED <u>3-30-2020</u>  |                  |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH                           |  |                         | MECHANIC <u>Bryan</u>                        |                  |
| SMOKES SHORTED VIBRATE OTHER _____                                      |  |                         | JOB NAME/LOCATION <u>Shop Lines</u>          | JOB NUMBER _____ |
| PROBLEM: <u>Trans. leak</u>                                             |  |                         |                                              |                  |
|                                                                         |  |                         |                                              |                  |
|                                                                         |  |                         |                                              |                  |
| REPAIRED: <u>replaced blown Trans hose</u>                              |  |                         |                                              |                  |
|                                                                         |  |                         |                                              |                  |
|                                                                         |  |                         |                                              |                  |
|                                                                         |  |                         |                                              |                  |
|                                                                         |  |                         |                                              |                  |
|                                                                         |  |                         |                                              |                  |
|                                                                         |  |                         |                                              |                  |
| PARTS: <u>hose &amp; seals</u> <u>158.<sup>00</sup></u> <u>Thompson</u> |  |                         |                                              |                  |
|                                                                         |  |                         |                                              |                  |
|                                                                         |  |                         |                                              |                  |
|                                                                         |  |                         |                                              |                  |
|                                                                         |  |                         |                                              |                  |

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

| EQUIPMENT INFORMATION                                                                                                                     |                                                                                        | EQUIPMENT DOWNTIME                           | COMPONENT CODES         |  |
|-------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------|----------------------------------------------|-------------------------|--|
| EQUIP. # <u>1005</u>                                                                                                                      | HOURS _____ DAYS _____<br><br>REASON<br><br>PARTS _____ LABOR _____<br><br>OTHER _____ | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |                         |  |
| MAKE <u>CAT</u>                                                                                                                           |                                                                                        | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |                         |  |
| MODEL <u>D6R</u>                                                                                                                          |                                                                                        | COMPONENT LOCATION                           |                         |  |
| SERIAL # _____                                                                                                                            |                                                                                        | FRONT REAR LEFT RIGHT UPPER LOWER            |                         |  |
| HOUR METER _____                                                                                                                          |                                                                                        | OTHER _____                                  |                         |  |
| MILES _____                                                                                                                               |                                                                                        |                                              |                         |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED<br>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH<br>SMOKES SHORTED VIBRATE OTHER _____ |                                                                                        | DATE: _____ DATE COMPLETED <u>5-20-20</u>    | MECHANIC <u>Charles</u> |  |
|                                                                                                                                           |                                                                                        | JOB NAME/LOCATION<br><u>Cedar Crossing</u>   | JOB NUMBER              |  |
| PROBLEM: <u>Idle cap bolts broken out.</u>                                                                                                |                                                                                        |                                              |                         |  |
| REPAIRED: <u>replaced cap and bolts</u>                                                                                                   |                                                                                        |                                              |                         |  |
| PARTS: <u>caps &amp; bolts</u> <u>298.82</u> <u>Thompson</u>                                                                              |                                                                                        |                                              |                         |  |

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

| EQUIPMENT INFORMATION                              |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                              |            |
|----------------------------------------------------|--|-------------------------|----------------------------------------------|------------|
| EQUIP. # <u>1005</u>                               |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |            |
| MAKE <u>CAT</u>                                    |  | REASON _____            | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |            |
| MODEL <u>D8R</u>                                   |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                           |            |
| SERIAL # _____                                     |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER            |            |
| HOUR METER _____                                   |  |                         | OTHER _____                                  |            |
| MILES _____                                        |  |                         |                                              |            |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED |  |                         | DATE: _____ DATE COMPLETED <u>6-4-20</u>     |            |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH      |  |                         | MECHANIC <u>Charles</u>                      |            |
| SMOKES SHORTED VIBRATE OTHER _____                 |  |                         | JOB NAME/LOCATION<br><u>Cedar Crossing</u>   | JOB NUMBER |
| PROBLEM: <u>Bad fuel cap</u>                       |  |                         |                                              |            |
| REPAIRED: <u>replaced cap</u>                      |  |                         |                                              |            |
| PARTS: <u>cap</u> <u>105. P17</u> <u>Thompson</u>  |  |                         |                                              |            |

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

| EQUIPMENT INFORMATION                                            |  | EQUIPMENT DOWNTIME      |  | COMPONENT CODES                              |  |
|------------------------------------------------------------------|--|-------------------------|--|----------------------------------------------|--|
| EQUIP. # <u>1005</u>                                             |  | HOURS _____ DAYS _____  |  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |  |
| MAKE <u>CAT</u>                                                  |  | REASON _____            |  | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |  |
| MODEL <u>D6R</u>                                                 |  | PARTS _____ LABOR _____ |  | COMPONENT LOCATION                           |  |
| SERIAL # _____                                                   |  | OTHER _____             |  | FRONT REAR LEFT RIGHT UPPER LOWER            |  |
| HOUR METER <u>7500 HRS</u>                                       |  |                         |  | OTHER _____                                  |  |
| MILES _____                                                      |  |                         |  |                                              |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED               |  |                         |  | DATE: _____ DATE COMPLETED <u>6-30-20</u>    |  |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH                    |  |                         |  | MECHANIC <u>Ben + Caleb</u>                  |  |
| SMOKES SHORTED VIBRATE OTHER _____                               |  |                         |  | JOB NAME/LOCATION <u>Cedar Crossing</u>      |  |
|                                                                  |  |                         |  | JOB NUMBER _____                             |  |
| PROBLEM: <u>Service</u>                                          |  |                         |  |                                              |  |
|                                                                  |  |                         |  |                                              |  |
|                                                                  |  |                         |  |                                              |  |
| REPAIRED: <u>Service</u>                                         |  |                         |  |                                              |  |
|                                                                  |  |                         |  |                                              |  |
|                                                                  |  |                         |  |                                              |  |
|                                                                  |  |                         |  |                                              |  |
|                                                                  |  |                         |  |                                              |  |
|                                                                  |  |                         |  |                                              |  |
|                                                                  |  |                         |  |                                              |  |
| PARTS: <u>All Filters</u> <u>227.79</u> <u>Tenn Filter 54.00</u> |  |                         |  |                                              |  |
|                                                                  |  |                         |  |                                              |  |
|                                                                  |  |                         |  |                                              |  |
|                                                                  |  |                         |  |                                              |  |
|                                                                  |  |                         |  |                                              |  |

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |                                                                                                               |                                                                                                                                                                                                                                                                                   |                                             |                         |                 |                        |                          |                 |                                    |                          |                 |                      |                         |                |                        |                          |                |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------|-------------------------|-----------------|------------------------|--------------------------|-----------------|------------------------------------|--------------------------|-----------------|----------------------|-------------------------|----------------|------------------------|--------------------------|----------------|
| <b>EQUIPMENT INFORMATION</b><br>EQUIP. # <u>1005</u><br>MAKE <u>Cat</u><br>MODEL <u>D6R</u><br>SERIAL # _____<br>HOUR METER <u>2564 HRS</u><br>MILES _____                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | <b>EQUIPMENT DOWNTIME</b><br>HOURS _____ DAYS _____<br>REASON _____<br>PARTS _____ LABOR _____<br>OTHER _____ | <b>COMPONENT CODES</b><br>BASIC MACHINE    HYDRAULIC    ENGINE    IMPLEMENTS<br>POWER TRAIN    ELECTRIC    DRIVE TRAIN    UNEXPLAINED<br><b>COMPONENT LOCATION</b><br>FRONT    REAR    LEFT    RIGHT    UPPER    LOWER<br>OTHER _____                                             |                                             |                         |                 |                        |                          |                 |                                    |                          |                 |                      |                         |                |                        |                          |                |
| REASON FOR FAILURE:    BROKEN    WORN    ABUSE    LOOSE    SEIZED<br>OVERHEAT    PLANNED    CONTAM    LEAKING    NOISY    SCRATCH<br>SMOKES    SHORTED    VIBRATE    OTHER _____                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |                                                                                                               | DATE: <u>7-28-20</u> DATE COMPLETED <u>8-3-20</u><br>MECHANIC <u>Ben</u><br><table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:70%;">JOB NAME/LOCATION<br/><u>Cedar Crossings</u></td> <td style="width:30%;">JOB NUMBER</td> </tr> </table> | JOB NAME/LOCATION<br><u>Cedar Crossings</u> | JOB NUMBER              |                 |                        |                          |                 |                                    |                          |                 |                      |                         |                |                        |                          |                |
| JOB NAME/LOCATION<br><u>Cedar Crossings</u>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | JOB NUMBER                                                                                                    |                                                                                                                                                                                                                                                                                   |                                             |                         |                 |                        |                          |                 |                                    |                          |                 |                      |                         |                |                        |                          |                |
| PROBLEM: <u>Engine power loss</u>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                                                                                                               |                                                                                                                                                                                                                                                                                   |                                             |                         |                 |                        |                          |                 |                                    |                          |                 |                      |                         |                |                        |                          |                |
| REPAIRED: <u>replaced ambient and boost sensor</u><br><u>removed starter to fix leak had starter</u><br><u>rebuilt. Oil in starter Replaced fuel filters</u>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |                                                                                                               |                                                                                                                                                                                                                                                                                   |                                             |                         |                 |                        |                          |                 |                                    |                          |                 |                      |                         |                |                        |                          |                |
| <table style="width:100%;"> <tr> <td style="width:40%;">PARTS: <u>2 filters + cap</u></td> <td style="width:20%; text-align: right;"><u>73.<sup>24</sup></u></td> <td style="width:40%; text-align: right;"><u>Thompson</u></td> </tr> <tr> <td><u>Oil pres sensor</u></td> <td style="text-align: right;"><u>183.<sup>07</sup></u></td> <td style="text-align: right;"><u>Thompson</u></td> </tr> <tr> <td><u>Ambient &amp; boost sensors</u></td> <td style="text-align: right;"><u>381.<sup>80</sup></u></td> <td style="text-align: right;"><u>Thompson</u></td> </tr> <tr> <td><u>oil treatment</u></td> <td style="text-align: right;"><u>25.<sup>63</sup></u></td> <td style="text-align: right;"><u>Advance</u></td> </tr> <tr> <td><u>Starter rebuilt</u></td> <td style="text-align: right;"><u>185.<sup>48</sup></u></td> <td style="text-align: right;"><u>Crook's</u></td> </tr> </table> |                                                                                                               |                                                                                                                                                                                                                                                                                   | PARTS: <u>2 filters + cap</u>               | <u>73.<sup>24</sup></u> | <u>Thompson</u> | <u>Oil pres sensor</u> | <u>183.<sup>07</sup></u> | <u>Thompson</u> | <u>Ambient &amp; boost sensors</u> | <u>381.<sup>80</sup></u> | <u>Thompson</u> | <u>oil treatment</u> | <u>25.<sup>63</sup></u> | <u>Advance</u> | <u>Starter rebuilt</u> | <u>185.<sup>48</sup></u> | <u>Crook's</u> |
| PARTS: <u>2 filters + cap</u>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | <u>73.<sup>24</sup></u>                                                                                       | <u>Thompson</u>                                                                                                                                                                                                                                                                   |                                             |                         |                 |                        |                          |                 |                                    |                          |                 |                      |                         |                |                        |                          |                |
| <u>Oil pres sensor</u>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 | <u>183.<sup>07</sup></u>                                                                                      | <u>Thompson</u>                                                                                                                                                                                                                                                                   |                                             |                         |                 |                        |                          |                 |                                    |                          |                 |                      |                         |                |                        |                          |                |
| <u>Ambient &amp; boost sensors</u>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | <u>381.<sup>80</sup></u>                                                                                      | <u>Thompson</u>                                                                                                                                                                                                                                                                   |                                             |                         |                 |                        |                          |                 |                                    |                          |                 |                      |                         |                |                        |                          |                |
| <u>oil treatment</u>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | <u>25.<sup>63</sup></u>                                                                                       | <u>Advance</u>                                                                                                                                                                                                                                                                    |                                             |                         |                 |                        |                          |                 |                                    |                          |                 |                      |                         |                |                        |                          |                |
| <u>Starter rebuilt</u>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 | <u>185.<sup>48</sup></u>                                                                                      | <u>Crook's</u>                                                                                                                                                                                                                                                                    |                                             |                         |                 |                        |                          |                 |                                    |                          |                 |                      |                         |                |                        |                          |                |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION                                                                                                                     | EQUIPMENT DOWNTIME      | COMPONENT CODES                                                             |            |
|-------------------------------------------------------------------------------------------------------------------------------------------|-------------------------|-----------------------------------------------------------------------------|------------|
| EQUIP. # <u>1005</u>                                                                                                                      | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS                                   |            |
| MAKE <u>CAT</u>                                                                                                                           | REASON _____            | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED                                |            |
| MODEL <u>D6R</u>                                                                                                                          | PARTS _____ LABOR _____ | COMPONENT LOCATION                                                          |            |
| SERIAL # _____                                                                                                                            | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER                                           |            |
| HOUR METER _____                                                                                                                          |                         | OTHER _____                                                                 |            |
| MILES _____                                                                                                                               |                         |                                                                             |            |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED<br>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH<br>SMOKES SHORTED VIBRATE OTHER _____ |                         | DATE: <u>10-14-20</u> DATE COMPLETED <u>10-21-20</u><br>MECHANIC <u>ALL</u> |            |
|                                                                                                                                           |                         | JOB NAME/LOCATION<br><u>Shop</u>                                            | JOB NUMBER |
| PROBLEM: <u>both blade lift cylinders leaking</u>                                                                                         |                         |                                                                             |            |
| REPAIRED: <u>Packed both blade cylinders.</u><br><u>Removed RT rear idler filled with oil, new fill plug.</u>                             |                         |                                                                             |            |
| PARTS: <u>2- seal kits</u> <u>262.24</u> <u>Thompson</u><br><u>Plugs</u> <u>3.52</u> <u>Thompson</u>                                      |                         |                                                                             |            |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION                              |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                              |            |
|----------------------------------------------------|--|-------------------------|----------------------------------------------|------------|
| EQUIP. # <u>1006</u>                               |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |            |
| MAKE <u>Cat</u>                                    |  | REASON                  | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |            |
| MODEL <u>D6R</u>                                   |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                           |            |
| SERIAL # _____                                     |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER            |            |
| HOUR METER _____                                   |  |                         | OTHER _____                                  |            |
| MILES _____                                        |  |                         |                                              |            |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED |  |                         | DATE: _____ DATE COMPLETED <u>3-2-21</u>     |            |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH      |  |                         | MECHANIC <u>Ben</u>                          |            |
| SMOKES SHORTED VIBRATE OTHER _____                 |  |                         | JOB NAME/LOCATION<br><u>MI Juliet Sub.</u>   | JOB NUMBER |
| PROBLEM: <u>blown blade hose</u>                   |  |                         |                                              |            |
|                                                    |  |                         |                                              |            |
| REPAIRED: <u>replaced hose</u>                     |  |                         |                                              |            |
|                                                    |  |                         |                                              |            |
|                                                    |  |                         |                                              |            |
|                                                    |  |                         |                                              |            |
|                                                    |  |                         |                                              |            |
|                                                    |  |                         |                                              |            |
|                                                    |  |                         |                                              |            |
| PARTS: <u>hose</u> <u>132.81</u> <u>Thompson</u>   |  |                         |                                              |            |
|                                                    |  |                         |                                              |            |
|                                                    |  |                         |                                              |            |
|                                                    |  |                         |                                              |            |
|                                                    |  |                         |                                              |            |
|                                                    |  |                         |                                              |            |

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

| EQUIPMENT INFORMATION                              |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                                  |            |
|----------------------------------------------------|--|-------------------------|--------------------------------------------------|------------|
| EQUIP. # <u>1005</u>                               |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS        |            |
| MAKE <u>CAT</u>                                    |  | REASON _____            | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED     |            |
| MODEL <u>D6R</u>                                   |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                               |            |
| SERIAL # _____                                     |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER                |            |
| HOUR METER _____                                   |  |                         | OTHER _____                                      |            |
| MILES _____                                        |  |                         |                                                  |            |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED |  |                         | DATE: <u>3-9-21</u> DATE COMPLETED <u>3-9-21</u> |            |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH      |  |                         | MECHANIC _____                                   |            |
| SMOKES SHORTED VIBRATE OTHER _____                 |  |                         | JOB NAME/LOCATION<br><u>M/ Juliet Sub.</u>       | JOB NUMBER |
| PROBLEM: <u>blown hose</u>                         |  |                         |                                                  |            |
| REPAIRED: <u>replaced blown blade hose</u>         |  |                         |                                                  |            |
| PARTS: <u>hose</u> <u>138.90</u> <u>Thompson</u>   |  |                         |                                                  |            |

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION                                        |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                              |                               |
|--------------------------------------------------------------|--|-------------------------|----------------------------------------------|-------------------------------|
| EQUIP. # <u>1005</u>                                         |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |                               |
| MAKE <u>CAT</u>                                              |  | REASON _____            | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |                               |
| MODEL <u>D6R</u>                                             |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                           |                               |
| SERIAL # _____                                               |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER            |                               |
| HOOR METER _____                                             |  |                         | OTHER _____                                  |                               |
| MILES _____                                                  |  |                         |                                              |                               |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED           |  |                         | DATE <u>5-20-21</u>                          | DATE COMPLETED <u>5-21-21</u> |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH                |  |                         | MECHANIC _____                               |                               |
| SMOKES SHORTED VIBRATE OTHER _____                           |  |                         | JOB NAME/LOCATION <u>MT Juliet Sub</u>       | JOB NUMBER _____              |
| PROBLEM: <u>Idler cap came off.</u>                          |  |                         |                                              |                               |
| <u>RT cap bolt broken</u>                                    |  |                         |                                              |                               |
| REPAIRED: <u>replaced caps &amp; bolts</u>                   |  |                         |                                              |                               |
| PARTS: <u>Caps &amp; bolts</u> <u>372.25</u> <u>Thompson</u> |  |                         |                                              |                               |

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION                              |  | EQUIPMENT DOWNTIME                       | COMPONENT CODES                              |  |
|----------------------------------------------------|--|------------------------------------------|----------------------------------------------|--|
| EQUIP. # <u>1005</u>                               |  | HOURS _____ DAYS _____                   | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |  |
| MAKE <u>CAT</u>                                    |  | REASON _____                             | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |  |
| MODEL <u>D6R</u>                                   |  | PARTS _____ LABOR _____                  | COMPONENT LOCATION                           |  |
| SERIAL # _____                                     |  | OTHER _____                              | FRONT REAR LEFT RIGHT UPPER LOWER            |  |
| HOUR METER _____                                   |  |                                          | OTHER _____                                  |  |
| MILES _____                                        |  |                                          |                                              |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED |  | DATE: _____ DATE COMPLETE <u>8/10-21</u> |                                              |  |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH      |  | MECHANIC <u>Ben</u>                      |                                              |  |
| SMOKES SHORTED VIBRATE OTHER _____                 |  | JOB NAME/LOCATION <u>Sparta Pk</u>       | JOB NUMBER _____                             |  |
| PROBLEM: <u>blown Transmission Hose</u>            |  |                                          |                                              |  |
| REPAIRED: <u>replaced hose</u>                     |  |                                          |                                              |  |
| PARTS: <u>hose</u> <u>164.49</u> <u>Thompson</u>   |  |                                          |                                              |  |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION                                      |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                                     |            |
|------------------------------------------------------------|--|-------------------------|-----------------------------------------------------|------------|
| EQUIP. # <u>1005</u>                                       |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS           |            |
| MAKE <u>CAT</u>                                            |  | REASON _____            | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED        |            |
| MODEL <u>D6R</u>                                           |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                                  |            |
| SERIAL # _____                                             |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER                   |            |
| OUR METER <u>8K HRS</u>                                    |  |                         | OTHER _____                                         |            |
| MILES _____                                                |  |                         |                                                     |            |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED         |  |                         | DATE: <u>9-16-21</u> DATE COMPLETED <u>11-12-21</u> |            |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH              |  |                         | MECHANIC <u>All</u>                                 |            |
| SMOKES SHORTED VIBRATE OTHER _____                         |  |                         | JOB NAME/LOCATION<br><u>Shop</u>                    | JOB NUMBER |
| PROBLEM: <u>Service</u>                                    |  |                         |                                                     |            |
| REPAIRED: <u>serviced</u>                                  |  |                         |                                                     |            |
| PARTS: <u>All Filters</u> <u>262.65</u> <u>Teaw Filter</u> |  |                         |                                                     |            |

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

| EQUIPMENT INFORMATION                                                                                                                     |  | EQUIPMENT DOWNTIME                                                                                                             | COMPONENT CODES                              |  |
|-------------------------------------------------------------------------------------------------------------------------------------------|--|--------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|--|
| EQUIP. # <u>1005</u>                                                                                                                      |  | HOURS _____ DAYS _____                                                                                                         | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |  |
| MAKE <u>CAT</u>                                                                                                                           |  | REASON _____                                                                                                                   | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |  |
| MODEL <u>D6R</u>                                                                                                                          |  | PARTS _____ LABOR _____                                                                                                        | COMPONENT LOCATION                           |  |
| SERIAL # _____                                                                                                                            |  | OTHER _____                                                                                                                    | FRONT REAR LEFT RIGHT UPPER LOWER            |  |
| HOUR METER _____                                                                                                                          |  |                                                                                                                                | OTHER _____                                  |  |
| MILES _____                                                                                                                               |  |                                                                                                                                |                                              |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED<br>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH<br>SMOKES SHORTED VIBRATE OTHER _____ |  | DATE: _____ DATE COMPLETED <u>12-8-21</u><br>MECHANIC <u>Anthony</u><br>JOB NAME/LOCATION <u>West Trinity</u> JOB NUMBER _____ |                                              |  |
| PROBLEM: <u>hyd tank cap</u>                                                                                                              |  |                                                                                                                                |                                              |  |
| REPAIRED: <u>new cap</u>                                                                                                                  |  |                                                                                                                                |                                              |  |
| PARTS: <u>CAP</u> <u>104.24</u> <u>Thompson</u>                                                                                           |  |                                                                                                                                |                                              |  |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

| EQUIPMENT INFORMATION                                                                                                                     |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                                                        |            |
|-------------------------------------------------------------------------------------------------------------------------------------------|--|-------------------------|------------------------------------------------------------------------|------------|
| EQUIP. # <u>1005</u>                                                                                                                      |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS                              |            |
| MAKE <u>Cat</u>                                                                                                                           |  | REASON _____            | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED                           |            |
| MODEL <u>D6R</u>                                                                                                                          |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                                                     |            |
| SERIAL # _____                                                                                                                            |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER                                      |            |
| HOUR METER _____                                                                                                                          |  |                         | OTHER _____                                                            |            |
| MILES _____                                                                                                                               |  |                         |                                                                        |            |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED<br>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH<br>SMOKES SHORTED VIBRATE OTHER _____ |  |                         | DATE: <u>12-14-21</u> DATE COMPLETED <u>12-14-21</u><br>MECHANIC _____ |            |
|                                                                                                                                           |  |                         | JOB NAME/LOCATION<br><u>West Trinity</u>                               | JOB NUMBER |
| PROBLEM: <u>Fuel leak</u>                                                                                                                 |  |                         |                                                                        |            |
|                                                                                                                                           |  |                         |                                                                        |            |
| REPAIRED: <u>replaced fuel hoses at filters</u>                                                                                           |  |                         |                                                                        |            |
|                                                                                                                                           |  |                         |                                                                        |            |
|                                                                                                                                           |  |                         |                                                                        |            |
|                                                                                                                                           |  |                         |                                                                        |            |
|                                                                                                                                           |  |                         |                                                                        |            |
|                                                                                                                                           |  |                         |                                                                        |            |
|                                                                                                                                           |  |                         |                                                                        |            |
| PARTS: <u>Fuel Hoses</u> <u>142.00</u> <u>IR-6</u>                                                                                        |  |                         |                                                                        |            |
|                                                                                                                                           |  |                         |                                                                        |            |
|                                                                                                                                           |  |                         |                                                                        |            |
|                                                                                                                                           |  |                         |                                                                        |            |
|                                                                                                                                           |  |                         |                                                                        |            |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

| EQUIPMENT INFORMATION                                                                                                                     |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                                                         |            |
|-------------------------------------------------------------------------------------------------------------------------------------------|--|-------------------------|-------------------------------------------------------------------------|------------|
| EQUIP. # <u>1005</u>                                                                                                                      |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS                               |            |
| MAKE <u>CAT</u>                                                                                                                           |  | REASON _____            | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED                            |            |
| MODEL <u>D6R</u>                                                                                                                          |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                                                      |            |
| SERIAL # _____                                                                                                                            |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER                                       |            |
| HOUR METER _____                                                                                                                          |  |                         | OTHER _____                                                             |            |
| MILES _____                                                                                                                               |  |                         |                                                                         |            |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED<br>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH<br>SMOKES SHORTED VIBRATE OTHER _____ |  |                         | DATE: <u>3-3-22</u> DATE COMPLETED <u>9-3-22</u><br>MECHANIC <u>Ben</u> |            |
|                                                                                                                                           |  |                         | JOB NAME/LOCATION<br><u>West Trinity</u>                                | JOB NUMBER |
| PROBLEM: <u>won't start</u>                                                                                                               |  |                         |                                                                         |            |
|                                                                                                                                           |  |                         |                                                                         |            |
|                                                                                                                                           |  |                         |                                                                         |            |
| REPAIRED: <u>replaced bad starter</u>                                                                                                     |  |                         |                                                                         |            |
|                                                                                                                                           |  |                         |                                                                         |            |
|                                                                                                                                           |  |                         |                                                                         |            |
|                                                                                                                                           |  |                         |                                                                         |            |
|                                                                                                                                           |  |                         |                                                                         |            |
|                                                                                                                                           |  |                         |                                                                         |            |
|                                                                                                                                           |  |                         |                                                                         |            |
|                                                                                                                                           |  |                         |                                                                         |            |
| PARTS: <u>starter</u> <u>513.28</u> <u>A+B Electric</u>                                                                                   |  |                         |                                                                         |            |
|                                                                                                                                           |  |                         |                                                                         |            |
|                                                                                                                                           |  |                         |                                                                         |            |
|                                                                                                                                           |  |                         |                                                                         |            |
|                                                                                                                                           |  |                         |                                                                         |            |
|                                                                                                                                           |  |                         |                                                                         |            |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION                                       |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                              |                  |
|-------------------------------------------------------------|--|-------------------------|----------------------------------------------|------------------|
| EQUIP. # <u>1005</u>                                        |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |                  |
| MAKE <u>CAT</u>                                             |  | REASON _____            | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |                  |
| MODEL <u>D6R</u>                                            |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                           |                  |
| SERIAL # _____                                              |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER            |                  |
| HOUR METER <u>8260 HRS</u>                                  |  |                         | OTHER _____                                  |                  |
| MILES _____                                                 |  |                         |                                              |                  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED          |  |                         | DATE: _____ DATE COMPLETED <u>3-29-22</u>    |                  |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH               |  |                         | MECHANIC <u>Ben</u>                          |                  |
| SMOKES SHORTED VIBRATE OTHER _____                          |  |                         | JOB NAME/LOCATION <u>West Trinity</u>        | JOB NUMBER _____ |
| PROBLEM: <u>left blade end bit missing</u>                  |  |                         |                                              |                  |
| REPAIRED: <u>replaced end bit. Trim to match</u>            |  |                         |                                              |                  |
| PARTS: <u>bit &amp; bolts</u> <u>191.78</u> <u>Thompson</u> |  |                         |                                              |                  |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

|                                                    |  |                         |  |                                                             |  |
|----------------------------------------------------|--|-------------------------|--|-------------------------------------------------------------|--|
| EQUIPMENT INFORMATION                              |  | EQUIPMENT DOWNTIME      |  | COMPONENT CODES                                             |  |
| EQUIP. # <u>1006</u>                               |  | HOURS _____ DAYS _____  |  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS                   |  |
| MAKE <u>CAT</u>                                    |  | REASON _____            |  | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED                |  |
| MODEL <u>D6K2</u>                                  |  | PARTS _____ LABOR _____ |  | COMPONENT LOCATION                                          |  |
| SERIAL # _____                                     |  | OTHER _____             |  | FRONT REAR LEFT RIGHT UPPER LOWER                           |  |
| HOUR METER _____                                   |  |                         |  | OTHER _____                                                 |  |
| MILES _____                                        |  |                         |  |                                                             |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED |  |                         |  | DATE: _____ DATE COMPLETED <u>4-15-22</u>                   |  |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH      |  |                         |  | MECHANIC <u>Ben</u>                                         |  |
| SMOKES SHORTED VIBRATE OTHER _____                 |  |                         |  | JOB NAME/LOCATION <u>Carver Town Homes</u> JOB NUMBER _____ |  |
| PROBLEM: <u>blow tilt cylinder hose</u>            |  |                         |  |                                                             |  |
| REPAIRED: <u>replaced hose</u>                     |  |                         |  |                                                             |  |
| PARTS: <u>hose</u> <u>1917.24</u> <u>Thompson</u>  |  |                         |  |                                                             |  |

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

|                                                                                                                                           |  |                         |  |                                                         |  |
|-------------------------------------------------------------------------------------------------------------------------------------------|--|-------------------------|--|---------------------------------------------------------|--|
| EQUIPMENT INFORMATION                                                                                                                     |  | EQUIPMENT DOWNTIME      |  | COMPONENT CODES                                         |  |
| EQUIP. # <u>1005</u>                                                                                                                      |  | HOURS _____ DAYS _____  |  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS               |  |
| MAKE <u>CAT</u>                                                                                                                           |  | REASON _____            |  | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED            |  |
| MODEL <u>D6R</u>                                                                                                                          |  | PARTS _____ LABOR _____ |  | COMPONENT LOCATION                                      |  |
| SERIAL # _____                                                                                                                            |  | OTHER _____             |  | FRONT REAR LEFT RIGHT UPPER LOWER                       |  |
| HOUR METER _____                                                                                                                          |  |                         |  | OTHER _____                                             |  |
| MILES _____                                                                                                                               |  |                         |  |                                                         |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED<br>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH<br>SMOKES SHORTED VIBRATE OTHER _____ |  |                         |  | DATE: <u>4-5-22</u> DATE COMPLETED <u>5-25-22</u>       |  |
|                                                                                                                                           |  |                         |  | MECHANIC <u>Ben</u>                                     |  |
| PROBLEM: <u>bent track pad</u><br><u>bent stack</u>                                                                                       |  |                         |  | JOB NAME/LOCATION <u>Anthony Smyth</u> JOB NUMBER _____ |  |
| REPAIRED: <u>replaced stack &amp; Track pad.</u>                                                                                          |  |                         |  |                                                         |  |
| PARTS: <u>Pad &amp; bolts</u> <u>289.28</u> <u>Thompson</u>                                                                               |  |                         |  |                                                         |  |
| <u>freight credit</u>                                                                                                                     |  |                         |  |                                                         |  |
| <u>stack</u> <u>368.40</u> <u>Thompson</u>                                                                                                |  |                         |  |                                                         |  |

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

| EQUIPMENT INFORMATION                                                                                |  | EQUIPMENT DOWNTIME                             | COMPONENT CODES                              |  |
|------------------------------------------------------------------------------------------------------|--|------------------------------------------------|----------------------------------------------|--|
| EQUIP. # <u>1005</u>                                                                                 |  | HOURS _____ DAYS _____                         | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |  |
| MAKE <u>Cat</u>                                                                                      |  | REASON _____                                   | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |  |
| MODEL <u>D6R</u>                                                                                     |  | PARTS _____ LABOR _____                        | COMPONENT LOCATION                           |  |
| SERIAL # _____                                                                                       |  | OTHER _____                                    | FRONT REAR LEFT RIGHT UPPER LOWER            |  |
| HOUR METER <u>8,500 HRS</u>                                                                          |  |                                                | OTHER _____                                  |  |
| MILES _____                                                                                          |  |                                                |                                              |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED                                                   |  | DATE: _____ DATE COMPLETED <u>6-21-22</u>      |                                              |  |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH                                                        |  | MECHANIC <u>All</u>                            |                                              |  |
| SMOKES SHORTED VIBRATE OTHER _____                                                                   |  | JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____ |                                              |  |
| PROBLEM: <u>service, hose &amp; wash</u>                                                             |  |                                                |                                              |  |
| REPAIRED: <u>serviced, washed, replaced left blade cylinder hose</u><br><u>replaced intake hood.</u> |  |                                                |                                              |  |
| PARTS: <u>Filters</u> <u>162.40</u> <u>Tenn Filter</u>                                               |  |                                                |                                              |  |
| <u>Air &amp; Trans Filters</u> <u>153.13</u> <u>Thompson</u>                                         |  |                                                |                                              |  |
| <u>hose</u> <u>243.51</u> <u>Thompson</u>                                                            |  |                                                |                                              |  |
| <u>Hood</u> <u>158.14</u> <u>Thompson</u>                                                            |  |                                                |                                              |  |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION                                    |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                              |                  |
|----------------------------------------------------------|--|-------------------------|----------------------------------------------|------------------|
| EQUIP. # <u>1005</u>                                     |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |                  |
| MAKE <u>CAT</u>                                          |  | REASON _____            | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |                  |
| MODEL <u>D6R</u>                                         |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                           |                  |
| SERIAL # _____                                           |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER            |                  |
| HOUR METER _____                                         |  |                         | OTHER _____                                  |                  |
| MILES _____                                              |  |                         |                                              |                  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED       |  |                         | DATE: _____ DATE COMPLETED <u>7.7.22</u>     |                  |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH            |  |                         | MECHANIC <u>Ben</u>                          |                  |
| SMOKES SHORTED VIBRATE OTHER _____                       |  |                         | JOB NAME/LOCATION <u>Stone Crest</u>         | JOB NUMBER _____ |
| PROBLEM: <u>Engine temp not stable</u>                   |  |                         |                                              |                  |
| REPAIRED: <u>replaced thermostat</u>                     |  |                         |                                              |                  |
| PARTS: <u>Reg. Hose + Gaskets 184.02</u> <u>Thompson</u> |  |                         |                                              |                  |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION                                              |  | EQUIPMENT DOWNTIME                        | COMPONENT CODES                              |  |
|--------------------------------------------------------------------|--|-------------------------------------------|----------------------------------------------|--|
| EQUIP. # <u>1005</u>                                               |  | HOURS _____ DAYS _____                    | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |  |
| MAKE <u>CAT</u>                                                    |  | REASON _____                              | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |  |
| MODEL <u>D6R</u>                                                   |  | PARTS _____ LABOR _____                   | COMPONENT LOCATION                           |  |
| SERIAL # _____                                                     |  | OTHER _____                               | FRONT REAR LEFT RIGHT UPPER LOWER            |  |
| HOURLY METER _____                                                 |  |                                           | OTHER _____                                  |  |
| MILES _____                                                        |  |                                           |                                              |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED                 |  | DATE: _____ DATE COMPLETED <u>7-22-22</u> |                                              |  |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH                      |  | MECHANIC <u>Ben</u>                       |                                              |  |
| SMOKES SHORTED VIBRATE OTHER _____                                 |  | JOB NAME/LOCATION <u>Stone Trace</u>      |                                              |  |
| PROBLEM: <u>blown hose and damaged hose</u>                        |  | JOB NUMBER _____                          |                                              |  |
| REPAIRED: <u>replaced both hydraulic hoses from hard</u>           |  |                                           |                                              |  |
| <u>nose to blade</u>                                               |  |                                           |                                              |  |
| PARTS: <u>2 hoses</u> <u>664.62</u> <u>Nashville Rubber Gasket</u> |  |                                           |                                              |  |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION                                                |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                              |                  |
|----------------------------------------------------------------------|--|-------------------------|----------------------------------------------|------------------|
| EQUIP. # <u>1005</u>                                                 |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |                  |
| MAKE <u>CAT</u>                                                      |  | REASON _____            | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |                  |
| MODEL <u>DGR</u>                                                     |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                           |                  |
| SERIAL # _____                                                       |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER            |                  |
| HOUR METER _____                                                     |  |                         | OTHER _____                                  |                  |
| MILES _____                                                          |  |                         |                                              |                  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED                   |  |                         | DATE: _____ DATE COMPLETED <u>7-29-22</u>    |                  |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH                        |  |                         | MECHANIC <u>Anthony</u>                      |                  |
| SMOKES SHORTED VIBRATE OTHER _____                                   |  |                         | JOB NAME/LOCATION <u>Stone Trace</u>         | JOB NUMBER _____ |
| PROBLEM: <u>Muffle &amp; stack broken</u>                            |  |                         |                                              |                  |
|                                                                      |  |                         |                                              |                  |
|                                                                      |  |                         |                                              |                  |
| REPAIRED: <u>replaced muffle &amp; stack</u>                         |  |                         |                                              |                  |
|                                                                      |  |                         |                                              |                  |
|                                                                      |  |                         |                                              |                  |
|                                                                      |  |                         |                                              |                  |
|                                                                      |  |                         |                                              |                  |
|                                                                      |  |                         |                                              |                  |
| PARTS: <u>muffle, stack &amp; hardware</u> <u>1362.<sup>79</sup></u> |  |                         |                                              |                  |
|                                                                      |  |                         |                                              |                  |
|                                                                      |  |                         |                                              |                  |
|                                                                      |  |                         |                                              |                  |
|                                                                      |  |                         |                                              |                  |
|                                                                      |  |                         |                                              |                  |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

|                                                                                                                                           |  |                         |  |                                                                             |  |
|-------------------------------------------------------------------------------------------------------------------------------------------|--|-------------------------|--|-----------------------------------------------------------------------------|--|
| EQUIPMENT INFORMATION                                                                                                                     |  | EQUIPMENT DOWNTIME      |  | COMPONENT CODES                                                             |  |
| EQUIP. # <u>1006</u>                                                                                                                      |  | HOURS _____ DAYS _____  |  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS                                   |  |
| MAKE <u>CAT</u>                                                                                                                           |  | REASON _____            |  | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED                                |  |
| MODEL <u>D6K</u>                                                                                                                          |  | PARTS _____ LABOR _____ |  | COMPONENT LOCATION                                                          |  |
| SERIAL # _____                                                                                                                            |  | OTHER _____             |  | FRONT REAR LEFT RIGHT UPPER LOWER                                           |  |
| HOUR METER _____                                                                                                                          |  |                         |  | OTHER _____                                                                 |  |
| MILES _____                                                                                                                               |  |                         |  |                                                                             |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED<br>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH<br>SMOKES SHORTED VIBRATE OTHER _____ |  |                         |  | DATE: <u>9-26-22</u> , DATE COMPLETED <u>9-27-22</u><br>MECHANIC <u>Ben</u> |  |
|                                                                                                                                           |  |                         |  | JOB NAME/LOCATION<br><u>Limestone</u>                                       |  |
|                                                                                                                                           |  |                         |  | JOB NUMBER                                                                  |  |
| PROBLEM: <u>Quit moving</u>                                                                                                               |  |                         |  |                                                                             |  |
|                                                                                                                                           |  |                         |  |                                                                             |  |
|                                                                                                                                           |  |                         |  |                                                                             |  |
| REPAIRED: <u>replaced park brake + override solenoids</u><br><u>repaired wiring</u>                                                       |  |                         |  |                                                                             |  |
|                                                                                                                                           |  |                         |  |                                                                             |  |
|                                                                                                                                           |  |                         |  |                                                                             |  |
|                                                                                                                                           |  |                         |  |                                                                             |  |
|                                                                                                                                           |  |                         |  |                                                                             |  |
|                                                                                                                                           |  |                         |  |                                                                             |  |
| PARTS: <u>2 solenoids</u> <u>26P. 08</u> <u>Thompson</u><br><u>233-7126</u>                                                               |  |                         |  |                                                                             |  |
|                                                                                                                                           |  |                         |  |                                                                             |  |
|                                                                                                                                           |  |                         |  |                                                                             |  |
|                                                                                                                                           |  |                         |  |                                                                             |  |
|                                                                                                                                           |  |                         |  |                                                                             |  |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

### EQUIPMENT INFORMATION

EQUIP. # 1005  
 MAKE Cat  
 MODEL D6R  
 SERIAL # \_\_\_\_\_  
 HOUR METER 9K HRS  
 MILES \_\_\_\_\_

### EQUIPMENT DOWNTIME

HOURS \_\_\_\_\_ DAYS \_\_\_\_\_  
 REASON \_\_\_\_\_  
 PARTS \_\_\_\_\_ LABOR \_\_\_\_\_  
 OTHER \_\_\_\_\_

### COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS  
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

### COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER  
 OTHER \_\_\_\_\_

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED  
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH  
 SMOKES SHORTED VIBRATE OTHER \_\_\_\_\_

DATE 12-8-22 DATE COMPLETED 12-12-22

MECHANIC \_\_\_\_\_

JOB NAME/LOCATION

Hawthorne

JOB NUMBER

PROBLEM: Service

REPAIRED: serviced

PARTS:

Filters

290.02

Term filter sales

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

| EQUIPMENT INFORMATION                                                                                                                     |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                                                          |  |
|-------------------------------------------------------------------------------------------------------------------------------------------|--|-------------------------|--------------------------------------------------------------------------|--|
| EQUIP. # <u>1005</u>                                                                                                                      |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS                                |  |
| MAKE <u>CAT</u>                                                                                                                           |  | REASON _____            | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED                             |  |
| MODEL <u>D6R</u>                                                                                                                          |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                                                       |  |
| SERIAL # _____                                                                                                                            |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER                                        |  |
| HOUR METER _____                                                                                                                          |  |                         | OTHER _____                                                              |  |
| MILES _____                                                                                                                               |  |                         |                                                                          |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED<br>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH<br>SMOKES SHORTED VIBRATE OTHER _____ |  |                         | DATE <u>2-13-23</u> DATE COMPLETED <u>2-21-23</u><br>MECHANIC <u>Ben</u> |  |
| PROBLEM: <u>left end bit broken</u>                                                                                                       |  |                         | JOB NAME/LOCATION <u>Stone Trace</u> JOB NUMBER _____                    |  |
| REPAIRED: <u>replaced end bit</u>                                                                                                         |  |                         |                                                                          |  |
| PARTS: <u>End bits</u> <u>Hardware</u> <u>121, 26</u> <u>Pittman Equipment</u> <u>Thompson</u>                                            |  |                         |                                                                          |  |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION                                                                                                                                                        |  | EQUIPMENT DOWNTIME      |  | COMPONENT CODES                              |                               |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|-------------------------|--|----------------------------------------------|-------------------------------|
| EQUIP. # <u>1005</u>                                                                                                                                                         |  | HOURS _____ DAYS _____  |  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |                               |
| MAKE <u>Cat</u>                                                                                                                                                              |  | REASON _____            |  | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |                               |
| MODEL <u>D6R</u>                                                                                                                                                             |  | PARTS _____ LABOR _____ |  | COMPONENT LOCATION                           |                               |
| SERIAL # _____                                                                                                                                                               |  | OTHER _____             |  | FRONT REAR LEFT RIGHT UPPER LOWER            |                               |
| HOOR METER <u>9200 HRS.</u>                                                                                                                                                  |  |                         |  | OTHER _____                                  |                               |
| MILES _____                                                                                                                                                                  |  |                         |  |                                              |                               |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED                                                                                                                           |  |                         |  | DATE <u>3-1-23</u>                           | DATE COMPLETED <u>3-29-23</u> |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH                                                                                                                                |  |                         |  | MECHANIC <u>All</u>                          |                               |
| SMOKES SHORTED VIBRATE OTHER _____                                                                                                                                           |  |                         |  | JOB NAME/LOCATION <u>Shop</u>                | JOB NUMBER _____              |
| PROBLEM: <u>needs rails &amp; check over</u>                                                                                                                                 |  |                         |  |                                              |                               |
| REPAIRED: <u>replaced rails, pads, left front idler, left top roller &amp; sprocket segments. New left end bit. one transmission hose. replaced Equiline bar &amp; pins.</u> |  |                         |  |                                              |                               |
| PARTS: <u>2 strips &amp; hardware</u> <u>325.50</u> <u>Thompson</u>                                                                                                          |  |                         |  |                                              |                               |
| <u>Rails Idler &amp; Top Roller</u>                                                                                                                                          |  |                         |  |                                              |                               |
| <u>End bits &amp; Hardware</u> <u>190.00</u> <u>P. Hman</u>                                                                                                                  |  |                         |  |                                              |                               |
| <u>3 pins</u> <u>1046.71</u> <u>Thompson</u>                                                                                                                                 |  |                         |  |                                              |                               |
| <u>hose &amp; fitting</u> <u>51.92</u> <u>Thompson</u>                                                                                                                       |  |                         |  |                                              |                               |
| <u>hose</u> <u>54.43</u> <u>Nashville Rubber &amp; Gasket</u>                                                                                                                |  |                         |  |                                              |                               |

# TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

| EQUIPMENT INFORMATION                              |  | EQUIPMENT DOWNTIME      | COMPONENT CODES                                  |            |
|----------------------------------------------------|--|-------------------------|--------------------------------------------------|------------|
| EQUIP. # <u>1005</u>                               |  | HOURS _____ DAYS _____  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS        |            |
| MAKE <u>Cat</u>                                    |  | REASON _____            | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED     |            |
| MODEL <u>D6R</u>                                   |  | PARTS _____ LABOR _____ | COMPONENT LOCATION                               |            |
| SERIAL # _____                                     |  | OTHER _____             | FRONT REAR LEFT RIGHT UPPER LOWER                |            |
| HOUR METER _____                                   |  |                         | OTHER _____                                      |            |
| MILES _____                                        |  |                         |                                                  |            |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED |  |                         | DATE <u>5-3-23</u> DATE COMPLETED <u>5-17-23</u> |            |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH      |  |                         | MECHANIC <u>Ben</u>                              |            |
| SMOKES SHORTED VIBRATE OTHER _____                 |  |                         | JOB NAME/LOCATION<br><u>To Shop</u>              | JOB NUMBER |
| PROBLEM: <u>Radiator leak</u>                      |  |                         |                                                  |            |

REPAIRED: had cores cleaned and pressure tested.  
drilled out and replaced broken bolts. replaced  
missing shroud bolts

|                                       |                |                 |
|---------------------------------------|----------------|-----------------|
| PARTS <u>hoses, seals &amp; clamp</u> | <u>525.67</u>  | <u>Thompson</u> |
| <u>band &amp; molded hoses</u>        | <u>329.34</u>  | <u>Thompson</u> |
| <u>6 spacers</u>                      | <u>144.47</u>  | <u>Thompson</u> |
| <u>clean flush &amp; test cores</u>   | <u>2086.50</u> | <u>EC5</u>      |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

### EQUIPMENT INFORMATION

EQUIP # 1005

MAKE Cat

MODEL D6R

SERIAL # \_\_\_\_\_

HOUR METER 9,500 HRS

MILES \_\_\_\_\_

### EQUIPMENT DOWNTIME

HOURS \_\_\_\_\_ DAYS \_\_\_\_\_

REASON \_\_\_\_\_

PARTS \_\_\_\_\_ LABOR \_\_\_\_\_

OTHER \_\_\_\_\_

### COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

### COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER \_\_\_\_\_

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER \_\_\_\_\_

DATE 8-10-23 DATE COMPLETED 8-11-23

MECHANIC Anthony

JOB NAME/LOCATION

Anthem

JOB NUMBER

PROBLEM: Service

REPAIRED: serviced

PARTS: All Filter

354, 44

Thompson

# TEC

THORNE'S EXCAVATING COMPANY, LLC  
SINCE 1963

| EQUIPMENT INFORMATION                                                                                                                     |                                                                                              | EQUIPMENT DOWNTIME                 | COMPONENT CODES                              |  |
|-------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------|------------------------------------|----------------------------------------------|--|
| EQUIP. # <u>1005</u>                                                                                                                      | MAKE <u>D6K Cat</u><br>MODEL <u>D6K</u><br>SERIAL # _____<br>HOUR METER _____<br>MILES _____ | HOURS _____ DAYS _____             | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS    |  |
|                                                                                                                                           |                                                                                              | REASON _____                       | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED |  |
|                                                                                                                                           |                                                                                              | PARTS _____ LABOR _____            | COMPONENT LOCATION                           |  |
|                                                                                                                                           |                                                                                              | OTHER _____                        | FRONT REAR LEFT RIGHT UPPER LOWER            |  |
|                                                                                                                                           |                                                                                              |                                    | OTHER _____                                  |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED<br>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH<br>SMOKES SHORTED VIBRATE OTHER _____ |                                                                                              | DATE: <u>7-15-24</u>               | DATE COMPLETED <u>7-16-24</u>                |  |
|                                                                                                                                           |                                                                                              | MECHANIC <u>BUN</u>                |                                              |  |
|                                                                                                                                           |                                                                                              | JOB NAME/LOCATION <u>Sports pk</u> | JOB NUMBER _____                             |  |
| PROBLEM: <u>solenoid valve</u>                                                                                                            |                                                                                              |                                    |                                              |  |
| REPAIRED: <u>replaced no. 2 solenoid on Trans. valve body.</u>                                                                            |                                                                                              |                                    |                                              |  |
| PARTS: <u>valve solenoid 214-3114 388. OF Thompson</u>                                                                                    |                                                                                              |                                    |                                              |  |

# TEC

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

|                                                                   |  |                        |  |                                                      |  |
|-------------------------------------------------------------------|--|------------------------|--|------------------------------------------------------|--|
| EQUIPMENT INFORMATION                                             |  | EQUIPMENT DOWNTIME     |  | COMPONENT CODES                                      |  |
| EQUIP. # <u>1005</u>                                              |  | HOURS _____ DAYS _____ |  | BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS            |  |
| MAKE <u>Cat</u>                                                   |  | REASON                 |  | POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED         |  |
| MODEL <u>D6R</u>                                                  |  | PARTS LABOR            |  | COMPONENT LOCATION                                   |  |
| SERIAL # _____                                                    |  | OTHER _____            |  | FRONT REAR LEFT RIGHT UPPER LOWER                    |  |
| HOUR METER _____                                                  |  |                        |  | OTHER _____                                          |  |
| MILES _____                                                       |  |                        |  |                                                      |  |
| REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED                |  |                        |  | DATE: <u>4-21-25</u> DATE COMPLETED <u>4-21-25</u>   |  |
| OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH                     |  |                        |  | MECHANIC <u>Ben</u>                                  |  |
| SMOKES SHORTED VIBRATE OTHER _____                                |  |                        |  | JOB NAME/LOCATION <u>Hartsville</u> JOB NUMBER _____ |  |
| PROBLEM: <u>Throttle switch</u>                                   |  |                        |  |                                                      |  |
|                                                                   |  |                        |  |                                                      |  |
|                                                                   |  |                        |  |                                                      |  |
| REPAIRED: <u>replaced switch</u>                                  |  |                        |  |                                                      |  |
|                                                                   |  |                        |  |                                                      |  |
|                                                                   |  |                        |  |                                                      |  |
|                                                                   |  |                        |  |                                                      |  |
|                                                                   |  |                        |  |                                                      |  |
|                                                                   |  |                        |  |                                                      |  |
| PARTS: <u>switch &amp; actuator</u> <u>157.66</u> <u>Thompson</u> |  |                        |  |                                                      |  |
|                                                                   |  |                        |  |                                                      |  |
|                                                                   |  |                        |  |                                                      |  |
|                                                                   |  |                        |  |                                                      |  |
|                                                                   |  |                        |  |                                                      |  |