

EQUIPMENT
REPAIRS

DATE 8-30-05

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #600 Forklift

REPAIRS MADE fix brakes

HOURS WORKED _____

PARTS USED

seals \$ 3.87

EQUIPMENT
REPAIRS

year 1996

Lift King
model # LK 8M22
Serial # LT0087
MAST - 2222 A22

DATE 12-22-99

MILEAGE/HOURS 1749

EQUIPMENT REPAIRED Lift King Fork Lift

REPAIRS MADE Complete service, fuel filter,
oil filter, Hyr filter

HOURS WORKED _____

PARTS USED

Fuel Filter \$9.00

Oil filter 18.00
Hyr Filter

Curt Beeler - 20.00

Battery - \$110.00

Tire Repair - \$6.00

2 Studs + Nuts - \$21.00

RR Tire \$116.00

Knob - 14.00

Light Lens - 7.00

Intake Heater - 52.00

EQUIPMENT
REPAIRS

DATE 9-27-00

MILEAGE/HOURS 1801

EQUIPMENT REPAIRED Lift King

REPAIRS MADE Replace bearing in mast

11-7-00 Antifreeze - 25°

HOURS WORKED _____

PARTS USED

Bolts - \$2.27

Bearing - \$85.00

EQUIPMENT
REPAIRS

DATE

7/9/01

MILEAGE/HOURS

1840

EQUIPMENT REPAIRED

Roller

REPAIRS MADE

Notes in Log, Drain Oil

Check Tires, Check Tires.

HOURS WORKED

PARTS USED

EQUIPMENT
REPAIRS

DATE

8/20/11

MILEAGE/HOURS

EQUIPMENT REPAIRED

Tractor

REPAIRS MADE

Rebuilding Brake Cable, Repair Lower Link
Drill & Set Cable

HOURS WORKED

PARTS USED

Cable - \$50.00
W-END - \$32.00

EQUIPMENT
REPAIRS

DATE 9-19-02

MILEAGE/HOURS 1890

EQUIPMENT REPAIRED #2600 Forklift 8000

REPAIRS MADE check Antifreeze

HOURS WORKED _____

PARTS USED

check to -40°

EQUIPMENT
REPAIRS

DATE 2-23-06

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #600 Forklift

REPAIRS MADE replace 4-D battery

HOURS WORKED _____

PARTS USED

battery @ 122.31

EQUIPMENT
REPAIRS

DATE 5-17-07

MILEAGE/HOURS 2134

EQUIPMENT REPAIRED #800 Forklift

REPAIRS MADE Complete service

HOURS WORKED _____

PARTS USED

oil
oil filter
fuel filter
Hydro filter

EQUIPMENT
REPAIRS

DATE 11-20-07

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #600 Forklift

REPAIRS MADE Removed trans. shifter replaced
broken tower pin. Made up pin

HOURS WORKED _____

PARTS USED

EQUIPMENT
REPAIRS

DATE 2-6-08

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #600 Lift King

REPAIRS MADE replaced left rear tire

HOURS WORKED _____

PARTS USED

1-11C-16 Tire \$133.²⁹ Lebaron Tire

Tube - \$15.⁶⁴ Lebaron Tire



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 600
MAKE Lift King
MODEL Fork lift
SERIAL # _____
HOUR METER _____
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 7-29-09

MECHANIC JAMES

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: Check over

REPAIRED: replaced ground terminal at battery
greased

PARTS:

Grd Terminal 4.00 NAPA

EQUIPMENT
REPAIRS

DATE 9-17-09

MILEAGE/HOURS 2208

EQUIPMENT REPAIRED #600 Lift King 8000

REPAIRS MADE Serviced

HOURS WORKED _____

PARTS USED

Oil Filter \$15.91
Fuel Filter

NAPA



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>600</u>	REASON PARTS LABOR OTHER _____	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Litking</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>8000</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>12-2-11</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>service + Hyd. leak</u>				
<u>Fuel separator bowl broken</u>				
REPAIRED: <u>replaced o-rings in control valves</u>				
<u>serviced</u>				
<u>Fuel water separator bowl broken, replaced</u>				
PARTS: <u>Oil, fuel + Hyd. Filters</u> 28. ^{1/2} NAPA				
<u>control valve o-rings</u> 6. ³⁴ Signal Ind. products				
<u>separator bowl</u> 2.5 ^{1/2} Diesel Power Tools				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 600
MAKE Litt King
MODEL 8000
SERIAL # LT0087
HOUR METER _____
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 12-5-12

MECHANIC JAMES + Jeff

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: need Alternator belt

REPAIRED: replaced belt

PARTS: belt 25-9530 \$28.00 NAPA

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 600
MAKE Lifting
MODEL 8000
SERIAL # _____
HOUR METER _____
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 2-5-14

MECHANIC James

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: won't start

REPAIRED: replaced bad 4D battery
made up new positive cable

PARTS: 4D Battery \$152.94 Advance Auto Parts

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 600

MAKE Lift King

MODEL 8000

SERIAL # _____

HOURLY METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED _____

MECHANIC James & Steve

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: Service & check over

Broken brake cable

REPAIRED: Serviced & changed seals in control valve

spools

removed cable

PARTS: Filters

46.2L

NAPA

cable assembly

192.21

Fleetpride

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>600</u>	HOURS _____ DAYS _____ REASON PARTS LABOR OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Lit King</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>8000</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>10-21-15</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>James & Steven</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: <u>won't pull</u>				
REPAIRED: <u>sealed Transmission pump cleaned out</u>				
<u>Transmission and suction filter.</u>				
PARTS: <u>Seals & O-rings</u> <u>33.00</u> <u>Nashville Hydraulics</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 600

MAKE Litking

MODEL Fu0

SERIAL # Forklift

HOURLY METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 2-7-17

MECHANIC James + Steven

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: Need serviced

REPAIRED: Serviced

PARTS: All Filters 82,74 NAPA

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 2001
MAKE Lift King
MODEL Fork lift forer
SERIAL # _____
HOUR METER _____
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 10-11-17

MECHANIC James & Jken

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: bad battery

REPAIRED: replaced battery

PARTS: 40-XHD 199.43 Interstate battery

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 2001

MAKE Litton

MODEL 8500

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 11-27-18

MECHANIC All

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: needs serviced

REPAIRED: Serviced

PARTS: All Filters

65.00

Napa

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 2001

MAKE Hyd King

MODEL 8000

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 9-12-19 DATE COMPLETED 9-14-19

MECHANIC All

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: needs right rear tire

REPAIRED: replaced tire

PARTS: 11-5-16

164.⁰⁰

Gateway Tire

Mant

24.⁰⁰

CO-OP

Trans Filter

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 2001
 MAKE LIT KING
 MODEL 8000
 SERIAL # _____
 HOUR METER _____
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
 OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 11-5-22
 MECHANIC ALL

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: Service

REPAIRED: Serviced

PARTS: All Filters

68.30

NAPA

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>2001</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>L.H. King</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>8000</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____ DATE COMPLETED <u>5-15-23</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Shop</u>	
PROBLEM: <u>bad starter</u>				JOB NUMBER _____	
REPAIRED: <u>had starter rebuilt.</u>					
PARTS: <u>Rebuilt starter</u> <u>137.19</u> <u>Crooks</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 2001

MAKE Lit King

MODEL 8000

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 1-22-24

MECHANIC Bryan

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: won't start won't move

REPAIRED: replaced battery & Trans. Filter

PARTS: 2 filters

65.00

Napa

N. Gold 1759

battery

228.27

Advance