

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0809

MAKE Cat

MODEL 259D

SERIAL # _____

HOUR METER 2600 HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____

LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 3-27-23 DATE COMPLETED 4-12-23

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: Service

Shop

REPAIRED: Service

PARTS: Filters

Plate

Tracks

224.77

36.94

3,300

Thompson

Thompson

H & H Auto Parts

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0809
 MAKE CAT
 MODEL 259D
 SERIAL # _____
 HOUR METER 3K HRS
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: 1-10-24 DATE COMPLETED 1-23-24

MECHANIC A. thony

JOB NAME/LOCATION
West Trinity

JOB NUMBER

PROBLEM: Service

REPAIRED: Serviced

PARTS: Filters 229.33 Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0809

MAKE Cat

MODEL 259D

SERIAL # _____

HOURLY METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE 6-3-24 DATE COMPLETED 6-10-24

MECHANIC Ben

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: Travel sensor & wiring

REPAIRED: replaced bad travel sensor & plate handle

PARTS: Sensor

364.58

Thompson

handles

253.00

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0809
 MAKE Cat
 MODEL 259D
 SERIAL # _____
 HOUR METER 3246 HRS
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 8.8.24

MECHANIC all

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: needs tracks

REPAIRED: new tracks

PARTS: 2 Track

3000.00

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0809
 MAKE 259D CAT
 MODEL 259D
 SERIAL # _____
 HOUR METER _____
 MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
 REASON _____
 PARTS _____ LABOR _____
 OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
 POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
 OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
 SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 8-12-24

MECHANIC ALL

JOB NAME/LOCATION

JOB NUMBER

Shop

PROBLEM: lights on

REPAIRED: replaced pedal assembly
repaired bucket sensor wiring
new Tracks

PARTS:

pedal
Tracks

410.50
3000.00

Thompson
Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0809</u>	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MAKE <u>Cat</u>		COMPONENT LOCATION		
MODEL <u>259D</u>		FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____		
SERIAL # _____		HOUR METER _____ MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>10-29-24</u> DATE COMPLETED <u>10-30-24</u> MECHANIC <u>ALL</u>		
		JOB NAME/LOCATION <u>Shop</u>		JOB NUMBER
PROBLEM: <u>Armrests & Quick link levers</u>				
REPAIRED: <u>repaired levers and replaced Armrests.</u>				
PARTS: <u>Armrests & bolts</u> <u>441.54</u> <u>Thompson</u> <u>lock hardware</u> <u>110.41</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0809</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____ DATE COMPLETED <u>3-5-25</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION	
				<u>old shop</u>	
				JOB NUMBER	
PROBLEM: <u>blown travel hose.</u>					
REPAIRED: <u>hose replaced hose</u>					
PARTS: <u>hose</u> <u>340.43</u> <u>Thompson</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0809</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>3500 NKS</u>				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: <u>3-11-25</u> DATE COMPLETED <u>4-2-25</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____	
PROBLEM: <u>service, not charging</u>					
REPAIRED: <u>serviced, replaced alternator, repaired damaged wiring</u>					
PARTS: <u>Filters</u> <u>232.00</u> <u>Thompson</u>					
<u>Alternator</u> <u>269.93</u> <u>A+B Electric</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0809</u>	HOURS _____ DAYS _____	REASON _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>			POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>259D</u>	PARTS _____ LABOR _____	OTHER _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>5-10-25</u>	DATE COMPLETED <u>5-19-25</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>RT Travel motor bad</u>				

REPAIRED: replaced motor.

PARTS: Travel motor 4390.67 + Tax Thompson

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

IP. # 0809

MAKE CAT

MODEL 259D

SERIAL # _____

HOUR METER _____

WHEELS _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SWITCHES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 7-29-25

MECHANIC Bryan

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: sprockets worn out

REPAIRED: replaced sprockets

PARTS: 2 sprockets

880.12

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0809</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>259D</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____	OTHER _____			
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: _____ DATE COMPLETED <u>12-16-25</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>Ben</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>TCAT</u>	JOB NUMBER	
PROBLEM: <u>won't start bad battery</u>				
REPAIRED: <u>replaced battery</u>				
PARTS: <u>65 AGM</u> <u>241.98</u> <u>Advance Auto Parts</u>				