

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0008</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Chery</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>L2 2500HD</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES <u>600 mi</u>					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: <u>8-2-22</u> DATE COMPLETED _____	
				MECHANIC <u>ALI</u>	
				JOB NAME/LOCATION <u>Shop</u>	
				JOB NUMBER _____	
PROBLEM: <u>new Truck, set up for pipe crew</u>					
REPAIRED: <u>set up for pipe crew.</u>					
PARTS: <u>Safety light</u> <u>375.00</u> <u>Truckers lighthouse</u>					
<u>Decals</u> <u>38.00</u> <u>Advance Sign</u>					
<u>Inverter</u> <u>530.00</u> <u>Advance Auto Parts</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>0008</u>	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Chevy</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>22' 2500</u>		COMPONENT LOCATION	
SERIAL # <u>Amigo</u>		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
MILES <u>73K mi</u>			

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED	DATE: <u>9-17-25</u> DATE COMPLETED <u>9-17-25</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH	MECHANIC <u>Bryan</u>
SMOKE SHORTED VIBRATE OTHER _____	JOB NAME/LOCATION <u>10 Shop</u> JOB NUMBER _____

PROBLEM: needs brakes

REPAIRED: replaced all brake pads

PARTS: front and rear pads 127.⁸⁷ Advance Auto Parts

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # For #0008

MAKE Stihl

MODEL STS500I

SERIAL # _____

HOURLY METER _____

MILES New

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 9-13-22

MECHANIC LDC

JOB NAME/LOCATION

JOB NUMBER

Carve Your Holes

PROBLEM: NEW SAW STS500I

Ser no 192233318

REPAIRED: _____

PARTS: Stihl 500

1760.00

LDC

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0008</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Chevy</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>2500</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # <u>Amigo</u>		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____ DATE COMPLETED <u>10-6-22</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Eric</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION <u>Ante Town Homes</u> JOB NUMBER _____	
PROBLEM: <u>Extra shells</u>					
REPAIRED: <u>2 shells left front 1 shell RT front</u>					
PARTS: <u>3 shells 9 dividers 353.43 Reading Truck</u>					

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0008

MAKE Chevy

MODEL 22' 250WHD

SERIAL # Amigo

HOURLY METER _____

MILES 8k mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 10-19-22

MECHANIC Brian

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: Service

REPAIRED: Service

PARTS: Filters

TFJ

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0008

MAKE Chevy

MODEL 22' 250w

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 10-26-22 DATE COMPLETED 11-8-22

MECHANIC Brian & Anthony

JOB NAME/LOCATION Carver Town Homes JOB NUMBER _____

PROBLEM: broken driver mirror

REPAIRED: replaced driver mirror

PARTS: Minor 489.⁹⁹ Wilson County Motors

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0008

MAKE Cherry

MODEL 22' 2500WD

SERIAL # _____

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____

LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 4-24-23

MECHANIC Charlie's Tire

JOB NAME/LOCATION

Charlie's Tire

JOB NUMBER

PROBLEM: cut tire

REPAIRED: replaced tire

PARTS: 245/75-17

306.53

Charlie's Tire

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0008

MAKE Chug

MODEL 22' 2500HR

SERIAL # Marty

HOURLY METER _____

MILES 457K mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE 3-19-24

DATE COMPLETED _____

MECHANIC _____

JOB NAME/LOCATION

JOB NUMBER

PROBLEM: service, needs brakes

REPAIRED: serviced, replaced front pads & rotors & rear pads

PARTS: 448 pads & rotors 460.18 Advance Auto Parts

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0008

MAKE Chery

MODEL 22 2500

SERIAL # Marty

HOURLY METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS

LABOR

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 4-17-24

MECHANIC Marty

JOB NAME/LOCATION

JOB NUMBER

Advance

PROBLEM: bad battery

REPAIRED: replaced batteries in gallon

PARTS: 2-48H6RP

401.25

Advance

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0008

MAKE Chevy

MODEL 22' 2500

SERIAL # Marty

HOUR METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 4-30-24

MECHANIC Bryan

JOB NAME/LOCATION

900 Dickerson

JOB NUMBER

PROBLEM: cut Tire

REPAIRED: _____

PARTS: New Tire 290.07

Charlies Tire

LT 245/75-17

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 0008

MAKE Chery

MODEL 22' 2500

SERIAL # _____

HOUR METER _____

MILES 54K mi

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 6-24-24 DATE COMPLETED 9-23-24

MECHANIC All

JOB NAME/LOCATION

Shop

JOB NUMBER

PROBLEM: wrecked front end and RT front passenger door

REPAIRED: replaced all broken front end parts
Josh painted door.
replaced door

PARTS: Baffle, Deflector & brackets 918.⁸⁹ Wilson County Motors
bumper brackets & Right 3000⁰⁰ Chery parts.com.
RT door 961.⁵⁶ Wilson County Motors
Tires & Alignment \$1,252.⁴¹ Charlie's Tire

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES
IP. # <u>0008</u>	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Chevy</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>22 2500</u>		COMPONENT LOCATION	
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____		OTHER _____	
REMARKS _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>6-27-25</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Bryan</u>
SHOCKS SHORTED VIBRATE OTHER _____			JOB NAME / LOCATION <u>Wilson Judicial</u> JOB NUMBER _____
PROBLEM: <u>hit pothole</u>			

REPAIRED: replaced cracked rim.

PARTS: Rim + mount \$219.50 Charlie's Tire