

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1009
MAKE DPT CAT
MODEL DPT
SERIAL # _____
HOUR METER _____
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 11-4-22
MECHANIC Ben

JOB NAME/LOCATION Stone Trace JOB NUMBER _____

PROBLEM: DPF misfire

REPAIRED: replaced spark plug, wire & coil.

PARTS: plug wire & coil 368.19 Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1009

MAKE CAT

MODEL D8T

SERIAL # _____

HOUR METER 7050 HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 12-6-22 DATE COMPLETED 12-15-22

MECHANIC Anthony

JOB NAME/LOCATION
STONE TRACE

JOB NUMBER

PROBLEM: Service

REPAIRED: serviced

PARTS: All Filters

771.9L

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1009

MAKE CAT

MODEL D8T

SERIAL # _____

HOURLY METER _____

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 1-30-23

MECHANIC Ben

JOB NAME/LOCATION
Stone Trace

JOB NUMBER

PROBLEM: loose cutting edge

REPAIRED: replaced center cutting edge bolts.

PARTS: bolts & nuts 226.⁷⁸ Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1009

MAKE CAT

MODEL DFT

SERIAL # _____

HOUR METER 7,700 HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 4-14-23 DATE COMPLETED 4-15-23

MECHANIC All


JOB NAME/LOCATION
Stone Trace

JOB NUMBER

PROBLEM: service cross brace broken

REPAIRED: serviced, removed cross brace welded & installed

PARTS: Filters 891.69 Thompson



THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

Equip. # #1009

MAKE CAT

MODEL D8T

SERIAL # _____

HOUR METER 8100 HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 6-20-23 DATE COMPLETED _____

MECHANIC _____

JOB NAME/LOCATION Stone Trace

JOB NUMBER _____

PROBLEM: Service

REPAIRED: Service'd

PARTS: Filters 787.311 Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1009
MAKE CAT
MODEL D8T
SERIAL # _____
HOUR METER 6,200 HRS
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
COMPONENT LOCATION
FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: 4-19-22 DATE COMPLETED _____


MECHANIC All

JOB NAME/LOCATION _____ JOB NUMBER _____

PROBLEM: Bought from Wael's Equipment

REPAIRED: check over fully service

Drain plug	29. ¹⁰	Thompson
PARTS: Oil Filters	794. ⁴⁸	Thompson
Return Filters		Thompson
Cab inner & hyd	177. ¹⁸	Thompson
Drain plug	249. ⁷²	Thompson
End bits & Hardware	1108. ⁹⁵	Thompson
End bit	458. ⁴⁸	Thompson



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

<p>EQUIPMENT INFORMATION</p> <p>EQUIP. # <u>1009</u></p> <p>MAKE <u>CAT</u></p> <p>MODEL <u>DPT</u></p> <p>SERIAL # _____</p> <p>HR METER _____</p> <p>MILES _____</p>	<p>EQUIPMENT DOWNTIME</p> <p>HOURS _____ DAYS _____</p> <p>REASON _____</p> <p>PARTS _____ LABOR _____</p> <p>OTHER _____</p>	<p>COMPONENT CODES</p> <p>BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS</p> <p>POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED</p> <p>COMPONENT LOCATION</p> <p>FRONT REAR LEFT RIGHT UPPER LOWER</p> <p>OTHER _____</p>
------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

<p>REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED</p> <p>OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH</p> <p>SMOKES SHORTED VIBRATE OTHER _____</p>	<p>DATE: _____ DATE COMPLETED <u>5-3-22</u></p> <p>MECHANIC <u>James</u></p> <p>JOB NAME/LOCATION <u>Cover for Hones</u> JOB NUMBER _____</p>
----------------------------------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------

PROBLEM: Trans. Filter clogged light on
sent to Ward Trans. ok going to Run

REPAIRED: replaced pressure switch on filter housing.

PARTS <u>Switch & Filter</u>	<u>265.³¹</u>	<u>Thompson</u>
<u>All books</u>	<u>1,400.⁰⁰</u>	<u>Thompson</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES
EQUIP. # <u>1009</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MODEL <u>DFT</u>	PARTS _____ LABOR _____	COMPONENT LOCATION
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER
HOUR METER <u>6,500 HRS</u>		OTHER _____
MILES _____		
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE: _____ DATE COMPLETED <u>8-30-22</u> MECHANIC <u>Ben</u>
PROBLEM: <u>roller broken off</u>		JOB NAME/LOCATION <u>Stone Trace</u> JOB NUMBER _____
REPAIRED: <u>replaced Top roller mounts</u>		
PARTS: <u>lower mounts & bolts</u> <u>836.⁰⁵</u> <u>Thompson</u>		
<u>Caps & bolts</u> <u>117.³²</u> <u>Thompson</u>		

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1009

MAKE CAT

MODEL D8T

SERIAL # _____

HR METER 6600 HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON _____

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: 9-8-22 DATE COMPLETED 9-17-22

MECHANIC Anthony + Brian

JOB NAME/LOCATION
Stone Trace

JOB NUMBER

PROBLEM: Service

REPAIRED: Service

PARTS: All Filters

724.29

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1009
MAKE CAT
MODEL DBT
SERIAL # _____
HOUR METER _____
MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____
REASON _____
PARTS _____ LABOR _____
OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS
POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER
OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH
SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 10/22/22
MECHANIC Ben

JOB NAME/LOCATION
Stone Trace

JOB NUMBER

PROBLEM: blown hose

REPAIRED: replaced hyd. pump hose.

PARTS: Pump Hose 499.42 Nashville Rubber + Basket

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION

EQUIP. # 1009

MAKE CAT

MODEL D8T

SERIAL # _____

HOURLY METER 5500 HRS

MILES _____

EQUIPMENT DOWNTIME

HOURS _____ DAYS _____

REASON

PARTS _____ LABOR _____

OTHER _____

COMPONENT CODES

BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS

POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED

COMPONENT LOCATION

FRONT REAR LEFT RIGHT UPPER LOWER

OTHER _____

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED

OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH

SMOKES SHORTED VIBRATE OTHER _____

DATE: _____ DATE COMPLETED 3-19-24

MECHANIC Anthony

JOB NAME/LOCATION
High Park

JOB NUMBER

PROBLEM: Service

REPAIRED: Service

PARTS: Filters

643.97

Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>1009</u> MAKE <u>CAT</u> MODEL <u>D8T</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
--------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: _____ DATE COMPLETED <u>2-2-21</u> MECHANIC <u>Bryano</u> JOB NAME/LOCATION <u>High Park</u> JOB NUMBER _____
-------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------

PROBLEM: won't start

REPAIRED: replaced all four batteries

PARTS: 4-29H-VHD 579.26 Interstate Battery

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES				
EQUIP. # <u>1009</u>	MAKE <u>D&T CAT</u>	HOURS _____ DAYS _____	BASIC MACHINE	HYDRAULIC	ENGINE	IMPLEMENTS	
MODEL <u>D&T</u>		REASON	POWER TRAIN	ELECTRIC	DRIVE TRAIN	UNEXPLAINED	
SERIAL # _____	HOUR METER _____	PARTS _____ LABOR _____	COMPONENT LOCATION				
MILES _____		OTHER _____	FRONT	REAR	LEFT	RIGHT	UPPER
			OTHER _____				

REASON FOR FAILURE: <input type="checkbox"/> BROKEN <input type="checkbox"/> WORN <input type="checkbox"/> ABUSE <input type="checkbox"/> LOOSE <input type="checkbox"/> SEIZED	DATE: <u>7-9-24</u>	DATE COMPLETED: <u>8-2-24</u>
<input type="checkbox"/> OVERHEAT <input type="checkbox"/> PLANNED <input type="checkbox"/> CONTAM <input type="checkbox"/> LEAKING <input type="checkbox"/> NOISY <input type="checkbox"/> SCRATCH	MECHANIC <u>Ben</u>	
<input type="checkbox"/> SMOKES <input type="checkbox"/> SHORTED <input type="checkbox"/> VIBRATE <input type="checkbox"/> OTHER _____	JOB NAME/LOCATION <u>Quail Run</u>	JOB NUMBER

PROBLEM: no A/C comp clutch bad

REPAIRED: replaced comp. & Drier. Replaced solenoids & sensors on ARD system. repaired bad wire.

ARD coil, wire & plug	391. ⁰⁰	Thompson
PARTS: <u>Comp.</u>	1119. ¹⁴	Thompson
<u>Drier</u>	114. ³³	Thompson
<u>Maint Pilot solenoid valves</u>	402. ²⁰	Thompson
<u>sensor</u>	228. ⁶⁶	Thompson
<u>sensor</u>	263. ⁷³	Thompson
<u>solenoid</u>	304. ⁷⁴	Thompson
<u>connector</u>	211. ¹¹	Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1009</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED
MAKE <u>CAT</u>	REASON _____	COMPONENT LOCATION	
MODEL <u>D8T</u>	PARTS _____ LABOR _____	FRONT REAR LEFT RIGHT UPPER LOWER	OTHER _____
SERIAL # _____	OTHER _____	OTHER _____	
HOUR METER _____			
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>12-3-24</u>	DATE COMPLETED <u>12-5-24</u>
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>All</u>	
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____
PROBLEM: <u>needs welding on blade</u>			
REPAIRED: <u>removed side bits, welded blade, installed side bits.</u>			
PARTS: <u>Edge bolts, nuts & washers 774.88 Thompson</u>			

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>1009</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D8T</u>	PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>8850 HRS</u>		OTHER _____	
MILES _____			
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>1-24-25</u> DATE COMPLETED <u>1-24-25</u>	MECHANIC <u>Ben</u>
		JOB NAME/LOCATION <u>566 Station</u>	JOB NUMBER
PROBLEM: <u>Engine Oil in Transmission</u> <u>Will Follow up.</u>			
REPAIRED: <u>Drained transmission + Torque converter.</u> <u>Changed filters and filled with new oil.</u>			
PARTS: <u>Oil</u> <u>904.86</u> <u>Filters</u> <u>741.84</u>			

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	REASON	LABOR	OTHER	MILES
EQUIP. # 1009		HOURS _____	REASON _____	LABOR _____	OTHER _____	_____
MAKE CAT		DAYS _____	REASON _____	LABOR _____	OTHER _____	_____
MODEL D8T		_____	REASON _____	LABOR _____	OTHER _____	_____
SERIAL # _____		_____	REASON _____	LABOR _____	OTHER _____	_____
HOUR METER 91 HRS		_____	REASON _____	LABOR _____	OTHER _____	_____
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED						
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH						
SMOKES SHORTED VIBRATE OTHER _____						
JOB NAME/LOCATION Wilson Industrial		JOB NUMBER _____				
MECHANIC Ben & Brian		DATE 3-11-25				
DATE COMPLETED 3-13-25		DATE _____				
COMPONENT CODES		COMPONENT LOCATION				
BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		FRONT REAR LEFT RIGHT UPPER LOWER				
POWER TRAIN ELECTRICAL DRIVE TRAIN UNEXPLAINED		OTHER _____				

PROBLEM: Service

REPAIRED: Serviced

PARTS: Filters

453.60

Thompson

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES			
QUIP. # <u>1009</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS			
MAKE <u>CAT</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED			
MODEL <u>D8T</u>		PARTS _____ LABOR _____		COMPONENT LOCATION			
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER			
HOUR METER _____				OTHER _____			
MILES _____							

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE: _____ DATE COMPLETED <u>6-4-25</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Ben</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION	
				<u>TCAT</u>	
				JOB NUMBER	

PROBLEM: low fuel pressure.

REPAIRED: replaced fuel transfer pump and filters, forced regen.

PARTS	<u>2-1R0749 Filters</u>	<u>58.46</u>	<u>Thompson</u>
	<u>1-326-1643 Filter</u>	<u>59.53</u>	<u>Thompson</u>
	<u>coil</u>	<u>132.83</u>	<u>Thompson</u>
	<u>pump</u>	<u>1,300.00</u>	<u>Thompson</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION EQUIP. # <u>1009</u> MAKE <u>Cat</u> MODEL <u>D8T</u> SERIAL # _____ HOUR METER _____ MILES _____	EQUIPMENT DOWNTIME HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	COMPONENT CODES BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
--------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: <u>1-28-26</u> DATE COMPLETED <u>2-2-26</u> MECHANIC <u>Ben</u> JOB NAME/LOCATION <u>Shop</u> JOB NUMBER _____
-------------------------------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------

PROBLEM: belt + pulley

REPAIRED: replaced alternator, belt and one idler pulley.

PARTS: <u>belt</u>	<u>133.48</u>	<u>Thompson</u>
<u>pulley</u>	<u>184.81</u>	<u>Thompson</u>
<u>Alternator</u>	<u>997.44</u>	<u>A+B Auto Truck repair</u>

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>1009</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>D8T</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>9,500 HRS</u>				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE <u>2-26-26</u> DATE COMPLETED <u>3-3-26</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC <u>Ben + Bryan</u>	
SMOKES SHORTED VIBRATE OTHER _____				JOB NAME/LOCATION _____	
				JOB NUMBER _____	

PROBLEM: no regen ignition. A/C clutch failure.
Temp sensor faulty.

REPAIRED: replaced bad ARD, sensor and spark plug
replaced damaged A/C comp. hose and o-rings.
replaced bad coolant sensor. serviced

PARTS: ARD, sensor and spark plug 2536.23 Thompson
Comp. hose + o-ring 1245.02 Thompson
coolant sensor 581.83 Thompson
Filters 544.12 Thompson