

EQUIPMENT
REPAIRS

DATE 11-01-05

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #201 140H

REPAIRS MADE Pinion gear, All wear strips
park lift cylinder, centershift cylinder

HOURS WORKED _____

PARTS USED

5- wear strips \$194.26
1- Pinion 465.61

seals
rings) \$815.18
strips

shims \$111.62

shaft \$133.95

2- sleeves \$149.28

slide, hoist
seals for 2 cylinders,
sleeves \$374.07

EQUIPMENT
REPAIRS

Boat - 10/19/05

DATE 10/24/05

MILEAGE/HOURS 5621

EQUIPMENT REPAIRED 140 H #201

REPAIRS MADE Chk, Oil, Air Cleaner, Filter,
Adjust Valve, Hose, Install DEGs,

HOURS WORKED _____

PARTS USED

EQUIPMENT
REPAIRS

DATE 1-6-06

MILEAGE/HOURS 6424

EQUIPMENT REPAIRED 201 140H

REPAIRS MADE switch on slope tile

HOURS WORKED _____

PARTS USED

switch @ 42.07

EQUIPMENT
REPAIRS

DATE 7-10-06
7-12-06

MILEAGE/HOURS _____

EQUIPMENT REPAIRED 201 140H

REPAIRS MADE replace starter sol. switch
& muffler

HOURS WORKED _____

PARTS USED

starter switch @ 52.44
muffler @ 417.18

EQUIPMENT REPAIRS

DATE 11-17-06

MILEAGE HOURS 6000

EQUIPMENT REPAIRED #201 140H

REPAIRS MADE complete service
all filters & hour meter.

HOURS WORKED _____

PARTS USED

all filters) \$ 142.50
meter
437.61

EQUIPMENT
REPAIRS

DATE 4-4-07

MILEAGE/HOURS 684 HRS

EQUIPMENT REPAIRED Cat 140H 201

REPAIRS MADE Packed left black lift cylinder.

HOURS WORKED _____

PARTS USED

Packing kit #84.76
Thompson Machinery

EQUIPMENT
REPAIRS

DATE 5-17-07

Charged 6000 hr.

MILEAGE/HOURS 74

EQUIPMENT REPAIRED 201 140H

REPAIRS MADE Charge Air brake valve,

4-wiper blades, check A/C. charged Dyer
on A/C.

HOURS WORKED _____

PARTS USED

Air brake valve \$

Disconnects

Dyer \$

2-wiper blades

1-wiper blades \$ 22.25

Belts

Teeth \$ 623.34

EQUIPMENT
REPAIRS

DATE 12-10-07

MILEAGE/HOURS _____

EQUIPMENT REPAIRED ~~201~~ 201 140H

REPAIRS MADE Replace Hydro hose to Blade
slide

HOURS WORKED _____

PARTS USED

Napa
Hose \$40.36

EQUIPMENT
REPAIRS

DATE 8-12-08

MILEAGE/HOURS 589 HRS

EQUIPMENT REPAIRED #201 140H

REPAIRS MADE Replaced batteries

HOURS WORKED _____

PARTS USED

2 - GRP 31 8 200.00

Interstate Battery

EQUIPMENT
REPAIRS

DATE 8-27-08

MILEAGE/HOURS 589 HRS

EQUIPMENT REPAIRED #201 140H

REPAIRS MADE Serviced

HOURS WORKED _____

PARTS USED

Oil
Hyd. Filters 42.⁹⁹ Thompson
Trans.
Air & fuel in stock

EQUIPMENT
REPAIRS

DATE 12-4-08

MILEAGE/HOURS _____

EQUIPMENT REPAIRED #201 140H CAT

REPAIRS MADE replaced rear trans seal at
Access. pulley


HOURS WORKED _____

PARTS USED

Seal


14.32

Thompson



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>201</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>140H</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # <u>22K1863</u>		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>2-16-09</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
			<u>Owl Hollow</u>	
PROBLEM: <u>broken bolts on left circle cylinder mount shaft</u>				
REPAIRED: <u>drilled and tapped holes replaced bolts</u>				
PARTS: <u>2-bolts in stock</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>201</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>CAT</u>	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>140H</u>	PARTS LABOR	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER _____		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: <u>8-26-09</u> DATE COMPLETED _____		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>JAMES & DANIEL</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER _____	
PROBLEM: <u>best tie rods & Ends</u> <u>Water pump leaking. Oil in coolant</u>				
REPAIRED: <u>removed And sealed Water pump, Engine oil cooler</u> <u>and Trans oil cooler flushed system. Had coolers checked</u> <u>at thompson. They are O.K.</u> <u>Filled with new anti-freeze</u> <u>Washed & Greased</u> <u>straightened Tie rod and left tie rod end.</u>				
PARTS: <u>Hose</u> <u>31.56</u> <u>Thompson</u> <u>seals & Gaskets</u> <u>143.07</u> <u>Thompson</u> <u>Anti-freeze</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>201</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>140H</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOURLY METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>2-26-10</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
			<u>Heartside</u>	
PROBLEM: <u>won't start</u>				
REPAIRED: <u>had starter rebuilt</u>				
PARTS: <u>Rebuilt starter</u> <u>206.48</u> <u>Crooks</u>				




THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>201</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>140H</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOURLY METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>4-16-10</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Shop</u>	JOB NUMBER
PROBLEM: _____				
REPAIRED: <u>replaced broken clutch pedal spring</u>				
PARTS: <u>spring</u> <u>\$19.00</u> <u>Thompson</u>				




THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>201</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>140H</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>5-21-10</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION	JOB NUMBER
			<u>Shop</u>	
PROBLEM: <u>left rear tire flat</u>				
REPAIRED: <u>replaced O-ring on rim</u>				
PARTS: <u>O-ring in stock</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>201</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>140H</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>10-27-10</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>JAMES</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Hearthside</u>	JOB NUMBER
PROBLEM: <u>Anti-Freeze test too much water</u>				
REPAIRED: <u>DRAINED two gallon and added two gallon of pure anti-freeze</u>				
PARTS: <u>2-Gal Anti-Freeze 26.⁰⁰</u> <u>Advance Auto Parts</u>				



THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>201</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>140H</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER _____			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE: _____ DATE COMPLETED <u>7-6-11</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Rockvale</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>JAMES</u>	JOB NUMBER
PROBLEM: _____				
REPAIRED: <u>replaced fan belts</u>				
<u>replaced comp. gov. set Air pressure</u>				
PARTS: <u>V belt set, AC belt</u> <u>106.00</u> <u>Thompson</u>				
<u>Gov.</u> <u>13.54</u> <u>NAPA</u>				