

TEC

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0521</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>CAT</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>313F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>2900 HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>6-22-23</u> DATE COMPLETED _____		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC <u>All</u>		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>To Shop</u> JOB NUMBER _____		
PROBLEM: <u>check over</u>				
REPAIRED: <u>serviced</u>				
PARTS: <u>Filters</u> <u>543.10</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0521</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>313F</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER <u>3500 HRS</u>		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>10-31-23</u> DATE COMPLETED <u>11-2-23</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC _____		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Artem</u>	JOB NUMBER _____	
PROBLEM: <u>Service</u>				
REPAIRED: <u>Service</u>				
PARTS: <u>Filters</u> <u>385.23</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0521</u>		HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>313F</u>		PARTS _____ LABOR _____	COMPONENT LOCATION	
SERIAL # _____		OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>1K HRS</u>			OTHER _____	
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED			DATE <u>8-6-24</u> DATE COMPLETED <u>8-9-24</u>	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH			MECHANIC <u>Anthony</u>	
SMOKES SHORTED VIBRATE OTHER _____			JOB NAME/LOCATION <u>Arthen</u>	JOB NUMBER _____
PROBLEM: <u>Service</u>				
REPAIRED: <u>Service</u>				
PARTS: <u>filters</u> <u>270.14</u> <u>Thompson</u>				

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
EQUIP. # <u>0521</u>		HOURS _____ DAYS _____		BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE <u>Cat</u>		REASON _____		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL <u>313F</u>		PARTS _____ LABOR _____		COMPONENT LOCATION	
SERIAL # _____		OTHER _____		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER <u>9,500 HRS</u>				OTHER _____	
MILES _____					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____				DATE: <u>3-11-25</u> DATE COMPLETED <u>3-14-25</u> MECHANIC <u>Ben + Bryan</u>	
PROBLEM: <u>Service</u>				JOB NAME/LOCATION <u>Wilson Judicial</u> JOB NUMBER _____	
REPAIRED: <u>serviced</u> <u>replaced main pump hose</u>					
PARTS: <u>Filters</u> <u>255.70</u> <u>Thompson</u> <u>Hose</u> <u>344.72</u> <u>Thompson</u>					