



Vehicle History Report (BC) #: 62673811

Report Date: July 7, 2025 | 6:36 p.m. EDT

Report Status: Complete

2007 LEXUS RX 350

Sport utility vehicle | 6 Cylinders | Gas


2T2HK31U17C007521

Country of Assembly: Canada

Last Reported Odometer: 137,444 KM



Accident/Damage Records Found

Last Registered In:
British Columbia
(Rebuilt/Rebuildable)

15 Service Records Found



U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of July 07, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

2T2HK31U17C007521

Vehicle History Report (BC)



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2008 Nov 27	British Columbia, Canada	
	Estimate: REAR CENTER Estimate Date: n/a	\$1,170.23
	Claim: COLLISION REAR CENTER	\$1,001.40
2009 Mar 11	British Columbia, Canada	
	Estimate: RIGHT REAR CORNER Estimate Date: n/a	\$2,534.17
	Claim: COLLISION RIGHT REAR CORNER	\$2,119.53
2012 Apr 1	British Columbia, Canada	
	Estimate: RIGHT REAR CORNER Estimate Date: n/a	\$1,159.86
	Claim: COLLISION RIGHT REAR CORNER	\$980.91

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
2022 Nov 7	British Columbia, Canada	
	Glass Record	\$1,182.06



Registration

This vehicle has been registered in the following locations in **Canada** (listed oldest to newest):

- In the province of **British Columbia** with **Salvage** branding.
- In the province of **British Columbia** with **Rebuilt/Rebuildable** branding.












We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

This vehicle has been registered in the state of **Illinois** in the **United States**. No major title problems were reported.

We checked for: Salvage, Junk, Rebuilt, Fire, Flood, Hail and Lemon.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
 2006 Apr 10		Lexus of Orland Orland Park, Illinois, United States	Vehicle serviced <ul style="list-style-type: none"> Pre-delivery inspection completed
 2006 Aug 2		Lexus of Orland Orland Park, Illinois, United States	Vehicle serviced
 2006 Oct 6	5,068 MI	Lexus of Orland Orland Park, Illinois, United States	Vehicle serviced <ul style="list-style-type: none"> 5,000 mile service performed
 2007 Jan 31	10,464 MI	Lexus of Orland Orland Park, Illinois, United States	Vehicle serviced <ul style="list-style-type: none"> 10,000 mile service performed
 2007 Feb 12	10,503 MI	Lexus of Orland Orland Park, Illinois, United States	Vehicle serviced <ul style="list-style-type: none"> Vehicle washed/detailed
 2007 Mar 14	11,806 MI	Lexus of Orland Orland Park, Illinois, United States	Vehicle serviced <ul style="list-style-type: none"> Vehicle washed/detailed
 2007 Apr 13	12,154 MI	Lexus of Orland Orland Park, Illinois, United States	Vehicle serviced
 2007 Aug 13	18,650 MI	Lexus of Orland Orland Park, Illinois, United States	Vehicle serviced <ul style="list-style-type: none"> Recommended maintenance performed 15,000 mile service performed Air filter replaced Cabin air filter checked Wipers/washers serviced
 2007 Sep 7		Lexus of Orland Orland Park, Illinois, United States	Vehicle serviced <ul style="list-style-type: none"> Pre-delivery inspection completed
 2007 Nov 7		Lexus of Orland Orland Park, Illinois, United States	Vehicle serviced <ul style="list-style-type: none"> Vehicle washed/detailed
2012 Dec 4	50,612 KM	Derosa Automotive Services Ltd. North Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Brakes serviced Drivability/performance checked Parking brake adjusted Rear brake pads replaced Rear brake rotor(s) replaced Rear brake rotor(s) resurfaced
2013 Feb 1		Derosa Automotive Services Ltd. North Vancouver, British Columbia, Canada	Vehicle serviced
 2023 Mar 4	77,705 MI	Jiffy Lube Bellingham, Washington, United States	Vehicle serviced <ul style="list-style-type: none"> Air filter checked Antifreeze/coolant checked Brake fluid checked Drive belts checked Exterior lights checked Fluids checked Oil and filter changed Tire condition and pressure checked Wipers/washers checked
2023 Aug 13	131,646 KM	Jiffy Lube #1084 Surrey, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Recommended maintenance performed Cabin air filter replaced/cleaned Fluids checked Oil and filter changed

2T2HK31U17C007521

ODOMETER		SOURCE	DETAILS
			<ul style="list-style-type: none">Vehicle washed/detailed
2025 May 3	137,444 KM	Jiffy Lube #1084 Surrey, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none">Air filter checkedAir filter replacedCabin air filter replaced/cleanedFluids checkedFuel injection system flushed/servicedOil and filter changedPower steering checkedTransmission fluid changedVehicle washed/detailed



Open Recalls

Recall #: BLC | - Certain 2004 - Early 2007 Model Year RX 330, RX 350 and RX 400h Vehicles Driver's Side Floor Carpet Cover and Retention Clip Recall Date: 2011 Feb 24

Recall Description

Toyota is recalling certain Model Year 2004-2006 Highlander, Highlander Hybrid, and Model Year 2004-2007 Lexus RX330, RX350, and RX400h vehicles. If the forward retention clip used to secure the floor carpet cover, which is located in front of the center console, is not installed properly the cover may lean toward the accelerator pedal and interfere with the accelerator pedal arm.

Remedy

Dealers will replace the floor carpet cover with a newly designed one free or charge. Owners may contact Toyota at 1-800-331-4331.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact LEXUS or visit Lexus's website. (<https://www.lexus.ca/lexus/en/maintain-your-lexus/campaigns>)



Stolen Vehicle Check

☒ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2006 Apr 10		Lexus of Orland Orland Park, Illinois, United States	Service Record	Vehicle serviced
2006 Aug 2		Lexus of Orland Orland Park, Illinois, United States	Service Record	Vehicle serviced
2006 Aug 4		Motor Vehicle Dept. Illinois, United States	Previous use	Fleet

2T2HK31U17C007521

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
 2006 Sep 6		Motor Vehicle Dept. Illinois, United States	DMV Record Adjustment	Dealer took title of this vehicle while it was in inventory Title issued or updated Loan or lien reported First Owner Reported
 2006 Oct 6	5,068 MI	Lexus of Orland Orland Park, Illinois, United States	Service Record	Vehicle serviced
 2007 Jan 31	10,464 MI	Lexus of Orland Orland Park, Illinois, United States	Service Record	Vehicle serviced
 2007 Feb 12	10,503 MI	Lexus of Orland Orland Park, Illinois, United States	Service Record	Vehicle serviced
 2007 Mar 14	11,806 MI	Lexus of Orland Orland Park, Illinois, United States	Service Record	Vehicle serviced
 2007 Apr 13	12,154 MI	Lexus of Orland Orland Park, Illinois, United States	Service Record	Vehicle serviced
 2007 Aug 13	18,650 MI	Lexus of Orland Orland Park, Illinois, United States	Service Record	Vehicle serviced
 2007 Sep 7		Lexus of Orland Orland Park, Illinois, United States	Service Record	Vehicle serviced
 2007 Nov 7		Lexus of Orland Orland Park, Illinois, United States	Service Record	Vehicle serviced
2007 Nov 29		Motor Vehicle Dept. RV, Canada	Registration Records	Registered/Renewed
 2007 Nov 29		Motor Vehicle Dept. Canada	Import Record	<p>From: United States To: Canada</p> <p>This vehicle has been imported into Canada from the US. For more information than is set out below, please contact RIV (www.riv.ca).</p> <p>Imported Into Canada As: Normal Case/Dossier: J332890 Import Date: 11/29/2007 Entered Customs: 11/29/2007 Inspection Date: 12/12/2007</p>

2T2HK31U17C007521

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2007 Dec 11		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2008 Nov 27		Insurance Records British Columbia, Canada	COLLISION	REAR CENTER
2008 Nov 27		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a REAR CENTER
2008 Dec 13		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2009 Mar 11		Insurance Records British Columbia, Canada	COLLISION	RIGHT REAR CORNER
2009 Mar 11		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a RIGHT REAR CORNER
2009 Dec 12		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2010 Dec 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2011 Feb 24		LEXUS	Recall	Manufacturer Recall Issued Recall # BLC
2011 Dec 17		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2012 Apr 1		Insurance Records British Columbia, Canada	COLLISION	RIGHT REAR CORNER
2012 Apr 1		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a RIGHT REAR CORNER
2012 Dec 4	50,612 KM	Derosa Automotive Services Ltd. North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2012 Dec 15		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2013 Feb 1		Derosa Automotive Services Ltd. North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2013 Dec 14		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Dec 13		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2015 Dec 12		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed

2T2HK31U17C007521

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 Apr 9		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Apr 16		British Columbia, Canada	Registration Event	Salvage
2016 Apr 16		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	New Owner Reported
2016 Jun 18		British Columbia, Canada	Registration Event	Rebuilt/Rebuildable
2016 Jun 18		British Columbia, Canada	Registration Event	Salvage
2016 Jun 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	New Owner Reported
2017 May 13		British Columbia, Canada	Registration Event	Rebuilt/Rebuildable
2018 May 20		British Columbia, Canada	Registration Event	Rebuilt/Rebuildable
2019 May 12		British Columbia, Canada	Registration Event	Rebuilt/Rebuildable
2019 Aug 18		British Columbia, Canada	Registration Event	Rebuilt/Rebuildable
2020 Feb 10		British Columbia, Canada	Registration Event	Rebuilt/Rebuildable
2020 Feb 10		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	New Owner Reported
2021 Feb 10		British Columbia, Canada	Registration Event	Rebuilt/Rebuildable
2022 Feb 10		British Columbia, Canada	Registration Event	Rebuilt/Rebuildable
2022 Feb 10		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Vehicle color noted as black
2022 Nov 7		Insurance Records British Columbia, Canada	Glass Record	\$1,182.06
2023 Feb 10		British Columbia, Canada	Registration Event	Rebuilt/Rebuildable
2023 Feb 10		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Vehicle color noted as black
 2023 Mar 4	77,705 MI	Jiffy Lube Bellingham, Washington, United States	Service Record	Vehicle serviced

2T2HK31U17C007521