

Vehicle History Report + Lien Check (BC) #: 62901363 Report Date: July 16, 2025 | 2:15 p.m. EDT Report Status: Complete Reference:



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of July 16, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report + Lien Check (BC)

🔍 Lien Check

No lien records found in British Columbia.

How We Check for Liens

CARFAX Canada uses the VIN to search government records in each Canadian province and territory (excluding Northwest Territories) where the vehicle is currently registered and where it has historically been registered. We do not check for liens or title in any U.S. state.

If a VIN has no registration records in Canada, we cannot check for liens. We cannot guarantee lien checks on trailers, recreational vehicles or heavy-duty equipment.

Purchasers should always get written confirmation from vendors that there is no lien on the vehicle.

CARFAX Canada Canadian Lien Guarantee



If for some reason our lien check fails to accurately reflect the Canadian enforceable lien status of a vehicle at the time of the search, CARFAX Canada will reimburse the party that purchased the report and relied on it to their detriment to a

maximum amount of (1) the value of the car (2) the value of the lien (3) Five Thousand Dollars Canadian (\$5,000.00), whichever is lower.



У Accident/Damage

There are no accidents/damage reported on this vehicle.

Registration

This vehicle has been registered in the province of British Columbia in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

Service Records

DATE	ODOMETER	SOURCE	DETAILS
2023 Sep 1	120,574 KM	Kal Tire - Nanaimo Nanaimo, British Columbia, Canada	Vehicle serviced Maintenance reminder reset Oil and filter changed

Open Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact CHEVROLET or visit GM's website. (https://my.gm.ca/gm/en/recalls) Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2011 Sep 3		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued of Renewed First Owner Reported
2012 Jul 14		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2013 Jun 29		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Mar 17		CHEVROLET	Recall	Manufacturer Recall Issued Recall # N140082
014 Jun 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
015 Jul 4		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
016 Jul 2		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
017 Jul 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
018 Jun 10		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
019 Jun 23		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
020 Jul 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
020 Dec 29		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
021 Jun 6		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as white
022 May 29		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as white
023 Jun 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as white
023 Sep 1	120,574 KM	Kal Tire - Nanaimo Nanaimo, British Columbia, Canada	Service Record	Vehicle serviced
024 Jul 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial

ODOMETE	SOURCE	RECORD TYPE	DETAILS
2025 Jul 1	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as white
Questions? We'r Visit us at support.carfax.ca	e here to help.		

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track: vehicles sold by insurance companies as salvage

- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts .

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The The vehicle status may not represent the vehicle actuately for a number of reasons, including a written on vehicle that name to cert reported to the bioly vehicle registry of a vehicle with major damage that was repaired by ISBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage. Consumers are encouraged to read ICBC's full statement of limitations at http://apps.icbc.com/registration/vchr/Limitation.html. ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, onemeter readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracy.es or omissions. The merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including the second with any report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including the second so and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

© 2025 CARFAX Canada ULC. All rights reserved.



				_	Work Order Summary Report	ummary Ro	eport		Page: Report Date:
			Maintenance Code		Mechanic		Labor Hours 0	urs Labor Cost 0 \$0.00	Labor Total \$0.00
	Ň							Shop Fee WO Total	\$8.44 \$8.44
Vehicle Nurriber	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed	d
823	21940-899	EXPRESS VAN	N 06/05/2013	3150	21047		SERVICE	Shop Fec	\$0.00
)								WO Total	\$0.00
Vehicle Num ber	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed	đ
823	21940-899	EXPRESS VAN	N 06/04/2013	3155	21047		service	Shop Fee	\$0.00
								WO Total	\$0.00
Vehicle Num ^{be} r	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed	d
823	21940-899	EXPRESS VAN	10/24/2014	3702	34479		DPREVOST: SERVICE DUE (Work Order Request #3216) ************************************	(Work **********	
System	Level	Action	Maintenance Code		Mechanic		**************************************	RDUE urs Labor Cost	Labor Total
								0 \$0.00	\$0.00
	2							0 \$0.00	¢0.00
)								Ship Fee WO Total	\$0.00
Vehicle Number 823	Account 21940-899	Model Express van	Dat 04/14/2015	WO# 3967	Odometer 39763	Hourmeter	Work Requested DPREVOST: SERVICE OVERDUE (Work Order Request #4469)	Work Performed RDUE	6
System	Level	Action N	Maintenance Code		Mechanic		Laber Hours 0	urs Labor Cost	Labor Total \$0.00
								Shop Fee	\$0.00

					Work Order Summary Report	ummary Re	port				Page: Report Date:
	interio		1								
823		INIOUCI		WO#	Odometer	Howmeter	Work Requested			Work Performed	ed
823 System	21940-899 Level	EXPRESS VAN Action M	VAN 11/15/2011 Maintenance Code	2199	Mechanic		INSTALL WINDSHIELD	HELD Labor Hours		Labor Cost	Lahor Fotal
Glass		Install	Body		<			0		\$0.00	
System	Level	Action	Maintenance Code		Part Number	Description	3	Part Qty	Unit Cost	Part Cost	Part Total
Glass		Install	Body		✓ 93809	INVOICE (INVOICE CLEARVIEW GLASS	<u> </u>		\$312.31	\$312.31
										Shop Fee	
										WO Total	\$312.31
Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested		_	Work Performed	ē.
823 Svistori	21940-899	EXPRESS VAN	/AN 12/13/2011	2276	3751		INSTALL GPS				:
Electrical		ACIION	Maintenance Coue		Mechanic			Labor Hours		Labor Cost	Labor Total
		Install	Body		LUCAS, STEVE			دى		\$90.00	\$90,00
System	Level	Action	Maintenance Code		Part Number	Description	-	Part Qty	Unit Cost	Part Cost	Part Total
Electrical	_	Install	Body		K12	ZONAR GPS	Š	0	\$0.000	\$0.00	\$0.00
										Shop Fee	\$0.00
Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested			WO Total	\$90.00
823	21940-899	EXPRESS VAN		2543	8251		RWEBBER: SERVICI			WORK FEFIORMED	HA GI
System	Level	Action	aint	i	Mechanic		Order Request #1988)	8) 8)			
Total	Ι	Service	A Service		MASON, BILL		!	4		\$120.00	\$120.00
System	Level	Action	Maintenance Code		Part Number	Description		Part Qty Unit Cost	Unit Cost	Part Cost	Part Total
Total	I	Service	A Service		73040-5	BACKUP ALARM	LARM	_	\$30.400	\$30.40	\$46.16
Total	-	Service	A Service		5W30	ENGINE OIL	L DEXOS I	6	\$2.140	\$12.84	
Total	1	Service	A Service		P550794	FILTER OIL 819	.819	June	\$2.920	\$2.92	
										Shop Fee	\$0.00
										WO Total	\$166.16
Vehicle Number 823	Account 21940-899	Model EXPRESS VAN	Dat 11/19/2012	WO # 2905	Odometer 14297	Hourmeter	Work Requested DPREVOST: SERVICE DUE (Work	3 DUE (Wo		Work Performed	_
							•				

* Checkmark next to Part Number or Mechanic represents outsourced work.

				_	Work Order Summary Repor	ummary R	eport	Page: Report Date:
Vehicle Number	Account	Model	Dat	WO#	Otlometer	Hourmeter	Work Requested	
823	21940-899	EXPRESS VAN	06/10/2015	3970	39763		DPREVOST: SERVICE OVERDUE	tt vi k E vi joj nicu
System	Level	Action M:	Maintenance Code		Mechanic		(Work Order Request #4472) Labor Hours	Labor Cost Labor Total
							0	\$0.00 \$0.00
								Shop Fee \$0,00
Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed
823	21940-899	EXPRESS VAN	01/12/2016	4289	48568		service	
								Shop Fee\$0.00WO Total\$0.00
Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed
823	21940-899	EXPRESS VAN	06/07/2016	4498	54145		Order Beauset #4636)	
System	Level	Action Ma	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
							0	\$0.00 \$0.00
								Shop Fee \$0.00
								WO Total \$0.00
Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed
		PRESS VA	07/04/2017	4938	67909		DPREVOST: SERVICE DUE (Work Order Request #4723)	
oystelli	Level	Action Mai	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
							0	\$0,00 \$0,00
								Shop Fee \$0.00
								WO Total \$0.00
iele Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed
823	21940-899	EXPRESS VAN	07/12/2018	5366	82330		service	
								Shop Fee \$0.00
* Date is Release Date.								
" Uneckinark heat to j	Part Number of N	* Checkmark lisst to Part Number or Mechanic represents outsourced work.	Sourced work.					

*

Account Model Dat WO# 21940-899 EXPRESS VAN 01/07/2021 6225 r Account Model Dat 4024 21940-899 EXPRESS VAN 0421/2022 6837 r Account Model Dat WO# 21940-899 EXPRESS VAN 0421/2022 6837 Level Model EXPRESS VAN 0421/2022 6837 Level Action Maintenance Code 7399 Level Action Maintenance Code 7399 21940-899 EXPRESS VAN 09/05/2023 7826 Level Action Maintenance Code 7826 Account Model Naintenance Code YO#	d Work Performed Shop Fee WO Total WO Total WO Total WO Total Shop Fee WO Total Shop Fee WO Total Shop Fee WO Total I Labor Hours Labor Cost I Shop Fee Vork Performed Labor Cost Shop Fee Work Performed Shop Fee Shop Fee WO Total Sl,43 Shop Fee WO Total Sl,43 Sl,43 Shop Fee Shop Fee WO Total Sl,43 Shop Fee Shop Fee	Hourmeter Description SERVICE	Part Number KAL ORD 6821010 Odometer	WO#	Dat	Model		
I Account Model Dat WOW Odometer Hormeter Work Requested Service Servi	lequested Work Performed Shop Fee WO Total WO Total E DUE Work Performed E DUE Shop Fee Shop Fee WO Total SI WO Total SI New TIRES Labor Hours Labor Cost Labor Part Qty Unit Cost Part Cost SI,432.340 I \$1,432.340 \$1,432.340 I \$1,432.340 \$1,432.340 Shop Fee 3 WO Total SI,432.340 E FOR SERVICE ON SEPT. 7 Labor Hours Labor Cost Labor Cost I \$1,4 I \$1,22.380 \$122.38 Shop Fee \$122.3	Hourmeter Description SERVICE	Part Number KAL ORD 6821010				Account	Vehicle Number
I Account Mold Dat VOB Odometer Hourneter Work Requested Work Requested Work Requested Sup Fee 1 Account Model Dat WOB 6235 164396 Service Service Sup Fee Work Requested Sup Fee Work Requested Sup Fee Sup Fee Work Requested Sup Fee Work Requested Sup Fee Work Requested Sup Fee Sup Fee Work Requested Sup Fee Work Requested Sup Fee	lequested Vork Performed Shop Fee WO Total WO Total E DUE E DUE C NEW TIRES Labor Hours E FOR SERVICE ON SEPT. 7 Labor Hours I \$1,432.340 O Part Qty I \$1,2380 O Part Cost I \$1,2380 O Part Cost I \$1,2380 O Part Cost I \$1,2380 O Stop Fee I abor Cost I \$1,2380 O Stop Fee I abor Cost I \$1,2380 O Stop Fee I abor Cost I \$1,2380 O Stop Fee I \$1,2380	Hourmeter Description SERVICE	Part Number KAL ORD 6821010					
I Account Madel Dat Wolf Outoneter Intruncter Work Requested Service Service Service Service Service Service Stop Fee NOT Tala 1 21940-390 EXPRESS VAN 0.0072021 6225 0.04396 Intruncter Work Requested Service Service Service Stop Fee NOT Tala 1 21940-390 Model Dat WOB Odometer Hourneter Work Requested Vork Requested Service Stop Fee	lequested Work Performed equested Work Performed E DUE Shop Fee E DUE Shop Fee equested Work Performed E DUE Work Performed equested Work Performed Labor Hours Labor Cost Labor Part Qty Unit Cost Part Part Qty Unit Cost Shop Fee I \$1,432.340 \$1,432.340 \$1,432.340 E FOR SERVICE ON SEPT. 7 Shop Fee 1 Labor Hours Labor Cost Labor 0 \$0.00 \$1,432.340 \$1,432.340 E FOR SERVICE ON SEPT. 7 Shop Fee \$1,432.340 0 \$0.00 \$0.00 \$1,432.340 1 \$122.380 \$122.38	Hourmeter Description SERVICE	Part Number KAL ORD 6821010					
I Account Made Dat. WOH Coloneter Hourneter Service Servirot and	lequested Work Performed Shop Fee WO Total WO Total E DUE E DUE Genested Vork Performed Labor Hours E FOR SERVICE ON SEPT. 7 Labor Hours 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	ption	Part Number					
Account Model Drt WOrk Odometer Hommeter Work Requested Work Requested Work Requested Work Requested Work Requested Strong Fee Strong Fee </td <td>tequested Work Performed equested Work Performed E DUE Shop Fee E DUE Shop Fee WO Total Work Performed equested Work Performed equested Work Performed E DUE Shop Fee E DUE Shop Fee equested Work Performed I Shop T Cost Labor Part Qty Unit Cost Part Cost Part Part Qty Unit Cost Part Cost Shop Fee I SI,432.340 SI,432.34 Shop Fee Shop Fee E FOR SERVICE ON SEPT. 7 Work Performed Labor Hours Labor Cost Labor So.00 0 \$0.00 \$0.00 \$0.00</td> <td></td> <td></td> <td></td> <td>Maintenance Code</td> <td></td> <td>Level</td> <td>System</td>	tequested Work Performed equested Work Performed E DUE Shop Fee E DUE Shop Fee WO Total Work Performed equested Work Performed equested Work Performed E DUE Shop Fee E DUE Shop Fee equested Work Performed I Shop T Cost Labor Part Qty Unit Cost Part Cost Part Part Qty Unit Cost Part Cost Shop Fee I SI,432.340 SI,432.34 Shop Fee Shop Fee E FOR SERVICE ON SEPT. 7 Work Performed Labor Hours Labor Cost Labor So.00 0 \$0.00 \$0.00 \$0.00				Maintenance Code		Level	System
Account Model Dat WOR Odometer Hourmeter Service Work Requested Work Requested 1 Account Model Dat WOR 0,8072021 6225 0,04396 Service	lequested Work Performed Shop Fee WO Total WO Total E DUE Shop Fee Shop Fee WO Total SI WO Total SI WO Total SI WO Total SI Shop Fee Labor Hours Labor Cost Labor 0 Part Qty Unit Cost Part Cost Part 1 \$1,432.340 Shop Fee Shop Fee						×	
Account Model Dat WO# Odometer Hourmeter Service Servi	lequested Work Performed Shop Fee WO Total E DUE Shop Fee E DUE Shop Fee MO Total Shop Fee WO Total Shop Fee WO Total SI Abor Hours Labor Cost Labor 0 S0.00 Part Cost Part Cost I SI,432.340 S1,432.340 S1,432.340 S1,432.340 S1,432.34 FOR SERVICE ON SEPT. 7		Mechanic		Maintenance Code		Level	System
I Account Madel Dat WO# Odometer Hourneter Service Work Requested Store Fer	d Work Performed Shop Fee WO Total WO Total WO Total Shop Fee WO Total I TRES Labor Hours Labor Cost I S1,432.340 Shop Fee Shop Fee WO Total Shop Fee WO Total Shop Fee WO Total Shop Fee Shop Fee WO Total Shop Fee Shop Fee Shop Fee WOrk Performed		120574	7826	N 09/05/2023	PRESS VA	21940-899	823
Account Model Dat WO# Odometer Hourmeter Work Requested work Requested Work Performed 21940-899 EXPRESS VAN 0/07/2021 625 104396 Bat Work Nodel Stop Fee Work Performed Account Model Dat WO# Odometer Hourmeter Work Requested Work Performed 1940-899 EXPRESS VAN 04/07/2021 637 111843 SERVICE DUE Service Stop Fee 21940-899 EXPRESS VAN 04/21/2022 637 111843 Service Work Requested Work Performed 21940-899 EXPRESS VAN 04/21/2023 7399 111843 Service Work Requested Work Performed 21940-899 EXPRESS VAN 0825/2023 7399 Ntchanic INSTALL NEW TIRES Work Performed 21940-899 Express VAN 0825/2023 7399 Michanic Norter Hourmeter Work Requested Work Performed 21940-899 Express VAN 0825/2023 7399 Michanic Norter Hourmeter Nort Requested Stop Fee <td>Work Performed Shop Fee WO Total Work Performed Shop Fee WO Total SI Work Performed Vor Hours D Part Qty Unit Cost I \$1,432.340 Shop Fee Shop Fee WO Total SI,432.34</td> <td></td> <td>Odometer</td> <td>WO#</td> <td></td> <td>Model</td> <td>Account</td> <td>Vehicle Number</td>	Work Performed Shop Fee WO Total Work Performed Shop Fee WO Total SI Work Performed Vor Hours D Part Qty Unit Cost I \$1,432.340 Shop Fee Shop Fee WO Total SI,432.34		Odometer	WO#		Model	Account	Vehicle Number
Acount Model Dat WO# Odometer Hommeter Service Service Stop Fee 21940-899 EXPRESS VAN 0.107/2021 6225 104396 Service Stop Fee Work Requested Stop Fee Work Performed Account Model Dat WO# Odometer Hommeter Work Requested Work Performed Stop Fee Work Performed 21940-899 EXPRESS VAN 0.4/21/2022 6837 111843 Work Requested Work Requested Work Performed 21940-899 EXPRESS VAN 0.4/21/2022 6837 111843 SERVICE DUE SINo Fee SINo Fee 21940-899 EXPRESS VAN 0.4/21/2022 6837 111843 SERVICE DUE SINo Fee SINo	Work Performed Shop Fee WO Total Work Performed Shop Fee WO Total SI Work Performed or Hours Labor Cost Labor 0 \$0.00 Part Qty Unit Cost Part Cost I \$1,432.340 \$1,432.34 Shop Fee							
Account Model Dat WO# Odometer Hourmeter Work Requested Work Performed 21940-899 EXPRESS VAN 01/07/2021 625 104396 Service Service Shop Fee Account Model Dat WO# Godometer Hourmeter Work Requested Work Performed Account Model Dat WO# Godometer Hourmeter Work Requested Work Performed 21940-899 EXPRESS VAN 04/21/2022 6337 111843 Work Requested Work Requested Work Performed 21940-899 EXPRESS VAN 04/21/2022 6337 111843 Work Requested Work Requested Service Shop Fee 21940-899 EXPRESS VAN 04/21/2022 6337 111843 Work Requested Work Requested Service Shop Fee S	Work Performed Shop Fee WO Total Work Performed Shop Fee Shop Fee Shop Fee Work Performed Shop Fee Work Performed Vork Performed Vork Performed Work Performed I \$1,432.340							
Account Model Dat WO# Colonater Hourmeter Work Requested Service Service Service Service Stop Fee Model Model Dat WO# Colonater Hourmeter Service Service Stop Fee	Work Performed Shop Fee WO Total Work Performed Shop Fee WO Total SI Work Performed Work Performed 0 S0.00 2000		CEDAR TIRE INV				-	
Account Model Dat WO# Odometer Hourmeter Work Requested Work Requested Work Performed 21940-899 EXPRESS VAN 01/07/2021 6225 104396 Work Requested Work Requested Work Performed Account Model Dat WO# Odometer Hourmeter Work Requested Work Performed 21940-899 EXPRESS VAN 04/21/2022 6837 111843 Work Requested Work Requested Work Performed 21940-899 EXPRESS VAN 04/21/2022 6837 111843 Work Requested Work Requested Work Performed 21940-899 EXPRESS VAN 04/21/2022 6837 111843 Work Requested Work Requested Work Performed 21940-899 EXPRESS VAN 08/25/2023 7399 116694 Hourmeter Mork Requested Work Performed 21940-899 EXPRESS VAN 08/25/2023 7399 116694 Hourmeter Mork Interformed Iabor Goat Labor Coat Labor Goat Labor Coat Labor	Work Performed Shop Fee WO Total Work Performed Shop Fee WO Total SI Work Performed Labor Cost Labor 0 \$0.00	Description	Part Number		Maintenance Code	Action	Level	System
Account Model Dat WO# Odometer Hourmeter Work Requested Work Requested Work Requested Work Performed 21940-899 EXPRESS VAN 01/07/2021 6225 104396 Work Requested Work Requested Work Performed Account Model Dat WO# Odometer Hourmeter Work Requested Service Sinop Fee Work Performed 21940-899 Model Dat WO# Odometer Hourmeter Service DUE	Work Performed Shop Fee WO Total Work Performed Shop Fee WO Total SI Work Performed Labor Cost Labor				2	•	-	
Acount Model Dat WO# Odometer Hourmeter Work Requested Work Requested Work Requested 21940-899 EXPRESS VAN 01/07/2021 6225 104396 Hourmeter Work Requested Service Shop Fee WO Total Acount Model Dat VO# Odometer Hourmeter Work Requested Service Shop Fee WO Total Acount Model Dat VO# Odometer Hourmeter Work Requested Service DUE Shop Fee <	Work Performed Shop Fee WO Total Work Performed Shop Fee WO Total SI		Mechanic		Maintenance Code	Action	Level	System
Acount Model Dat WO# Odometer Hourmeter Work Requested Work Requested Work Performed 21940-899 EXPRESS VAN 01/07/2021 6225 104396 Bat Work Requested Work Requested Work Requested Shop Fee WO Total Account Model Dat WO# Odometer Hourmeter Work Requested Work Requested Work Performed Account Model Dat WO# Odometer Hourmeter Work Requested Work Performed 21940-899 EXPRESS VAN 04/21/2022 6837 111843 SERVICE DUE Shop Fee Shop Fee Shop Fee Shop Fee Model Shop Fee Shop Fee <t< td=""><td>I Work Performed Shop Fee WO Total Work Performed Shop Fee WO Total SI</td><td>INST/</td><td>116694</td><td></td><td>AN 08/25/2023</td><td>EXPRESS VA</td><td>21940-899</td><td>823</td></t<>	I Work Performed Shop Fee WO Total Work Performed Shop Fee WO Total SI	INST/	116694		AN 08/25/2023	EXPRESS VA	21940-899	823
Acount Model Dat WO# Odometer Hourmeter Work Requested Work Requested 21940-899 EXPRESS VAN 01/07/2021 622.5 104396 Work Barrice Stop Fee 21940-899 Model Dat VO# Odometer Hourmeter Work Requested Work Performed 21940-899 EXPRESS VAN 01/07/2021 623 104396 Work Stop Fee Acount Model Dat WO# Odometer Hourmeter Work Requested Stop Fee 21940-899 EXPRESS VAN 04/21/2022 6837 111843 SERVICE DUE SInop Fee 21940-899 EXPRESS VAN 04/21/2022 6837 111843 Work Requested Service DUE VOT total WOT total Sinop Fee Sinop Fee Sinop Fee Sinop Fee	ed Work Performed Shop Fee WO Total ed Work Performed Shop Fee WO Total SI		Odometer	WO#	Dat	Model	Account	Vehicle Number
Account Model Dat WO# Odometer Hourmeter Work Requested Work Requested 21940-899 EXPRESS VAN 01/07/2021 6225 104396 Work Requested Work Requested Work Requested 21940-899 EXPRESS VAN 01/07/2021 6225 104396 Service Shop Fee 21940-899 EXPRESS VAN 01/07/2021 6837 111843 SERVICE DUE Shop Fee 21940-899 EXPRESS VAN 04/21/2022 6837 111843 SERVICE DUE Song Fee 21940-899 EXPRESS VAN 04/21/2022 6837 111843 Service Song Fee	ed Work Performed Shop Fee WO Total d Work Performed Shop Fee							
Account Model Dat WO# Odometer Hourmeter Work Requested Work Reformed 21940-899 EXPRESS VAN 01/07/2021 6225 104396 Work Requested Work Reformed Account Model 01/07/2021 6225 104396 Service Shop Fee 21940-899 EXPRESS VAN 01/07/2021 6225 104396 Work Requested Work Reformed Account Model UV 0# Odometer Hourmeter Work Requested Work Requested 21940-899 EXPRESS VAN 04/21/2022 6837 111843 SERVICE DUE Work Requested	ed Work Performed Shop Fee WO Total d Work Performed							
Acount Model Dat WO# Odometer Hourmeter Work Requested Work Performed 21940-899 EXPRESS VAN 01/07/2021 6225 104396 service Shop Fee Acount Model Dat VO# Odometer Hourmeter Work Requested Work Performed Acount Model Dat VO# Odometer Hourmeter Work Requested Shop Fee Model Dat WO# Odometer Hourmeter Work Requested Work Performed	Work Performed Shop Fee WO Total Work Performed	SERV	111843	6837		EXPRESS V/	21940-899	823
Account Model Dat WO# Odometer Hourmeter Work Requested Work Reformed 21940-899 EXPRESS VAN 01/07/2821 6225 104396 service Shop Fee WO Total WO Total WO Total WO Total WO Total	Requested Work Performed Shop Fee WO Total		Odometer	WO#	Dat	Model		Vehicle Number
Account Model Dat WO# Odometer Hourmeter Work Requested Work Performed 21940-899 EXPRESS VAN 01/07/2021 6225 104396 service Shop Fee	Requested Work Performed Shop Fee							
Account Model Dat WO# Odometer Hourmeter Work Requested Work Performed 21940-899 EXPRESS VAN 01/07/2021 6225 104396 service	Requested							
Account Model Dat WO# Odometer Hourmeter Work Requested Work Performed		servic	104396	6225		EXPRESS V.	21940-899	823
WO Total			Odometer	WO#	Dat	Model		Vehicle Number
work Order Summary Keport		ummary Keport	work Order s					

* Checkmark next to Part Number or Mechanic represents outsourced work.

	WO Total									
UT Shon Fre	Ē	, AND FILL O	DECOMISSION UNIT, AND FILL OUT FORM			9554	06/25/2025	EXPRESS VAN	21940-899	620
Work Performed			Work Requested	Hourmeter	Odometer	WO#		Model	Account	Vehicle Nurmber
WO Total \$166.65	1									
Shop Fee										
\$9.450 \$9.45	59	1		FILTER	B7449				_	
\$6,200 \$37.20	€9	6		engine oil	5W20					
			port	ummary Re	Work Order Summary Report	~				

Report Total

\$4,307.62

* Checkmark next to Part Number or Mechanic represents outsourced work.

* Date is Release Date.