

2006 THOMAS SCHOOL BUS

Bus school | 4 Cylinders | Diesel

1T7YU4A2X61269384

Country of Assembly: United States

Last Reported Odometer: n/a

LIEN CHECK



No Lien Records Found



No Accident/Damage Records Found



Last Registered In:
British Columbia (Normal)



0 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of July 17, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report + Lien Check (BC)

Lien Check

✓ No lien records found in **British Columbia**.

How We Check for Liens

CARFAX Canada uses the VIN to search government records in each Canadian province and territory (excluding Northwest Territories) where the vehicle is currently registered and where it has historically been registered. We do not check for liens or title in any U.S. state.

If a VIN has no registration records in Canada, we cannot check for liens. We cannot guarantee lien checks on trailers, recreational vehicles or heavy-duty equipment.

Purchasers should always get written confirmation from vendors that there is no lien on the vehicle.

CARFAX Canada Canadian Lien Guarantee



If for some reason our lien check fails to accurately reflect the Canadian enforceable lien status of a vehicle at the time of the search, CARFAX Canada will reimburse the party that purchased the report and relied on it to their detriment to a maximum amount of (1) the value of the car (2) the value of the lien (3) Five Thousand Dollars Canadian (\$5,000.00), whichever is lower.

Accident/Damage

✓ There are no accidents/damage reported on this vehicle.

Registration

✓ This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

Open Recalls

✓ No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact THOMAS.

Stolen Vehicle Check

✓ This vehicle is not actively declared stolen.

Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2005 Jun 8		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported

1T7YU4A2X61269384

ODOMETER	SOURCE	RECORD TYPE	DETAILS
2006 Sep 10	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2008 Sep 13	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2009 Sep 12	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2010 Sep 4	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2011 Sep 3	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2012 Sep 1	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2013 Aug 31	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Jul 19	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2015 Sep 5	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Jul 2	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Aug 26	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Jun 10	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Aug 26	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Jun 9	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Aug 25	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Jul 1	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Aug 20	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2021 May 30	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as yellow
2021 Aug 17	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as yellow
2022 May 29	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed

1T7YU4A2X61269384

ODOMETER	SOURCE	RECORD TYPE	DETAILS
			Vehicle colour noted as yellow
2022 Aug 22	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as yellow
2023 Jun 25	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as yellow
2023 Sep 1	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as yellow
2024 Aug 30	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as yellow



Questions? We're here to help.

Visit us at support.carfax.ca

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registration/vchr/Limitation.html>.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada. <https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2025 CARFAX Canada ULC. All rights reserved.



1T7YU4A2X61269384

Work Order Summary Report

Page: 1
Report Date: 7/15/2025

~~Vehicle Number~~ ~~Account~~ ~~Model~~
5682 53040-799 Safetyliner

~~Date~~ ~~WO#~~
02/19/2020 5861

~~Odometer~~ ~~Hourmeter~~
447233

~~Work Requested~~
side door buzzer not working

~~Work Performed~~
Shop Fee \$0.00
WO Total \$0.00

Vehicle Number Account Model Dat WO#
5682 53040-799 Safetyliner 04/01/2020 5894

Work Requested
r/s mirror doesn't de fog DUPLICATE RO
DONE ON RO5904

Work Performed
Shop Fee \$0.00
WO Total \$0.00

Vehicle Number Account Model Dat WO# Odometer Hourmeter
5682 53040-799 Safetyliner 03/31/2020 5903 237500

Work Requested
b1 service/ oil leak at fan /pass side mirror
Labor Hours 0

Work Performed
Labor Cost Labor Total
\$0.00 \$0.00

System Level Action Maintenance Code
1 2
1

Part Number
GREASE

Description
Grease

Part Qty Unit Cost
1 \$3.000

Part Cost Part Total
\$3.00 \$3.00

Shop Fee \$15.00
WO Total \$18.00

Vehicle Number Account Model Dat WO# Odometer Hourmeter
5682 53040-799 Safetyliner 03/31/2020 5904 237500

Work Requested
b1 service /battery post need cleanig / pass mirror
Labor Hours 0

Work Performed
Labor Cost Labor Total
\$0.00 \$0.00

System Level Action Maintenance Code
2
2

Part Number
TBB7170GH

Description
THOMAS MIRROR

Part Qty Unit Cost
1 \$681.020

Part Cost Part Total
\$681.02 \$681.02

Shop Fee \$15.00
WO Total \$696.02

Vehicle Number Account Model Dat WO# Odometer Hourmeter
5682 53040-799 Safetyliner 03/31/2020 5919 449539

Work Requested
Back seat panel broken / REPAIR REAR
X MEMBERS

Work Performed

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.

Work Order Summary Report

Page: 2
Report Date: 7/15/2025

System	Level	Action	Maintenance Code	Mechanic	Labor Hours	Labor Cost	Labor Total		
	1				0	\$0.00	\$0.00		
System	Level	Action	Maintenance Code	Part Number	Description	Part Qty	Unit Cost	Part Cost	Part Total
	1			2.5 X 2.5	STEEL	2	\$10.500	\$21.00	\$21.00
						Shop Fee	\$15.00		
						WO Total	\$36.00		

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed		
5682	53040-799	Safetyliner	03/31/2020	5943	239616		RELINE ALL BRAKES/REPAIR ABS CODES			
System	Level	Action	Maintenance Code	Mechanic			Labor Hours	Labor Cost	Labor Total	
System	1						0	\$0.00	\$0.00	
	2						0	\$0.00		
	3						0	\$0.00		
System	Level	Action	Maintenance Code	Part Number	Description	Part Qty	Unit Cost	Part Cost	Part Total	
	1			10023940	ABS SENSOR BRACKET	0	\$0.000	\$0.00	\$2,211.70	
	1			8235-85123399002	FRONT DRUMS	2	\$242.075	\$484.15		
	1			7843-WK4715QBRT	FRONT LINNING KIT	2	\$103.005	\$206.01		
	1			8235-85123570002	REAR DRUMS	2	\$321.575	\$643.15		
	1			7843-WK4711QBRT	REAR LINNING	2	\$165.965	\$331.93		
	3			10023940	ABS Sensor Bracket	2	\$15.000	\$30.00		
	3			3566160C1	AXLE GASK	2	\$12.330	\$24.66		
	3			801563	SENSOR ABS STRAIGHT	2	\$107.500	\$215.00		
	3			TM11447672	Wheel Seal	2	\$51.100	\$102.20		
Shop Fee								\$15.00		
WO Total								\$2,226.70		

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed	
5682	53040-799	Safetyliner	04/03/2020	5948	240000		B2 SERVICE / CVI	Labor Cost	Labor Total
System	Level	Action	Maintenance Code	Mechanic	Labor Hours	Labor Cost	Labor Total		
	2		Provincial Inspection	mackennan,jamie	0	\$0.00	\$0.00		

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.



Work Order Summary Report

Level	Action	Maintenance Code	Part Number	Description	Part Qty	Unit Cost	Part Cost	Part Total
2		Provincial Inspection			0	\$0.000	\$0.00	\$12.56
2		Provincial Inspection	CVI DECAL		1	\$3.700	\$3.70	
2		Provincial Inspection	15W40	ENGINE OIL	2	\$2.930	\$5.86	
2		Provincial Inspection	GREASE	Grease	1	\$3.000	\$3.00	

Shop Fee	\$15.00
WO Total	<u>\$27.56</u>

Vehicle Num br	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed		
								Labor Hours	Labor Cost	Labor Total
5682	53040-799	Safetyliner	05/27/2020	6014	240100		Replace Governor	0	\$0.00	\$0.00
System	Level	Action	Maintenance Code		Mechanic					
	1									
System	Level	Action	Maintenance Code		Part Number	Description	Part Qty	Unit Cost	Part Cost	Part Total
	1				FS284358N	Governor Valve	1	\$43.960	\$43.96	\$43.96

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	06/17/2020	6025	240329		PASSENGER HEATER NOT WORKING	
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
	1						0	\$0.00 \$0.00
System	Level	Action	Maintenance Code		Part Number	Description	Part Qty Unit Cost	Part Cost Part Total
	1				BSM 202270		1 \$33.710	\$33.71 \$33.71

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	09/15/2020	6090	449535		rear top middle c/l out	<div>Shop Fee</div> <div>WO Total</div> <div>\$0.00</div> <div>\$0.00</div>

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
----------------	---------	-------	------	-----	----------	-----------	----------------	----------------

* Clickmark next to Part Number or Mechanic represents outsourced work.

Work Order Summary Report

Ordered by Site
Date Range
Active and Inactive/Fleet and not in fleet
5682 53040-799 Safetyliner

09/25/2020 6104 449539
* rear middle c/l out /pass side back running light out

Shop Fee \$0.00
WO Total \$0.00

Vehicle Number Account Model Dat WO# Odometer Hourmeter Work Requested
5682 53040-799 Safetyliner 11/16/2020 6146 449539 upper rear middle marker light out

Shop Fee \$0.00
WO Total \$0.00

Vehicle Number Account Model Dat WO# Odometer Hourmeter Work Requested
5682 53040-799 Safetyliner 12/07/2020 6196 449539 rear upper marker light out

Shop Fee \$0.00
WO Total \$0.00

Vehicle Number Account Model Dat WO# Odometer Hourmeter Work Requested
5682 53040-799 Safetyliner 12/21/2020 6211 449539 repair wipers

Shop Fee \$0.00
WO Total \$0.00

Vehicle Number Account Model Dat WO# Odometer Hourmeter Work Requested
5682 53040-799 Safetyliner 12/22/2020 6219 242661 h3 service

Shop Fee \$0.00
WO Total \$0.00

Vehicle Number Account Model Dat WO# Odometer Hourmeter Work Requested
5682 53040-799 Safetyliner 04/20/2021 6338 449539 cvt
System Level Action Maintenance Code Mechanic Labor Hours
1 Provincial Inspection 0

Shop Fee \$0.00
WO Total \$0.00

Vehicle Number Account Model Dat WO# Odometer Hourmeter Work Requested
5682 53040-799 Safetyliner 06/09/2021 6412 449539 repair water leak

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.

Do not stamp
Active and Inactive/Infected and not in fleet

Work Order Summary Report

Page: 5
Report Date: 7/15/2025

Shop Fee \$0.00
WO Total \$0.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
----------------	---------	-------	------	-----	----------	-----------	----------------	----------------

Shop Fee \$0.00
WO Total \$0.00

5682	53040-799	Safetyliner	06/23/2021	6420	449539		b3 service	
Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed

Shop Fee \$0.00
WO Total \$135.00

5682	53040-799	Safetyliner	01/18/2022	6638	449539		REPLACE HOOD STRUTS/ REPLACE CRACKED RAD HOSE	
Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed

Shop Fee \$0.00
WO Total \$106.75

5682	53040-799	Safetyliner	02/10/2022	6722	449539		b1 /rear window button/check steering	
Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed

Shop Fee \$0.00
WO Total \$351.23

5682	53040-799	Safetyliner	02/04/2022	6729	252544		seal /binding in steering when turning	
Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed

Shop Fee \$0.00
WO Total \$15.00

5682	53040-799	Safetyliner	03/11/2022	6779	253017		b2 service door window condens	
Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed

Shop Fee \$0.00
WO Total \$135.00

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.

Ordered by Site
Active and Inactive/Fleet and not in fleet

Work Order Summary Report

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	04/21/2022	6818	253968		cvi change oil cooler / heater pump	Labor Cost Labor Total
System	Level	Action	Maintenance Code		Mechanic	Labor Hours		\$0.00 \$262.50
	1		Provincial Inspection			0		Shop Fee \$0.00
								WO Total \$1,719.71

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	05/13/2022	6877	254959		changr muffler	Shop Fee \$0.00
								WO Total \$425.30

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	05/24/2022	6889	255449		B2 SERVICE DUE	Shop Fee \$0.00
							repair wire for eng. compartment light	WO Total \$227.50

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	06/21/2022	6952	258018		a service	Shop Fee \$0.00
							service	WO Total \$374.44

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	09/26/2022	6964	259018		REPAIR COOLANT LEAK L/F	Labor Cost Labor Total
System	Level	Action	Maintenance Code		Mechanic	Labor Hours		\$21.00 \$21.00
	1				MACLENNAN, JAMIE	0.5		Shop Fee \$15.00
								WO Total \$36.00

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	10/27/2022	7126	260755		B2 SERVICE, PASSENGER SIDE MIRROR ADJUSTMENT KNOB IS LOOSE	Labor Cost Labor Total
System	Level	Action	Maintenance Code		Mechanic	Labor Hours		

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.

Ordered by Site
 Active and Inactive/Fleet and not in fleet

Work Order Summary Report

MACLENNAN, JAMIE

2 \$84.00 \$84.00
 Shop Fee \$15.00
 WO Total \$99.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Labor Hours	Labor Cost	Labor Total
5682	53040-799	Safetyliner	12/01/2022	7189	263300		B 1 SERVICE			
System	Level	Action	Maintenance Code		Mechanic					
	1				benson, rob			2.5	\$105.00	\$105.00
System	Level	Action	Maintenance Code		Part Number	Description		Part Qty	Unit Cost	Part Cost
	1							0	\$0.000	\$0.00
									Shop Fee	\$15.00
									WO Total	\$120.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Labor Hours	Labor Cost	Labor Total
5682	53040-799	Safetyliner	01/06/2023	7252	264189		DRIVER COMPLAINT REAR WINDOW ALARM LITE ON AS WELL AS ALARM CHECK ADJUSTMENT OF RIGHT MIRROR ARM, ADJUST AS NEEDED.			
System	Level	Action	Maintenance Code		Mechanic					
	1				MORRIS, DAVE			3.5	\$147.00	\$147.00
System	Level	Action	Maintenance Code		Part Number	Description		Part Qty	Unit Cost	Part Cost
	1				BOSCH	relay		1	\$24.760	\$24.76
	1				HEH-011727	window switch		1	\$36.720	\$36.72
									Shop Fee	\$15.00
									WO Total	\$223.48

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Labor Hours	Labor Cost	Labor Total
5682	53040-799	Safetyliner	01/12/2023	7296	265003		B2 SERVICE			
System	Level	Action	Maintenance Code		Mechanic					
	1				benson, rob			2.5	\$105.00	\$105.00
									Shop Fee	\$15.00
									WO Total	\$120.00

* Date is Release Date.
 * Checkmark next to Part Number or Mechanic represents outsourced work.



Active and 1 inactive/infect and not in fleet

Work Order Summary Report

Vehicle Number 5682
Account 53040-799
Model Safetyliner
Date 03/23/2023
WO# 7313

Work Requested
EMERGENCY DOOR SEAT WILL NOT
STAY UP, UPPER LH CORNER
RUBBER FOR WINDSHIELD COMING
OFF

System	Level	Action	Mechanic	Labor Hours	Labor Cost	Labor Total
System	1		MACLENNAN, JAMIE	1	\$42.00	\$126.00
	2		MACLENNAN, JAMIE	2	\$84.00	
	Level	Action	Part Number	Description	Part Qty	Unit Cost
	1		1234	CABLES FOR DPF FILTER	2	\$13.750
						\$27.50
					Shop Fee	\$15.00
					WO Total	\$168.50

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Labor Hours	Labor Cost	Labor Total
5682	53040-799	Safetyliner	02/14/2023	7363	267631		B3 SERVICE DUE.			
System	Level	Action			Mechanic					
	1				benSON, rob			3	\$126.00	\$126.00
									Shop Fee	\$0.00
									WO Total	\$126.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Labor Hours	Labor Cost	Labor Total
5682	53040-799	Safetyliner	03/29/2023	7474	269742		A SERVICE			
System	Level	Action			Mechanic					
	1				Provincial Inspection			0	\$0.00	\$210.00
	2				BENSON, ROB			3	\$126.00	
	2				PARADISE,			2	\$84.00	
	Level	Action			Part Number	Description	Part Qty	Unit Cost	Part Cost	Part Total
	2				15W40	ENGINE OIL	27	\$5.950	\$160.65	\$451.99
	2				P550761	FILTER OIL 56 SERIES	1	\$21.390	\$21.39	
	2				N60B 45004523	main entrance window	1	\$269.950	\$269.95	
									Shop Fee	\$15.00
									WO Total	\$676.99

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.



Active and Inactive/Fleet and not in fleet

Work Order Summary Report

Page: 9
Report Date: 7/15/2025

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	04/26/2023	7475	271775		MVI INSPECTION	
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
	1				BENSON, ROB		2.5	\$105.00 \$105.00
							Shop Fee	\$15.00
							WO Total	\$120.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	04/13/2023	7494	270224		CHECK STEERING,PULLS TO RIGHT? ENTRANCE DOORS SEEM LOOSE? CLUNK NOISE COMING FROM RIGHTSIDE WHEN TURNING RIGHT?	
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
	1				MACLENNAN, JAMIE		2	\$84.00 \$126.00
	1				BENSON, ROB		1	\$42.00
							Shop Fee	\$15.00
							WO Total	\$141.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	04/20/2023	7528	271439		VOLUME NOT LOUD ENOUGH ON 2 WAY	
							Shop Fee	\$0.00
							WO Total	\$0.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	04/25/2023	7535	271775		REPAIRS TO EXHAUST SYSTEM	
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
	1				BENSON, ROB		4.5	\$189.00 \$210.00
	1				PARADISE,		0.5	\$21.00
	2						0	\$0.00
System	Level	Action	Maintenance Code		Part Number	Description	Part Qty Unit Cost Part Cost Part Total	
	1				556X007784	EXH CLAMPS	3 \$15.880 \$47.64 \$191.13	
	1				TBB62241161	EXHAUST PIPE	1 \$97.630 \$97.63	

* Date is Release Date.

* Checkmark next to Part Number or Mechanic represents outsourced work.

2	766327	ADEL CLAMP	2	\$6,590	\$13,18
	10 INCH BY 4	FLEX PIPE	1	\$32,680	\$32,68

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed		
5682 System	53040-799	Safetyliner	05/10/2023	7574	272620		B1 SERVICE DUE.			
	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost	Labor Total	
	1				PARADISE,		1.25	\$52.50	\$105.00	
	1				BENSON, ROB		1.25	\$52.50		
								Shop Fee	\$15.00	
								WO Total	\$120.00	

							Work Performed			
Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested			
5682	53040-799	Safetyliner	12/13/2023	7586	280857		CHECK FRONT END FOR WOBBLE AT 90 KM/HR			
System	Level	Action	Maintenance Code	Mechanic	Hourmeter	Description	Part Qty	Labor Hours	Labor Cost	Labor Total
								1	\$42.00	\$168.00
								1.5	\$63.00	
								1.5	\$63.00	
System	Level	Action	Maintenance Code	Part Number	Hourmeter	Description	Part Qty	Unit Cost	Part Cost	Part Total
								1	\$540.57	\$540.57
Shop Fee									\$15.00	
WO Total									\$723.57	

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed			
								Labor Hours	Labor Cost	Labor Total	Shop Fee
5682	53040-799	Safetyliner	07/27/2023	7649	274622		REAR COMPARTMENT LIGHT OUT. DRIVERS WINDOW FOGGED	5	\$210.00	\$210.00	
System	Level 1	Action	Maintenance Code	Mechanic	PARADISE,	Description	Part Qty	Unit Cost	Part Cost	Part Total	Shop Fee
System	Level 1	Action	Maintenance Code	Part Number	003F/TBB 148235	drivers slider	1	\$507.260	\$507.26	\$507.26	

* Checkmark next to Part Number or Mechanic represents outsourced work.

Order # [REDACTED]
Active and Inactive/Fleet and not in fleet

Work Order Summary Report

WO Total \$732.26

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	06/20/2023	7679	275308		BACK PASSENGER SIDE CLUNKING CHECK BRAKE ADJUSTMENT, AIR LEAK @ EMERGENCY DOOR RELEASE HANDLE	

System	Level	Action	Maintenance Code	Mechanic	Labor Hours	Labor Cost	Labor Total
	1			BENSON, ROB	1	\$42.00	\$84.00
	1			PARADISE,	1	\$42.00	
						Shop Fee	\$15.00
						WO Total	\$99.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed	
5682	53040-799	Safetyliner	06/29/2023	7700	275546		B2 SERVICE	Labor Cost	Labor Total
System	Level	Action	Maintenance Code		Mechanic		Labor Hours		
	1				MACLENNAN, JAMIE		2	\$84.00	\$84.00
								Shop Fee	\$15.00
								WO Total	\$99.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	07/31/2023	7773	275898		REPAIR RUST HOLE ABOVE # 2 AXLE RH WHEEL WELL. REPLACE 2 MISSING SCREWS # 2 AXLE RH WHEEL WELL. REPAIR SEAT # 6 LH SEAT BACK. REPLACE # 1 RH TIRE AT WEAR BARS WITH USED ONE. MIDDLE RIGHT UPPER MARKER LIGHT OUT. LH REAR UPPER BRAKE LIGHT LENS BROKEN. FRONT 6 DOME LIGHTS NOT WORKING. REAR EXTERIOR EMERGENCY EXIT WINDOW HANDLE SEIZED.	
System	Level	Action	Maintenance Code	Mechanic	Labor Hours	Labor Cost	Labor Total	
	1			BENSON, ROB	2	\$84.00	\$336.00	
	1			PARADISE,	6	\$252.00		
	2				0	\$0.00		

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.

Active and Inactive/Fleet and not in fleet
System

Maintenance Code

Part Number

Description

Part Qty

Unit Cost

Part Cost

Part Total

Work Order Summary Report

Page: 12
Report Date: 7/15/2025

1	10062928		1	\$40.760	\$40.76	\$157.62
1	52006560	int light switch cover	1	\$32.750	\$32.75	
2	FIB 100868	kitty hair	1	\$63.010	\$63.01	
2	SHW 469038	primer	1	\$21.100	\$21.10	

Shop Fee \$15.00
WO Total \$508.62

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Labor Hours	Labor Cost	Labor Total
5682	53040-799	Safetyliner	10/16/2023	7931	277343		REPLACE BOTH BATTERIES			
System	Level	Action	Maintenance Code		Mechanic					
	1				BENSON, ROB	0.75			\$31.50	\$63.00
	1				PARADISE,	0.75			\$31.50	
System	Level	Action	Maintenance Code		Part Number	Description	Part Qty	Unit Cost	Part Cost	Part Total
	1				8D-HD-MF	1400CCA 43SRC MF	2	\$407.650	\$815.30	\$815.30
									Shop Fee	\$15.00
									WO Total	\$893.30

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Labor Hours	Labor Cost	Labor Total
5682	53040-799	Safetyliner	10/24/2023	7952	277825		B3 SERVICE			
System	Level	Action	Maintenance Code		Mechanic					
	1				PARADISE,	2			\$84.00	\$136.50
	1				BENSON, ROB	1.25			\$52.50	
									Shop Fee	\$15.00
									WO Total	\$151.50

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Labor Hours	Labor Cost	Labor Total
5682	53040-799	Safetyliner	11/14/2023	8010	279088		CHANGE WIPERS			
System	Level	Action	Maintenance Code		Mechanic					
	1				MACLENNAN, JAMIE	0.5			\$21.00	\$21.00
									Shop Fee	\$0.00

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.

Active and Inactive/Fleet and not in fleet

Work Order Summary Report

Page: 13
Report Date: 7/15/2025

WO Total \$21.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	11/15/2023	8017	279088		PASSENGER SIDE CONVEX MIRROR LOOSE	
System	Level	Action	Maintenance Code		Mechanic			
	1				BENSON, ROB			
						Labor Hours		
						0.5		
							Labor Cost	Labor Total
							\$21.00	\$21.00
							Shop Fee	\$15.00
							WO Total	\$36.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	12/08/2023	8048	280386		ASERVICE	
System	Level	Action	Maintenance Code		Mechanic			
	1				PARADISE,			
					Part Number			
					15W40			
					P550761			
						Description		
						ENGINE OIL		
						27		
						\$5.220		
						\$140.94		
						\$162.43		
						1		
						\$21.490		
						\$21.49		
							Shop Fee	\$15.00
							WO Total	\$282.43

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	12/12/2023	8112	490366		REPAIR P/S FRONT WINDOW FIRST SEAT	
System	Level	Action	Maintenance Code		Mechanic			
	1				PARADISE,			
						Labor Hours		
						1		
							Labor Cost	Labor Total
							\$42.00	\$42.00
							Shop Fee	\$15.00
							WO Total	\$57.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	12/18/2023	8126	218012		REPAIR P/S WIPER	
System	Level	Action	Maintenance Code		Mechanic			
	1							
						Labor Hours		
						0		
							Labor Cost	Labor Total
							\$0.00	\$0.00
							Shop Fee	\$15.00
							WO Total	\$57.00

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.

Ordered by Site

Active and Inactive/Fleet and not in fleet

System

Level Action

Maintenance Code

Work Order Summary Report

Page: 14

Report Date: 7/15/2025

Part Number	Description	Part Qty	Unit Cost	Part Cost	Part Total
1234	WIPER ARM	190.33	\$0.000	\$0.00	\$132.66
USED ARM	WIPER	1	\$132.660	\$132.66	

Shop Fee	\$15.00
WO Total	\$147.66

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	01/15/2024	8178	281758		MAIN ENTERANCE DOOR DOESNT CLOSE PROPERLY	
System	Level Action	Maintenance Code			Mechanic			
	1				PARADISE,	1.25	Labor Hours	Labor Cost Labor Total
						\$52.50		\$52.50
						Shop Fee		\$15.00
						WO Total		\$67.50

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	01/25/2024	8223	282166		RUNNER STRIP AT THE DASH BOARD AREA NEEDS SCREWED DOWN. SEAT AT SIDE EMERGENCY DOOR BROKEN	
System	Level Action	Maintenance Code			Mechanic			
	1				MACLENNAN, JAMIE	1	Labor Hours	Labor Cost Labor Total
						\$42.00		\$42.00
						Part Qty Unit Cost Part Cost Part Total		
					0	\$0.000		\$0.00
						Shop Fee		\$15.00
						WO Total		\$57.00

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	02/07/2024	8239	283498		B1 SERVICE, CHECK CROSSING GATE OPERATION	
System	Level Action	Maintenance Code			Mechanic			
	1				PARADISE,	2.5	Labor Hours	Labor Cost Labor Total
						\$105.00		\$126.00
					BENSON, ROB	0.5		\$21.00
						Shop Fee		\$15.00
						WO Total		\$141.00

* Date is Release Date.

* Checkmark next to Part Number or Mechanic represents outsourced work.

Ordered by Site

Active and 1 Negative/Infleet and not in fleet

Work Order Summary Report

Page: 15
Report Date: 7/15/2025

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	02/12/2024	8280	283523		REAR ENG. LID NOT LATCHING	
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
	1				PARADISE,		0.5	\$21.00 \$21.00
							Shop Fee	\$15.00
							WO Total	\$36.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	03/07/2024	8359	284795		B SERVICE	
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
	1		Provincial Inspection				0	\$0.00 \$147.00
	2				PATENAUDE, DOUC		3.5	\$147.00
System	Level	Action	Maintenance Code		Part Number	Description	Part Qty Unit Cost Part Cost Part Total	
	2				P550794	FILTER OIL 815	1 \$2,920 \$2.92 \$2.92	
							Shop Fee	\$15.00
							WO Total	\$164.92

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	03/27/2024	8365	24952		REPAIR LEAKING POWERSTEERING LINES	
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
	1				PATENAUDE, DOUC		2	\$84.00 \$168.00
	1				PARADISE,		2	\$84.00
							Shop Fee	\$15.00
							WO Total	\$183.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	04/17/2024	8403	490366		RED FLASHING STOP LIGHT DRIVERS SIDE REAR OUT	
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
	1				MACLENNAN, JAMIE		0.5	\$21.00 \$21.00
							Shop Fee	\$0.00

* Date is Release Date.

* Checkmark next to Part Number or Mechanic represents outsourced work.

Ordered by Site
Active and 1 relative/fleet and not in fleet

Work Order Summary Report

WO Total \$21.00

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	05/15/2024	8407	285163		REPLACE DRIVERS SIDE HEADLIGHT	
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
	1				MACLENNAN, JAMIE		0.5	\$21.00 \$21.00
System	Level	Action	Maintenance Code		Part Number	Description	Part Qty Unit Cost Part Cost Part Total	
	1				H6024	HEADLIGHT	1 \$12.920 \$12.92 \$12.92	
					Shop Fee		\$15.00	
					WO Total		\$48.92	

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	05/02/2024	8414	285953		MVI INSPECTION	
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
	1				MACLENNAN, JAMIE		2	\$84.00 \$84.00
	2						0	\$0.00
					Shop Fee		\$15.00	
					WO Total		\$99.00	

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	05/02/2024	8473	285953		PASSENGER SIDE WHEEL WELL SPRAYS WATER INSIDE PASSENGER AREA	
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
	1				BENSON, ROB		3.5	\$147.00 \$168.00
	1				MACLENNAN, JAMIE		0.5	\$21.00
					Shop Fee		\$15.00	
					WO Total		\$183.00	

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	08/27/2024	8517	289424		REAR PASSENGER SIDE RED LIGHT NOT WORKING.	
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
	1				BENSON, ROB		0.5	\$21.00 \$21.00

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.

Work Order Summary Report

Ordered by Site

Active and Inactive/Fleet and not in Fleet

System Level Action

Maintenance Code

Part Number

Description

Part Qty

Unit Cost

Part Cost

Part Total

H6024

HEADLIGHT

1 \$12.920

\$12.92

\$12.92

Shop Fee \$15.00

WO Total \$48.92

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	06/05/2024	8573	287785		B3 SERVICE	
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
	1				PARADISE,		4	\$168.00 \$168.00
							Shop Fee	\$15.00
							WO Total	\$183.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	06/06/2024	8578	287785		REPLACE 2 FRONT STEER AXLE AIRLINES	
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
	1				PARADISE,		1	\$42.00 \$42.00
System	Level	Action	Maintenance Code		Part Number	Description	Part Qty Unit Cost	Part Cost Part Total
	1				16324	air brake line	2 \$22.430	\$44.86 \$44.86
							Shop Fee	\$0.00
							WO Total	\$86.86

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	08/08/2024	8674	289424		WINDOWS	
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
	1				PARADISE,		2	\$84.00 \$84.00
System	Level	Action	Maintenance Code		Part Number	Description	Part Qty Unit Cost	Part Cost Part Total
	1				ABPN60B45004523	ent door glass	1 \$879.180	\$879.18 \$1,356.52
	1				ABP N60B45000830	side glass	2 \$238.670	\$477.34
							Shop Fee	\$15.00
							WO Total	\$1,455.52

Vehicle Number Account Model Date WO# Odometer Hourmeter Work Requested Work Performed

* Date is Release Date.

* Checkmark next to Part Number or Mechanic represents outsourced work.

Work Order Summary Report

Ordered by Site

Active and Inactive/Fleet and not in fleet

5682 53040-799 Safetyliner

System Level Action

08/27/2024 8683
Maintenance Code

289424

Mechanic

SANFORD, KELLEY

Part Number

B1-1200-0300-060

ORD # 059080

17681

LORDCO INV# 7010

ORDER # 059030

RDD# 059044

INV # 0000107106

060751

BODY REPAIRS

Labor Hours

96

Part Qty

1

1

2

1

1

1

1

6

Labor Cost

\$4,032.00

Part Cost

\$29.75

\$72.95

\$81.950

\$211.730

\$326.960

\$14.670

\$226.240

\$48.290

Shop Fee \$15.00

WO Total \$5,382.94

Work Performed

Work Requested
REPAIRS AS PER CVSE INSPECTION

Labor Hours

15.5

Part Qty

0

2

2

2

Shop Fee \$15.00

WO Total \$1,130.34

Vehicle Number

5682

System

Account

53040-799

Level

1

Action

Maintenance Code

Maintenance Code

Maintenance Code

Maintenance Code

Maintenance Code

Maintenance Code

Maintenance Code

Maintenance Code

Maintenance Code

Maintenance Code

Maintenance Code

Maintenance Code

Maintenance Code

Maintenance Code

Maintenance Code

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.

Page: 19
Report Date: 7/15/2025Page: 19
Report Date: 7/15/2025

Shop Fee	\$15.00
WO Total	\$336.52

Shop Fee	\$15.00
WO Total	\$141.00

* Checkmark next to Part Number or Mechanic represents outsourced work.

Ordered by **Sgt**
Active and Inactive/Inlet and not in fleet
 System Level 1 Action

Work Order Summary Report

Page: 20
 Report Date: 7/15/2025

Mechanic
 BENSON, ROB

Mechanic
 BENSON, ROB

Labor Hours
 3

Labor Cost
 \$126.00

Labor Total
 \$126.00

Shop Fee
 \$15.00

WO Total
 \$141.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	01/08/2025	9004	503231		ROAD RUNNER COMING TO INSTALL GLASS FOR DRIVERS SIDE FRONT. COMING MONDAY DEC 9/24	
System	Level 1	Action					Labor Hours	Labor Cost Labor Total
							0	\$0.00 \$0.00
System	Level 1	Action					Part Number Part Qty Unit Cost Part Cost Part Total	
							INV 22074 1 \$330.400 \$330.40 \$806.39	
							INV XA804531225 1 \$475.990 \$475.99	
							Shop Fee \$0.00	
							WO Total \$806.39	

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	01/14/2025	9078	294872		SIGNAL LIGHTS DONT CANCEL. EXIT DOOR SEAT BUSTED	
System	Level 1	Action					Labor Hours	Labor Cost Labor Total
							2	\$84.00 \$84.00
							Shop Fee \$15.00	
							WO Total \$99.00	

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	01/17/2025	9089	295173		B2 SERVICE	
System	Level 1	Action					Labor Hours	Labor Cost Labor Total
							7.5	\$315.00 \$315.00
							Shop Fee \$15.00	
							WO Total \$330.00	

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5682	53040-799	Safetyliner	02/26/2025	9204	297020		B3 SERVICE	

* Date is Release Date.
 * Checkmark next to Part Number or Mechanic represents outsourced work.

Ordered by Site
 Date
 Active and Inactive/Fleet and not in fleet
 System

Work Order Summary Report

Page: 21
 Report Date: 7/15/2025

Maintenance Code
 Provincial Inspection
 Level Action
 1
 2
 3

Mechanic
 PARADISE,
 Part Number
 63030
 Description
 3030 PIGGYBACK
 Labor Hours
 0
 2.5
 0
 Part Qty Unit Cost Part Cost Part Total
 1 \$39.220 \$39.22 \$39.22

Shop Fee \$15.00
 WO Total \$159.22

Vehicle Number Account Model Dat WO#
 5682 53040-799 Safetyliner 03/11/2025 9249
 System Level Action Maintenance Code
 1
 1
 Level Action Maintenance Code
 1
 1
 1

Odometer Hourmeter Work Requested Work Performed
 297328
 REPLACE EXHAUST PIPE AFTER
 TURBO
 Labor Hours Labor Cost Labor Total
 3 \$126.00 \$168.00
 1 \$42.00
 Part Qty Unit Cost Part Cost Part Total
 3 \$30.213 \$90.64 \$469.79
 1 \$53.820 \$53.82
 1 \$325.330 \$325.33
 Description
 4" exhaust clamps
 clamp
 exh pipe
 Part Number
 90546K-10
 A6209970590
 TBB 62241161

Shop Fee \$15.00
 WO Total \$652.79

Vehicle Number Account Model Dat WO#
 5682 53040-799 Safetyliner 04/02/2025 9306
 System Level Action Maintenance Code
 1
 Level Action Maintenance Code
 1

Odometer Hourmeter Work Requested Work Performed
 507852
 REPAIR RH STOP LIGHT
 Labor Hours Labor Cost Labor Total
 0.5 \$21.00 \$21.00
 Part Qty Unit Cost Part Cost Part Total
 1 \$32.670 \$32.67 \$32.67
 Description
 rear brake light
 Part Number
 G-L5L700R

Shop Fee \$15.00
 WO Total \$68.67

Vehicle Number Account Model Dat WO# Odometer Hourmeter Work Requested Work Performed

* Date is Release Date.
 * Checkmark next to Part Number or Mechanic represents outsourced work.

Work Order Summary Report

Page: 22
Report Date: 7/15/2025

Ordered by Site
Active and Inactive/Infect and not in fleet
5682
System

53040-799
Level Action

9328
Mechanic
MACLENNAN, JAMIE

05/08/2025
Maintenance Code

MVI INSPECTION
Labor Hours

2.5
Labor Cost \$105.00
Labor Total \$105.00

Shop Fee \$15.00
WO Total \$120.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Labor Hours	Labor Cost	Labor Total
5682	53040-799	Safetyliner	05/09/2025	9388	300412		A SERVICE			
System	Level Action	Maintenance Code			Mechanic					
	1				PARADISE,			3.5	\$147.00	\$147.00
System	Level Action	Maintenance Code			Part Number	Description		Part Qty	Unit Cost	Part Total
	1				15W40	ENGINE OIL		27	\$5.660	\$152.82
	1				P550761	FILTER OIL 56 SERIES		1	\$22.960	\$22.96
									Shop Fee	\$15.00
									WO Total	\$337.78

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Labor Hours	Labor Cost	Labor Total
5682	53040-799	Safetyliner	06/16/2025	9511	302783		REPAIR MAIN ENTRANCE DOOR			
System	Level Action	Maintenance Code			Mechanic					
	1				ERHARDT, BRANDON			2	\$84.00	\$84.00
									Shop Fee	\$15.00
									WO Total	\$99.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Labor Hours	Labor Cost	Labor Total
5682	53040-799	Safetyliner	06/16/2025	9516	302993		B1 SERVICE			
System	Level Action	Maintenance Code			Mechanic					
	1				PARADISE,			1.25	\$0.00	\$0.00
	1				ERHARDT, BRANDON			1.25	\$0.00	\$0.00
									Shop Fee	\$15.00
									WO Total	\$15.00

Report Total \$26,018.46

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.