



Vehicle History Report (BC) #: 61145545

Report Date: May 1, 2025 | 5:08 p.m. EDT

Report Status: Complete

Reference:

## 2012 FIAT 500 LOUNGE

Hatchback | 4 Cylinders | Gas

3C3CFFCR7CT123301

Country of Assembly: Mexico

Last Reported Odometer: 101,553 KM

PF18591A



Accident/Damage Records Found



Last Registered In:  
British Columbia (Normal)



10 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)



This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of May 01, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

3C3CFFCR7CT123301

# Vehicle History Report (BC)



## Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2019 Nov 15	British Columbia, Canada	
	Estimate: COLLISION   Estimate Date: n/a	\$0.00
	Claim: COLLISION	\$0.00



## Registration

This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.

*We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



## Service Records

DATE	ODOMETER	SOURCE	DETAILS
2017 Jun 2	31,480 KM	Mid Island Brake & Muffler Ltd. Nanaimo, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Oil and filter changed</li></ul>
2018 Mar 29	40,127 KM	Great Canadian Oil Change Nanaimo, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Oil and filter changed</li></ul>
2018 Oct 2	47,592 KM	Great Canadian Oil Change Nanaimo, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Oil and filter changed</li><li>Wiper(s) replaced</li></ul>
2019 Apr 27	61,237 KM	The Great Canadian Oil Change Nanaimo, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Oil and filter changed</li></ul>
2019 Aug 14	69,145 KM	Great Canadian Oil Change Nanaimo, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Maintenance inspection completed</li><li>Oil and filter changed</li></ul>
2019 Nov 25	72,210 KM	Nanaimo Chrysler Ltd Nanaimo, British Columbia, Canada	<b>Vehicle serviced</b>
2021 Jan 27	81,174 KM	The Great Canadian Oil Change Nanaimo, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Maintenance inspection completed</li><li>Oil and filter changed</li></ul>
2021 Oct 30	86,253 KM	The Great Canadian Oil Change Nanaimo, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Maintenance inspection completed</li><li>Fluids checked</li><li>Oil and filter changed</li></ul>

	ODOMETER	SOURCE	DETAILS
2023 Jun 1	95,816 KM	The Great Canadian Oil Change Nanaimo, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Maintenance inspection completed</li> <li>Fluids checked</li> <li>Oil and filter changed</li> </ul>
2024 May 22	101,553 KM	The Great Canadian Oil Change Nanaimo, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Maintenance inspection completed</li> <li>Fluids checked</li> <li>Oil and filter changed</li> </ul>



## Open Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact FIAT or visit Fiat's website. (<https://www.mopar.com/en-ca/my-vehicle/recalls/search.html>)



## Stolen Vehicle Check

This vehicle is not actively declared stolen.



## Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2012 Apr 7		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2013 Feb 23		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Mar 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2015 Feb 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2015 Jul 4		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2015 Jul 25		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2016 May 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 May 27		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Jun 2	31,480 KM	Mid Island Brake & Muffler Ltd. Nanaimo, British Columbia, Canada	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2017 Oct 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Mar 29	40,127 KM	Great Canadian Oil Change Nanaimo, British Columbia, Canada	Service Record	Vehicle serviced
2018 May 27		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Oct 2	47,592 KM	Great Canadian Oil Change Nanaimo, British Columbia, Canada	Service Record	Vehicle serviced
2019 Apr 27	61,237 KM	The Great Canadian Oil Change Nanaimo, British Columbia, Canada	Service Record	Vehicle serviced
2019 Jun 3		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Aug 14	69,145 KM	Great Canadian Oil Change Nanaimo, British Columbia, Canada	Service Record	Vehicle serviced
2019 Nov 15		Insurance Records British Columbia, Canada	COLLISION	
2019 Nov 15		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a COLLISION
2019 Nov 25	72,210 KM	Nanaimo Chrysler Ltd Nanaimo, British Columbia, Canada	Service Record	Vehicle serviced
2020 Jun 2		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Jan 27	81,174 KM	The Great Canadian Oil Change Nanaimo, British Columbia, Canada	Service Record	Vehicle serviced
2021 Jun 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2021 Oct 30	86,253 KM	The Great Canadian Oil Change Nanaimo, British Columbia, Canada	Service Record	Vehicle serviced
2022 Jul 6		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2023 Jun 1	95,816 KM	The Great Canadian Oil Change	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
		Nanaimo, British Columbia, Canada		
2024 May 22	101,553 KM	The Great Canadian Oil Change Nanaimo, British Columbia, Canada	Service Record	Vehicle serviced
2025 Apr 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray



Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)

#### ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registration/vehcl/Limitation.html>.  
ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.  
<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2025 CARFAX Canada ULC. All rights reserved.



3C3CFFC7CT123301



SERVICE & PARTS

MOPAR PEOPLE. MOPAR PARTS

## VEHICLE CHECKUP

# THE TOTAL CHECKUP

- The Right People, Factory Trained Technicians...
- The Right Parts, Mopar Genuine...
- The Right Equipment, Specialized Diagnostic Equipment...
- The Right Price, Value for your money...
- **THE RIGHT CHOICE** when it comes to the quality care your vehicle deserves.

## COMPLETE 85-POINT INSPECTION

Date 06/06/2025 12:30:45 PM

Make FIAT

Vehicle Model 500

Repair Form No. 220804

Year 2012

Registration No. \_\_\_\_\_

Kilometres 106198

Service Manager \_\_\_\_\_


Technician HARRY MILLER





## Interior Inspection


31. Check seat belts (front and rear)
32. Check instrument panel, warning lights indicator
33. Check instrument panel lighting
34. Check front and rear defrosters
35. Check horn
36. Check multifunction switch
37. Check power door lock system
38. Check keyless entry system
39. Check remote control mirror operation
40. Check glove box and glove box light
41. Check hood, latch and fuel door cable
42. Check air bag system
43. Check inside rearview mirror



## COMMENTS


## Exterior Inspection

44. Check windshield
45. Check side glasses and back glass
46. Check wiper arms and blades
47. Check body damage(s)
48. Check outside mirror(s)
49. Check all exterior lights
50. Check spare tire and support
51. Check wheels (mag wheels – wheel covers)



## Inspection under the Vehicle

52. Check engine oil pan
53. Check transmission oil pan
54. Check all fluids
55. Check oils, coolants and leaks
56. Check physical damage(s)
57. Check upper and lower ball joints
58. Check brake calipers/wheel cylinders
59. Check brake/flex-hoses tubing
60. Check struts/shocks
61. Check tie rod ends/C.V. boots
62. Check upper and lower control arms
63. Check sway bar bushings
64. Check coil springs
65. Check suspension supports
66. Check exhaust system
67. Check emergency brake cables
68. Check front brakes
69. Check rear brakes
70. Check brake rotors and drums
71. Check tire pressure \_\_\_\_\_lb.



Wear – \_\_\_\_\_ %

Wear – \_\_\_\_\_ %



FRT 7 /32

RRT 6 /32

– FLT 7 /32

– RLT 6 /32

8mm


8mm rotors extremely rusty



## COMMENTS

### Road Test

- 72. Check engine performance
- 73. Check transmission performance
- 74. Check brake system operation
- 75. Check steering operation
- 76. Check steering driveability
- 77. Check hand brake system
- 78. Check transfer case
- 79. Check differential noises
- 80. Check cruise control operation
- 81. Check instrument panel gauge operation
- 82. Check neutral switch operation
- 83. Check buzzes, squeaks and rattles
- 84. Check C.V. joints
- 85. Check overall vehicle performance




---

---

---

---

---

---

---

---

---

---

---

---

---

---

### Estimated Cost of Recommended Repairs

	Parts	Labour	Cost
Scan Tool Analysis-Assisted Inspection			
Engine Inspection			
Interior Inspection			
Exterior Inspection			
Inspection under the Vehicle			
Road Test			
			TAX
			TOTAL

### Comments

fuel light on, didnt drive on hwy

driver front DRL not working.

large oil leak, leaking onto valve cover, suspect pcv seals leaking.

The customer has requested that a vehicle inspection report be prepared and attests that Chrysler is authorized to do so. The customer attests that the vehicle in question is able to undergo the tests involving a complete road test of the vehicle.

The customer recognizes that:

1. The customer, Jeep, Dodge and Ram retailer is responsible for the safety of the vehicle, or for any damages it may sustain while in the retailer's possession, or during the tests required to complete the vehicle inspection report, unless the Chrysler, Jeep, Dodge and Ram retailer accepts responsibility for any intentional acts or negligence on its part, or on the part of its employees.

2. The tests conducted by the Chrysler, Jeep, Dodge and Ram retailer include a physical inspection or an electronic analysis of the normally accessible areas listed on the inspection form. The tests do not include the internal inspection of the various areas of the vehicle.

3. The brake rotors 75% rust pads and rotors.

jounce bumper on left rear coil spring broken

Customer Signature \_\_\_\_\_

Date \_\_\_\_\_

# PARKSVILLE

## CHRYSLER DODGE JEEP

230 Sheffy Road • Parksville, B.C. • V9P 1V6 • Sales & Service: (250) 248-3281 • Parts: (250) 248-6831  
 Body Shop (250) 248-3733 • Fax Number: (250) 248-2086  
 Toll Free Phone #: 1 (800) 561-3281 • tbarkhouse@parksvillechrysler.com • www.parksvillechrysler.com

SO# 220804

### SERVICE ORDER INTERNAL COPY



Status: [REDACTED] 2:34:46 PM

User: KATIEM Page 1

Advisor	KATIE	Promised	06/04/2025 5:00 PM	Tag#	
Shop	S1	Opened	06/04/2025 4:08 PM	Location	
Priority		Cashiered	06/06/2025 12:34 PM	PO #	

License	Odom In	Odom Out	In Service Date	Stock No
	106198	106200		PF18591A
Year	Make	Model	Model Number	Colour
2012	FIAT	500	FFFP24	SILVER
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
3C3CFFCR7CT123301				
Engine	1.4L 16-VALVE I4 MULTI-AIR ENGINE	Fleet #		

Request	Description	Job	CSR	Status
85PT	USED CAR 85PT INSPECTION AND SERVICE -- ****GREEN BAG AND WHEEL LOCK KEY IF EQUIPPED****	1	213	Original
Labour	Description	Type	Tech	Amount
85PT	USED CAR 85PT INSPECTION AND SERVICE -- ****GREEN BAG AND WHEEL LOCK KEY IF EQUIPPED****	IL	292	210.00
Technician	292 -			
Cause	used inspection			
Correction	fuel light on, didnt drive on hwy driver front DRL not working. large rumble from tires or wheel bearing, right front bearing noisy, left rear bearing noisy large oil leak, leaking onto valve cover, suspect pcv seals leaking. also recomend changing vaccume pump seal engine air filter. rear tires worn very poorly. 4 tires plus alignment rear brake rotors 75% rust - pads and rotors. jounce bumper on left rear coil spring broken			
		Labour Total		210.00
		Request Total		210.00

Request	Description	Job	CSR	Status
UCD	ANTITHEFT PROTECTION PACKAGE -- INSTALL NITROGEN IN TIRES -- INSTALL ETCHING ON VEHICLE -- ****GREEN BAG AND WHEEL LOCK KEY IF EQUIPPED****	2	213	Original
Labour	Description	Type	Tech	Amount
UCD	ANTITHEFT PROTECTION PACKAGE -- INSTALL NITROGEN IN TIRES -- INSTALL ETCHING ON VEHICLE -- ****GREEN BAG AND WHEEL LOCK KEY IF EQUIPPED****	IL	292	50.00
Technician	292 -			
Correction	UCD ANTITHEFT - ANTITHEFT PROTECTION PACKAGE -- INSTALL NITROGEN IN TIRES -- INSTALL ETCHING ON VEHICLE -- ****GREEN BAG AND WHEEL LOCK KEY IF EQUIPPED****			
		Labour Total		50.00
		Request Total		50.00

Request	Description	Job	CSR	Status
NOTE	SENDING AWAY - NOT COMPLETING WORK	3	213	Approved

### WHEELS REQUIRE RE-TORQUE BETWEEN 50-100 KM'S

I N	GST #: R104083114 PST #: 1012-1189 I HEREBY AUTHORIZE THE REPAIR WORK HEREIN SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIAL AND AGREE THAT TO THE EXTENT PERMITTED BY LAW YOU ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND YOUR CONTROL OR FOR ANY DELAYS CAUSED BY HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION, UNTIL PAYMENT IN FULL OF THE WITHIN ACCOUNT, I HEREBY ACKNOWLEDGE THE EXISTENCE OF A MECHANIC'S LIEN IN FAVOUR OF THE WITHIN DEALER ON THE VEHICLE DESCRIBED HEREIN IN RESPECT OF THE MATERIAL SUPPLIED AND SERVICES RENDERED UNDER THIS WORK ORDER FOR THE FULL AMOUNT CHARGED THEREFORE IF FURTHER ACKNOWLEDGE THAT THE SAID LIEN SHALL CONTINUE IN FORCE AT ALL TIMES, WHETHER THE VEHICLES IS IN MY POSSESSION OR POSSESSION OF THE DEALER, UNTIL THE WITHIN ACCOUNT IS PAID IN FULL WHILE THE VEHICLE IS IN MY POSSESSION IT SHALL AT ALL TIMES BE SUBJECT TO REPOSSESSION ON DEMAND BY THE DEALER UNTIL THE WITHIN ACCOUNT IS PAID IN FULL.		ODOMETER OUT	
	DATE _____ CUSTOMER SIGNATURE _____		DATE OUT	
			PHONE WHEN READY YES <input type="checkbox"/> NO <input type="checkbox"/>	
			RESIDENCE PHONE	
O U T	INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS WORK ORDER		BUSINESS PHONE	
	DATE _____ CUSTOMER SIGNATURE _____		TIME PROMISED	
			CASH <input type="checkbox"/> OK KEY	
			CHARGE <input type="checkbox"/>	
		INTERNAL <input type="checkbox"/>		

# PARKSVILLE

## CHRYSLER DODGE JEEP

230 Shelly Road • Parksville, B.C. • V9P 1V6 • Sales & Service: (250) 248-3281 • Parts: (250) 248-6831  
 Body Shop (250) 248-3733 • Fax Number: (250) 248-2086  
 Toll Free Phone #: 1 (800) 561-3281 • tbarkhouse@parkvillechrysler.com • www.parkvillechrysler.com


SO# 220804

Status  
 Printed 06/06/2025 12:34:46 PM

### SERVICE ORDER INTERNAL COPY



User KATIEM Page 2



Advisor KATIE  
 Shop S1  
 Priority  
 Promised 06/04/2025 5:00 PM  
 Opened 06/04/2025 4:08 PM  
 Cashiered 06/06/2025 12:34 PM  
 Tag#  
 Location  
 PO #

License Odom In 106198 Odom Out 106200 In Service Date  
 Year 2012 Make FIAT Model 500 Model Number FFFP24 Stock No PF18591A  
 Vehicle ID No 3C3CFFCR7CT123301 Selling Dealer Extended Warranty Colour SILVER  
 Engine 1.4L 16-VALVE I4 MULTI-AIR ENGINE Fleet # Delivery Date

Labour Description  
 NOTE SENDING AWAY - NOT COMPLETING WORK  
 Technician 999 - Type CP Tech 999 Amount 0.00

Request Description  
 TOTALCHECK Chrysler Canada Total Checkup  
 Job 4 CSR 213 Status Approved

Pay Type	Labour	Parts	Fees	Misc	Supplies	Sublet	Env	Ded	GST	PST	Total
Customer	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
Warranty	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
Internal	260.00	0.00	0.00	0.00	30.76	0.00	0.00	0.00	0.00	0.00	290.76
Total	260.00	0.00	0.00	0.00	30.76	0.00	0.00	0.00	0.00	0.00	290.76

INTERNAL  
 ACCOUNT 127 DESCRIPTION USED CARS TYPE CONTROL # PF18591A AMOUNT COMMENTS 290.76 T123301 - 2012 FIAT 500 LOUNGE 2dr HB

### WHEELS REQUIRE RE-TORQUE BETWEEN 50-100 KM'S

I N  O U T	<small>GST #: R1G4080114 PST #: 1012-1159</small> I HEREBY AUTHORIZE THE REPAIR WORK HEREIN SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIAL AND AGREE THAT TO THE EXTENT PERMITTED BY LAW YOU ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND YOUR CONTROL OR FOR ANY DELAYS CAUSED BY HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION, UNTIL PAYMENT IN FULL OF THE WITHIN ACCOUNT, I HEREBY ACKNOWLEDGE THE EXISTENCE OF A MECHANIC'S LIEN IN FAVOUR OF THE WITHIN DEALER ON THE VEHICLE DESCRIBED HEREIN IN RESPECT OF THE MATERIAL SUPPLIED AND SERVICES RENDERED UNDER THIS WORK ORDER FOR THE FULL AMOUNT CHARGED THEREFOR. IF FURTHER ACKNOWLEDGE THAT THE SAID LIEN SHALL CONTINUE IN FORCE AT ALL TIMES, WHETHER THE VEHICLE IS IN MY POSSESSION OR POSSESSION OF THE DEALER, UNTIL THE WITHIN ACCOUNT IS PAID IN FULL WHILE THE VEHICLE IS IN MY POSSESSION IT SHALL AT ALL TIMES BE SUBJECT TO REPOSSESSION ON DEMAND BY THE DEALER UNTIL THE WITHIN ACCOUNT IS PAID IN FULL. DATE _____ CUSTOMER SIGNATURE _____		ODOMETER OUT DATE OUT PHONE WHEN READY YES <input type="checkbox"/> NO <input type="checkbox"/> RESIDENCE PHONE BUSINESS PHONE TIME PROVIDED
	INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS WORK ORDER DATE _____ CUSTOMER SIGNATURE _____		CASH <input type="checkbox"/> OK KEY CHARGE <input type="checkbox"/> INTERNAL <input type="checkbox"/>