

Technician Work Sheet Service Writer :

Print Date: 7/23/2025

2011 Chevrolet - Traverse LS

Mat # : 6995

VIN # : 1GNKREED0 BJ261950

Color :

Engine : 3.6L,V6 (217CI) VIN(D)

Location :

Lic # : 61950

Lic. State : B.C.

Repair Order #

000000

TIMS AUTO REPAIR

Home - - - Cellular 250-753-1755

Schedule : 4/25/25 4:00 P.M.

Promised Date : 4/25/25 5:00 P.M.

Inspection Date : 4/25/25

Status :

Last Service :

Unit # :

Current Odometer : 0

Trans :

Previous Mileage : 0

Brakes : 4-Wheel ABS

Elapsed Mileage : 0

Manufacture Date : 4/25/25

Part Number	Part Description	Qty	Part Location
<input type="checkbox"/> PP	PURCHASE PRICE	1.00	
<input type="checkbox"/> pac	dealer pac	1.00	
<input type="checkbox"/> 14D1169ACHF1	PAD KIT FRT/Disc Brake Pad Set (Front)	1.00	
<input type="checkbox"/> PH10575	SPIN ON OIL ** price includes Eco Fee of \$0.650/Engine Oil Filter	1.00	
<input type="checkbox"/> 90117	ILTR6E11 LASER IRIIDIUM SPARK PLUG/Spark Plug	6.00	
<input type="checkbox"/> VS 50808 R	ENGINE VALVE COVER GASKET SET/Engine Valve Cover Gasket Set	1.00	
<input type="checkbox"/> PH10575	SPIN ON OIL ** price includes Eco Fee of \$0.650/Engine Oil Filter	1.00	

Labor Description

Charged Hours

<input type="checkbox"/> GENERAL OVERVIEW		1.00
TIRE PRESSURE CHECKED, FRONT END CHECK, BRAKE CHECK, EXHAUST CHECK, BELTS& HOSES CHECK, AIR AND FUEL FILTER, ALL FLUID LEVELS, LIGHTS. FRONT TIRES HAVE (%) REM, REAR TIRES HAVE (%) REM, FRONT BRAKES HAVE (%) REM, REAR BRAKES HAVE (%) REM, CHARGING SYSTEM IS GOOD, COOLANT IS GOOD TO (-)		
Technician : <none>		
<input type="checkbox"/> BRAKE SHOES &/OR PADS - Remove & Replace - Front or Rear - [Includes: Clean, lube and/or replace Brake Hardware as necessary. Adjust Brakes (where applicable). Includes: Repack Wheel Bearings (where applicable). DOES NOT include refinishing.]		1.10
Technician : <none>		
<input type="checkbox"/> VALVE COVER GASKET - Remove & Replace - Both - [Includes: R&I Intake Manifold.] - [Includes: Camshaft Covers on Over Head Cam Engines.]		4.29
Technician : <none>		

Sublet

<input type="checkbox"/> DETAILING		
Technician : <none>		

Year:	Make: <i>Chen</i>	Model: <i>traverse</i>	Mileage: <i>215 915</i>
Vin:	Customer:		

Items	OK	MARGINAL	REPAIR	Notes
Driveability				
Restraint system/SRS light	/			
Emergency brake adjustment	/			
Heater & A/C operation	/			
Instrument panel warning lights			/	<i>CEL</i>
Operation of exterior lights				
Wiper blades	/			
Condition of engine & trans oil	/			
Condition of drive belts	/			
Condition of air filter	/			
Condition of radiator & hoses	/			
Condition of coolant	/			
Brake hydraulic /clutch system	/			
Condition of battery/ cables/ clamps	/			
Condition of power steering fluid	/			
Tire wear- front/rear	/			<i>80% 50%</i>
Condition of brakes-front			/	<i>10%</i>
Condition of brakes-rear	/			<i>80%</i>
Condition of axle shaft boots & joints	/			
Condition of shocks/struts	/			
Visual fluid leaks?	/	/		<i>minor</i>
Condition of exhaust system.	/			
Condition of suspension	/			
Condition of steering components	/			
License plate screws and Tims sticker				