



Midas - Courtenay
(250) 338-7211
store9936@midasstores.com
2275 Cliffe Ave, Courtenay, BC,
Canada, V9N 2L5

Inspection Report

Against Estimate#: 10591
Created: May 16, 2025
Service Advisor: Garret Cole

2011 Hyundai Elantra GLS
VIN: KMHDC8AE7BU107703
Mileage: 218708 km
License Plate:

Courtesy Inspection


Category	Items	Conditions	Status
----------	-------	------------	--------

Need Immediate Attention

General	Vehicle Condition		NEED IMMEDIATE ATTENTION
---------	-------------------	--	--------------------------


Rear subframe is rusting out badly. Needs rear subframe and everything attached to it. Front subframe is rusting out at the rear right side of the subframe mount.

Attachments-6



taken-on: May 16, 2025 4:04pm

[View on Web](#)




taken-on: May 16, 2025 4:07pm

[View on Web](#)




taken-on: May 16, 2025 4:07pm

[View on Web](#)



taken-on: May 16, 2025 4:08pm

[View on Web](#)



taken-on: May 16, 2025 4:09pm

[View on Web](#)



taken-on: May 16, 2025 4:10pm

[View on Web](#)

General	Exterior Lights - Rear		NEED IMMEDIATE ATTENTION
---------	------------------------	--	--------------------------



Midas - Courtenay
(250) 338-7211
store9936@midasstores.com
2275 Cliffe Ave, Courtenay, BC,
Canada, V9N 2L5


Inspection Report

Against Estimate#: 10591
Created: May 16, 2025
Service Advisor: Garret Cole

Both license plate lights are out.

General	Cabin Air Filter	Restricted	NEED IMMEDIATE ATTENTION
---------	------------------	------------	--------------------------

Attachments-1



taken-on: May 16, 2025 3:54pm

[View on Web](#)

Fluids & Exhaust System	Engine Oil	OEM Interval	NEED IMMEDIATE ATTENTION
-------------------------------	------------	--------------	--------------------------

Need Monitoring

General	Wipers - Front	Chatter / Streaking	NEED MONITORING
---------	----------------	---------------------	-----------------

General	Engine Air Filter	Restricted / Dirty	NEED MONITORING
---------	-------------------	--------------------	-----------------

General	Belts (Except Timing)		NEED MONITORING
---------	-----------------------	--	-----------------

Belt noise when cold.

General	Other Notable		NEED MONITORING
---------	---------------	--	-----------------

No timing belt sticker in the engine bay.

Checked & OK

General	Horn	CHECKED & OK
---------	------	--------------

General	Dash Indicator Lights	CHECKED & OK
---------	-----------------------	--------------

General	Exterior Lights - Front	CHECKED & OK
---------	-------------------------	--------------

General	Wipers - Rear	CHECKED & OK
---------	---------------	--------------

General	Hood / Hatch Supports	CHECKED & OK
---------	-----------------------	--------------

General	Battery / Cables	CHECKED & OK
---------	------------------	--------------

General	Hoses	CHECKED & OK
---------	-------	--------------



Midas - Courtenay
(250) 338-7211
store9936@midasstores.com
2275 Cliffe Ave, Courtenay, BC,
Canada, V9N 2L5

Inspection Report

Against Estimate#: 10591
Created: May 16, 2025
Service Advisor: Garret Cole

Fluids & Exhaust System	Coolant	CHECKED & OK
Fluids & Exhaust System	Brake Fluid	CHECKED & OK
Fluids & Exhaust System	Fluid Leaks	CHECKED & OK
Fluids & Exhaust System	Exhaust System	CHECKED & OK