

COMPLETE

31-POINT INSPECTION

Date Aug 1 / 25 Year / Make / Model 2018 CHEVY SONIC
VIN 1G1SD6SB0J4120104 Mileage 166178 kms. Stock OG

☒ OK Checked and OK

☐ MR May Require Further Attention

☐ RA Requires immediate Attention

Under Hood Inspection

- 1 Check Battery Voltage/Amperage/Charging
- 2 Check Starter
- 3 Check Coolant Levels
- 4 Check Oil levels
- 5 Check Power Steering
- 6 Check Master Brake Cylinder
- 7 Check Belts
- 8 Check Ignition System
- 9 Check Engine & Trans Supports

OK	MR	RA
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐

Comments

Interior Inspection

- 10 Check Seat Belts
- 11 Check Instrument Panel, Warning Lights
- 12 Check Front & Rear Defroster
- 13 Check Hazard Lights & Horn
- 14 Check Power Lock System
- 15 Check Hood Latch & Fuel Filler Door Cable
- 16 Check Air Bag System
- 17 Check inside Rear-view Mirror

☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐

Exterior Inspection

- 18 Check Windshield, Wiper arms and Blades
- 19 Check Outside Mirrors
- 20 Check All Exterior Lights
- 21 Check Wheels & Spare Tire

☒	☐	☐
☒	☐	☐
☒	☐	☒
☒	☐	☐

R/S HIGH BEAM OUT
HID Bulb.

Inspection Under Hood

- 22 Check Physical Damage
- 23 Check Upper & Lower Ball Joints
- 24 Check Brake Calipers/Wheel Cylinders/Tubes
- 25 Check Struts/Shocks
- 26 Check Tie Rod Ends/CV Boots
- 27 Check Upper & Lower Control Arms
- 28 Check Sway Bars Bushings
- 29 Check Emergency Brake Cables
- 30 Check Front / Rear Brakes
- 31 Check Tires

☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐

Front Wear - 80%

Rear Wear - 70%

5/32

4/32

Notes

low

TRANS OIL LEAK

Curtis