

Work Order Summary Report

Page: 1
Report Date: 7/15/2025



Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	01/10/2020	5838	3347422		1st emg. window buzzer/ engine light / rivets by rear tires missing	Shop Fee \$0.00 WO Total \$0.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	02/19/2020	5860	3347422		noise in r/front of bus when he hits bumps	Shop Fee \$0.00 WO Total \$0.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	02/27/2020	5881	459957		steering not returning smoothly as normal /may be nothing ?	Shop Fee \$0.00 WO Total \$0.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	06/03/2020	5886			DPREVOST: B2 service (Work Order Request #4729)	
System	Level	Action	Maintenance Code		Mechanic	Labor Hours		Labor Cost Labor Total
	1					0		\$0.00 \$0.00
							Shop Fee	\$0.00
							WO Total	\$0.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	02/18/2020	5887	458801		DPREVOST: B2 service (Work Order Request #4732)	
System	Level	Action	Maintenance Code		Mechanic	Labor Hours		Labor Cost Labor Total
	1					0		\$0.00 \$0.00
							Shop Fee	\$0.00
							WO Total	\$0.00

Vehicle Number Account Model Date WO# Odometer Hourmeter Work Requested Work Performed

5683 53040-799 Safetyliner 02/27/2020 5896 459957 check for lack of power

* Date is Release Date.

* Checkmark next to Part Number or Mechanic represents outsourced work.

Work Order Summary Report

Page: 2
Report Date: 7/15/2025

Shop Fee \$0.00
WO Total \$0.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	04/03/2020	5917	461228		B3 service due	
System	Level	Action	Maintenance Code		Mechanic	Labor Hours		Labor Cost Labor Total
	1					0		\$0.00 \$0.00
System	Level	Action	Maintenance Code		Part Number	Part Qty	Unit Cost	Part Cost Part Total
	1				ANTIFREEZE	1	\$5.000	\$5.00 \$14.95
	1				GREASE	1	\$3.000	\$3.00
	1				15/40 WT	2	\$2.930	\$5.86
	1				W/W FLUID	1	\$1.090	\$1.09
								Shop Fee \$15.00
								WO Total \$29.95

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	06/03/2020	5933	3347422		LOW POWER COMPLAINT	
								Shop Fee \$15.00
								WO Total \$15.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	06/17/2020	6005	461779		Hole in #10 passenger seat back Right and left rear turn signal lamp lenses are cracked/weathered/checked.	
System	Level	Action	Maintenance Code		Mechanic	Labor Hours		Labor Cost Labor Total
	1					0		\$0.00 \$0.00
System	Level	Action	Maintenance Code		Part Number	Part Qty	Unit Cost	Part Cost Part Total
	1				WELDON TURN SIGN	2	\$20.000	\$40.00 \$40.00
								Shop Fee \$15.00
								WO Total \$55.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	06/18/2020	6028	462962		AIR LEAK AT DASH VALVE	

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.

Work Order Summary Report

Page: 3
Report Date: 7/15/2025

System	Level	Action	Maintenance Code	Mechanic	Labor Hours	Labor Cost	Labor Total		
	1				0	\$0.00	\$0.00		
System	Level	Action	Maintenance Code	Part Number	Description	Part Qty	Unit Cost	Part Cost	Part Total
	1			R955276567N	DASH VALVE	1	\$26.970	\$26.97	\$40.41
	1			248502N	Push Pull Yellow Button	1	\$13.440	\$13.44	

Shop Fee \$15.00
WO Total \$55.41

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	09/18/2020	6084	463951		a service	
								Shop Fee \$0.00 WO Total \$0.00


Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed	
5683	53040-799	Safetyliner	10/07/2020	6114	465500		cvi	Labor Hours	Labor Cost
System	Level	Action	Maintenance Code		Mechanic			Labor Total	
	1		Provincial Inspection					0	\$0.00
								\$0.00	\$0.00

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	11/02/2020	6147	466964		b1 service /right turn in eng comp not working ?	
								Shop Fee \$0.00 WO Total \$0.00

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	12/11/2020	6204	469902		b2 service	
								Shop Fee \$0.00 WO Total \$0.00

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	12/23/2020	6233	470525		front brakes	
								Shop Fee \$0.00

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.



Work Order Summary Report

WO Total \$0.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	01/15/2021	6245	471411		trunk lid /loose bulb behind r/ turn arrow inside	

Shop Fee \$0.00
WO Total \$0.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	02/01/2021	6273	472451		B3 SERVICE	

Shop Fee \$0.00
WO Total \$0.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	03/17/2021	6299	475501		needs x arm replaced	

Shop Fee \$0.00
WO Total \$0.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	05/03/2021	6364	477813		b1 service	

Shop Fee \$0.00
WO Total \$0.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	06/14/2021	6374	3347422		hi pitch noise from engine when accelerating	

Shop Fee \$0.00
WO Total \$0.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	06/08/2021	6413	480144		b3 service /repair exhaust	

Shop Fee \$0.00
WO Total \$0.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
----------------	---------	-------	------	-----	----------	-----------	----------------	----------------

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.

Work Order Summary Report

Page: 5
Report Date: 7/15/2025

5683 53040-799 Safetyliner

06/25/2021 6424

3347422

pass bottom rear marker light/drivers side
cross arm wigaleiy batt cable has a rubbed
spot?

Shop Fee \$0.00
WO Total \$0.00

5683 53040-799 Safetyliner

10/21/2021 6515

482706

Work Requested
CVI / RH TURN INDICATOR ON DASH
INTERMITTANT

Shop Fee \$0.00
WO Total \$135.00

Vehicle Number 5683
Account 53040-799
Model Safetyliner
System Level Action
1

Date 11/02/2021
WO# 6516
Maintenance Code
Provincial Inspection

Odometer 3347422
Hourmeter

Work Requested
cvi / pass mirror bottom not defrosting
Labor Hours 0

Work Performed
Labor Cost \$0.00
Shop Fee \$0.00
WO Total \$135.00

5683 53040-799 Safetyliner

11/05/2021 6564

483448

Work Requested
check out wiper d/s

Work Performed
Shop Fee \$0.00
WO Total \$45.00

5683 53040-799 Safetyliner

01/18/2022 6596

485181

Work Requested
washer sprayer on drivers side needs
adjusted

Work Performed
Shop Fee \$0.00
WO Total \$30.00

5683 53040-799 Safetyliner

01/18/2022 6625

485181

Work Requested
a service

Work Performed
Shop Fee \$0.00
WO Total \$295.48

Vehicle Number Account Model Date WO# Odometer Hourmeter Work Requested Work Performed

* Date is Release Date.

* Checkmark next to Part Number or Mechanic represents outsourced work.

Work Order Summary Report

Page: 6
Report Date: 7/15/2025

Vehicle Number 53040-799 Safetyliner

Date 01/17/2022

WO# 6683

Odometer 485287

Work Requested INSTALLED HEADLIGHTS AND 12V POWER PLUG

Shop Fee \$0.00
WO Total \$608.74

Vehicle Number 53040-799 Safetyliner

Date 03/04/2022

WO# 6764

Odometer 487882

Work Requested b service

Shop Fee \$0.00
WO Total \$590.00

Vehicle Number 53040-799 Safetyliner

Date 04/25/2022

WO# 6836

Odometer 489115

Work Requested REPLACE ALT BELT AND TENSIONER

Shop Fee \$0.00
WO Total \$692.27

Vehicle Number 53040-799 Safetyliner

Date 04/27/2022

WO# 6852

Odometer 489202

Work Requested l/s rear marker light

Shop Fee \$0.00
WO Total \$17.50

Vehicle Number 53040-799 Safetyliner

Date 05/12/2022

WO# 6854

Odometer 3347422

Work Requested r/side compartment door wont open

Shop Fee \$0.00
WO Total \$17.50

System Level 1 Action Maintenance Code

Date 05/12/2022

WO# 6854

Odometer 3347422

Work Requested r/side compartment door wont open

Shop Fee \$0.00
WO Total \$17.50

Vehicle Number 53040-799 Safetyliner

Date 05/26/2022


WO# 6891

Odometer 490347

Work Requested B2 SERVICE DUE

Shop Fee \$0.00

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.



Work Order Summary Report

Page: 7
Report Date: 7/15/2025


WO Total \$70.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed		
5683	53040-799	Safetyliner	08/09/2022	7018	492876		REPLACE BOTH LH AND RH FRONT WINDOW GLASS			
System	Level	Action	Maintenance Code		Mechanic	Labor Hours	Labor Cost	Labor Total		
	1				MACLENNAN, JAMIE	1	\$42.00	\$42.00		
	2					0	\$0.00			
System	Level	Action	Maintenance Code		Part Number	Description	Part Qty	Unit Cost	Part Cost	Part Total
	1				ABPN60B53003183	WINDSHIELD LH TTB	1	\$420.360	\$420.36	\$1,113.28
	1				ABPN60B53003184	WINDSHIELD RH TTB	1	\$188.920	\$188.92	
	2				CONTRACTOR	LABOUR	1	\$504.000	\$504.00	
								Shop Fee	\$15.00	
								WO Total	\$1,170.28	

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed		
5683	53040-799	Safetyliner	09/13/2022	7067	493197		B2 SERVICE			
System	Level	Action	Maintenance Code		Mechanic	Labor Hours		Labor Cost	Labor Total	
	1				benson, rob	2		\$84.00	\$84.00	
System	Level	Action	Maintenance Code		Part Number	Description	Part Qty	Unit Cost	Part Cost	Part Total
	1						0	\$0.000	\$0.00	\$0.00
								Shop Fee	\$15.00	
								WO Total	\$99.00	

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed		
5683	53040-799	Safetyliner	10/03/2022	7092	493854		REPLACE MUFFLER, BRACKETS, AND HARDWARE. TRIM DRIVERS SEAT BASE.			
System	Level	Action	Maintenance Code		Mechanic	Labor Hours		Labor Cost	Labor Total	
	1				benson, rob	8		\$336.00	\$336.00	
System	Level	Action	Maintenance Code		Part Number	Description	Part Qty	Unit Cost	Part Cost	Part Total
	1				UNLIMITED FABRIC	MADE MUFFLER BRACKETS	2	\$100.000	\$200.00	\$691.22
	1				556 M110674	MUFFLER	1	\$491.220	\$491.22	

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.



Work Order Summary Report


Shop Fee \$15.00
WO Total \$1,042.22

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed		
5683	53040-799	Safetyliner	10/19/2022	7124	495166		B1 SERVICE, LOAD TEST BATTERIES AND POSSIBLY CHANGE,CVI INSPECTION, COOLANT LEAK			
System	Level	Action	Maintenance Code				Labor Hours	Labor Cost	Labor Total	
	1		Provincial Inspection				0	\$0.00	\$420.00	
System	2						10	\$420.00		
	2									
System	Level	Action	Maintenance Code							
	2									

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed	
5683	53040-799	Safetyliner	01/03/2023	7191	498710		B 3 SERVICE		
System	Level	Action	Maintenance Code	1	Mechanic	MORRIS, DAVE	Labor Hours	Labor Cost	Labor Total
								Shop Fee	\$15.00
								WO Total	\$120.00

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed		
5683	53040-799	Safetyliner	01/17/2023	7262	501148		A SERVICE DUE			
System	Level	Action	Maintenance Code	1	Mechanic	MACLENNAN, JAMIE	Labor Hours	Labor Cost	Labor Total	
								2	\$84.00	\$126.00
System	Level	Action	Maintenance Code	1	benison, rob		Part Qty	Unit Cost	Part Cost	Part Total
								1	\$42.00	
System	Level	Action	Maintenance Code	1	P550761	FILTER OIL 56 SERIES	1	\$21.390	\$21.39	\$75.49
								2	\$27.050	\$54.10
System	Level	Action	Maintenance Code	1	B5-2700-1175-120	gas shocks	2	\$27.050	\$54.10	
								Shop Fee	\$15.00	
								WO Total	\$216.49	

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.



Work Order Summary Report


Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed			
5683	53040-799	Safetyliner	03/31/2023	7317	502879		REPLACE FRONT WINDSHIELD GLASS DRIVERS SIDE				
System	Level	Action	Maintenance Code		Mechanic	Labor Hours		Labor Cost	Labor Total		
	1					0		\$0.00	\$0.00		
System	Level	Action	Maintenance Code		Part Number	Description	Part Qty	Unit Cost	Part Cost	Part Total	
	1				53003183	left hand windshield	1	\$366.800	\$366.80	\$618.80	
	1				ROAD RUNNER INV	lb windshield repair	1	\$252.000	\$252.00		
								Shop Fee	\$0.00		
								WO Total	\$618.80		

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed			
5683	53040-799	Safetyliner	02/02/2023	7343	502685		B1 SERVICE (PAST DUE)				
System	Level	Action	Maintenance Code		Mechanic	Labor Hours		Labor Cost	Labor Total		
	1				benson, rob	1.5		\$63.00	\$126.00		
	1				MACLENNAN, JAMIE	1.5		\$63.00			
								Shop Fee	\$15.00		
								WO Total	\$141.00		

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed			
5683	53040-799	Safetyliner	03/16/2023	7421	505164		B2 SERVICE DUE. TORN SEATS.				
System	Level	Action	Maintenance Code		Mechanic	Labor Hours		Labor Cost	Labor Total		
	1				BENSON, ROB	1.25		\$52.50	\$147.00		
	1				MORRIS, DAVE	1.25		\$52.50			
	2				PARADISE,	1		\$42.00			
								Shop Fee	\$15.00		
								WO Total	\$162.00		

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed			
5683	53040-799	Safetyliner	04/13/2023	7490	506458		SQUEAKY WINDSHIELD MOTOR				
System	Level	Action	Maintenance Code		Mechanic	Labor Hours		Labor Cost	Labor Total		
	1				MACLENNAN, JAMIE	0.5		\$21.00	\$21.00		

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.



Work Order Summary Report

Shop Fee \$0.00
WO Total \$21.00


Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	04/17/2023	7522	507236		REPAIRS TO HIGH LOW BEAM SWITCH ON COLUMN	
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
	1				MACLENNAN, JAMIE		2	\$84.00 \$84.00
System	Level	Action	Maintenance Code		Part Number	Description	Part Qty Unit Cost Part Cost Part Total	
	1				577 99006	universal turn signal	1 \$158.04 \$158.04	
					Shop Fee		\$15.00	
					WO Total		\$257.04	

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	05/01/2023	7536	508187		B3 SERVICE	
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
	1				BENSON, ROB		1.25	\$52.50 \$105.00
	1				PARADISE,		1.25	\$52.50
					Shop Fee		\$15.00	
					WO Total		\$120.00	

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	05/08/2023	7570	508548		REPLACE MIKE ON 2 WAY RADIO	
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
	1				MACLENNAN, JAMIE		0.5	\$21.00 \$21.00
					Shop Fee		\$0.00	
					WO Total		\$21.00	

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	06/05/2023	7622	510929		A SERVICE	
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
	1				BENSON, ROB		1.5	\$63.00 \$126.00
	1				PARADISE,		1.5	\$63.00

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.



Work Order Summary Report

System	Level	Action	Maintenance Code	Part Number	Description	Part Qty	Unit Cost	Part Cost	Part Total
	1			15W40	ENGINE OIL	27	\$5.950	\$160.65	\$215.65
	1			P121922	FILTER AIR	1	\$33.610	\$33.61	
	1			P550761	FILTER OIL 56 SERIES	1	\$21.390	\$21.39	

Shop Fee \$15.00
WO Total \$356.65

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Labor Hours	Labor Cost	Labor Total
5683	53040-799	Safetyliner	06/12/2023	7652	511657		REAR UPPER RIGHT SIDE CLEARANCE LIGHT OUT			
System	Level	Action	Maintenance Code		Mechanic			0.5	\$21.00	\$21.00
	1				PARADISE,					


Shop Fee \$0.00
WO Total \$21.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed		
5683	53040-799	Safetyliner	06/20/2023	7671	511923		CHECK FOR AIR LEAKS AND FRONT MARKER LIGHT OUT			
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost	Labor Total	
	1				MACLENNAN, JAMIE		1	\$42.00	\$42.00	
System	Level	Action	Maintenance Code		Part Number	Description	Part Qty	Unit Cost	Part Cost	Part Total
	1				47073	led light	1	\$30.610	\$30.61	\$35.50
	1				66910	pig tail	1	\$4.890	\$4.89	

Shop Fee \$15.00
WO Total \$92.50

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed			
5683	53040-799	Safetyliner	07/10/2023	7689	513313		B1 SERVICE	Labor Hours	Labor Cost	Labor Total	
System	Level	Action	Maintenance Code		Mechanic			2.5	\$105.00	\$105.00	
					PARADISE,						
System	Level	Action	Maintenance Code		Part Number	Description		Part Qty	Unit Cost	Part Cost	Part Total
	1							0	\$0.000	\$0.00	\$0.00
									Shop Fee	\$15.00	

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.



Work Order Summary Report

WO Total \$120.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	08/03/2023	7774	513314		3 OR 4 SEAT BACKS WITH CUTS/HOLES #1 RIGHT EMERGENCY EXIT WINDOW ALARM INTERMITTENT	
System	Level	Action	Maintenance Code		Mechanic	Labor Hours	Labor Cost	Labor Total
	1				PARADISE,	2	\$84.00	\$84.00
							Shop Fee	\$15.00
							WO Total	\$99.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	09/20/2023	7883	513646		AIR LEAK ?	
System	Level	Action	Maintenance Code		Mechanic	Labor Hours	Labor Cost	Labor Total
	1		Provincial Inspection			0	\$0.00	\$42.00
	2				MACLENNAN, JAMIE	1	\$42.00	
							Shop Fee	\$0.00
							WO Total	\$42.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed			
5683	53040-799	Safetyliner	10/13/2023	7899	514858		B2 SERVICE				
System	Level	Action	Maintenance Code		Mechanic			Labor Hours	Labor Cost	Labor Total	
					PARADISE,		2	\$84.00	\$168.00		
					BENSON, ROB		2	\$84.00			
System	Level	Action	Maintenance Code		Part Number	Description		Part Qty	Unit Cost	Part Cost	Part Total
								0	\$0.000	\$0.00	\$0.00
								Shop Fee	\$15.00		
								WO Total	\$183.00		

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	10/31/2023	7962	517019		REPAIRS TO UNDER SEAT HEATERS AND DRIVERS FAN LOOSE AND FLOPPING AROUND	
System	Level	Action	Maintenance Code		Mechanic	Labor Hours	Labor Cost	Labor Total

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.

Work Order Summary Report

Page: 13
Report Date: 7/15/2025

1 PARADISE, \$84.00 \$315.00
1 BENSON, ROB \$231.00
5.5
Part Number Part Qty Unit Cost Part Cost Part Total
1000044188 heater motor 4 \$181.370 \$725.48 \$725.48
Shop Fee \$15.00
WO Total \$1,055.48

Vehicle Number Account Model Dat WO# Odometer Hourmeter Work Requested Work Performed
5683 53040-799 Safetyliner 11/08/2023 7994 517726 B2 SERVICE
System Level Action Maintenance Code Mechanic PARADISE, Labor Hours Labor Cost Labor Total
1 2.5 \$105.00 \$105.00
Shop Fee \$15.00
WO Total \$120.00

Vehicle Number Account Model Dat WO# Odometer Hourmeter Work Requested Work Performed
5683 53040-799 Safetyliner 11/27/2023 7997 517742 REPLACE TRANSMISSION LINES
System Level Action Maintenance Code Mechanic Labor Hours Labor Cost Labor Total
1 0 \$0.00 \$0.00
Part Number Part Qty Unit Cost Part Cost Part Total
PETERBILT NB 143 repairs to rad trans line an 1 \$7,455.880 \$7,455.88 \$7,455.88
Shop Fee \$0.00
WO Total \$7,455.88

Vehicle Number Account Model Dat WO# Odometer Hourmeter Work Requested Work Performed
5683 53040-799 Safetyliner 11/29/2023 8070 518075 CHECK COOLANT LEVEL, NOTE POSSIBLE EGR COOLER, REPAIR WIPERS
System Level Action Maintenance Code Mechanic BENSON, ROB Labor Hours Labor Cost Labor Total
1 1.5 \$63.00 \$63.00
Shop Fee \$15.00
WO Total \$78.00

Vehicle Number Account Model Dat WO# Odometer Hourmeter Work Requested Work Performed
* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.

Work Order Summary Report

5683 53040-799 Safetyliner 12/12/2023 8111

519300

CHECK FOR AIR LEAK AT
EMERGENCY DOOR VALVE ABOVE
P/S WINDOW

System 5683 53040-799 Safetyliner 12/12/2023 8111

Level 1 Action Maintenance Code *
Mechanic MACLENNAN, JAMIE

Labor Hours 0.5

Labor Cost \$21.00 Labor Total \$21.00
Shop Fee \$0.00
WO Total \$21.00

Vehicle Number 5683 Account 53040-799 Model Safetyliner Dat 01/05/2024 WO# 8130

Odometer 520204

Work Requested B3 SERVICE

Work Performed

System 5683 53040-799 Safetyliner 01/05/2024 8130

Level 1 Action Maintenance Code
Mechanic PARADISE,

Labor Hours 2.5

Labor Cost \$105.00 Labor Total \$105.00
Shop Fee \$15.00
WO Total \$120.00

Vehicle Number 5683 Account 53040-799 Model Safetyliner Dat 01/04/2024 WO# 8150

Odometer 520122

Work Requested OIL LEAK AT FAN DRIVE ?

Work Performed

System 5683 53040-799 Safetyliner 01/04/2024 8150

Level 1 Action Maintenance Code
Mechanic MACLENNAN, JAMIE

Labor Hours 0.5

Labor Cost \$21.00 Labor Total \$21.00
Shop Fee \$0.00
WO Total \$21.00

Vehicle Number 5683 Account 53040-799 Model Safetyliner Dat 01/18/2024 WO# 8155

Odometer 520769

Work Requested RE INSTALL RH REAR FENDER
FLARE

Work Performed

System 5683 53040-799 Safetyliner 01/18/2024 8155

Level 1 Action Maintenance Code
Mechanic PARADISE,

Labor Hours 1.5

Labor Cost \$63.00 Labor Total \$63.00
Shop Fee \$15.00
WO Total \$78.00

Vehicle Number 5683 Account 53040-799 Model Safetyliner Dat 01/18/2024 WO# 8188

Odometer 520769

Work Requested REPLACE STIKING THERMOSTAT.

Work Performed


System 5683 53040-799 Safetyliner 01/18/2024 8188

Level 1 Action Maintenance Code
Mechanic MACLENNAN, JAMIE

Labor Hours 2

Labor Cost \$84.00 Labor Total \$84.00
Part Qty Unit Cost Part Cost Part Total

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.



Work Order Summary Report

A0052032675 TWO THERMOSTATS AND ORING 1 \$262.670 \$262.67 \$262.67
Shop Fee \$15.00
WO Total \$361.67

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed		
5683	53040-799	Safetyliner	02/07/2024	8244	521563		CHECK OIL LEAK AT RAD FAN PUMP	Labor Cost	Labor Total	
System	Level	Action	Maintenance Code		Mechanic			Labor Hours		
	1				PARADISE,			0.5	\$21.00	\$21.00
								Shop Fee	\$0.00	
								WO Total	\$21.00	

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed		
5683	53040-799	Safetyliner	02/20/2024	8284	521616		REPLACE LH HEAD LIGHT	Labor Cost	Labor Total	
System	Level	Action	Maintenance Code		Mechanic			Labor Hours		
	1				PATENAUIDE, DOUC			0.5	\$21.00	\$21.00
								Shop Fee	\$0.00	
								WO Total	\$21.00	

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed		
5683	53040-799	Safetyliner	02/13/2024	8288	52113		SERVICE CALL FOR BUS BROKEN DOWN ON JINGLE POT AND EAST WELLINGTON	Labor Cost	Labor Total	
System	Level	Action	Maintenance Code		Mechanic			Labor Hours		
	1				PARADISE,			0	\$0.00	\$0.00
								Part Qty	Unit Cost	Part Cost
					Part Number	Description		1	\$51.950	\$51.95
					PFH-MAX-HD	8 GUAGE FUSE HOLDER				\$56.06
	1				PMAX-30	FUSE		1	\$4.110	\$4.11
								Shop Fee	\$15.00	
								WO Total	\$71.06	

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed		
5683	53040-799	Safetyliner	04/26/2024	8302	522546		A SERVICE	Labor Cost	Labor Total	
System	Level	Action	Maintenance Code		Mechanic			Labor Hours		

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.



Work Order Summary Report

System	1									
	Level	Action	Maintenance Code		PATENAUDE, DOUC	5	\$210.00	\$210.00		
	1				Part Number					
					Description	26	\$5,220	\$135.72	\$157.21	
					15W40					
					FILTER OIL 56 SERIES	1	\$21.490	\$21.49		
					P550761					
							Shop Fee	\$15.00		
							WO Total	\$382.21		

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed		
								Labor Hours	Labor Cost	Labor Total
5683	53040-799	Safetyliner	03/04/2024	8339	522900		REPAIR ROOF LEAK, REPLACE PRESSURE CAP FOR FUEL TANK	1	\$42.00	\$84.00
System	Level	Action	Maintenance Code		Mechanic					
	1				BENSON, ROB			1	\$42.00	
System	Level	Action	Maintenance Code		Part Number	Description		Part Qty	Unit Cost	Part Cost
	1				PATENAUDE, DOUC			1		\$42.00
System	Level	Action	Maintenance Code		Part Number	Description		Part Qty	Unit Cost	Part Cost
	1				3578833C3	CAP RADIATOR		1	\$8.89	\$8.89



Work Order Summary Report

X007784	1	STEP CLAMP 4"	\$7,640	\$7,64	\$7,64
Shop Fee				\$15.00	
WO Total				\$190.64	

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed		
5683	53040-799	Safetyliner	08/27/2024	8657	527687		BODY REPAIRS			
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost	Labor Total	
	1				SANFORD, KELLEY		100	\$4,200.00	\$4,200.00	
	2						0	\$0.00		
System	Level	Action	Maintenance Code		Part Number	Description	Part Qty	Unit Cost	Part Cost	Part Total
								\$365.140	\$365.14	\$2,893.74
								\$20.540	\$20.54	
								\$48.290	\$48.29	
								\$335.200	\$335.20	
								\$18.130	\$54.39	
								\$102.680	\$102.68	
								\$23.530	\$23.53	
								\$232.100	\$232.10	
								\$1,091.130	\$1,091.13	
								\$56.290	\$56.29	
System	Level	Action	Maintenance Code		Part Number	Description	Part Qty	Unit Cost	Part Cost	Part Total
								\$97.630	\$97.63	
								\$179.480	\$179.48	
								\$144.000	\$144.00	
System	Level	Action	Maintenance Code		Part Number	Description	Part Qty	Unit Cost	Part Cost	Part Total
								\$107.500	\$107.50	
System	Level	Action	Maintenance Code		Part Number	Description	Part Qty	Unit Cost	Part Cost	Part Total
	2				10047279	SCR SAFETY CABLE	1	\$35.840	\$35.84	
								Shop Fee	\$15.00	
								WO Total	\$7,108.74	

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	08/09/2024	8671	527686		REPLACE FOGGED WINDOWS	

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.


Work Order Summary Report

System	Level	Action	Maintenance Code	Mechanic	Labor Hours	Labor Cost	Labor Total
System	1			PARADISE,	7.5	\$315.00	\$315.00
				Part Number			
				TBB148235	1	\$429.990	\$429.99
				driver slider			\$1,361.65
	1			ABPN60B45004523	1	\$404.680	\$404.68
	1			ent door glass			
	1			ABPN60B45000830	2	\$263.490	\$526.98
				side storm			
						Shop Fee	\$15.00
						WO Total	\$1,691.65

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed		
5683	53040-799	Safetyliner	08/27/2024	8692	527687		REPAIRS AS PER CVSE INSPECTION			
System	Level	Action	Maintenance Code	Mechanic			Labor Hours	Labor Cost	Labor Total	
	1			PARADISE,			4	\$168.00	\$168.00	
				Part Number						
				1156			1	\$2.670	\$2.67	\$148.22
				Description						
	1			B1-1200-0300-060			1	\$42.670	\$42.67	
				lift support						
	1			B-2418			2	\$51.440	\$102.88	
				mud flaps						
								Shop Fee	\$15.00	
								WO Total	\$331.22	

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed	
5683	53040-799	Safetyliner	10/24/2024	8728	528080		RH EMERGENCY WINDOW NOT WORKING		
System	Level	Action	Maintenance Code	Mechanic	Labor Hours	Labor Cost	Labor Total		
	1		Provincial Inspection		0	\$0.00	\$42.00		
	2			MACLENNAN, JAMIE	1	\$42.00			
							Shop Fee	\$15.00	
							WO Total	\$57.00	

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	10/01/2024	8783	529034		REPLACE DAMAGED MIRROR, AND REPAIR BODY DAMAGE	
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
* Date is Release Date.								
* Checkmark next to Part Number or Mechanic represents outsourced work.								



Work Order Summary Report

System	1		PARADISE,		1.5		\$63.00	\$63.00		
	Level	Action	Maintenance Code	Part Number	Description	Part Qty	Unit Cost	Part Cost	Part Total	
	1			7170GH	thomas mirror head	1	\$682.370	\$682.37	\$682.37	
							Shop Fee	\$15.00		
							WO Total	\$760.37		

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed	
5683	53040-799	Safetyliner	10/09/2024	8822	529953		REPAIR KICK PANEL.		
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost	Labor Total
	1				SANFORD, KELLEY		0.5	\$21.00	\$21.00
								Shop Fee	\$15.00
								WO Total	\$36.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	10/29/2024	8828	530277		MVI INSPECTION	
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
	1				SANFORD, KELLEY		3	\$126.00 \$126.00
								Shop Fee \$15.00
								WO Total \$141.00

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed			
5683	53040-799	Safetyliner	10/29/2024	8857	530271		REPAIRS TO TRANSMISSION WIRING AND BUSTED OUT DASH FROM VANDALISM.				
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost	Labor Total		
	1				SANFORD, KELLEY		17.5	\$735.00	\$735.00		
System	Level	Action	Maintenance Code		Part Number	Description	Part Qty	Unit Cost	Part Cost	Part Total	
	1				804V/POL31191PF	IGNITION SWITCH	1	\$74.500	\$74.50	\$98.12	
	1				47072	MARKER LAMP	1	\$23.620	\$23.62		
								Shop Fee	\$15.00		
								WO Total	\$848.12		

Vehicle Number Account Model Dat WO# Odometer Hourmeter Work Requested Work Performed


* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.

Vehicle Number	Account	Model	Dat	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	01/17/2025	9022	534776		CHECK MIC COORD FOR	

* Checkmark next to Part Number or Mechanic represents outsourced work.

Work Order Summary Report

Page: 21
Report Date: 7/15/2025



System	Level	Action	Maintenance Code	Mechanic	UNRAVELING	Labor Hours	Labor Cost	Labor Total
	1			SANFORD, KELLEY		0.5	\$21.00	\$21.00
							Shop Fee	\$15.00
							WO Total	\$36.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	01/07/2025	9044	533546		B1 SERVICE	
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
	1				PARADISE,		2.5	\$105.00 \$105.00
							Shop Fee	\$15.00
							WO Total	\$120.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	01/14/2025	9077	533920		FRONT LH AMBER RUNNING LIGHT OUT	
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
	1				MACLENNAN, JAMIE		0.5	\$21.00 \$21.00
							Shop Fee	\$0.00
							WO Total	\$21.00

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	02/04/2025	9138	535862		B2 SERVICE	
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
	1				PARADISE,		3.5	\$147.00 \$147.00
System	Level	Action	Maintenance Code		Part Number	Description	Part Qty Unit Cost Part Cost	Part Total
	1				R955276567N	DASH VALVE	1 \$26.970 \$26.97	\$26.97
							Shop Fee	\$15.00
							WO Total	\$188.97

Vehicle Number	Account	Model	Date	WO#	Odometer	Hourmeter	Work Requested	Work Performed
5683	53040-799	Safetyliner	03/05/2025	9231	538275		B3 SERVICE, CHECK CRACK,	
System	Level	Action	Maintenance Code		Mechanic		Labor Hours	Labor Cost Labor Total
	1				PARADISE,		2.5	\$105.00 \$105.00

* Date is Release Date.
* Checkmark next to Part Number or Mechanic represents outsourced work.

Work Order Summary Report

System Level Action

Maintenance Code

Part Number

Description

1

Part Qty Unit Cost

Part Cost Part Total

0 \$0.000 \$0.00 \$0.00

Shop Fee \$15.00
WO Total \$120.00

Vehicle Number Account Model Dat WO#

5683 53040-799 Safetyliner 04/25/2025 9342

System Level Action Maintenance Code

1

Odometer 540288

Hourmeter

Work Requested A SERVICE

Labor Hours 5

Labor Cost \$210.00 Labor Total \$210.00

Mechanic PARADISE,

Part Number

Part Qty

Unit Cost

Part Cost Part Total

27 \$5.660 \$152.82 \$175.78

15W40

Description ENGINE OIL

Part Qty

Unit Cost

Part Cost Part Total

1 \$22.960 \$22.96

P550761

Description FILTER OIL 56 SERIES

Part Qty

Unit Cost

Part Cost Part Total

1 \$22.960 \$22.96

Shop Fee \$15.00
WO Total \$400.78

Vehicle Number Account Model Dat WO#

5683 53040-799 Safetyliner 05/14/2025 9400

System Level Action Maintenance Code

1

Odometer 542658

Hourmeter

Work Requested B1 SERVICE

Labor Hours 0

Labor Cost \$0.00 Labor Total \$0.00

Mechanic

Part Number

Part Qty

Unit Cost

Part Cost Part Total

0 \$0.00 \$0.00

Shop Fee \$15.00
WO Total \$15.00

Vehicle Number Account Model Dat WO#

5683 53040-799 Safetyliner 07/08/2025 9415

Work Requested REAR TOP MARKER LIGHT OUT

Labor Hours

Labor Cost \$0.00 Labor Total \$0.00

Shop Fee \$0.00
WO Total \$0.00

Vehicle Number Account Model Dat WO#

5683 53040-799 Safetyliner 06/16/2025 9508

System Level Action Maintenance Code

1

Odometer 545402

Hourmeter

Work Requested B2 SERVICE

Labor Hours 3

Labor Cost \$0.00 Labor Total \$126.00

Mechanic ERHARDT, BRANDON

Part Number

Part Qty

Unit Cost

Part Cost Part Total

3 \$126.00 \$126.00

ERHARDT, BRANDON

Description

Part Qty


Unit Cost

Part Cost Part Total

3 \$126.00 \$126.00

* Date is Release Date.

* Checkmark next to Part Number or Mechanic represents outsourced work.



Work Order Summary Report

Page: 23
Report Date: 7/15/2025

0	\$0.000	\$0.00	\$0.00
		Shop Fee	\$15.00
		WO Total	\$141.00

Report Total

\$31,720.90

* Date is Release Date.

* Checkmark next to Part Number or Mechanic represents outsourced work.