

COMPLETE 31-POINT INSPECTION

Date SEPT 12/25 Year / Make / Model 2013 MINI COOPER.
VIN WMWZC5C55DWP30232 Mileage 222565 km Stock 7

OK Checked and OK

MR May Require Further Attention

RA Requires immediate Attention

Under Hood Inspection

- 1 Check Battery Voltage/Amperage/Charging
- 2 Check Starter
- 3 Check Coolant Levels
- 4 Check Oil levels
- 5 Check Power Steering
- 6 Check Master Brake Cylinder
- 7 Check Belts
- 8 Check Ignition System
- 9 Check Engine & Trans Supports

OK	MR	RA	Comments
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	

Interior Inspection

- 10 Check Seat Belts
- 11 Check Instrument Panel, Warning Lights
- 12 Check Front & Rear Defroster
- 13 Check Hazard Lights & Horn
- 14 Check Power Lock System
- 15 Check Hood Latch & Fuel Filler Door Cable
- 16 Check Air Bag System
- 17 Check inside Rear-view Mirror

OK	MR	RA	Comments
☒	☐	☐	
☒	☐	☒	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	

CHECK ENGINE LIGHT ON
- ENGINE IN LIMP MODE

Exterior Inspection

- 18 Check Windshield, Wiper arms and Blades
- 19 Check Outside Mirrors
- 20 Check All Exterior Lights
- 21 Check Wheels & Spare Tire

OK	MR	RA	Comments
☒	☒	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	

CHIPPED GLASS.

Inspection Under Hood

- 22 Check Physical Damage
- 23 Check Upper & Lower Ball Joints
- 24 Check Brake Calipers/Wheel Cylinders/Tubes
- 25 Check Struts/Shocks
- 26 Check Tie Rod Ends/CV Boots
- 27 Check Upper & Lower Control Arms
- 28 Check Sway Bars Bushings
- 29 Check Emergency Brake Cables
- 30 Check Front / Rear Brakes
- 31 Check Tires

OK	MR	RA	Comments
☒	☒	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	

ENGINE OIL LEAKS

Front Wear - 85%
8/32

Rear Wear - 60%
9/32

Notes

ENGINE RUNS VERY ROUGH.

Chris