

COMPLETE

31-POINT INSPECTION

Date SEPT 23/25

Year / Make / Model

2009 SUBARU IMPREZA WRX

VIN JF1GE766796522705

Mileage

168873kms

Stock

10

OK

Checked and OK

MR

May Require Further Attention

RA

Requires immediate Attention

Under Hood Inspection

- 1 Check Battery Voltage/Amperage/Charging
- 2 Check Starter
- 3 Check Coolant Levels
- 4 Check Oil levels
- 5 Check Power Steering
- 6 Check Master Brake Cylinder
- 7 Check Belts
- 8 Check Ignition System
- 9 Check Engine & Trans Supports

OK

MR

RA

Comments



OIL IN COOLANT
ADDED 1L 5W30

Interior Inspection

- 10 Check Seat Belts
- 11 Check Instrument Panel, Warning Lights
- 12 Check Front & Rear Defroster
- 13 Check Hazard Lights & Horn
- 14 Check Power Lock System
- 15 Check Hood Latch & Fuel Filler Door Cable
- 16 Check Air Bag System
- 17 Check inside Rear-view Mirror



Exterior Inspection

- 18 Check Windshield, Wiper arms and Blades
- 19 Check Outside Mirrors
- 20 Check All Exterior Lights
- 21 Check Wheels & Spare Tire



DRIVING LIGHT LENSES
BOTH BROKEN.

Inspection Under Hood

- 22 Check Physical Damage
- 23 Check Upper & Lower Ball Joints
- 24 Check Brake Calipers/Wheel Cylinders/Tubes
- 25 Check Struts/Shocks
- 26 Check Tie Rod Ends/CV Boots
- 27 Check Upper & Lower Control Arms
- 28 Check Sway Bars Bushings
- 29 Check Emergency Brake Cables
- 30 Check Front / Rear Brakes
- 31 Check Tires



Front Wear - 60%

Rear Wear - 85%



7/32

R/S FRONT TIRE WORN
OUT ON INSIDE OF TIRE.

L/S HEAD GASKET LEAKING EXTERNALLY

CLUTCH SLIPS UNDER POWER IN 3RD.

CRACKS

Notes

Tow