Vehicle History Report + Lien Check (BC) #: 63613583 Report Date: August 16, 2025 | 2:19 p.m. EDT Report Status: Complete

Reference:

2014 NISSAN PATHFINDER S

Sport utility vehicle | 6 Cylinders | Gas 5N1AR2MM6EC731651

Country of Assembly: United States Last Reported Odometer: 179,999 KM

LIEN CHECK



No Lien Records Found





Accident/Damage Records Found



Last Registered In: British Columbia (Normal)



18 Service Records Found



No U.S. History Found



2 Open Recalls Found



Not Actively Declared Stolen




No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of August 16, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report + Lien Check (BC)



- No lien records found in British Columbia.
- No lien records found in Manitoba.
- No lien records found in Newfoundland.
- No lien records found in Nova Scotia.

How We Check for Liens

CARFAX Canada uses the VIN to search government records in each Canadian province and territory (excluding Northwest Territories) where the vehicle is currently registered and where it has historically been registered. We do not check for liens or title in any U.S. state.

If a VIN has no registration records in Canada, we cannot check for liens. We cannot guarantee lien checks on trailers, recreational vehicles or heavy-duty equipment.

Purchasers should always get written confirmation from vendors that there is no lien on the vehicle.

CARFAX Canada Canadian Lien Guarantee

If for some reason our lien check fails to accurately reflect the Canadian enforceable lien status of a vehicle at the time of the search, CARFAX Canada will reimburse the party that purchased the report and relied on it to their detriment to a maximum amount

of (1) the value of the car (2) the value of the lien (3) Five Thousand Dollars Canadian (\$5,000.00), whichever is lower.



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
D 2016 Jul 12	Manitoba, Canada	
	Estimate: Rear Estimate Date: n/a	\$1,598.41
	Claim: Collision Rear	Not Reported
	Damage Detail: Damage reported: minor damage	
	Damage to rear	



Registration

- This vehicle has been registered in the following locations in Canada (listed oldest to newest):
 - In the province of Manitoba with Normal branding.
 - In the province of Nova Scotia with Normal branding.
 - In the province of Newfoundland with Normal branding.
 - In the province of British Columbia with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



DATE	ODOMETER	SOURCE	DETAILS	
2014 Oct 8		Crown Nissan		the same
			Vehicle serviced	
		Winnipeg, Manitoba, Canada	Pre-delivery inspection completed	
			Nitrogen fill tires	
7044	tion of the contract of any property of the contract to the property of the contract to the group of the first		 VIN glass etching vin etched 	
2014 Oct 14		Service Facility	Vehicle serviced	
		Winnipeg, Manitoba, Canada		
		,	Pre-delivery inspection completedVIN glass etching vin etched	
2014 Nov 7			Same and the same	
201414007		Birchwood Honda West	Vehicle serviced	M
		Winnipeg, Manitoba, Canada		
2014 Nov 10	terrepresentative processes representative (p.) (process had representative (p.) (p.)			
_0.71104 10		Birchwood Nissan	Vehicle serviced	
		Winnipeg, Manitoba, Canada		
2014 Nov 24	141 have			
		Birchwood Nissan	Vehicle serviced	
		Winnipeg, Manitoba, Canada	 Maintenance inspection completed 	
2014 Dec 17		Birchwood Nissan		***************************************
			Vehicle serviced	
ours (J.) (ormatiche processor (processor (p		Winnipeg, Manitoba, Canada	 Maintenance inspection completed 	
2015 Feb 6		Birchwood Nissan	Vol. 1.1.	~~~
		Winnipeg, Manitoba, Canada	Vehicle serviced	
#180		1-3,	 Maintenance inspection completed 	
2015 May 22	6,405 KM	Birchwood Nissan	Vehicle serviced	~~~~~
		Winnipeg, Manitoba, Canada	Maintenance inspection completed	
		, 3,, 	Recommended maintenance performed	
			Oil and filter changed	
	77.70		Tire(s) replaced	
2015 Jun 1	6,779 KM	Birchwood Nissan		1765-1-1
		Winnipeg, Manitoba, Canada	Vehicle serviced	
		manipeg, manicoba, canada	 Maintenance inspection completed Sunroof weatherstrip replaced 	
	The state of the s		2011 Oot WeatherStrip replaced	
2015 Sep 23	13,010 KM	Birchwood Nissan	Vehicle serviced	
		Winnipeg, Manitoba, Canada	Maintenance inspection completed	
			Tires rotated	
	Discourage W. Solder		 Vehicle washed/detailed 	
2016 Feb 22	17,162 KM	Birchwood Nissan	78 (Salamontaring) - Common (1945) - Common (1	***************************************
	,		Vehicle serviced	
		Winnipeg, Manitoba, Canada	Maintenance inspection completed April the fifty of the second completed	
			 Anti-theft/keyless remote battery replaced Vehicle washed/detailed 	
2016 May 9	19,383 KM	The state of the s		
	ININ COCICI	Birchwood Nissan	Vehicle serviced	
		Winnipeg, Manitoba, Canada	Maintenance inspection completed Potton completed	
			 Battery serviced Brakes checked 	
			Front seat cushion replaced	
			Front seat track replaced	
**************************************			Oil and filter changed	
2016 Jun 27	20,947 KM	Birchwood Nissan		
-		Winnipeg, Manitoba, Canada	Vehicle serviced	
			Maintenance inspection completed	
2019 May 31	65,962 KM	Jiffy Lube #1501	Volice of the second se	~~*************************************
		Dartmouth, Nova Scotia, Canada	Vehicle serviced • Maintenance inspection completed	
		· Conda	Air filter checked	
			Air filter replaced	

Air filter replaced

	ODOMETER	SOURCE	DETAILS
			Oil and filter changed
2019 Aug 19		Service Facility	Vehicle serviced Inspection performed
2023 Jun 7	122,302 KM	Elec-Tech Auto Winnipeg, Manitoba, Canada	Vehicle serviced A/C system checked A/C compressor replaced A/C expansion/orifice valve replaced A/C receiver/dryer replaced Antifreeze/coolant flushed/changed Drive belt(s) replaced Front wheel bearing(s)/hub(s) replaced Serpentine belt replaced
2024 Feb 5	134,906 KM	Great Canadian Oil Change Nanaimo, British Columbia, Canada	Vehicle serviced Maintenance inspection completed Air filter checked Air filter replaced Fluids checked Oil and filter changed
2024 Apr 22	179,999 KM	Kerry 's Car & Truck Centre Parksville, British Columbia, Canada	Vehicle serviced Noise checked Rear brake pads replaced Rear brakes replaced



🍕 🖣 Open Recalls

Recall #: PC786 | PTHFR STP LMP SWTH NTB21-003 Recall Date: 2021 Jan 29

Recall Description

Due to the location of the stop lamp switch on the brake pedal, a chattering condition may occur in the stop lamp relay. Under certain driving conditions, such as frequent stop-and go driving with repeated brake pedal input, the chattering can degrade the relay contact service life.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit Nissan's website. (https://www.nissanusa.com/recalls-vin.html)

Recall #: R24C6 | PTH HD LTH FNL RPR NTB25-010 Recall Date: 2025 Feb 10

Recall Description

ON CERTAIN 2013-2016 PATHFINDER VEHICLES, DUST OR DIRT CONTAMINATION MAY ACCUMULATE ON AND AROUND THE SECONDARY LATCH LEVER PIVOT JOINT, OVER TIME, THE BUILD-UP OF CONTAMINATION, COMBINED WITH A LACK OF PROPER INSPECTION AND MAINTENANCE OF THE SECONDARY LATCH (AS DESCRIBED IN THE OWNER S MANUAL), CAN CREATE MECHANICAL BINDING THAT COULD CAUSE THE LEVER TO REMAIN IN THE OPEN POSITION AFTER IT HAS BEEN DISENGAGED. IN ADDITION, THIS CONTAMINATION CAN SCRATCH THE SECONDARY LATCH S PROTECTIVE ANTI-CORROSION COATING, ALLOWING CORROSION OF THE BARE METAL IN THE PIVOT JOINT.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit Nissan's website. (https://www.nissanusa.com/recalls-vin.html)



This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2014 Oct 8		Crown Nissan Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2014 Oct 14		Service Facility Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2014 Nov 7		Birchwood Honda West Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2014 Nov 10	erenterenterente de la Qui de for pre executation de la hallamagne appropriet en la qui	Birchwood Nissan Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2014 Nov 13		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as gray
2014 Nov 24		Birchwood Nissan Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2014 Dec 17		Birchwood Nissan Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2015 Feb 6		Birchwood Nissan Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2015 Feb 13		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2015 May 22	6,405 KM	Birchwood Nissan Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2015 Jun 1	6,779 KM	Birchwood Nissan Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2015 Sep 23	13,010 KM	Birchwood Nissan Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2016 Feb 13		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2016 Feb 22	17,162 KM	Birchwood Nissan Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2016 May 9	19,383 KM	Birchwood Nissan Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced

NAME OF THE OWNER OWNER OF THE OWNER OWNE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 Jun 27	20,947 KM	Birchwood Nissan Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2016 Jul 12	A 400 - 100		Damage Event	Damage reported: minor damage Damage to rear
2016 Jul 12	To Valida Administrativa de Proposiciones	Insurance Records Manitoba, Canada	Collision	Estimate Date: n/a Rear
2016 Jul 12	21,416 KM	Manitoba, Canada	Collision	Rear
2016 Aug 17	er er von de deutsche deutsch	Motor Vehicle Dept. Nova Scotia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Aug 13	од на почет в на при	Motor Vehicle Dept. Nova Scotia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 May 31	65,962 KM	Jiffy Lube #1501 Dartmouth, Nova Scotia, Canada	Service Record	Vehicle serviced
2019 Aug 19	35.907	Service Facility	Service Record	Vehicle serviced
2019 Aug 26	The Walter commission and applying the commission of the commissio	Motor Vehicle Dept. Happy Valley-Goose Bay, Newfoundland, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2020 Nov 1		Motor Vehicle Dept. Happy Valley-Goose Bay, Newfoundland, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2021 Jan 29	от в настрой в достояння подного до 1928 M. М. на постояння подного достояння подного достояння подного достоян	NISSAN	Recall	Manufacturer Recali Issued Recali # PC786
2021 Nov 1		Motor Vehicle Dept. Happy Valley-Goose Bay, Newfoundland, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2022 Nov 1		Motor Vehicle Dept. Happy Valley-Goose Bay, Newfoundland, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2023 Jun 7	122,302 KM	Elec-Tech Auto Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2023 Sep 5		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2024 Feb 5	134,906 KM	Great Canadian Oil Change Nanaimo, British Columbia, Canada	Service Record	Vehicle serviced
2024 Apr 22	179,999 KM	Kerry 's Car & Truck Centre Parksville, British Columbia,	Service Record	Vehicle serviced

makan maraj jiji jiham maran ji ji jijika haman mara ji ji ji ji ji	ODOMETER	SOURCE	RECORD TYPE	DETAILS
, 2024 Sep 5		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2025 Feb 10		NISSAN	Recall	Manufacturer Recall Issued
				Recall # R24C6



Questions? We're here to help.

Visit us at support.carfax.ca

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track: vehicles sold by insurance companies as salvage salvage vehicles which have been rebuilt, inspected, and relicensed

- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the 8.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage. Consumers are encouraged to read ICBCs full statement of limitations at http://apps.icbc.com/registration/vchr/kimitation.html.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data registrations, actuent, information, service records, recall information, outside readings or other information where uscrepances that apply to this venicle are not rejected in this report. CARTAN Canada, its source data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided. strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, particular purpose regarding this report or its contents, weither CARPAX Canada nor any or its source data providers shall be liable for any losses, expenses or parages in connection with any report or any information. Other information about the wehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARPAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada. https://www.carfax.ca/abour-carfax/privacy-legal/conditions-of-use

© 2025 CARFAX Canada ULC. All rights reserved.

