

2014 SUBARU OUTBACK 3.6R LIMITED

Sport utility vehicle | 6 Cylinders | Gas 4S4BRJMC4E2220550

Country of Assembly: United States Last Reported Odometer: 199,055 KM



Accident/Damage Records Found



Last Registered In: British Columbia (Normal)



30 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



Questions? We're here to help.

Visit us at support.carfax.ca

No Import/Export Records Found

This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of September 11, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

# **Vehicle History Report (BC)**



## Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
@ 2014 Nov 10	North York, Ontario, Canada	A144
	Police Reported Accident: Accident reported: minor damage	
	Vehicle involved in a rear-end collision	
	with another motor vehicle	
	Damage to front	
	Estimate: Front Center   Estimate Date: 2015 jan 22	£5.500.40
		\$5,599.10
	Claim: Collision	<b></b>
		\$5,538.00



### Registration

- This vehicle has been registered in the following locations in Canada (listed oldest to newest):
  - In the province of Ontario with Normal branding.
  - In the province of British Columbia with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



### **Service Records**

DATE	ODOMETER	SOURCE	DETAILS	
2014 Jan 31	2,636 KM	Willowdale Subaru	Vehicle serviced	
		Thornhill, Ontario, Canada	Four tires balanced	
		, , , , , , , , , , , , , , , , , , , ,	Tire(s) balanced	
2014 May 1	6,614 KM	ACTIVE GREEN & ROSS	Vehicle serviced	*** *** * * **************************
		North York, Ontario, Canada	Maintenance inspection completed	
			Four wheel alignment performed	
			Oil and filter changed	
			<ul> <li>Tire condition and pressure checked</li> </ul>	
			<ul> <li>Tire(s) changed</li> </ul>	
			Tires rotated	
2014 Sep 29	15,606 KM	Willowdale Subaru	Vehicle serviced	
		Thornhill, Ontario, Canada	<ul> <li>Battery/charging system checked</li> </ul>	
			Fluids checked	
			Oil and filter changed	
2014 Nov 13	17,267 KM	ACTIVE GREEN & ROSS	Vehicle serviced	
		North York, Ontario, Canada	Four wheel alignment performed	
			Tire condition and pressure checked	
			Tire(s) balanced	
			Tires rotated	

	ODOMETER	SOURCE	DETAILS
2015 May 6	26,882 KM	ACTIVE GREEN & ROSS North York, Ontario, Canada	Vehicle serviced  Maintenance inspection completed  Brakes serviced  Oil and filter changed  Tire condition and pressure checked  Tire(s) balanced  Windshield washer checked
2015 Nov 23	41,944 KM	Active Green & Ross Thornhill, Ontario, Canada	Vehicle serviced     Four tires balanced     Tire(s) balanced     Tires rotated
2016 Dec 9	73,533 KM	Active Green & Ross Toronto, Ontario, Canada	Vehicle serviced  Tire condition and pressure checked Tire(s) changed Wiper(s) replaced
2017 Apr 12	81,582 KM	Active Green & Ross Toronto, Ontario, Canada	Vehicle serviced  Maintenance inspection completed Alignment checked Four tires balanced Four tires mounted Oil and filter changed Tire condition and pressure checked Tire repaired Tire valve stem(s)/core(s) replaced
2017 Apr 28	82,254 KM	Willowdale Subaru Thornhill, Ontario, Canada	Vehicle serviced
2017 Aug 10	88,131 KM	Active Green & Ross Toronto, Ontario, Canada	Vehicle serviced  Maintenance inspection completed Four wheel alignment performed Oil and filter changed Tie rod end(s) replaced Tire repaired
2017 Nov 6	91,765 KM	Active Green & Ross Toronto, Ontario, Canada	Vehicle serviced  Maintenance inspection completed  Four tires balanced  Lights checked  Oil and filter changed  Tail light bulb(s) replaced  Tire(s) balanced  Tire(s) changed
2017 Nov 22	93,450 KM	Willowdale Subaru Thornhill, Ontario, Canada	Vehicle serviced  • Four wheel alignment performed  • Interior trim checked  • Steering/suspension checked
2018 Jan 10	95,123 KM	Active Green & Ross Toronto, Ontario, Canada	Vehicle serviced  Maintenance inspection completed Headlight bulb(s) replaced Headlight(s) replaced
2018 Apr 26		Active Green & Ross Toronto, Ontario, Canada	Vehicle serviced  • Maintenance inspection completed  • Oil and filter changed  • Tire condition and pressure checked  • Tire(s) changed

	ODOMETER	SOURCE	DETAILS
2018 Sep 17	104,440 KM	Active Green & Ross Toronto, Ontario, Canada	Vehicle serviced  Maintenance inspection completed  Air filter replaced  Cabin air filter replaced/cleaned  Light bulb(s) replaced  Oil and filter changed
2018 Nov 5	106,146 KM	Active Green & Ross Toronto, Ontario, Canada	Vehicle serviced
2019 May 10	111,682 KM	Active Green & Ross Toronto, Ontario, Canada	Vehicle serviced  • Maintenance inspection completed  • Fluids checked  • Oil and filter changed
2019 Aug 13	116,882 KM	Willowdale Subaru Thornhill, Ontario, Canada	Vehicle serviced
2019 Nov 5	120,527 KM	Active Green & Ross Toronto, Ontario, Canada	Vehicle serviced  • Maintenance inspection completed  • Air filter replaced  • Cabin air filter replaced/cleaned  • Fog light bulb(s) replaced  • Oil and filter changed
2020 May 27	132,639 KM	Active Green & Ross Toronto, Ontario, Canada	Vehicle serviced  Maintenance inspection completed  Lug nut(s)/bolt(s) replaced  Oil and filter changed
2020 Aug 26	138,151 км	Active Green & Ross Toronto, Ontario, Canada	Vehicle serviced  Maintenance inspection completed  Headlight bulb(s) replaced  Lights checked  Oil and filter changed  Rear wiper blade replaced  Wiper(s) replaced
2020 Nov 23	147,249 KM	Octagold Ventures LTD North Vancouver, British Columbia, Canada	Vehicle serviced  • Air filter replaced  • Oil and filter changed
2021 Jan 22	149,373 KM	Octagold Ventures LTD North Vancouver, British Columbia, Canada	Vehicle serviced
2021 Dec 9	161,408 KM	Kal Tire - Vancouver Vancouver, British Columbia, Canada	Vehicle serviced  One tire balanced  One tire mounted
2022 Mar 15	165,289 KM	Midas Auto Service Experts Vancouver, British Columbia, Canada	Vehicle serviced  Oil and filter changed  Tires rotated
2023 Nov 14	186,059 KM	Kal Tire 673 Vancouver, British Columbia, Canada	Vehicle serviced  Alignment checked  Wipers/washers checked
2024 Mar 14	189,537 KM	Jiffy Lube #3003 Vancouver, British Columbia, Canada	Vehicle serviced  Maintenance inspection completed  Oil and filter changed

	ODOMETER	SOURCE	DETAILS
2024 May 15	190,070 KM	Kal Tire - Vancouver Vancouver, British Columbia, Canada	Vehicle serviced  • Alignment checked
2024 Dec 11	198,569 KM	Kal Tire - Vancouver Vancouver, British Columbia, Canada	Vehicle serviced  • Alignment checked
2025 Jan 10	199,055 км	Jiffy Lube #3003 Vancouver, British Columbia, Canada	Vehicle serviced  • Maintenance inspection completed  • Air filter checked  • Air filter replaced  • Fluids checked  • Oil and filter changed  • Windshield washer checked

## Open Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and nonsafety related recall campaigns, please contact SUBARU or visit Subaru's website. (https://www.subaru.ca/WebPage.aspx?WebSiteID=282&WebPageID=21091)



### Stolen Vehicle Check

This vehicle is not actively declared stolen.



## **Detailed History**

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2013 Dec 20		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Personal Vehicle colour noted as black
2014 Jan 31	2,636 KM	Willowdale Subaru Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2014 May 1	6,614 KM	ACTIVE GREEN & ROSS North York, Ontario, Canada	Service Record	Vehicle serviced
2014 Sep 29	15,606 KM	Willowdale Subaru Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2014 Nov 10		Police Reported Accident Ontario, Canada	Police Report	Accident Reported:     minor damage     Vehicle involved in a rear-end collision     with another motor vehicle     Damage to front
2014 Nov 10		Insurance Records Ontario, Canada		

, and the second	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2014 Nov 13	17,267 KM	ACTIVE GREEN & ROSS North York, Ontario, Canada	Service Record	Vehicle serviced
2015 Jan 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2015 Jan 22	20,067 KM	Insurance Records North York, Ontario, Canada	Estimate Repair	Incident Date: 2014-11-10 Front Center
2015 May 6	26,882 KM	ACTIVE GREEN & ROSS North York, Ontario, Canada	Service Record	Vehicle serviced
2015 Nov 23	41,944 KM	Active Green & Ross Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2016 Dec 9	73,533 KM	Active Green & Ross Toronto, Ontario, Canada	Service Record	Vehicle serviced
2017 Jan 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2017 Apr 12	81,582 KM	Active Green & Ross Toronto, Ontario, Canada	Service Record	Vehicle serviced
2017 Apr 28	82,254 KM	Willowdale Subaru Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2017 Aug 10	88,131 KM	Active Green & Ross Toronto, Ontario, Canada	Service Record	Vehicle serviced
2017 Nov 6	91,765 KM	Active Green & Ross Toronto, Ontario, Canada	Service Record	Vehicle serviced
2017 Nov 22	93,450 KM	Willowdale Subaru Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2018 Jan 10	95,123 KM	Active Green & Ross Toronto, Ontario, Canada	Service Record	Vehicle serviced
2018 Apr 26		Active Green & Ross Toronto, Ontario, Canada	Service Record	Vehicle serviced
2018 Sep 17	104,440 KM	Active Green & Ross Toronto, Ontario, Canada	Service Record	Vehicle serviced
2018 Nov 5	106,146 KM	Active Green & Ross Toronto, Ontario, Canada	Service Record	Vehicle serviced
2019 May 10	111,682 KM	Active Green & Ross Toronto, Ontario, Canada	Service Record	Vehicle serviced
2019 Aug 13	116,882 KM	Willowdale Subaru Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2019 Nov 5	120,527 KM	Active Green & Ross Toronto, Ontario, Canada	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2020 May 27	132,639 KM	Active Green & Ross Toronto, Ontario, Canada	Service Record	Vehicle serviced
2020 Aug 26	138,151 KM	Active Green & Ross Toronto, Ontario, Canada	Service Record	Vehicle serviced
2020 Nov 23	147,249 KM	Octagold Ventures LTD North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2021 Jan 22	149,373 KM	Octagold Ventures LTD North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2021 Mar 5	And the second s	Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2021 Dec 9	161,408 KM	Kal Tire - Vancouver Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2022 Mar 15	165,289 KM	Midas Auto Service Experts Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2022 Mar 22		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2023 Apr 4		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2023 Nov 14	186,059 KM	Kal Tire 673 Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2024 Mar 14	189,537 KM	Jiffy Lube #3003 Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2024 Apr 15		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black
2024 May 15	190,070 KM	Kal Tire - Vancouver Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2024 Dec 11	198,569 KM	Kal Tire - Vancouver Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2025 Jan 10	199,055 KM	Jiffy Lube #3003 Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2025 Apr 15		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as black



### ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle addition, the estimate information may not represent the vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at http://apps.icbc.com/registration/vchr/Limitation.html.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, accident information, service records, recall information, of meter independent of the registrations, accident information, service records, recall information, of meter independent in registrations, declarations, accident information, service records, recall information, of meter independent in registrations, declarations, accident information, service records, recall information, service records, record information, service records, r satisfy of an arrange meters assay, and control canada and assay of the contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX. Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada. https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use

© 2025 CARFAX Canada ULC. All rights reserved.

