



Vehicle History Report + Lien Check (BC) #: 65239722

Report Date: October 22, 2025 | 3:34 p.m. EDT

Report Status: Complete

Reference:

2004 TOYOTA SIENNA XLE

Van passenger | 6 Cylinders | Gas

5TDZA22C14S063442

Country of Assembly: United States

Last Reported Odometer: 306,434 KM

LIEN CHECK



No Lien Records Found



Accident/Damage Records Found



Last Registered In:
British Columbia (Normal)



5 Service Records Found



No U.S. History Found



2 Open Recalls Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of October 22, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

5TDZA22C14S063442

Vehicle History Report + Lien Check (BC)



Lien Check

✓ No lien records found in **British Columbia**.

✓ No lien records found in **Nova Scotia**.

How We Check for Liens

CARFAX Canada uses the VIN to search government records in each Canadian province and territory (excluding Northwest Territories) where the vehicle is currently registered and where it has historically been registered. We do not check for liens or title in any U.S. state.

If a VIN has no registration records in Canada, we cannot check for liens. We cannot guarantee lien checks on trailers, recreational vehicles or heavy-duty equipment.

Purchasers should always get written confirmation from vendors that there is no lien on the vehicle.

CARFAX Canada Canadian Lien Guarantee



If for some reason our lien check fails to accurately reflect the Canadian enforceable lien status of a vehicle at the time of the search, CARFAX Canada will reimburse the party that purchased the report and relied on it to their detriment to a maximum amount of (1) the value of the car (2) the value of the lien (3) Five Thousand Dollars Canadian (\$5,000.00), whichever is lower.



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
❗ 2006 Jul 16	Nova Scotia, Canada	
	Claim: Collision	\$2,696.00
❗ 2016 Oct 22	British Columbia, Canada	
	Estimate: LEFT FRONT CORNER Estimate Date: n/a	\$3,408.16
	Claim: ANIMAL COLLISION LEFT FRONT CORNER	\$3,408.16



Registration

✓ This vehicle has been registered in the following locations in **Canada** (listed oldest to newest):

- In the province of **Nova Scotia** with **Normal** branding.
- In the province of **British Columbia** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2013 Apr 12	221,941 KM	Mid Island Brake & Muffler Ltd. Courtenay, British Columbia, Canada	Vehicle serviced Oil and filter changed
2017 Feb 21	269,654 KM	Kal Tire 060 Courtenay, British Columbia, Canada	Vehicle serviced Brakes checked
2018 Jun 12	282,255 KM	Mid Island Brake & Muffler Ltd. Courtenay, British Columbia, Canada	Vehicle serviced - Oil and filter changed - Rear spring(s) replaced - Transmission fluid changed - Transmission fluid flushed
2019 Jul 27	293,982 KM	Kal Tire 060 Courtenay, British Columbia, Canada	Vehicle serviced Battery/charging system checked
2022 Dec 30	306,434 KM	Kal Tire 060 Courtenay, British Columbia, Canada	Vehicle serviced Tire repaired



Open Recalls

Recall #: CAN220 | 220 - Remedy Notice - Certain 2004-2005 and 2007-2009 model year Sienna vehicles - Shift Lock Solenoid Assembly

Recall Date: 2013
Sep 26

Recall Description

The subject vehicles are equipped with a shift lever assembly which contains a shift interlock system. One of the components of the interlock system is a shift lock solenoid to prevent the shift lever from moving out of P position unless the ignition is ON and the brake pedal is depressed. Due to manufacturing issues, there is a possibility that the solenoid could be damaged and the shift lever could be moved out of P position without depressing the brake pedal. This could result in a vehicle roll away, which could cause a crash.

Remedy

Any Toyota dealer will replace the shift lock solenoid assembly in the subject vehicle.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact TOYOTA or visit [Toyota's website](https://www.toyota.ca/toyota/en/owners/recalls). (<https://www.toyota.ca/toyota/en/owners/recalls>)

Recall #: CAN243 | 243 - Remedy Notice - Certain 2004-2011 Model Year Sienna vehicles. Sienna Spare Tire Cable Assembly

Recall Date: 2014
May 22

Recall Description

The 2004 through 2011 model year Sienna 2WD vehicles equipped with a spare tire carrier stowed under the vehicle have a light-weight, foam water splash protector installed in front of the spare tire carrier. Due to variation in the placement of the splash protector or loss of the protector during normal usage, water splashed rearward with high concentrations of road salt can reach the spare tire carrier and corrode the spare tire carrier assembly cable. If the vehicle is operated in cold climate regions where road salt is frequently used, in an extreme case, the cable may break due to excessive corrosion and the spare tire may separate from the vehicle, increasing the risk of a crash.

Remedy

Toyota will inspect and, if necessary, replace the entire Spare Tire Carrier assembly with an improved carrier

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed,



Stolen Vehicle Check

✓ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2003 Jan 1		Motor Vehicle Dept. Nova Scotia, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2004 Jan 1		Motor Vehicle Dept. Nova Scotia, Canada	Canadian Renewal	Registration Issued or Renewed
2004 Mar 11		Motor Vehicle Dept. Nova Scotia, Canada	Canadian Renewal	Registration Issued or Renewed
2005 Jan 1		Motor Vehicle Dept. Nova Scotia, Canada	Canadian Renewal	Registration Issued or Renewed
2006 Jan 1		Motor Vehicle Dept. Nova Scotia, Canada	Canadian Renewal	Registration Issued or Renewed
2006 Jul 16		Insurance Records Nova Scotia, Canada		
2007 Nov 6		Motor Vehicle Dept. Nova Scotia, Canada	Registration Records	Registered/Renewed
2007 Nov 6		Motor Vehicle Dept. Nova Scotia, Canada	Canadian Renewal	Registration Issued or Renewed
2008 Nov 29		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2009 Oct 31		Motor Vehicle Dept. Nova Scotia, Canada	Registration Records	Registration Expired
2009 Nov 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2010 Nov 27		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2011 Dec 3		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2012 Sep 8		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2013 Mar 9		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2013 Apr 12	221,941 KM	Mid Island Brake & Muffler Ltd. Courtenay, British Columbia, Canada	Service Record	Vehicle serviced
2013 Sep 26		TOYOTA	Recall	Manufacturer Recall Issued Recall # CAN220
2014 Mar 8		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2014 May 22		TOYOTA	Recall	Manufacturer Recall Issued Recall # CAN243
2015 Mar 7		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Mar 12		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Oct 22		Insurance Records British Columbia, Canada	ANIMAL COLLISION	LEFT FRONT CORNER
2016 Oct 22		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a LEFT FRONT CORNER
2017 Feb 21	269,654 KM	Kal Tire 060 Courtenay, British Columbia, Canada	Service Record	Vehicle serviced
2017 Mar 11		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Mar 10		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Jun 12	282,255 KM	Mid Island Brake & Muffler Ltd. Courtenay, British Columbia, Canada	Service Record	Vehicle serviced
2019 Feb 24		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Jul 27	293,982 KM	Kal Tire 060 Courtenay, British Columbia, Canada	Service Record	Vehicle serviced
2020 Mar 6		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Feb 21		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2022 Mar 6		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2022 Dec 30	306,434 KM	Kal Tire 060 Courtenay, British Columbia,	Service Record	Vehicle serviced

5TDZA22C14S063442

ODOMETER	SOURCE	RECORD TYPE	DETAILS
	Canada		
2023 Mar 12	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2024 Mar 12	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2025 Mar 12	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2025 Oct 15	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as gray



Questions? We're here to help.

Visit us at support.carfax.ca

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registration/vchr/Limitation.html>.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2025 CARFAX Canada ULC. All rights reserved.

