



ISLAND AUTOMOTIVE

250-248-8995

Auto Repair

 Satisfactory
 May Require Further Attention
 Requires Immediate Attention

STOCK #	14125	VEHICLE	09 MATRIX
CUSTOM		ODOMETER	231021

Interior / Exterior

Headlights (check high and low beam)

Tailights

Turn signal

Brake lights

Hazard warning lights

Interior lights

Windshield washer spray, operation, blades

Parking brake

Horn operation

Battery Performance

Pass

Fail

Under Hood

Engine oil level New

Coolant level & Protection level -46°C

Power steering fluid level

Brake fluid level*

Windshield washer fluid level

Transmission fluid level

External drive belts and radiator hoses

Oil filters

Under Vehicle

Brake lines/Hoses/Parking brake cable

Shock absorbers/Struts/Suspension

Exhaust System

Engine oil and/or fluid leaks

Drive shaft/Constant velocity boots & bands

Tire Condition

 25 - 4.5mm

 4 - 2.5mm

 2mm or less

Left Front

  

Wear Pattern

Wear Pattern

Right Front

  

Tire thread 6/mm

Tire thread 6/mm

Left Rear

  

Wear Pattern

Wear Pattern

Right Rear

  

Tire thread 7/mm

Tire thread 7/mm

Front tire inflation set to: 32 psi

Rear tire inflation set to: 32 psi

Brake Condition

 5mm or more

 3 - 4mm

 2mm or less

Left Front

  

8 mm 90 %

8 mm 90 %

Right Front

  

Left Rear

  

8 mm 90 %

8 mm 90 %

Right Rear

  

Comments:

- New oil + Filter