

COMPLETE

31-POINT INSPECTION

Date Nov 14/85

Year / Make / Model

2009 CHEV AVALANCHE

VIN 3GNFK12091209625

Mileage 342072 k.m.

Stock 152

OK Checked and OK

MR May Require Further Attention

RA Requires immediate Attention

Under Hood Inspection

- 1 Check Battery Voltage/Amperage/Charging
- 2 Check Starter
- 3 Check Coolant Levels
- 4 Check Oil levels
- 5 Check Power Steering
- 6 Check Master Brake Cylinder
- 7 Check Belts
- 8 Check Ignition System
- 9 Check Engine & Trans Support

OK	MR	RA
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☒	☐
☒	☐	☐

Comments

KEY/IGNITION WORN HARD TO GET KEY TO WORK

Interior Inspection

- 10 Check Seat Belts
- 11 Check Instrument Panel, Warning Lights
- 12 Check Front & Rear Defroster
- 13 Check Hazard Lights & Horn
- 14 Check Power Lock System
- 15 Check Hood Latch & Fuel Filler Door Cable
- 16 Check Air Bag System
- 17 Check inside Rear-view Mirror

OK	MR	RA
☒	☐	☐
☒	☐	☒
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☒	☐
☒	☐	☐

CHECK ENGINE LIGHTS
AIR BAG FAULTS
LOW TIRE FAULTS

AIR BAG FAULTS

Exterior Inspection

- 18 Check Windshield, Wiper arms and Blades
- 19 Check Outside Mirrors
- 20 Check All Exterior Lights
- 21 Check Wheels & Spare Tire

OK	MR	RA
☒	☒	☐
☒	☐	☐
☒	☐	☒
☒	☐	☒

CHIPPED GLASS
L/S HIGH BEAM OUT.
L/S REVERSE LIGHT OUT.

Inspection Under Hood

- 22 Check Physical Damage
- 23 Check Upper & Lower Ball Joints
- 24 Check Brake Calipers/Wheel Cylinders/Tubes
- 25 Check Struts/Shocks
- 26 Check Tie Rod Ends/CV Boots
- 27 Check Upper & Lower Control Arms
- 28 Check Sway Bars Bushings
- 29 Check Emergency Brake Cables
- 30 Check Front / Rear Brakes
- 31 Check Tires

OK	MR	RA
☒	☒	☐
☒	☐	☐
☒	☐	☐
☒	☐	☒
☒	☐	☒
☒	☐	☒
☒	☐	☒
☒	☐	☒
☒	☐	☒
☒	☐	☐
☒	☐	☐

RUSTED OUT

REAR COIL SPRINGS BROKEN

R/S FRONT WHEEL BEARING WORN OUT.

PARK BRAKE NOT WORKING.

Front Wear - 20%

Rear Wear - 20%

9/32

9/32

Notes

OIL LEAKS, FRAME VERY RUSTY.

CURTIS