

# COMPLETE

## 31-POINT INSPECTION

Date Nov 21/25 Year / Make / Model 2011 GMC SIERRA  
 VIN 1GTR2VE30B72166907 Mileage 147880kms. Stock 156

**OK** Checked and OK      **MR** May Require Further Attention      **RA** Requires immediate Attention

### Under Hood Inspection

|   | OK                               | MR                    | RA                    | Comments |
|---|----------------------------------|-----------------------|-----------------------|----------|
| 1 Check Battery Voltage/Amperage/Charging | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> |          |
| 2 Check Starter                           | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> |          |
| 3 Check Coolant Levels                    | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> |          |
| 4 Check Oil levels                        | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> |          |
| 5 Check Power Steering                    | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> |          |
| 6 Check Master Brake Cylinder             | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> |          |
| 7 Check Belts                             | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> |          |
| 8 Check Ignition System                   | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> |          |
| 9 Check Engine & Trans Support            | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> |          |

### Interior Inspection

|  | OK                               | MR                    | RA                    | Comments |
|--|----------------------------------|-----------------------|-----------------------|----------|
| 10 Check Seat Belts                          | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> |          |
| 11 Check Instrument Panel, Warning Lights    | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> |          |
| 12 Check Front & Rear Defroster              | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> |          |
| 13 Check Hazard Lights & Horn                | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> |          |
| 14 Check Power Lock System                   | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> |          |
| 15 Check Hood Latch & Fuel Filler Door Cable | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> |          |
| 16 Check Air Bag System                      | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> |          |
| 17 Check inside Rear-view Mirror             | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/> |          |

### Exterior Inspection

|  | OK                               | MR                    | RA                               | Comments                     |
|--|----------------------------------|-----------------------|----------------------------------|------------------------------|
| 18 Check Windshield, Wiper arms and Blades | <input checked="" type="radio"/> | <input type="radio"/> | <input checked="" type="radio"/> | WINDSHIELD CHIPPED + CRACKED |
| 19 Check Outside Mirrors                   | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/>            |                              |
| 20 Check All Exterior Lights               | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/>            |                              |
| 21 Check Wheels & Spare Tire               | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/>            |                              |

### Inspection Under Hood

|   | OK                               | MR                    | RA                               | Comments  |
|---|----------------------------------|-----------------------|----------------------------------|---|
| 22 Check Physical Damage                      | <input checked="" type="radio"/> | <input type="radio"/> | <input checked="" type="radio"/> | ★ FRAME RUSTED OUT. HOLE IN FRAME.                    |
| 23 Check Upper & Lower Ball Joints            | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/>            |   |
| 24 Check Brake Calipers/Wheel Cylinders/Tubes | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/>            |   |
| 25 Check Struts/Shocks                        | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/>            |   |
| 26 Check Tie Rod Ends/CV Boots                | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/>            |   |
| 27 Check Upper & Lower Control Arms           | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/>            |   |
| 28 Check Sway Bars Bushings                   | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/>            |   |
| 29 Check Emergency Brake Cables               | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/>            |   |
| 30 Check Front / Rear Brakes                  | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/>            | Front Wear - 80%<br>9/32      Rear Wear - 20%<br>7/32 |
| 31 Check Tires                                | <input checked="" type="radio"/> | <input type="radio"/> | <input type="radio"/>            |   |

**Notes**  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

*Tan*

*Curator*