

COMPLETE

31-POINT INSPECTION

Date Dec 5/25 Year / Make / Model 2014 Ford F150
 VIN 1FTFW1ET7EKF96365 Mileage 214644 kms Stock ØG

☒ OK Checked and OK ☒ MR May Require Further Attention ☐ RA Requires immediate Attention

	OK	MR	RA	Comments
Under Hood Inspection				
1 Check Battery Voltage/Amperage/Charging	☒	☐	☐	
2 Check Starter	☒	☐	☐	
3 Check Coolant Levels	☒	☐	☐	
4 Check Oil levels	☒	☐	☐	
5 Check Power Steering	☒	☐	☐	
6 Check Master Brake Cylinder	☒	☐	☐	
7 Check Belts	☒	☐	☐	
8 Check Ignition System	☒	☐	☐	
9 Check Engine & Trans Supports	☒	☐	☐	
Interior Inspection				
10 Check Seat Belts	☒	☐	☐	
11 Check Instrument Panel, Warning Lights	☒	☒	☐	<u>LOW TIRE FAULTS</u>
12 Check Front & Rear Defroster	☒	☐	☐	
13 Check Hazard Lights & Horn	☒	☐	☐	
14 Check Power Lock System	☒	☐	☐	
15 Check Hood Latch & Fuel Filler Door Cable	☒	☐	☐	
16 Check Air Bag System	☒	☐	☐	
17 Check inside Rear-view Mirror	☒	☐	☐	
Exterior Inspection				
18 Check Windshield, Wiper arms and Blades	☒	☐	☐	
19 Check Outside Mirrors	☒	☐	☐	
20 Check All Exterior Lights	☒	☐	☐	
21 Check Wheels & Spare Tire	☒	☐	☐	
Inspection Under Hood				
22 Check Physical Damage	☒	☐	☐	
23 Check Upper & Lower Ball Joints	☒	☐	☐	
24 Check Brake Calipers/Wheel Cylinders/Tubes	☒	☐	☐	
25 Check Struts/Shocks	☒	☐	☐	
26 Check Tie Rod Ends/CV Boots	☒	☐	☐	
27 Check Upper & Lower Control Arms	☒	☐	☐	
28 Check Sway Bars Bushings	☒	☐	☐	
29 Check Emergency Brake Cables	☒	☐	☐	
30 Check Front / Rear Brakes	☒	☐	☐	Front Wear - <u>90%</u> Rear Wear - <u>90%</u>
31 Check Tires	☒	☐	☐	<u>6/32</u> <u>6/32</u>

Notes
SIGNS OF COOLANT IN OIL -
POSSIBLE HEAD GASKET ISSUE
Curtis