

COMPLETE

31-POINT INSPECTION

Date DEC 5/25 Year / Make / Model 2009 CHEV AVEO
 VIN KL1TV55E39B349226 Mileage 176514 kms Stock 1

☒ OK Checked and OK

☐ MR May Require Further Attention

☐ RA Requires immediate Attention

Under Hood Inspection

- 1 Check Battery Voltage/Amperage/Charging
- 2 Check Starter
- 3 Check Coolant Levels
- 4 Check Oil levels
- 5 Check Power Steering
- 6 Check Master Brake Cylinder
- 7 Check Belts
- 8 Check Ignition System
- 9 Check Engine & Trans Supports

OK	MR	RA	Comments
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☒	ADDED 2L 5W30
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	

Interior Inspection

- 10 Check Seat Belts
- 11 Check Instrument Panel, Warning Lights
- 12 Check Front & Rear Defroster
- 13 Check Hazard Lights & Horn
- 14 Check Power Lock System
- 15 Check Hood Latch & Fuel Filler Door Cable
- 16 Check Air Bag System
- 17 Check inside Rear-view Mirror

OK	MR	RA	Comments
☒	☐	☐	
☒	☒	☐	CHECK ENGINE LIGHT ON.
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	

Exterior Inspection

- 18 Check Windshield, Wiper arms and Blades
- 19 Check Outside Mirrors
- 20 Check All Exterior Lights
- 21 Check Wheels & Spare Tire

OK	MR	RA	Comments
☒	☐	☐	
☒	☐	☐	
☒	☐	☒	L/S BRAKE LIGHT OUT.
☒	☐	☐	

Inspection Under Hood

- 22 Check Physical Damage
- 23 Check Upper & Lower Ball Joints
- 24 Check Brake Calipers/Wheel Cylinders/Tubes
- 25 Check Struts/Shocks
- 26 Check Tie Rod Ends/CV Boots
- 27 Check Upper & Lower Control Arms
- 28 Check Sway Bars Bushings
- 29 Check Emergency Brake Cables
- 30 Check Front / Rear Brakes
- 31 Check Tires

OK	MR	RA	Comments
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☐	
☒	☐	☒	PARK BRAKE STICKS ON
☒	☐	☒	Front Wear - 70% Rear Wear - 0%
☒	☐	☒	3/32 6/32

Notes

100 ENGINE OIL LEAKS.

CW