



Vehicle Inspection Form

Stock #: P3572 Year: 2012 Make: BUICK Model: ENCLOSURE
 V.I.N. #: 5GAKUKKDSH52711140 Odometer: 102752

ENGINE	Good	Service Required	Repaired
Change Oil, Lube Filter (Mandatory)	/		
Noise (Lifter, Piston) (Hot and Cold)	/		
Motor Mounts	/		
Turbo/Supercharger (If Equipped)			
Fluid Leaks:			
Intake	/		
Oil Pan	/		
Cylinder Heads	/		
Rear Main	/		
Misc.			
TRANSMISSION/TRANSFER CASE	Good	Service Required	Repaired
Fluid Level/Condition (Clean, Discoloured)			
Shift Quality (Synchro's) (If Manual)			
Shift Points (If Automatic)	/		
Slipping (If Automatic)	/		
Fluid Leaks/Seals/Gaskets	/		
DRIVE AXLE	Good	Service Required	Repaired
Noise/Vibration	/		
Fluid Leaks/Seals/Gaskets			
CV/U Joints/Drive Shaft/Sleady Bearing	/		
Wheel Bearings/Spindles	/		
CV boots	/		
Locking Hubs			
Hub/Bearing Assembly			
STEERING	Good	Service Required	Repaired
Fluid Level/Leaks			
Steering Rack inc. Bellows	/		
Lines/Hoses/Pump	/		
Linkages/Tie Rods/Couplings	/		
Idle/Pitman Arms			
Steering Dampener			
Alignment Pull			
BRAKE SYSTEM	Good	Service Required	Repaired
Master Cylinder/Fluid Level	/		
Pump/Booster	/		
Caliper/Wheel Cylinders	/		
Anti-Lock Brakes (Is the Light On?)	/		
ABS Check for Codes	/		
Inspect Brake Lines for Cracks (Steel/Rubber)	/		
Pads% Remaining LF <u>10</u> RF <u>10</u> RR <u>8</u> RR <u>8</u>			
Tires% Remaining LF <u>5</u> RF <u>5</u> LR <u>5</u> RR <u>5</u>			
AIR CONDITIONING	Good	Service Required	Repaired
Blower Motor (All Speeds)			
Compressor/Clutch			
Condenser/Evaporator			
Idle pulley			
A/C Temperature Reading		/	°C

**Shaded Areas Require
Reinspection After 120 Days**

ELECTRICAL	Good	Service Required	Repaired
Alternator <u>144</u> Volts _____ Amps	/		
Starter/Solenoid/Drive	/		
Power Windows/Seal Motor	/		
Wiper Motors/Washers	/		
Power Locks/Trunk Release	/		
Power Roof Motor			
Power Antenna			
Rear Defroster	/		
All Manual Switches	/		
Cruise Control	/		
Computer Scan Codes	/		
Speedometer/Odometer	/		
Instrument Panel/Gauges/Lights	/		
Horn/Warning Indicators	/		
Radio/CD/Tape/Speakers/Amp	/		
FRONT/REAR SUSPENSION	Good	Service Required	Repaired
Control Arms/Bushings	/		
Ball Joints Specs LU _____ RU _____ LL _____ RL _____ (in Thousands of an inch) Rear LL _____ RL _____	/		
Mounts/Bushings	/		
Shocks/Springs/Struts	/		
Torsion Bars/Radius Arms			
Stabilizer Shaft/Links/Bushings	/		
Electronic Air Suspension			
COOLING/FUEL SYSTEM	Good	Service Required	Repaired
Water Pump/Thermostat	/		
Engine Fan/Module/Clutch	/		
Belts & Hoses	/		
Radiator/Heater Core	/		
Coolant Level/Condition/Leaks	/		
Coolant Strength/Condition	/		
Coolant System Pressure Test	/		
Fuel Tank/Lines	/		
Fuel Injection Pump/Vacuum Pump	/		
ROAD TEST	Good	Service Required	Repaired
Engine Performance			
Transmission Performance	/		
Up/Down Shifting Smoothness	/		
Transmission Noise/Vibration	/		
Rear Differential Performance	/		
Rear Differential Noise/Vibration	/		
Transfer Case Performance (4x4)	/		
Transfer Case Noise/Vibration (4x4)	/		
Brake Performance (Inc. ABS)	/		
Brake Noise/Vibration	/		
Suspension Noise/Vibration	/		
ALTERATIONS/MODIFICATIONS			
Lift Kit Yes _____ No _____			
Air Induction System Altered Yes _____ No _____			
Tire Size Matches Vehicle Build Plate Yes _____ No (oversized) _____			

Dealership: _____

R.O # Attached: 342230

[Signature]
Technician Signature

10/15/12
Date

Technician Name: SHAWN

Technician License #: 5222

Used Vehicle Manager Signature _____ Date _____

I acknowledge receipt of this inspection report and understand it's contents, signing below I agree that the vehicle I've purchased from Nanaimo Mitsubishi has been fully inspected to my satisfaction and no mechanical work is required to complete the sale of this vehicle unless otherwise noted on the Bill of Sale.

Customer Signature : _____ Date : _____

Nanaimo Mitsubishi Representative : _____ Date : _____