COMPLETE
31-POINT INSPECTION

Date Jan 5 2026 Year / Make / Model 2017 BMW X1

VIN WBXHT3C3945F74294 Mileage 162218 Stock

(OK) Checked and OK (MR) May Require Further Attention (RA) Requires immediate Attention

	OK	MR	RA	Comments
Under Hood Inspection				
1 Check Battery Voltage/Amperage/Charging	✓			
2 Check Starter	✓			
3 Check Coolant Levels	✓			
4 Check Oil levels	✓			
5 Check Power Steering	✓			
6 Check Master Brake Cylinder	✓			
7 Check Belts	✓			
8 Check Ignition System	✓			
9 Check Engine & Trans Supports	✓			
Interior Inspection				
10 Check Seat Belts	✓			
11 Check Instrument Panel, Warning Lights	✓			
12 Check Front & Rear Defroster	✓			
13 Check Hazard Lights & Horn	✓			
14 Check Power Lock System	✓			
15 Check Hood Latch & Fuel Filler Door Cable	✓			
16 Check Air Bag System	✓			
17 Check inside Rear-view Mirror	✓			
Exterior Inspection				
18 Check Windshield, Wiper arms and Blades	✓			
19 Check Outside Mirrors	✓			
20 Check All Exterior Lights	✓			
21 Check Wheels & Spare Tire	✓			
Inspection Under Hood				
22 Check Physical Damage	✓			
23 Check Upper & Lower Ball Joints	✓			
24 Check Brake Calipers/Wheel Cylinders/Tubes	✓			
25 Check Struts/Shocks	✓			
26 Check Tie Rod Ends/CV Boots	✓			
27 Check Upper & Lower Control Arms	✓			
28 Check Sway Bars Bushings	✓			
29 Check Emergency Brake Cables	✓			
30 Check Front / Rear Brakes	✓			Front Wear - 70% Rear Wear - 70%
31 Check Tires	✓			

SIGNS of COOLANT LEAK

MISFIRE UNDER LOAD

Notes COOLANT LOW