

COMPLETE 31-POINT INSPECTION

Date FEB 13/26 Year / Make / Model 2014 DODGE JOURNEY.
 VIN 3C4PDCAB9ET176432 Mileage 220814 kms. Stock 102

OK Checked and OK **MR** May Require Further Attention **RA** Requires immediate Attention

Under Hood Inspection

	OK	MR	RA	Comments
1 Check Battery Voltage/Amperage/Charging	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
2 Check Starter	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
3 Check Coolant Levels	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
4 Check Oil levels	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
5 Check Power Steering	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
6 Check Master Brake Cylinder	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
7 Check Belts	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
8 Check Ignition System	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
9 Check Engine & Trans Supports	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	

Interior Inspection

10 Check Seat Belts	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
11 Check Instrument Panel, Warning Lights	<input checked="" type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	TRACTION CONTROL FAULTS ABS FAULTS
12 Check Front & Rear Defroster	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
13 Check Hazard Lights & Horn	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
14 Check Power Lock System	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
15 Check Hood Latch & Fuel Filler Door Cable	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
16 Check Air Bag System	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
17 Check inside Rear-view Mirror	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	

Exterior Inspection

18 Check Windshield, Wiper arms and Blades	<input checked="" type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	CRACKED GLASS
19 Check Outside Mirrors	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
20 Check All Exterior Lights	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
21 Check Wheels & Spare Tire	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	

Inspection Under Hood

22 Check Physical Damage	<input checked="" type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	BOTH REAR WHEEL BEARINGS FAILED.
23 Check Upper & Lower Ball Joints	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
24 Check Brake Calipers/Wheel Cylinders/Tubes	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
25 Check Struts/Shocks	<input checked="" type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	STRUTS WORN OUT
26 Check Tie Rod Ends/CV Boots	<input checked="" type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	L/S OUTER TIE ROD WORN OUT
27 Check Upper & Lower Control Arms	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
28 Check Sway Bars Bushings	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
29 Check Emergency Brake Cables	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	
30 Check Front / Rear Brakes	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	Front Wear - 30% Rear Wear - 40%
31 Check Tires	<input checked="" type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	ALL TIRES NEEDED REPLACED.

Notes
TOX
 ENGINE OIL LEAKS. OIL PAN
 RUSTED THROUGH
 CURTIS