COMPLETE
31-POINT INSPECTION

Date Feb 5 2026 Year / Make / Model 2017 BMW X1

VIN WBXHT3C3945F74094 Mileage 162218 Stock

(OK) Checked and OK (MR) May Require Further Attention (RA) Requires immediate Attention

		OK	MR	RA	Comments
Under Hood Inspection					
1	Check Battery Voltage/Amperage/Charging	✓			
2	Check Starter	✓			
3	Check Coolant Levels			✓	SIGNS OF COOLANT LEAK
4	Check Oil levels	✓			
5	Check Power Steering	✓			
6	Check Master Brake Cylinder	✓			
7	Check Belts	✓			
8	Check Ignition System			✓	MISFIRE UNDER LOAD
9	Check Engine & Trans Supports	✓			
Interior Inspection					
10	Check Seat Belts	✓			
11	Check Instrument Panel, Warning Lights	✓			
12	Check Front & Rear Defroster	✓			
13	Check Hazard Lights & Horn	✓			
14	Check Power Lock System	✓			
15	Check Hood Latch & Fuel Filler Door Cable	✓			
16	Check Air Bag System	✓			
17	Check inside Rear-view Mirror	✓			
Exterior Inspection					
18	Check Windshield, Wiper arms and Blades	✓			
19	Check Outside Mirrors	✓			
20	Check All Exterior Lights	✓			
21	Check Wheels & Spare Tire	✓			
Inspection Under Hood					
22	Check Physical Damage	✓			
23	Check Upper & Lower Ball Joints	✓			
24	Check Brake Calipers/Wheel Cylinders/Tubes	✓			
25	Check Struts/Shocks	✓			
26	Check Tie Rod Ends/CV Boots	✓			
27	Check Upper & Lower Control Arms	✓			
28	Check Sway Bars Bushings	✓			
29	Check Emergency Brake Cables	✓			
30	Check Front / Rear Brakes	✓			Front Wear - 70% Rear Wear - 70%
31	Check Tires	✓			

Notes - COOLANT LOW

- TRANSMISSION BEHAVES ODDLY, MAY BE RELATED TO MISFIRE, REQ FURTHER DIAGNOSIS