



Commercial Vehicle Inspection Report

Decal Number: FW37144
Decal Expiry Date: 2024-Jan-31
Inspection Number: 20371249

Inspection Result:
PASS

Facility: 5 POINT HEAVY EQUIPMENT / S6720 Inspection Type: Complete Inspection Start Date/Time: 2023-Jan-10 06:24 AM
Inspector: BLACKMORE, CODY MICHAEL / 300295 Inspection Class: Class 2 - Heavy Vehicle with LGW 5501 kg or more Inspection Complete Date/Time: 2023-Jan-10 08:29 AM
Work Order Number: 7036 Inspection Reason: Annual

Vehicle Jurisdiction: British Columbia Brake Type: Hydraulic Owner/Lessee Name: [Redacted]
Registration Number: 13105077 Fuel Type: Gasoline Address: [Redacted]
VIN: 3C7WRTCJ3EG191148 Odometer: 239891 KM City: [Redacted]
Plate Number: NH4788 Hub Odometer: Province/State: [Redacted]
Licenced GVW (kg): 17300 Body Style: Flat Deck Postal Code/ZIP: [Redacted]
Vehicle Year: 2014 Model: Country: [Redacted]
Make: DODGE Unit/Fleet Number: 218

	Result	Comment
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3H - Hydraulic Brakes	Passed	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Not Applicable	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Tire Tread Depth (mm)					
Axles (front)	Outer Left	Inner Left	Inner Right	Outer Right	Steering Axle?
1	10			10	
2	7	8	8	8	
Comment:					

Brake Lining/Pad Measurement (mm)			
Axles (front)	Lining/Pad	Left	Right
1	Pad	10	10
2	Pad	10	10
Comment:			

Rotor Thickness or Drum Inside Diameter Measurement (mm)			
Axles (front)	Rotor/Drum	Left	Right
1	Rotor	34.00	33.00
2	Rotor	35.00	35.00
Comment:			

Inspection Comments:

Has this Vehicle been road tested? No When?

Name of the person who did the road test:

Inspector Name: BLACKMORE, CODY MICHAEL

Signature:

This Inspection Report was submitted to CVSE on 2023-Jan-10 08:31 AM

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/MP at the Commercial Vehicle Safety Enforcement.

CVSE0014

1/10/2023 8:31:10 AM



Commercial Vehicle Inspection Report

Decal Number: GJ18302
Decal Expiry Date: 2026-Mar-31
Inspection Number: 21282858

Inspection Result:
PASS

FACILITY: 5 POINT HEAVY EQUIPMENT / S6720
INSPECTOR: BLACKMORE, CODY MICHAEL / 300295
WORK ORDER #: 8893
INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Annual
INSP. START: 2025-Mar-24 06:00 AM PDT
INSP. COMPLETE: 2025-Mar-24 08:00 AM PDT

VEHICLE JUR: British Columbia
PLATE #: NH4788
LICENCED GVW(kg): 17300
VEHICLE YEAR: 2014
MAKE: DODGE/RAM
MODEL:
REGI: 13105077
UNIT/FLEET#: 218
BODY STYLE: Flat Deck
ODOMETER: 242030 KM
HUB ODOMETER:
BRAKE TYPE: Hydraulic
FUEL TYPE: Gasoline
VIN: 3C7WRTCJ3EG191148
OWNER/LESSEE NAME:
ADDRESS:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Repaired (same day) STEADY BEARING REPLACED
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3H - Hydraulic Brakes	Passed
Section 4 - Steering	Passed
Section 5 - Instruments and Auxillary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Axles	Outer L	Inner L	Inner R	Outer R	Steering
1	12			12	✓
2	7	7	7	7	

Comment:

Lining/Pad	Left	Right
Lining (Shoe)	10	6
Lining (Shoe)	10	7

Comment:

Rotor/Drum	Left	Right
Drum	310.00	308.00
Drum	305.00	311.00

Comment:

Inspection Comments:
Has this Vehicle been road tested? No
Inspector: BLACKMORE, CODY MICHAEL
Road Test Date:
Signature:
Road Tester:

This Inspection Report was submitted to CVSE on 2025-Mar-25 01:26 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION
The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations, it is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement
CVSE0014
3/25/2025 1:26:42 PM PDT