

Glenoak Ford

A division of Victoria Ford Alliance Ltd
 651 Allandale Road
 Victoria, BC V9C 0S8
 Phone: 250-478-6171
 www.glenoakfordwestshore.com

SO# 11S26392

Status
 Printed 04/25/2025 11:37:30 AM

SERVICE INVOICE CUSTOMER COPY



User gowwarhb Page 1

Advisor	Brian Warhurst	Promised	04/22/2025 5:00 PM	Tag#	5652
Shop	S1	Opened	04/09/2025 9:37 AM	Location	
Priority	10	Cashiered		PO #	

License	Odom In	Odom Out	In Service Date	Stock No
SK5892	237379	237379	03/30/2013	
Year	Make	Model	Model Number	Color
2013	FORD	F-150	W1E	BLACK
Vehicle ID No	Selling Dealer		Extended Warranty	Delivery Date
1FTFW1ET6DKE25766				12/17/2016
Engine	3.5L ECOBOOST V6 ENGINE		Fleet #	

Request	Description	Job	CSR	Status
13	CUSTOMER STATES DRIVER SIDE TURBO IS WOBBLY -> CUSTOMER STATES VEHICLE WAS SCANNED AND THE CODE P0299 DISPLAYED AND HIS TECH SAID IT WAS RELATED - PLEASE CHECK AND ADVISE	1	GOWWAR	Original

Labor	Description	Type	Amount
13	CHECK ENGINE LIGHT ON (PLEASE USE WRITE UP JOB AID) \$159.95 (FIRST HOUR)	C	159.95
Technician	6RS -		
Cause	CHECKED FIRST FOR DTC'S , SELF TEST RETRIEVED P0299 P0016. RAN OASIS FOUND TECHNICAL SERVICE BULLETINS FOR EACH CODE.		
	Labor Total		159.95
	Request Sub-total		159.95

TSB 17 0026 ADDRESSES P0016 AND IT STATES THAT THE TIMING COMPONENTS REQUIRE REPLACING.

TSB 16 0013 FOR P0299 HAD ME TEST BOTH TURBO WASTEGATE ACTUATORS AND AS BOTH OPERATE NORMALLY AND SMOOTHLY WITH THE PRESSURE TESTER IT DOES NOT APPLY.

INSPECTED BOTH SIDE TURBOS AND MANIFOLDS , UNSURE WHAT "WOBBLY" IS REGARDING BUT THE DRIVER'S SIDE IS NOT LEAKING.

AS THE RIGHT HAND MANIFOLD STUD IS BROKEN AND LEAKING IT SHOULD BE REPAIRED BEFORE ANY FURTHER DIAGNOSIS FOR THE UNDERBOOST CODE AS THIS CAN CAUSE THIS CODE TO SET.

Correction NEEDS THE TIMING COMPONENTS REPLACED .

NEEDS THE RIGHT HAND EXHAUST MANIFOLD REPLACED.

Request	Description	Job	CSR	Status				
60	PASSENGER SIDE EXHAUST MANIFOLD IS LEAKING	2	997	Approved				
Labor	Description		Type	Amount				
60	PASSENGER SIDE EXHAUST MANIFOLD IS LEAKING		C	1,277.64				
Part	Description	Shp	OH	Bin	Type	Retail	Price	Amount
BL3Z 9430 D	MANIFOLD ASY - EXHAU	1	1	J	CSL	374.00	374.00	374.00
IN STOCK								
BL3Z 9448 C	GASKET	1	1	J	CSL	114.93	114.93	114.93

Payment is required on invoice. No statement will be issued. **No refunds or exchanges on electrical, glass or special order parts.**
 I agree that until payment in full of the within account, I hereby acknowledge the existence of a mechanic's lien in favour of the within dealer on the vehicle described herein in respect of the material supplied and services rendered under this work order for the full amount charged therefor. I further acknowledge that the said lien shall continue in force at all times, whether the vehicle is in my possession or possession of the dealer until the within account is paid in full. While the vehicle is in my possession it shall at all times be subject to repossession on the demand by the dealer until the within account is paid in full.

Indebtedness is hereby acknowledged in the sum of \$_____ being all or the balance owing for repairs, parts and accessories described on this Invoice. **Terms:** Net 30 days, interest of 2% per month (26.8% per annum) charged on all overdue accounts.

Customer Signature X_____ Date: _____

Thank you for your business!

GST# 105056725

Glenoak Ford

A division of Victoria Ford Alliance Ltd
 651 Allandale Road
 Victoria, BC V9C 0S8
 Phone: 250-478-6171
 www.glenoakfordwestshore.com

SO# 11S26392

Status
 Printed 04/25/2025 11:37:31 AM

SERVICE INVOICE CUSTOMER COPY



User gowwarhb Page 2

Advisor	Brian Warhurst	Promised	04/22/2025 5:00 PM	Tag#	5652
Shop	S1	Opened	04/09/2025 9:37 AM	Location	
Priority	10	Cashiered		PO #	

License	Odom In	Odom Out	In Service Date	Stock No
SK5892	237379	237379	03/30/2013	
Year Make	Model	Model Number	Color	
2013 FORD	F-150	W1E	BLACK	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1FTFW1ET6DKE25766			12/17/2016	
Engine	3.5L ECOBOOST V6 ENGINE	Fleet #		

IN STOCK								
CL3Z 9450 A	GASKET - EXHAUST MAN	1	1	J	CSL	37.57	37.57	37.57
IN STOCK								
W712244 S300	STUD	9	16	J	CSL	3.12	3.12	28.08
EDM								
W701706 S430	NUT - HEX. - FLANGED	8	37	J	CSL	5.40	5.40	43.20
IN STOCK								
BL3Z 9450 A	GASKET	1	3	J	CSL	50.92	50.92	50.92
IN STOCK								
W520514 S440	NUT - HEX.	2	14	J	CSL	3.41	3.41	6.82
IN STOCK								
W716667 S900	STUD	2	7	J	CSL	25.70	25.70	51.40
EDM								
BL3Z 6A968 B	CONNECTOR - OIL TUBE	2	1	PD16	CSL	18.03	18.03	36.06
J								
BL3Z 6A968 C	CONNECTOR - OIL TUBE	4	4	PD16	CSL	20.49	20.49	81.96
BL3Z 6A968 JD	CONNECTOR - OIL TUBE	2	2	PD16	CSL	24.02	24.02	48.04
BL3Z 8A520 A	TUBE ASY	1	0	9	CSL	43.14	43.14	43.14
W715673 S900	BOLT	3	6	PD55	CSL	22.11	22.11	66.33
BL3Z 8K153 AB	TUBE - WATER OUTLET	1	0	9	CSL	84.94	84.94	84.94
BL3Z 6N652 B	GASKET	1	3	PD14	CSL	14.76	14.76	14.76

Technician	946 -	Parts Total	1,082.15
Cause	REPLACE RIGHT SIDE EXHAUST MANIFOLD RE/RE RIGHT FRONT WHEEL RE/RE RIGHT FRONT WHEEL WELL LINER TIME PUNCH FOR REMOVAL OF 3 BROKEN BOLTS INSTALLED NEW COOLANT FITTINGS AND LINES, LINES WERE CORRODED	Labor Total	1,277.64
Correction	EXHAUST MANIFOLD COMES WITH A THIN COAT OF OIL TO PREVENT RUST THE CUSTOMER MAY SMEEL THAT OIL BURNING OFF THIS IS PERFECTLY NORMAL	Request Sub-total	2,359.79

Payment is required on invoice. No statement will be issued. **No refunds or exchanges on electrical, glass or special order parts.**
 I agree that until payment in full of the within account, I hereby acknowledge the existence of a mechanic's lien in favour of the within dealer on the vehicle described herein in respect of the material supplied and services rendered under this work order for the full amount charged therefor. I further acknowledge that the said lien shall continue in force at all times, whether the vehicle is in my possession or possession of the dealer until the within account is paid in full. While the vehicle is in my possession it shall at all times be subject to repossession on the demand by the dealer until the within account is paid in full.

Indebtedness is hereby acknowledged in the sum of \$ _____ being all or the balance owing for repairs, parts and accessories described on this Invoice. **Terms:** Net 30 days, interest of 2% per month (26.8% per annum) charged on all overdue accounts.

Customer Signature X _____ Date: _____

Thank you for your business!

GST# 105056725

Glenoak Ford

A division of Victoria Ford Alliance Ltd
 651 Allandale Road
 Victoria, BC V9C 0S8
 Phone: 250-478-6171
 www.glenoakfordwestshore.com

SO# 11S26392

Status
 Printed 04/25/2025 11:37:31 AM

SERVICE INVOICE CUSTOMER COPY



User gowwarhb Page 4

Advisor	Brian Warhurst	Promised	04/22/2025 5:00 PM	Tag#	5652
Shop	S1	Opened	04/09/2025 9:37 AM	Location	
Priority	10	Cashiered		PO #	

License	Odom In	Odom Out	In Service Date	Stock No
SK5892	237379	237379	03/30/2013	
Year Make	Model	Model Number	Color	
2013 FORD	F-150	W1E	BLACK	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1FTFW1ET6DKE25766			12/17/2016	
Engine	3.5L ECOBOOST V6 ENGINE	Fleet #		

Labor	Description	Type	Amount
99	LUBRICO PAYING \$2756.08 / CUSTOMER PAYS \$150 DEDUCTIBLE AND APPROVED WORK ON LINE 2	C	0.00
Technician	999GOW -		
Correction	NOTED		

Request	Description	Job	CSR	Status
60	REPLACED CAM PHASERS	5	GOWWAR	Approved

Labor	Description	Type	Amount
60	REPLACED CAM PHASERS	C	215.94

Part	Description	Shp	OH	Bin	Type	Retail	Price	Amount
AT4Z 6256 B	SPROCKET - CAMSHAFT	2	0	J	CSL	285.87	285.87	571.74
INSTOCK								
AT4Z 6C525 D	CAM	2	0	J	CSL	297.26	297.26	594.52
INSTOCK								
AT4Z 6279 D	BOLT	2	2	J	CSL	12.16	12.16	24.32
INSTOCK								
AT4Z 6279 E	BOLT	2	2	J	CSL	12.89	12.89	25.78
INSTOCK								
7T4Z 8527 A	SEAL	1	2	J	CSL	10.13	10.13	10.13
INSTOCK								
BR3Z 8507 C	GASKET - WATER PUMP	1	1	J	CSL	63.44	63.44	63.44
INSTOCK								
ZC 31 B	CLEANER - METAL SURF	1	73	1	CSL	12.63	12.63	12.63
FL 500 SB12	FILTER ASY - OIL	1	55	BCNTR	CSL	18.83	18.83	18.83
ENFILT	TXLEV ECO FEE	1	0	BULK	CSL	0.60	0.60	0.60
CXO 5W30 BSP	MOTORCRAFT SAE 5W-30	6	267	BULK	CSL	8.45	8.45	50.70
ENOIL	TXLEV EHC	6	0	BULK	CSL	0.10	0.10	0.60
CVC 13 G	ANTI-FREEZE	1	74	2	CSL	36.32	36.32	36.32
EANTICBC	TXLEV COOLANT CONTAINER LEVY	1	0	BULK	CSL	0.15	0.15	0.15
EANTILBC	TXLEV COOLANT/LTR LEVY	4	0	BULK	CSL	0.20	0.20	0.80
Technician	946 -							
Parts Total								1,410.56

Payment is required on invoice. No statement will be issued. **No refunds or exchanges on electrical, glass or special order parts.**
 I agree that until payment in full of the within account, I hereby acknowledge the existence of a mechanic's lien in favour of the within dealer on the vehicle described herein in respect of the material supplied and services rendered under this work order for the full amount charged therefor. I further acknowledge that the said lien shall continue in force at all times, whether the vehicle is in my possession or possession of the dealer until the within account is paid in full. While the vehicle is in my possession it shall at all times be subject to repossession on the demand by the dealer until the within account is paid in full.

Indebtedness is hereby acknowledged in the sum of \$ _____ being all or the balance owing for repairs, parts and accessories described on this Invoice. **Terms:** Net 30 days, interest of 2% per month (26.8% per annum) charged on all overdue accounts.

Customer Signature X _____ Date: _____

Glenoak Ford

A division of Victoria Ford Alliance Ltd
 651 Allandale Road
 Victoria, BC V9C 0S8
 Phone: 250-478-6171
 www.glenoakfordwestshore.com

SO# 11S26392

Status
 Printed 04/25/2025 11:37:32 AM

SERVICE INVOICE CUSTOMER COPY



User gowwarhb Page 5

Advisor	Brian Warhurst	Promised	04/22/2025 5:00 PM	Tag#	5652
Shop	S1	Opened	04/09/2025 9:37 AM	Location	
Priority	10	Cashiered		PO #	

License	Odom In	Odom Out	In Service Date	Stock No
SK5892	237379	237379	03/30/2013	
Year Make	Model	Model Number	Color	
2013 FORD	F-150	W1E	BLACK	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1FTFW1ET6DKE25766			12/17/2016	
Engine	3.5L ECOBOOST V6 ENGINE	Fleet #		

Cause completed cam phaser re/re
 Correction

Labor Total	215.94
Request Sub-total	1,626.50
Labor	3,567.68
Parts	3,383.38
Supplies	55.00
Sub-Total	7,006.06
GST	350.30
PST	490.42
Total Invoice	7,846.78

LUBRICO PAYING 2,990.19
\$2990.19

CUSTOMER PAY 4,856.59
\$150 DEDUDCTIBLE
+ REMAINING
TOTAL

Additional Work Authorization

Date / Time	Contact	Phone Number	Comments	Amount
04/11/2025 5:35:30 PM				\$2,517.70

Payment is required on invoice. No statement will be issued. **No refunds or exchanges on electrical, glass or special order parts.**
 I agree that until payment in full of the within account, I hereby acknowledge the existence of a mechanic's lien in favour of the within dealer on the vehicle described herein in respect of the material supplied and services rendered under this work order for the full amount charged therefor. I further acknowledge that the said lien shall continue in force at all times, whether the vehicle is in my possession or possession of the dealer until the within account is paid in full. While the vehicle is in my possession it shall at all times be subject to repossession on the demand by the dealer until the within account is paid in full.

Indebtedness is hereby acknowledged in the sum of \$_____ being all or the balance owing for repairs, parts and accessories described on this Invoice. **Terms:** Net 30 days, interest of 2% per month (26.8% per annum) charged on all overdue accounts.

Customer Signature X _____ Date: _____

Thank you for your business!

GST# 105056725