# Mandalina Control of C

## THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

MAKE Magnum  MODEL MCT 3060  SERIAL # / gbb Plant	EQUIPMENT DOWNTIME HOURS DAYS REASON PARTS LABOR OTHER	COMPONENT CODES  BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS  POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED  COMPONENT LOCATION  FRONT REAR LEFT RIGHT UPPER LOWER  OTHER
REASON FOR FAILURE: BROKEN WORN  OVERHEAT PLANNED CONTAM LEAKIN  SMOKES SHORTED VIBRATE OTHER  PROBLEM: bonght we	IG NOISY SCRATCH	DATE: DATE COMPLETED/2-11-19  MECHANIC All  JOB NAMEALOCATION JOB NUMBER  5 19
REPAIRED: shecked	sut sent	to Joves Brymmett
PARTS:		

### TEC

#### THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT COD	ES		
EQUIP. # 2210	HOURSDAYS	BASIC MACHINE HYDRAULIC ENG	GINE IMPLEMENTS		
MAKE MASIUM	REASON	POWER TRAIN ELECTRIC DRIVE TI	RAIN UNEXPLAINED		
MODEL 66	PARTS LABOR	COMPONENT LOCAT	TON		
SERIAL# 9091		FRONT REAR LEFT RIGHT L	JPPER LOWER		
HOUR METER	OTHER				
MILES					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		MECHANIC BUSAN			
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		,	JOB NUMBER		
SMOKES SHORTED VIBRATE OTHER		JOB NAME LOCATION			
PROBLEM: Jervice 4-che	PROBLEM: Jerlice & check over				
	,				
	REPAIRED: Wheel serils				
ven Tires			0		
New Tires seviced Decals					
1. 54175 /50	13 \$ 160.16	Charlies Tive	2		
wheel seals 3.23 Traile Depot					
wheel seals	94.72	TIP P			
wire	<b>ツ</b> た。	Truck 100			
50X		A SECURIT OF THE SECURITY OF T			

FOR THE PARTY OF T

#### THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION	EQUIPMENT DOWNTIME	COMPONENT CODES		
EOUIP.11 Z210	HOURSDAYS	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE Magnum	REASON	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MAKE Manun MODEL / 134 to plant	PARTS LABOR	COMPONENT LOCATION		
SERIAL#		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER	OTHER	OTHER		
MILES				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE: DATE COMPLETED 9-24-21		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC BEN		
SMOKES SHORTED VIBRATE OTHER		JOB NAME/LOCATION JOB NUMBER		
PROBLEM: Wort start				
		·		
	10.21/	· H		
REPAIRED: bad battery replaced battery				
PARTS: GRP 24	169,00	Adience		
PARTS: GIII MAUNICE		Maunice		
	And the second s			