

TEC

THORNE'S EXCAVATING COMPANY, LLC SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME		COMPONENT CODES	
QUIP. #	0521	HOURS	DAYS	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS	
MAKE	CAT	REASON		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED	
MODEL	313F	PARTS	LABOR	COMPONENT LOCATION	
SERIAL #		OTHER		FRONT REAR LEFT RIGHT UPPER LOWER	
HOUR METER	2900 HRS			OTHER	
MILES					
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED				DATE 6-22-23 DATE COMPLETED	
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH				MECHANIC All	
SMOKES SHORTED VIBRATE OTHER				JOB NAME LOCATION	
PROBLEM: check over				To Shop	
				JOB NUMBER	

REPAIRED: serviced

PARTS: Filters 543.10 Thompson

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0521</u>	HOURS _____ DAYS _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Cat</u>	REASON _____	POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>313F</u>	PARTS _____ LABOR _____	COMPONENT LOCATION		
SERIAL # _____	OTHER _____	FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER <u>3500 HRS</u>		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED		DATE <u>10-31-23</u> DATE COMPLETED <u>11-2-23</u>		
OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH		MECHANIC _____		
SMOKES SHORTED VIBRATE OTHER _____		JOB NAME/LOCATION <u>Arheim</u>	JOB NUMBER _____	
PROBLEM: <u>Service</u>				
REPAIRED: <u>Serviced</u>				
PARTS: <u>Filters</u> <u>385.23</u> <u>Thompson</u>				

TEC

THORNE'S EXCAVATING COMPANY, LLC

SINCE 1963

EQUIPMENT INFORMATION		EQUIPMENT DOWNTIME	COMPONENT CODES	
EQUIP. # <u>0521</u>	HOURS _____ DAYS _____ REASON PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS		
MAKE <u>Cat</u>		POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED		
MODEL <u>313F</u>		COMPONENT LOCATION		
SERIAL # _____		FRONT REAR LEFT RIGHT UPPER LOWER		
HOUR METER <u>1K HRS</u>		OTHER _____		
MILES _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____		DATE <u>8-6-24</u>	DATE COMPLETED <u>8-9-24</u>	
		MECHANIC <u>Anthony</u>		
		JOB NAME/LOCATION <u>Arther</u>	JOB NUMBER	
PROBLEM: <u>Service</u>				
REPAIRED: <u>Service</u>				
PARTS: <u>filters</u> <u>270.14</u> <u>Thompson</u>				

THORNE'S EXCAVATING COMPANY, LLC
SINCE 1963

SINCE 1963					
EQUIPMENT INFORMATION EQUIP. # <u>0521</u> MAKE <u>Cat</u> MODEL <u>313F</u> SERIAL # _____ HOUR METER <u>9,500 HRS</u> MILES _____	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th style="width: 50%; text-align: center;">EQUIPMENT DOWNTIME</th> <th style="width: 50%; text-align: center;">COMPONENT CODES</th> </tr> <tr> <td style="vertical-align: top;"> HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____ </td> <td style="vertical-align: top;"> BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____ </td> </tr> </table>	EQUIPMENT DOWNTIME	COMPONENT CODES	HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____
EQUIPMENT DOWNTIME	COMPONENT CODES				
HOURS _____ DAYS _____ REASON _____ PARTS _____ LABOR _____ OTHER _____	BASIC MACHINE HYDRAULIC ENGINE IMPLEMENTS POWER TRAIN ELECTRIC DRIVE TRAIN UNEXPLAINED COMPONENT LOCATION FRONT REAR LEFT RIGHT UPPER LOWER OTHER _____				
REASON FOR FAILURE: BROKEN WORN ABUSE LOOSE SEIZED OVERHEAT PLANNED CONTAM LEAKING NOISY SCRATCH SMOKES SHORTED VIBRATE OTHER _____	DATE: <u>3-11-25</u> DATE COMPLETED <u>3-14-25</u> MECHANIC <u>Ben + Bryan</u> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th style="width: 80%; text-align: center;">JOB NAME/LOCATION</th> <th style="width: 20%; text-align: center;">JOB NUMBER</th> </tr> <tr> <td style="text-align: center;"><u>Wilson Judicial</u></td> <td></td> </tr> </table>	JOB NAME/LOCATION	JOB NUMBER	<u>Wilson Judicial</u>	
JOB NAME/LOCATION	JOB NUMBER				
<u>Wilson Judicial</u>					
PROBLEM: <u>Service</u> 					
REPAIRED: <u>serviced</u> <u>replaced main pump hose</u> 					
<table style="width: 100%;"> <tr> <td style="width: 30%;"> PARTS: <u>Filters</u> <u>Hose</u> </td> <td style="width: 30%; text-align: center;"> <u>255.70</u> <u>344.72</u> </td> <td style="width: 40%; text-align: center;"> <u>Thompson</u> <u>Thompson</u> </td> </tr> </table>		PARTS: <u>Filters</u> <u>Hose</u>	<u>255.70</u> <u>344.72</u>	<u>Thompson</u> <u>Thompson</u>	
PARTS: <u>Filters</u> <u>Hose</u>	<u>255.70</u> <u>344.72</u>	<u>Thompson</u> <u>Thompson</u>			